

October-24 PUBLIC WORKS MONTHLY REPORT

DEDARTMENT	LIQUIDO V	EADO TOTAL	
DEPARTMENT	HOURS Y	EARS TOTAL	London Administration of TAC has a fallent assistance of a section Od 5
			402.0 hours of street repair, 74.0 hours of alley repair, 101.0 hours of sweeping, 91.5 hours of repair of street equipment, 100.0 hours of shop cleanup/shop equipment, 47.0
TREET	700 F	6783 5	hours of repair of street requipment, 100 o nours of snow removal.
IKEEI	720.5	6/63.3	nous of Jepail of Street Harkers/signage, 24 o Hours of Show Temoval.
		-	
TREET SWEEPING	101	1051 5	101.0 hours of street sweeping, 148.5 tons of debris pick up, 273 total miles with 244 Miles
			residential streets and 29 business miles pick up, \$24.00 cost per mile.
		13	
-			
CE & SNOW	24	588	24.0 hours of snow removal related operations.
			Installation of snow boxes and preparing sander units. Preping new AMI snow blade to
			loader.
25			
ARKS	502	4683 5	294.5 Hrs. of Mowing/Landscaping. 151.5 Hrs. of Watering, 5.5 Hrs. of Office & Records
			45.5 Hrs. of Park Equipment Maintenance, 11.0 Hrs. of Park Clean up, garbage, leaves
			5.0 Hrs of Replacement Repair of Playground Equipment.
SARBAGE	790	7724.5	667.0 Hrs of sanitation pickup, 36.0 Hrs of sanitation alley pickup and 87.0 of sanitation
			equipment maintenance.
			490.4 Ton of garbage hauled to the landfill, 1,143.96 gallons of fuel use, \$3,185.48,
			3,186 miles traveled, 81 Trips to the Landfill and 4,214 Tons YTD
VATER	307	2995	2.0 Hrs. of Meter Reading, 5.5 Hrs. of Meter Repairs, 23.5 Hrs. of Maintenance of Water
			Equipment, 226.0 Hrs. of Maintenance of Hydrants, Valves and Mains, 2.0 Hrs of
			Office and Records, 33.5 Hrs. of Treatment Plant Operations. 16.5 Hrs. of Lead/Copper rule
			reporting.
			All hydrants have been flushed and all valves exercise for fall 2024
EWER	403	3609.5	5.0 hours of sewer main cleaning & TV inspection, 133.0 hours of maintenance of
			Sewer mains, manholes & equipment, 24.0 Hrs. of Maintenance of Lift Stations, 33.0.
		1-	Hrs. of Maintenance of Storm Sewers, 2.0 Hrs. of Office & Records, 265.0 of Treatment
			Plant Operation & Maintenance,
GENERAL CITY	70.5	582.5	70.5 hrs. of General Clean-up of City property
			63.0 Hrs of Overtime, 207.0 Hrs of Vacation, 119.5 Hrs. of Sick leave
			Total Man Hours for the Month of August = 3,683.5
SHOP MECHANICAL	91.5	1113 5 STREET	Unit 117-2 - Replace hatteries
SHOP, MECHANICAL	91.5	1113.5 STREET	Unit 117-2 - Replace batteries
SHOP, MECHANICAL	91.5	1113.5 STREET	Unit 013 - Jeep Regular Service
SHOP, MECHANICAL	91.5	1113.5 STREET	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse
SHOP, MECHANICAL	91.5	1113.5 STREET	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries
SHOP, MECHANICAL	91.5		Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system
SHOP, MECHANICAL	91.5	1113.5 STREET SWEEPING	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer
SHOP, MECHANICAL	91.5		Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers
SHOP, MECHANICAL	91.5		Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer
SHOP, MECHANICAL	91.5		Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers
SHOP, MECHANICAL	91.5	SWEEPING	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add lail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers
SHOP, MECHANICAL	91.5		Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander
HOP, MECHANICAL	91.5	SWEEPING	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild
HOP, MECHANICAL	91.5	SWEEPING	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks
SHOP, MECHANICAL	91.5	SWEEPING	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields
HOP, MECHANICAL	91.5	SWEEPING	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1 - Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner
SHOP, MECHANICAL	91.5	SWEEPING	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1 - Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake
HOP, MECHANICAL	91.5	SWEEPING	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 -
HOP, MECHANICAL	91.5	SWEEPING	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 -
HOP, MECHANICAL	91.5	SWEEPING	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 -
HOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor
HOP, MECHANICAL	91.5	SWEEPING	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1 - Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters
HOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Installi GPS, Change out hydraulic filters Unit 421 - Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch.
HOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1 - Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters Unit 421 - Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch Unit 422 -
HOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters Unit 421 - Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch Unit 422 - Unit 835 - Replaced all batteries, Replaced hold down straps,
SHOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add lail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters Unit 421 - Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch. Unit 422 - Unit 835 - Replaced all batteries, Replaced hold down straps, Unit 417-
SHOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters Unit 421- Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch. Unit 422 - Unit 835 - Replaced all batteries, Replaced hold down straps, Unit 417- Unit 215 - Check over front drivetrain, Install all new tires, Rpl. Idler pitman and alignment
SHOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add lail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters Unit 421 - Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch. Unit 422 - Unit 835 - Replaced all batteries, Replaced hold down straps, Unit 417-
SHOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters Unit 421- Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch. Unit 422 - Unit 835 - Replaced all batteries, Replaced hold down straps, Unit 417- Unit 215 - Check over front drivetrain, Install all new tires, Rpl. Idler pitman and alignment
SHOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters Unit 421- Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch. Unit 422 - Unit 835 - Replaced all batteries, Replaced hold down straps, Unit 417- Unit 215 - Check over front drivetrain, Install all new tires, Rpl. Idler pitman and alignment Unit 217 -
SHOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters Unit 421- Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch. Unit 422 - Unit 835 - Replaced all batteries, Replaced hold down straps, Unit 417- Unit 215 - Check over front drivetrain, Install all new tires, Rpl. Idler pitman and alignment Unit 217 -
SHOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1- Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters Unit 421- Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch. Unit 422 - Unit 835 - Replaced all batteries, Replaced hold down straps, Unit 417- Unit 215 - Check over front drivetrain, Install all new tires, Rpl. Idler pitman and alignment Unit 217 -
SHOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1 - Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters Unit 421 - Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch Unit 422 - Unit 835 - Replaced all batteries, Replaced hold down straps, Unit 417- Unit 215 - Check over front drivetrain, Install all new tires, Rpl. Idler pitman and alignment Unit 217 - Unit 013 - Regular Service
SHOP, MECHANICAL	91.5	SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 013 - Jeep Regular Service Unit 117-1 - Replace 40 amp fuse 544 P-1. Replaced Batteries Unit 095 Tandom - Replaced turbo, adjust valves and injection system P-1 - (NEW) add tail pipe, noted small hydraulic leak on machine, notified dealer P-2 - Replaced dirt shoes and scrapers Tennet - Change out main broom and side skirts rubbers Unit 506 - Installed Sander Unit 195 - Installed Sander, Installed Sander Inverted Sheild Installed Snow Boxes on all trucks Salt Dog Sander B - Repaired all deflector shields Salt Dog Sander A - Replace dirve motor for spinner Unit #6 - Replace E-Brake Unit #7 - Unit #5 - AC - Add oil to compressor motor Unit 425 - Install GPS, Change out hydraulic filters Unit 421 - Sent in hydraulic oil samples, Replace gripper arm hose and proxy switch Unit 422 - Unit 835 - Replaced all batteries, Replaced hold down straps, Unit 417- Unit 215 - Check over front drivetrain, Install all new tires, Rpl. Idler pitman and alignment Unit 217 - Unit 013 - Regular Service