

### **Description:**

These projects are identified and may appear as part of the city's Capital Improvement Program, further out than the 6-year TIP.

Chip seal (Major, Hillcrest, E. Loop Road)

TIP Year: Not Listed Project Type: Maintenance Project Cost: \$35k Funding: 95% Grant

Average Priority Score from Workshop: 3 (mid)

**Workshop Comment Summary:** 

Traffic Justifies

Chip seal Vancouver (needs more)


TIP Year: Not Listed Project Type: Maintenance Project Cost: \$45k Funding: 95% Grant

Average Priority Score from Workshop: 3 (mid)

**Workshop Comment Summary:** 

Traffic Justifies

#### **East End SR-14 Roundabout**



TIP Year: Not Listed

**Project Type:** Improvement

Project Cost: \$4.2M

Funding: 85% Grant

**Average Priority Score from** 

Workshop: 3 (mid)

## **Workshop Comment Summary:**

Traffic Justifies

• Like roundabouts! Needs more engineering. Agree with slowing traffic. Also Wash DOT. Creates safety issue to turn left on Lutheran Church Road over what exists today. Yes, like this. Many new homes 71 in Chinidere

Mtn. Estates. Need traffic control. How do people turn on Lutheran Church Road?

#### **El Paso Road Reconstruction**

TIP Year: Not Listed Project Type: Improvement Project Cost: Unknown Funding: 100% City

Average Priority Score from Workshop: 2 (mid-low)

Workshop Comment Summary: None

Foster Creek Road (acquire additional ROW)

TIP Year: Not Listed Project Type: Improvement Project Cost: Unknown Funding: 100% City

**Average Priority Score from Workshop**: 4 (mid-high)

Workshop Comment Summary: None.

**Iman Loop-Iman Cemetery Sidewalk** 

TIP Year: Not Listed Project Type: Improvement Project Cost: \$75k Funding: 95% Grant

**Average Priority Score from Workshop**: 1 (low)

**Workshop Comment Summary:** 

• Property is about to change hands

Monda Road (straighten out intersection with Iman Cemetery Road)

TIP Year: Not Listed Project Type: Improvement Project Cost: \$200k Funding: 95% Grant

**Average Priority Score from Workshop**: 4 (mid-high)

**Workshop Comment Summary:** 

• Reconstruction to be at same time of Iman Cemetery Road reconstruction

**Rock Creek Bridge Replacement** 

TIP Year: Not Listed Project Type: Improvement Project Cost: \$8.2M Funding: 95% Grant

Average Priority Score from Workshop: None

**Workshop Comment Summary:** 

• Important to protect infrastructure under the bridge

**Roosevelt Street Overlay** 

TIP Year: Not Listed Project Type: Maintenance Project Cost: \$670k Funding: 100% City

Average Priority Score from Workshop: None

Workshop Comment Summary: None.

Russell Avenue Phase 2 (Vancouver-Second)

TIP Year: Not Listed Project Type: Improvement Project Cost: \$400k Funding: 85% Grant

Average Priority Score from Workshop: 1

Workshop Comment Summary: None.



# **Overall Stormwater System Repair/Upgrade**

TIP Year: Not Listed Project Type: Improvement Project Cost: \$500k Funding: 95% Grant

**Average Priority Score from Workshop**: 4 (mid-high)

# **Workshop Comment Summary:**

• Should include manhole leveling with pavement

Vancouver Sidewalk – East End (Columbia to City Hall)

TIP Year: Not Listed Project Type: Improvement Project Cost: \$125k Funding: 95% Grant

Average Priority Score from Workshop: 3 (mid)

Workshop Comment Summary: None.

### **West End Roundabout**



TIP Year: Not Listed Project Type: Improvement Project Cost: \$2.5M Funding: 85% Grant

Average Priority Score from Workshop: 3 (mid)

## **Workshop Comment Summary:**

• Like roundabouts! Good to consider slowing traffic, however wouldn't this be Wash DOT? Do East side first. Ok.