

SECTION 6: Fire Hydrant Repairs

Work Description	Bid Unit	Bid Price/Unit
Replace Existing Fire Hydrant	Lump Sum	\$ 4300
Replace Existing Fire Hydrant add Valve	Lump Sum	\$ 4500
Raise Existing Fire Hydrant (12" to 18")	Lump Sum	\$ 1100
Raise Existing Fire Hydrant (18" to 24")	Lump Sum	\$ 1300
Seat repair hot M&H and Mueller only	Lump Sum	\$ 2200
Seat repair with valve	Lump Sum	\$ 1400
Bonnet Repair	Lump Sum	\$ 350
Break away coupling replacement	Lump Sum	\$ 1000
Break away kit replacement	Lump Sum	\$ 1100
Upper rod replacement	Lump Sum	\$ 1200
Upper body removal	Lump Sum	\$ 1100
Replacing an Oil screw	Lump Sum	\$ 100
2.5 Nozzle Replacement	Lump Sum	\$ 500
4.5 Nozzle Replacement	Lump Sum	\$ 500
2.5 Cap Replacement	Lump Sum	\$ 100
4.5 Cap Replacement	Lump Sum	\$ 100
2.5 Cap Gasket Replacement	Lump Sum	\$ 100
4.5 Cap Gasket Replacement	Lump Sum	\$ 100
Bonnet Replacement	Lump Sum	\$ 350
Upper Body Replacement	Lump Sum	\$ 1100
Installation of a 6-inch Extension	Lump Sum	\$ 900
Installation of a 12-inch Extension	Lump Sum	\$ 1000
Installation of an 18-inch Extension	Lump Sum	\$ 1100
Installation of a 2-foot Extension	Lump Sum	\$ 1300
2.5 Lead In Nozzle Repair	Lump Sum	\$ 300
4.5 Lead In Nozzle Repair	Lump Sum	\$ 400
Repositioning and Aligning an upper body	Lump Sum	\$ 4300
Installing Hydrant	Lump Sum	\$ 4300
Replacing Lower Barrel	Lump Sum	\$ 2000

Total Section 6 \$ 38,100.00