INVOICE

The Roofing Consultants 35057 Mayer Dr Hempstead, TX 77445 (832) 270-6260

Sales Representative

Josh Tillery (832) 270-6260

josh@txroofingconsultants.com



Hempstead library 2331 11th street Hempstead tx, TX 77444

ROOFING REPARS DUE TO STORM

125-442-544700

Invoice #

1034

Date

1/14/2025

Amount Due

\$6,632,25

Due Date

Due on Receipt

Item	Description	Qty	Price	Amount
Ridge cap		3.00	\$142.76	\$428.28
Valley metal	Registration # 020226 Joan Sargent Waller Co. Treasurer Deputy Date 01 20 25	3.00	\$167.88	\$503.64
3in1 galvanized pipe Jack		6.00	\$98.64	\$591.84
Tamko heritage shingles		9.00	\$250.00	\$2,250.00
Nails		2.00	\$78.66	\$157.32
Ice & water shield		3.00	\$147.65	\$442.95
8" pipe jacks		3.00	\$123.67	\$371.01
Caulking		4.00	\$29.84	\$119.36
Synthetic underlayment		2.00	\$98.60	\$197.20
OSB decking		2.00	\$33.77	\$67.54
Weatherwood paint		3.00	\$16.45	\$49.35
Step flashing		2.00	\$126.88	\$253.76
Labor		1.00	\$1,200.00	\$1,200.00

JAN27/25PM3:20TREASURER

PAYMENT OPTIONS

· Cash Job: We accept cash, check and ACH (bank transfer). Payment is due upon completion of each trade.

• Insurance Claim: Your first insurance check amount, deductible, or any upgrade/additional work is expected upon completion of each trade.

 Financing Job: Upon completion of the job, we will send you a certificate of completion to the financing company. Any amounts above the financed amount must be paid in full upon completion of the job.

 Credit/Debit Card Payments: A 3% fee may be added to the invoice amount, Visa, MasterCard, and all other major credit cards accepted.

· Late fee may apply after 15 days.

Sub Total

\$6,632.25

Total

\$6,632.25

Amount Paid

\$0.00

Balance Due

\$6,632.25

SPECIAL INSTRUCTIONS

- 1. Replaced all rotted areas.
 2. Replace leaking valley on rear of building.
 3. Replace all 8" leaking pipe caps.
 4. Replace all pipe jacks on building.
 5. Reseal all flashings on building.
 6. Replace damaged ridge cap.
 7. Replace damaged roof shingles on the front.
 8. Replace damaged roof shingles on the rear.
 9. Rebuild where shingles are installed incorrectly.
 10. Build up low areas where it's sagging.

All repairs are back with a 5 year leak free guarantee.

CEO - Josh Tillery

Cell - 832-270-6260