CHANGE ORDER

	CITA	CHANGE ONDER		
			Dated:	June 28, 2022
OWNER'S Contract No.:	C22015	ENGINEER'S Proj	ect No.:	225284
Project:				
	HIGHLAND PA	ARK TRAILS PARKING L	OT 	
CONTRACTOR:	VISTA C	ONSTRUCTION, L.L.C.		
Contract For: Public W	orks	Contract Date:	Mach 8, 2022	
То:	VISTA C	ONSTRUCTION, L.L.C.		
You are directed to make t	the changes noted below			
			CITY OF WEST	MONROE
			Owner	
		Ву:	Staci Mitchell,	Mayor
		Dated:	June 30, 2	022
Nature of Changes:		ocation of lot, unforseen subsurforseen subsurface conditions &		
Enclosures:	see enclosure for costs	3		
These changes result in the	following adjustments to th	e Contract Price and Contract T	ime:	
Contract Price Prior to This Change Order:			74,1	60.00
Net (Increase) Resulting fro	\$	6,5	78.26	
Current Contract Price Including this Change Order:			80,7	38.26

Contract Time Prior to This Change Order:	60 Days 60 Days Days		
Net (Add) Resulting from This Change Order:			
Current Contract Time Including This Change Order:			
The Above Changes Are Recommended:		S. E. HUEY CO. Project Engineer	
	By:	Don R. Arrington, P.E.	
	Date:	June 29, 2022	
The above Changes Are Approved As Recommended:		CITY OF WEST MONROE Owner	
	Ву:	Staci Mitchell, Mayor	
	Date:		
The above Changes Are Accepted:		VISTA CONSTRUCTION, L.L.C. Contractor	
	Ву:		

Highland Park Trails Parking Lot-Explanation of Change Order #1

- Poor soils conditions at original site delayed construction
- Decision on how to handle (undercut bad areas and replace, undercut bad areas and allow soils to air dry, re-locate parking lot, combination) took time
- Decision was to move parking lot site 100' to the east
- Site re-location resulted in a longer 6' concrete sidewalk required to tie parking lot to trails (additional 40') additional cost of \$3,000 for this move
- Still some bad soils at new site (much smaller area of it)
- Poor soils removed, replaced with compacted stone
- Cost of this replacement:
 23.93 CY replaced material X \$130/CY (excavation/spreading & replaced crushed stone)
 = \$3111.53 X 1.15 (GC markup) = \$3,578.26 additional cost
- Additional time of 60 calendar days for unforeseen conditions (at both locations), engineering assessment of repairs, as well as bad weather days