

Westwood Public Works

To: Governing Body
From: John Sullivan, Director of Public Works
Date: February 6, 2024
Re: Monthly Status Report

- W. 47th Street Project: We have received 22 of the 26 clamshells. I expect the remaining 4 to be delivered at anytime. I am arranging the install. We have one streetlight fixture that has 4 of the 6 LED arrays not working. We have received the parts for this repair. We also have a pedestrian fixture that has failed. The parts are ordered. Something struck another one of the “47” signs at 47th and Fisher. We will make the repairs as soon as our bucket truck is repaired. The remaining parts of the project are complete. KDOT is working on the final accounting for the project.
- 2023 F-550 and Equipment: We have received the truck cab and chassis. The truck is currently at American equipment being outfitted.
- CCLIP funding: Our project has been funded. This includes work on the replacement of the concrete intersection at W. 47th Street and Rainbow. We will not have any City funds in this project. Project will be in 2026.
- Storm Debris Removal: We have begun the reimbursement process. More to come as we work through the process. I am meeting with FEMA for what hope is the last time on February 7th. More to come.
- Stone wall damage: We had a vehicle accident at W. 51st Terrace and Belinder Avenue that resulted in damage to the stone wall on the corner. We have been reimbursed for the expense by the insurance company. When the weather is more favorable, we will have the repairs completed.
- Stone wall damage and light pole damage: I have the replacement Medalion, and we will be installing it when we get the bucket truck back.
- Bicycle Repair Station: This project is complete.
- Garage Door Openers at PW Bldg.: Our door openers have failed and are obsolete. They are the original openers from when we installed them in 1989. The new ones have been ordered and will be installed soon.
- Bucket Truck Repairs: The main seal on the center boom has developed a hydraulic due to a fault seal. We are having it repaired and should get it back soon.
- Brush Chipper: The rear engine seal has failed causing the unit to lose oil. We are having it repaired and expect it back soon.