








Description	road patch after water fix the fire hydrant 2 yards of concrete
Attachments	 <p>IMG_5071.jpeg</p>  <p>IMG_5070.jpeg</p>
<b>History</b>	
Ftr ID	19

Description	road patch after water leak
Attachments	 IMG_0268.jpeg
<b>History</b>	
Ftr ID	21

Description	redid the driveway atfer putting stormpipe in April 30,2026
Attachments	 IMG_0201.jpeg  IMG_5007.jpeg
<b>History</b>	
Ftr ID	19

Description	road patched after sewer got finish working on the line 7 yards on of concrete
Attachments	 <p>IMG_5028.jpeg</p>  <p>IMG_5027.jpeg</p>
<b>History</b>	
Ftr ID	18

Description road patched after sewer got finish 10 yards of concrete

Attachments



IMG\_0199.jpeg



IMG\_0200.jpeg



IMG\_0196.jpeg



IMG\_0197.jpeg



IMG\_0238.jpeg



IMG\_0237.jpeg






IMG\_0232.jpeg



**History**



Ftr ID













10



Description	water dug up a water leak and street came back and fix the driveway
Attachments	 <p data-bbox="505 279 711 317">IMG_0206.jpeg</p>  <p data-bbox="505 564 711 602">IMG_0207.jpeg</p>
<b>History</b>	
Ftr ID	16



Description	road patched after water fixed leak in the rd 2 yards of concrete
Attachments	 IMG_5069.jpeg
<b>History</b>	
Ftr ID	20



Description	road patch after fixing the culvert under the road .50 yards of concrete
Attachments	 <p data-bbox="505 281 711 317">IMG_5057.jpeg</p>  <p data-bbox="505 564 711 600">IMG_5060.jpeg</p>
<b>History</b>	
Ftr ID	21



Description	curb install after sewer manhole
Attachments	 <p data-bbox="505 218 711 260">IMG_5130.jpeg</p>  <p data-bbox="505 392 711 434">IMG_5131.jpeg</p>
<b>History</b>	
Ftr ID	22




Description	city hall sidewalk project
Attachments	 
	 
	 
	 
	 
	 
<b>History</b>	
Ftr ID	4







Description	curb install after sewer manhole
Attachments	 IMG_5130.jpeg  IMG_5131.jpeg
<b>History</b>	
Ftr ID	22

Description	road patched after sewer got finish working on the line 7 yards on of concrete
Attachments	 <p>IMG_5028.jpeg</p>  <p>IMG_5027.jpeg</p>
<b>History</b>	
Ftr ID	18

Description	finish the sidewalk that connects to the trail 2.50 yards of concrete
Attachments	 <p data-bbox="505 317 711 352">IMG_5067.jpeg</p>  <p data-bbox="505 600 711 636">IMG_5068.jpeg</p>
<b>History</b>	
Ftr ID	20

Description	road patch after fixing the culvert under the road .50 yards of concrete
Attachments	 <p data-bbox="505 279 711 317">IMG_5057.jpeg</p>  <p data-bbox="505 564 711 602">IMG_5060.jpeg</p>
<b>History</b>	
Ftr ID	21


Description	jet culvert to get it to flow again
Attachments	 IMG_4933.jpeg
	 IMG_4934.jpeg
	 IMG_4935.jpeg
<b>History</b>	
Ftr ID	18




Description	southview stromwater
Attachments	      <p>IMG_0135.jpeg</p> <p>IMG_0137.jpeg</p> <p>IMG_4551.jpeg</p> <p>IMG_4556.jpeg</p> <p>IMG_4869.jpeg</p> <p>IMG_4868.jpeg</p>

**History**

2026-01-29 13:41:51 Willardstreets@gmail.com  
redoing the ditching to improve the water flow and flooding adding shot rock ,giveon baskets and widening the ditches

Ftr ID	1
--------	---

Description	dirt work water department fixed water line
Attachments	 4891.jpeg
<b>History</b>	
Ftr ID	9

Manhole #	
WO#	W1122
Status	Completed
Title	Water leak And Dirt work
Description	<p>Water service line leak</p> <p>Parts Used  1- 1"x 1" CTS to CTS fitting  1 New Meter setter  1-1"CTS to thread  1- 1" Valve.  1 Meter pit and lid  6' of 1" CTS</p>
Work Performed	Crew excavated water leak on 6886 Farm rd 124 chasing service line leak. Line was crippled temporarily disrupting water service to one customer for repairs. Repairs were made quickly and old out of service meter sharing the same trench was capped with a new valve and buried. New meter pit was installed and dirt work and clean up was completed.
Type	Basic Work Order
Owner	Greedygrapple@gmail.com[26241]
Assignee	
Date Created	2026-06-15 07:29:38
Date Started	2026-06-15 07:31:48
Date Completed	2026-06-15 07:31:48
Date Planned	2026-06-15
Asset	585535:57
Recurring	
Attachments	 20260612_110315.jpg  20260612_114211.jpg  20260612_114424.jpg




20260612\_141043.jpg






20260612\_155515.jpg


## History



2026-06-15 07:31:48 Greedygrapple@gmail.com  
Initial Status is Completed


Description	dirt work after water leak
Attachments	 IMG_0269.jpeg
<b>History</b>	
Ftr ID	11



Description	dirt work water department leak water line
Attachments	 IMG_5144.jpeg
<b>History</b>	
Ftr ID	8

Description	
Attachments	 20260615_131533.jpg  13513535320260615_131530.jpg
<b>History</b>	
Ftr ID	13

Description	dirt work after water leak
Attachments	 4889.jpeg
<b>History</b>	
Ftr ID	10

Manhole #	
WO#	W1019
Status	Completed
Title	Basic Work Order
Description	Remove Abandoned fire hydrant and dirt work
Work Performed	Crew excavated and removed out of service fire hydrant to rebuild and put back into service elsewhere. New hydrant was installed in its place in 2008. Dirt work was completed.
Type	Basic Work Order
Owner	Robinsonsafewater@gmail.com[26242]
Assignee	Derrickbostron@icloud.com Sebournka@gmail.com Wardkramer44@yahoo.com
Date Created	2026-03-18 15:10:40
Date Started	2026-03-18 15:13:45
Date Completed	2026-03-18 15:13:45
Date Planned	2026-03-18
Asset	
Recurring	
Attachments	 1000004561.jpg  1000004564.jpg
<b>History</b>	
2026-03-18 15:13:45 Robinsonsafewater@gmail.com Initial Status is Completed	
2026-03-18 15:18:24 Robinsonsafewater@gmail.com Assignees Changed from Derrickbostron@icloud.com[34943], Wardkramer44@yahoo.com[26250], willardmo123@gmail.com[28697] to Derrickbostron@icloud.com[34943], Sebournka@gmail.com[26251], Wardkramer44@yahoo.com[26250]	

Description	dirt work after water leak
Attachments	 4804.jpeg
<b>History</b>	
Ftr ID	12

Description	Dirt wok after water service line leak completed. Installed and repaired mailboxes
Attachments	 <p data-bbox="505 281 792 317">20260612_155517.jpg</p>  <p data-bbox="505 501 792 537">20260612_114424.jpg</p>
<b>History</b>	
Ftr ID	14