

Public Art Maintenance Doc – Due Aug 7th, 2026

Re-Intention

Artwork Name:

~~Flight of the Moon~~

Location:

Library, corner of Memorial Dr. & Wilserville Rd.

Date of inspection:

6/23/26

Name of inspector/ACHC member:

Jason Jones

1. Overall Condition to look for (Check the boxes if applicable and add any notes)

☒ Artwork looks stable and safe –

☒ No obvious damage or missing parts –

☒ No signs of vandalism or graffiti –

☒ Area around artwork is clean, maintained and accessible –

☐ Is there a plaque? If yes, what does it say –

It appears the plaque is missing.

Additional Comments:

There is a white rectangle that may have been space for a plaque, but there is not currently any note of the artist or title.

2. Structural / Safety Check (Look for anything that could make the artwork unsafe)

☒ No loose, cracked, or broken parts –

☒ Base/foundation appears solid –

☒ No sharp edges –

☒ No major leaning or movement –

☒ No trip hazards nearby –

Additional Comments:

3. Surface Condition (Check the visible surfaces)

☐ No heavy rust, corrosion, or rot –

There is a lot of rust.

☐ Paint/coating is in good condition –

If there was a coating, it seems gone.

☐ No major stains or discoloration –

There is some bird poop.

☐ No peeling, bubbling, or flaking –

There is flaking.

☐ No excessive dirt buildup, moss, etc –

There is moss.

Additional Comments:

It could use a makeover.

4. Environment Around the Artwork

☒ Landscaping is maintained –

☒ Drainage looks adequate (no standing water) -

☒ Benches/signage nearby are in good shape –

Additional Comments:

5. Photos

Please take:

- One overall photo
- Photos of any damage or concerns
- Close-up photos if needed (i.e plaque)

Condition Rating

Choose one:

☐ Good — no action needed

☒ Fair — minor maintenance needed

☐ Poor — repair needed soon

☐ Critical — immediate attention required

Follow-Up Needed

☐ None

☒ Cleaning

☐ Graffiti removal

☒ Repair

☐ Safety review

☐ Further professional inspection

Additional Notes:

Cleaning is needed, and maybe
a protective coating is in order
for identification, replacement
of the plaque is recommended.