

	<b>BluePrime Pools</b>
Complete Proposal Returned	Yes
Total Pool Repair cost + Equipment	\$ 199,965.01
Score of work	Plaster, 30 days chemicals and maintenance after fill, Total coping replacement, Total tile replacement, Installation of expansion material in joints, Sand Change all filters, replace 2 failed pool lights, rebuild plumbing valves, correct heater electrical, replace seals on leaking pumps, replace signage and depth markers as needed. Includes 185 sq ft of gunite if needed
Additional Optional Scope #1	Total replacement of stamped decking (16,500 sq feet)
Optional Scope Price #1	\$ 179,250.00
Additional Optional Scope #2	Automated controls
Optional Scope Price #2	\$ 6,200.00
Important notes	inspection notes signs of possible structure cracks. If structural, this bid includes \$10,000 in repairs to gunite. If not structural, \$10,000 would come off the cost of bid, Pressure test will be conducted during initial 10 day period
Timeline	Start date of January 6, complete and swimmable in 100 days. (April 16)
References (if provided)	Tray Payne, Gary Andrews, Randy Andrews, Canterbury Pointe, Raider Ranch, Madewell Construction + others
Warranty	3 years tile and coping + limited lifetime warranty thru manufacturer due to them being certified installers

<b>Westex Pools</b>	
Yes	
\$	217,050.00
Plaster, 14 days chemical and maintenance after fill, total coping replacement, total tile replacement, Sand change all filters, rebuild pumps, Replacement of Vacless Safety System, replace pressure guages, replacement of cracked skimmers, correct auto-fill floats, expansion joint sealant around coping, misc repairs to volleyball anchors, depth markers etc	
Noted no cracking that could be structural, noted the Vacless Safety System was not working properly, Pressure test will be conducted once pool is drained	
Start date of mid to late February, complete and swimmable in 9 weeks. (mid April)	
Elks Lodge, Preston Trails Apartments, Residence Inn, Home2Suites + others	
1 year on workmanship, 10 year manufacture warranty on plaster	