



Approx. 12-inch CMP
Pipe location/outlet unconfirmed
Outlet location unknown

Install culvert
Reconstruct
driveway path at
crossing

Grading to
channelize
flow

Masonry Retaining Wall
Channelized flow
Scour occurring at toe of wall
Geocells failing
Exposed CTV, FO lines

Pipe obstructions. Not apparent
where inlet/outlet is to culvert or
size

Replace culvert
Realign to
shorten distance
Check for trees,
utility boxes,
ROW,
easements

Install headwall w/
rock riprap
Relocate utility box

Remove/replace Culvert
Realign outlet and direct
outlet away from existing
driveway wall

Approximate Flow Path

1

2

3

4

5

6

PRELIMINARY FOR REVIEW ONLY
This document is for interim review and is not intended for construction, bidding, permit, or other unauthorized purposes. The schematic layout illustrated is conceptual and for informational purposes only.

No detailed engineering analysis, design or survey has performed in the preparation of this document.

Brookhollow Drive

Westwood Drive

ZC Camp