PHASE I ENVIRONMENTAL SITE ASSESSMENT

TOWN OF WARRENTON DPW COMPLEX SITE A

8499 BINGHAM ROAD
WARRENTON, VIRGINIA 20186

ECS PROJECT NO. 47:13457-A

FOR: BOHLER ENGINEERING

SEPTEMBER 16 2022

September 16 2022

Katherine Roberts
Bohler Engineering
28 Blackwell Park Lane
Suite 201
Warrenton, Virginia 20186

ECS Project No. 47: 13457-A

Reference: Phase I Environmental Site Assessment Report, Town of Warrenton DPW Complex Site A, 8499 Bingham Road, Warrenton, Faquier County, Virginia 20186

Dear Mrs. Roberts:

ECS Mid-Atlantic, LLC (ECS) is pleased to provide you with the results of our Phase I Environmental Site Assessment (ESA) for the referenced site. ECS's services were provided in general accordance with ECS Proposal No. 47:22797-EP authorized on July 27, 2022 and generally meet the requirements of ASTM E1527-21, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, which ECS believes to be in accordance with EPA Standards and Practices for All Appropriate Inquiries contained in 40 CFR Part 312.

If there are questions regarding this report, or a need for further information, please contact the undersigned.

Sincerely,

ECS Mid-Atlantic, LLC

Josh Peckham
Environmental Scientist
jpeckham@ecslimited.com
571-919-0668

Ryan J. Croyle, REM
Environmental Principal
rcroyle@ecslimited.com
717-767-4788

Project Summary

Town of Warrenton DPW Complex Site A
8499 Bingham Road
Warrenton, Virginia 20186

Report Section		No Further Action	REC	CREC	HREC	BER	Comment
4.0	User Provided Information					✔	The user confirmed the parcel has been used by Fauquier county as a Landfill Site.
5.1	Federal ASTM Databases					✔	The adjacent facility is a household waste landfill with several listed violations
5.2	State ASTM Databases					✔	The adjacent facility is a household waste landfill with several listed violations
5.3	Additional Environmental Record Sources	✔					
6.0	Historical Use Information		✔			✔	The subject property was historically used as part of the adjoining landfill. A large earthen mound of construction material from the facility remains on the property. The adjacent facility is a household waste landfill.
7.0	Site and Area Reconnaissance		✔			✔	A large earthen mound of unknown construction material lies on the east side of the property. The adjacent facility to the east is a household waste landfill.
8.0	Additional Services	✔					

Report Section		No Further Action	REC	CREC	HREC	BER	Comment
9.0	Interviews	✔					No owner interview

ENVIRONMENTAL PROFESSIONAL STATEMENT

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in § 312.10 of 40 CFR 312. We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Signature for Unknown User

Unknown User
Environmental Senior Project Manager
September 16 2022

Ryan J. Croyle, REM
Environmental Principal
September 16 2022

TABLE OF CONTENTS

PAGE

1.0 EXECUTIVE SUMMARY 1

2.0 INTRODUCTION 4

2.1 Purpose and Reason for Performing Phase I ESA 4

2.2 Scope of Services 4

2.3 Definitions 4

2.4 Limitations 5

2.5 Data Gaps 6

2.6 Limiting Conditions/Deviations 6

3.0 SUBJECT PROPERTY DESCRIPTION 8

3.1 Subject Property Location and Legal Description 8

3.2 Physical Setting and Hydrogeology 8

3.3 Current Use and Description of the Site 9

4.0 USER PROVIDED INFORMATION 10

4.1 Title Information 10

4.2 Environmental Liens or Activity and Use Limitations 10

4.3 Specialized Knowledge 10

4.4 Commonly Known or Reasonably Ascertainable Information 10

4.5 Valuation Reduction for Environmental Issues 10

4.6 Owner, Property Manager, and Occupant Information 10

4.7 Degree of Obviousness 10

5.0 RECORDS REVIEW 11

5.1 Federal ASTM Databases 12

5.1.1 Federal RCRIS - Generators 12

5.2 State ASTM Databases 13

5.2.1 Solid Waste Facilities/ Landfill (SWL/LF) List 13

5.3 Additional Environmental Record Sources 13

5.3.1 Additional Non-ASTM Federal Databases 13

5.3.2 Additional Non-ASTM State Databases 13

5.3.2.1 Manifest Information (PA MANIFEST) 13

5.3.3 Other Proprietary Databases 14

5.3.4 Unmapped (Orphan) Facilities and Sites 14

5.4 Regulatory Review Summary 14
6.0 HISTORICAL USE INFORMATION 15
6.1 Aerial Photograph Review 15
6.2 Sanborn Fire Insurance Map Review 17
6.3 Historical USGS Topographic Maps 17
6.4 City Directory Review 18
6.5 Property Tax Files 19
6.6 Recorded Land Title Records 19
6.7 Building Department Records 19
6.8 Zoning/Land Use Records 19
6.9 Previous Reports 20
6.10 Other Historical Sources 20
6.10.1 State Environmental Agency 20
6.10.2 Local Fire Department 20
6.10.3 Local Health Department 20
6.11 Historical Use Summary 21
7.0 SITE AND AREA RECONNAISSANCE 22
7.1 Methodology 22
7.2 On-Site Features 22
7.2.1 Observed Geologic, Hydrogeologic, Hydrologic, and Topographic Conditions 22
7.2.2 Past Site Uses 22
7.2.3 Current Uses 22
7.3 Adjoining and Nearby Properties 23
7.4 Site and Area Reconnaissance Summary 24
8.0 ADDITIONAL SERVICES 25
9.0 INTERVIEWS 26
10.0 FINDINGS AND CONCLUSIONS 27
10.1 Findings and Opinions 27
10.2 Significant Data Gaps 28
10.3 De Minimis Conditions 28
10.4 Conclusions 28
11.0 REFERENCES 29

TABLE OF APPENDICES

Appendix I: Figures

Appendix II: Interviews, Correspondence and User Questionnaire

Appendix III: Regulatory Records Documentation

Appendix IV: Historical Research Documentation

Appendix V: Site Photographs

Appendix VI: Statement of Qualifications

Appendix VII: Acronyms

1.0 EXECUTIVE SUMMARY

ECS Mid-Atlantic, LLC (ECS) was contracted by Bohler Engineering to perform an ASTM E1527-21, Phase I Environmental Site Assessment (ESA) of the Town of Warrenton DPW Complex Site A located at 8499 Bingham Road in Warrenton, Faquier County, Virginia (i.e. subject property). This Executive Summary is an integral part of the Phase I ESA report. ECS recommends that the report be read in its entirety.

The subject property is identified by the Fauquier County GIS as a portion of the parcel identified with the Property Identification Number (PIN) 6983-81-0145-000 and owned by the Board of Supervisors of Faquier County. The subject property is an approximate 10 acre tract that is located in a predominantly agricultural area of Warrenton, VA. The subject property is a portion of a much larger parcel that houses the Fauquier County Landfill facilities. The subject property consists of primarily unimproved land, with a large earthen mound rising across most of the east and north of the site. A small utility shed and some transmission lines occupy the northwest corner of the property.

The subject property is located in a rural area of Warrenton, Virginia. Based on our review of site topography and conditions observed during the site reconnaissance, it is our professional opinion that properties to the east are presumed to be hydrogeologically up-gradient of the subject property. The subject property is bound on the north by commercial facilities, on the east and south by industrial landfill facilities and on the west by undeveloped land. ECS identified the adjacent landfill operations to represent a potential BER for the subject property.

Based on the records search, site reconnaissance and interviews, it appears that the subject property was historically used as agricultural land from at least 1952, if not earlier, until approximately 2002, when it became a part of the adjacent landfill construction. Prior to 1927, it appears that the site was undeveloped. Records indicate the subject parcel has been owned by Fauquier County. Historical records prior to 1894 were not reasonably ascertainable for the subject property.

A regulatory database search report was provided by EDR. The database search involves researching a series of Federal, State, Local, and other databases for facilities and properties that are located within specified minimum search distances from the subject property. The report did not directly identify the subject property on the databases researched. The EDR report identified several facilities within the minimum ASTM search distances that share a tax parcel with the subject property. Based on our review of available public records, issues associated with the the listings in the database report are not believed to represent a REC for the subject property.

ASTM E1527-21 defines a "*data gap*" as: "a lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information." ECS was not able to conduct an interview with the property owner or someone with considerable knowledge of the property. ECS considers this to be a data gap for the assessment; however, based on conditions observed at the property and the consistent agricultural use of the property that converted to a portion of a C&D landfill, the absence of an owner interview was not considered to be a significant data gap, and was not considered likely impact our ability to render a professional opinion regarding the subject property.

A *"significant data gap"* is "a data gap that affects the ability of the environmental professional to identify a recognized environmental condition." Significant data gaps that would be expected to impact our ability to render a professional opinion concerning the subject property were not identified.

We have performed a Phase I Environmental Site Assessment in general conformance with the scope and limitations of ASTM E1527-21 of the Town of Warrenton DPW Complex Site A located at 8499 Bingham Road in Warrenton, Faquier County, Virginia, the subject property. Any exceptions to, or deletions from, this practice are described in Section 2.6 of this report. This assessment has revealed the following Recognized Environmental Conditions in relation to the subject property.

- The subject property started operating as a portion of the Fauquier County Landfill that is located on the parent parcel between 2002 and 2008. The landfill was reportedly used for storage of construction & demolition (C&D) waste material. Historical records and site visit observations revealed an earthen mound to the east of the subject property that extends to the north. Records reviewed do not indicate the nature of the material stockpiled on the subject property. Due to the historic use of the subject property as a part of C&D waste landfill activities, and the same use of the adjacent property, ECS considers the historic use to represent an REC for the subject property.
- The property shares a parcel with the Fauquier County Landfill, with several of the facilities and disposal areas adjoining the subject property to the east and south. This collection site is designated for the disposal of household trash, bulk waste and recycling as well as C&D waste. Based on our review of available historical and regulatory records, the adjacent facility was cited for violations in the past, and it is possible household waste debris may be present on the subject property, As a result of this use, ECS considers the facility to represent an REC for the subject property.

Table of Critical Dates

Item	Date
Report Issuance Date	September 16 2022
Date of Interview with Past and Present Owners and Occupants	August 23, 2022
Date of Recorded Environmental Cleanup Lien Search	N/A
Date of Government Record Review Report	August 12, 2022
Date of Visual Inspection of Subject and Adjoining Properties	August 22, 2022
Earliest Date of Interviews, Lien Search, Record Reviews, and Inspections	August 12, 2022
Report Viability Date	February 8, 2023

2.0 INTRODUCTION

2.1 Purpose and Reason for Performing Phase I ESA

The purpose of the ESA was to:

- evaluate the probability of impact to the surface water, groundwater and/or soils within the property boundaries through a review of regulatory information and a reconnaissance of the subject property and vicinity;
- evaluate historical land usage to identify previous conditions that could potentially impact the environmental condition of the subject property;
- conduct all appropriate inquiry as defined by ASTM E1527-21 and 40 CFR Part 312;
- evaluate the potential for on-site and off-site contamination; and,
- provide a professional opinion regarding the potential for environmental impact at the site and a list of Recognized Environmental Conditions (RECs).

The ESA should allow the Users the opportunity to qualify for landowner liability protection under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) provided certain stipulations are met. The landowner liability protections are: an innocent landowner, a contiguous property owner, or a bona fide prospective purchaser. The User must meet the protection stipulations detailed in CERCLA to qualify as well as meet the User Obligations contained within the ASTM E1527-21 standard.

The reason for conducting this ESA is to perform all appropriate inquiries into the uses and prior ownership of the subject property for due diligence in support of a pending property transaction as well as to serve as a feasibility survey on behalf of the User.

2.2 Scope of Services

The environmental assessment was conducted in general accordance with ASTM E1527-21, which ECS believes to be in accordance with EPA Standards and Practices for All Appropriate Inquiry (40 CFR §312.10). The environmental assessment was conducted under the supervision or responsible charge of an individual that qualifies as an environmental professional, as defined in 40 CFR §312.10.

ECS was contracted by Bohler Engineering to perform an ASTM E1527-21, Phase I Environmental Site Assessment (ESA) of the Town of Warrenton DPW Complex Site A located at 8499 Bingham Road in Warrenton, Faquier County, Virginia. ECS was not contracted to address non-scope considerations.

2.3 Definitions

ASTM E1527-21 defines a "*recognized environmental condition (REC)*" as "(1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment." For the purposes of this definition,

"likely" is that which is neither certain nor proved, but can be expected or believed by a reasonable observer based on the logic and/or experience of the environmental professional, and/or available evidence, as stated in the report to support the opinions given therein.

ASTM E1527-21 defines a "*historical recognized environmental condition (HREC)*" as "a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls (for example, activity and use limitations or other property use limitations). A historical recognized environmental condition is not a recognized environmental condition."

ASTM E1527-21 defines a "*controlled recognized environmental condition (CREC)*" as "recognized environmental condition affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls (for example, activity and use limitations or other property use limitations)."

ASTM E1527-21 defines a "*business environmental risk (BER)*" as "a risk that can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of commercial real estate, not necessarily related to those environmental issues required to be investigated in this practice." This assessment does not include ASTM Non-Scope items or identify business environmental risks unless specifically requested by the Client, and included in Section 8.0 of this report.

ASTM E1527-21 defines a "*de minimis condition" as "a* condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A condition determined to be a *de minimis* condition is not a recognized environmental condition nor a controlled recognized environmental condition."

2.4 Limitations

The ESA involved a reconnaissance of the subject property and contiguous properties and a review of regulatory and historical information in general accordance with the ASTM standard and EPA regulation referenced herein. No non-scope considerations or additional issues such as asbestos, radon, wetlands or mold were investigated, unless otherwise described in Section 8.0 of this report.

Note: vapor migration in the subsurface is described in Guide E2600 published by ASTM. ECS has not conducted a Vapor Encroachment Screen in accordance with the E2600 guide.

The conclusions and/or recommendations presented within this report are based upon a level of investigation consistent with the standard of care and skill exercised by members of the same profession currently practicing in the same locality under similar conditions. The intent of this assessment is to identify the potential for recognized environmental conditions in connection with the subject property; however, no environmental site assessment can completely eliminate uncertainty regarding the potential for recognized environmental conditions in connection with the

subject property. The findings of this ESA are not intended to serve as an audit for health and safety compliance issues pertaining to improvements or activities at the subject property. ECS is not liable for the discovery or elimination of hazards that may potentially cause damage, accidents or injury.

Observations, conclusions and/or recommendations pertaining to environmental conditions at the subject property are necessarily limited to conditions observed, and or materials reviewed at the time this study was undertaken. It was not the purpose of this study to determine the actual presence, degree or extent of contamination, if any, at this subject property. This could require additional exploratory work, including sampling and laboratory analysis. No warranty, expressed or implied, is made with regard to the conclusions and/or recommendations presented within this report.

This report is provided for the exclusive use of Bohler Engineering. This report is not intended to be used or relied upon in connection with other projects or by other unidentified third parties. The use of this report by any undesignated third party or parties will be at such party's sole risk and ECS disclaims liability for any such third party use or reliance. The use of this report is subject to the same terms, conditions and scope of work reflected in this report and the associated proposal.

2.5 Data Gaps

ASTM E1527-21 defines a "*data gap*" as: "a lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information." A *"significant data gap"* is "a data gap that affects the ability of the environmental professional to identify a recognized environmental condition."

Data failures (historical data gaps) were identified during the historical research of this subject property. Use of the subject property was generally documented back to 1894. Historical information was missing for various periods. However, due to the apparent consistent historical agricultural use, the historical data gaps are not expected to impact our ability to render a professional opinion regarding the subject property.

ECS was not able to conduct an interview with the property owner or someone with considerable knowledge of the property. ECS considers this to be a data gap for the assessment; however, based on conditions observed at the property and the consistent residential use of the property since its development, the absence of an owner interview was not considered to be a significant data gap, and was not considered likely to impact our ability to render a professional opinion regarding the subject property.

Significant data gaps that would be expected to impact our ability to render a professional opinion concerning the subject property were not identified.

2.6 Limiting Conditions/Deviations

ASTM E1527-21 requires that the Environmental Professional identify limiting conditions, deletions, and deviations from the ASTM E1527-21 standard, if any, including client-imposed constraints. The following limiting conditions and/or deviations were encountered during the performance of this Phase I ESA:

- Dense vegetation covered portions of the subject property and may have obscured environmentally significant features and direct observation of the ground surface.
- ECS was not able to conduct an interview with the property owner or someone with considerable knowledge of the property. The lack of an owner interview is considered a limitation of this study.

3.0 SUBJECT PROPERTY DESCRIPTION

3.1 Subject Property Location and Legal Description

Site Name	Town of Warrenton DPW Complex Site A
Property Address	8499 Bingham Road
Property City, State	Warrenton, Virginia
Property County	Faquier County
Number of Parcels	Portion of One (1)
Property ID Number(s)	6983-81-0145-000
Property Size	10 Acres
Property Owner of Record	Board of Supervisors of Faquier County
Property Legal Description	N/A

3.2 Physical Setting and Hydrogeology

USGS Topographic Map	
Quad Designation	Warrenton, VA Quadrangle 7.5 Minute
Date	2019
Subject Property Settings	
Average Subject Property Elevation (in feet or meters)	540 ft
General Sloping Direction	West
Bodies of Water	One small ponded area on the south side.
General Directions of Surface Flow	Southwest
Presumed Direction of Groundwater Flow	Southwest
Geologic Province	Piedmont
Up-gradient Property Direction	East

Nearby Properties' Setting	
General Sloping Direction	West
Bodies of Water	Mill Run stream to the west of the property, Large stormwater pond bordering the south of the property, with several larger ponds beyond.
General Directions of Surface Flow	Southwest
Presumed Direction of Groundwater Flow	Southwest

Regional influences such as karst conditions, impermeable soils, etc. may have an impact on groundwater flow. The actual groundwater flow direction cannot be determined without site-specific information obtained through the gauging of groundwater monitoring wells.

3.3 Current Use and Description of the Site

The subject property is an approximate 10 acre tract that is located in a predominantly agricultural area of Warrenton, VA. The subject property is a portion of a much larger parcel that houses the Fauquier County Landfill facilities. The subject property consists of primarily unimproved land, with a large earthen mound rising across most of the east and north of the site. A small utility shed and some transmission lines occupy the northwest corner of the property.

4.0 USER PROVIDED INFORMATION

The ASTM standard includes disclosure and obligations of the User to help the Environmental Professional identify the potential for Recognized Environmental Conditions associated with the subject property. A User Questionnaire was submitted to Katherine Roberts with Bohler Engineering. The user questionnaire was completed by Frank Cassidy, Director of Public Works & Utilities for the Town of Warrenton, VA on September 9, 2022. Section 4.0 is based on the completed User Questionnaire. A copy of the completed User Questionnaire is included in Appendix II.

4.1 Title Information

ECS was not provided with title information by the User. If this information is provided following the issuance of this report and information contained therein materially changes the outcome of this report, ECS will issue an addendum to this report.

4.2 Environmental Liens or Activity and Use Limitations

ECS was not provided with information on environmental liens or activity and use limitations for our review. It should be noted by the User of this report that if the User does not obtain activity and use limitation information, the User that is seeking to qualify for an innocent landowner, a contiguous property owner, or a bona fide prospective purchaser liability defense may lose these rights to qualify under CERCLA. If the activity use information is provided following issuance of this report and information contained therein materially changes the outcome of this report, ECS will issue an addendum to this report.

4.3 Specialized Knowledge

The User did not provide specialized knowledge of the subject property.

4.4 Commonly Known or Reasonably Ascertainable Information

The user stated the land was previously used by Fauquier County as a landfill site.

4.5 Valuation Reduction for Environmental Issues

No information pertaining to the valuation reduction for environmental issues was provided to ECS.

4.6 Owner, Property Manager, and Occupant Information

The user stated that the property was formerly owned by Fauquier County.

4.7 Degree of Obviousness

The User did not provide information related to obvious indicators that point to the presence or likely presence of contamination at the subject property.

5.0 RECORDS REVIEW

A regulatory records search of ASTM standard and supplemental databases was conducted for the subject property and is included in Appendix III. The regulatory search report in the appendix includes additional details about the regulatory databases that were reviewed. The regulatory records search involves searching a series of databases for facilities that are located within a specified distance from the subject property. The ASTM standard specifies an approximate minimum search distance from the subject property for each database. Pursuant to ASTM, the approximate minimum search distance may be reduced for each standard environmental record except for Federal NPL site list, and Federal RCRA TSD list. According to ASTM, government information obtained from nongovernmental sources may be considered current if the source updates the information at least every 90 days or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public. The following table indicates the standard environmental record sources and the approximate minimum search distances for each record.

Standard Environmental Record Sources	Approximate Minimum Search Distance Per ASTM (miles)	Subject Property	Off-Site Properties
Federal NPL	1.0	No	0
Federal Delisted NPL	0.5	No	0
Federal CERCLIS	0.5	No	0
Federal CERCLIS NFRAP	0.5	No	0
Federal RCRA CORRACTS	1.0	No	0
Federal RCRA non-CORRACTS TSD	0.5	No	0
Federal RCRA Generators	Subject Site and Adjoining Properties	Yes	1
Federal IC/EC	Subject Site Only	No	N/A
Federal ERNS	Subject Site Only	No	N/A
State and Tribal Hazardous Waste Sites (NPL Equivalent)	1.0	No	0
State and Tribal Hazardous Waste Sites (CERCLIS Equivalent)	0.5	No	0
State and Tribal Landfill and/or solid waste disposal sites	0.5	Yes	1

Standard Environmental Record Sources	Approximate Minimum Search Distance Per ASTM (miles)	Subject Property	Off-Site Properties
State and Tribal Leaking Tanks	0.5	No	0
State and Tribal Registered UST and AST	Subject Site and Adjoining Properties	No	0
State and Tribal IC/EC	Subject Site Only	No	N/A
State and Tribal Voluntary Cleanup (VCP)	0.5	No	0
State and Tribal Brownfield Sites	0.5	No	0

Based on our knowledge of the subject property and the surrounding area, ECS attempts to verify and interpret this data. While this attempt at verification is made with due diligence, ECS cannot guarantee the accuracy of the record(s) search beyond that of information provided by the regulatory report(s). ECS makes no warranty regarding the accuracy of the database report information included within the regulatory report(s).

The regulatory database search was performed by EDR, and their report is dated August 12, 2022. ECS did not reduce the minimum ASTM search distances stipulated in the standard. The regulatory databases reviewed by ECS included supplemental databases researched by EDR.

5.1 Federal ASTM Databases

5.1.1 Federal RCRIS - Generators

RCRIS identifies facilities that generate hazardous wastes as defined by the RCRA. Very small quantity generators (VSQG) (previously identified as conditionally exempt small quantity generators or CESQGs) generate less than 100 kilograms of hazardous waste, or less than 1 kilogram of acutely hazardous waste, per month. Small quantity generators (SQGs) generate between 100 and 1,000 kilograms of hazardous waste per month. Large quantity generators (LQGs) generate more than 1,000 kilograms of hazardous waste or more than 1 kilogram of acutely hazardous waste per month.

No facilities were identified within the boundaries of the subject property.

One facility on the same parcel as the subject property (EPA IDs: VAR000517722) was identified on the RCRIS Generator database as **FAUQUIER COUNTY HHW (6438 College Street)** and historically as **FAUQUIER CO. LANDFILL-DEPT.OF ENV. SERV**. The listing is described below:

The facility is listed by the database as approximately 681 feet from the subject property and was identified as a RCRA-VSQG in 2009 as Fairfax County Household Hazardous Waste. This collection site is designated for the disposal of household trash, bulk waste and recycling. The facility was listed as a conditionally exempt small quantity generator of solid wastes (NAICS Code:562111). The facility received eight (8) notices of violations during a compliance inspection by the State on September 9, 2005. The facility received eight warning letters from the State on November 8-9, 2005 as acts of enforcement on the previous violations. The facility was listed as returning to compliance on December 14, 2005. Additional information pertaining to this listing can be viewed in the regulatory report included in Appendix III. Due to the listed violations and the proximity of the facility on the same parcel as the subject property, ECS considers this to be a BER for the subject property.

5.2 State ASTM Databases

5.2.1 Solid Waste Facilities/ Landfill (SWL/LF) List

The SWL is a list of state-permitted solid waste facilities. These facilities may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

No facilities were identified within the boundaries of the subject property.

One facility on the same parcel as the subject property was identified on the SWL/LF database as **CORRAL FARM WASTE MANAGEMENT FACILITY (6438 College Street)**. The listing is described below:

> The facility was identified as two split listings of a transfer station and materials recovery facility. This data lists one-hundred and seventy-eight (178) entries for permits issued to the facilities. These primarily consist of financial assurance records, routine compliance reports, and miscellaneous administrative permitting. Two notices of violation were issued for the property on December 13, 2018 regarding unspecified water violations and the Construction General Permit VAR051470. After review, ECS does not consider the permitting or enforcement entries to represent a REC for the subject property. However ECS does consider the listing of the facility on the landfill database, and the reported violations, to represent a BER for the subject property.

5.3 Additional Environmental Record Sources

5.3.1 Additional Non-ASTM Federal Databases

Neither the subject property nor properties within the designated search radii were identified on the Non-ASTM Federal databases researched for this assessment.

5.3.2 Additional Non-ASTM State Databases

5.3.2.1 Manifest Information (PA MANIFEST)

The Manifest database contains information pertaining to hazardous waste manifest listings.

No facilities were identified within the boundaries of the subject property.

One facility on the same parcel as the subject property (EPA IDs: VAR000517722) was identified on the RCRIS Generator database as **FAUQUIER COUNTY HHW (6438 College Street)**. The listing is described below:

> This database listing contains four identical entries for Manifest Number:015831253JJK for 70 pounds of unspecified hazardous material transported to Chem Cycle Inc in Lewisberry Pa. on October 21, 2017. Based on our review of reasonably ascertainable information, due to the listing of the material having been properly removed from the facility, ECS does not consider this listing to be a REC for the subject property.

5.3.3 Other Proprietary Databases

Neither the subject property nor properties within the designated search radii were identified on the proprietary databases researched for this assessment.

5.3.4 Unmapped (Orphan) Facilities and Sites

One property was identified on the Orphan Summary List. These facilities are considered unmappable because the facility information in the database is insufficient and/or does not report accurate facility location.

5.4 Regulatory Review Summary

A regulatory database search report was provided by EDR. The database search involves researching a series of Federal, State, Local, and other databases for facilities and properties that are located within specified minimum search distances from the subject property. The report did not identify the subject property on the databases researched. The EDR report identified several adjacent facilities that share a tax parcel with the subject property within the minimum ASTM search distances. Based on our review of available public records, ECS does consider the listings to be potential sources of soil, groundwater, or vapor impact to the subject property. The adjacent facility is a landfill designated for the disposal of household trash, bulk waste and recycling, and during our review of available public records the property was noted with several potential violations. Because of this ECS considers the facility to represent a BER for the subject property.

6.0 HISTORICAL USE INFORMATION

6.1 Aerial Photograph Review

ECS reviewed aerial photographs of the subject property and immediately surrounding properties for evidence of former usage which may indicate potential environmental issues. The aerial photographs were obtained from Historic Aerials NETR Online and EDR. The aerial photographs reviewed were dated 1952, 1960, 1966, 1970, 1971, 1977, 1980, 1994, 2002, 2003, 2005, 2006, 2008, 2009, 2011, 2012, 2013, 2014, 2016, 2018. Aerial photographs dated prior to 1952 were not available for review. The ECS review is dependent on the quality and scale of the photographs.

The following is a description of relevant information from the aerial photographs:

Year(s)	Subject Property	Adjoining Properties	REC? (yes or no)
1952-1966	Subject property was situated on a portion of a large agricultural field.	Surrounded by agricultural land on all sides. Some residential structures lie beyond to the west situated along a road that runs to the west. and some structures of unknown use lie to the northeast. Subject property is bordered by a road to the north. A linear drainage feature is visible bordering the west side of the property.	No
1966-1971	Subject Property remains unchanged.	The road beyond the western property was developed into a larger, multi-lane highway. The drainage feature to the west is headed by a small pond in the northwest.	No
1971-2002	Subject Property remains unchanged.	The road beyond to the west was furthered developed with additional lanes. The facility to the northeast developed with additional structures.	No

Year(s)	Subject Property	Adjoining Properties	REC? (yes or no)
2002-2003	A linear landscaped area is visible on the north of the subject property parallel to the road.	A linear forested area is visible to the west and east of the subject property. The small pond to the northwest is no longer visible. The facility to the northeast is no longer visible. Former agricultural lands beyond to the north developed into a large community college facility and parking area. Lands to the northeast, east, and south were visibly under development and clearing for construction of large landfill facility	No
2003-2005	Subject Property remains unchanged.	Landfill facility construction appears complete and facility appears operational	Yes
2005-2008	Subject Property remains unchanged.	Access road constructed east of the subject property	Yes
2008-2011	Linear raised earthen mound area visible in the northeast of the property	Property to the west is primarily forested.	Yes
2011-2012	Barren/cleared area visible on east side of the property.	Access road to the east changed in shape.	Yes
2012-2013	Linear earthen mound area visibly constructed across most of the north of the subject property. Large area on the east of the site cleared from construction operations.	Adjacent properties remain primarily unchanged	Yes
2013-2014	East of subject property now constructed into large earthen mound that extends across the north of the site.	Adjacent properties remain primarily unchanged	Yes

Year(s)	Subject Property	Adjoining Properties	REC? (yes or no)
2014-2016	Vegetation cleared from mound for what appeared to be additional construction operations to add material .	Storm water pond under southeast of the subject property	Yes
2016-2018	Additional construction underway to add material in the northeast.	Southeast pond construction complete.	Yes

6.2 Sanborn Fire Insurance Map Review

In an effort to identify past uses, ECS utilized EDR to search for historical Sanborn Fire Insurance Maps (Sanborn) for the subject property and surrounding area. Sanborn maps were not available for this area. The absence of such maps generally indicates that the subject property is located in an area where Sanborn maps were not produced because the area was rural or it was not economically feasible. ECS does not expect the lack of Sanborn maps to impact our ability to render a professional opinion concerning the subject property given the amount of historical information obtained from our research, the USGS topographic map, aerial photographs, city directories, and other historical records obtained. A copy of the Unmapped Property report is included within Appendix IV.

6.3 Historical USGS Topographic Maps

Topographic maps are produced by the United States Geological Survey (USGS) for various time periods. ECS reviewed topographic maps of the subject property and immediately surrounding properties for evidence of former usage that may indicate potential environmental issues. The topographic maps were obtained from Historic Aerials NETR Online and United States Geological Survey (USGS) and were dated 1894, 1897, 1927, 1930, 1945, 1948, 1957, 1958, 1961, 1966, 1968, 1972, 1978,1982, 1986, 1994, 1999, 2011, 2013, 2016, 2019. Topographic maps dated prior to 1894 were not available for review.

The following is a description of relevant information from the topographic maps:

Year(s)	Subject Property	Adjoining Properties	REC? (yes or no)
1894-1927	Maps depict the site sloping generally downhill to the northeast, with a tributary of the Bull Run stream intersecting the site to the northeast.	Maps depict a roadway to the east of the subject property, beyond the adjacent properties.	No

Year(s)	Subject Property	Adjoining Properties	REC? (yes or no)
1927-1930	Maps depict the site sloping generally downhill to the southwest, with a stream depicted to the southwest.	Roads are depicted to the north of the site and beyond adjacent properties to the west of the site. some small structures lie of these roads.	No
1930-1968	Maps depict the stream in the southwest intersecting the subject property in the southwest.	Adjacent properties remain primarily unchanged	No
1968-1972	Subject Property remains unchanged.	The stream to the west of the site is depicted as running linear north to south and headed by a pond to the northeast of the subject property.	No
1972-2013	Subject Property remains unchanged.	A new structure is depicted to the northeast of the subject property.	No
2013-2016	Subject Property remains unchanged.	structures no longer depicted on maps. Large pond depicted to the south of the subject property.	No
2016	Subject Property topography visibly changed by raised area in the east, still primarily slopes to the southwest.	Contours of landfill visible to the southeast of the subject property.	Yes

6.4 City Directory Review

One of the ASTM standard historical sources to be reviewed for previous subject property uses is local street directories, commonly known as City Directories. The purpose of the directory review is to identify past occupants of the subject property, adjoining properties, or nearby properties. In some rural areas, street directories information is limited.

ECS reviewed city directories obtained from EDR. The subject property address utilized for the research was 8499 Bingham Road. The directories reviewed were dated 1963, 1966, 1970, 1974, 1978, 1983, 1988, 1992, 1995, 2000, 2005, 2010, 2014, 2017. No listings were found for the subject property. The directories reviewed did not provide listings for the subject property or surrounding area. Directories dated prior to 1963 were not available for review. A copy of the city directory report is included in Appendix IV.

The following is a description of relevant information from the city directories:

Year(s)	Subject Property	Adjoining Properties	REC? (yes or no)
1963-2017	No directory results	No directory results	No

6.5 Property Tax Files

Property tax files may include records of past ownership, appraisals, maps, sketches, photos, or other information kept by the local jurisdiction for property tax assessment purposes. According to the Faquier County tax assessor online information, the subject property is owned by Board of Supervisors of Faquier County. The subject property is a 10-acre portion of the parcel identified with the Parcel Identification Number (PIN) 6983-81-0145-000.

6.6 Recorded Land Title Records

Recorded land title records may include leases, land contracts, and AULs recorded by the local jurisdiction. Land title records may provide only a list of the names of previous owners and may be of limited use; however, they may provide useful information about uses or occupancy of the property when employed in combination with other sources.

ECS was not provided with Land Title Records. Given historical information gained from other sources reviewed in this section, this is not considered to be a significant data gap that would affect our ability to render a professional opinion concerning the property's environmental quality.

6.7 Building Department Records

The term building department records means those records of the local government indicating permissions of the local government to construct, alter or demolish improvements on the property.

ECS obtained a list of building permits from EDR via the Lightbox™ Application. The provided building permits were for residential structures on the same parcel, but not located within or adjacent to the subject property.

6.8 Zoning/Land Use Records

The term zoning/land use records refers to records of the local government indicating the uses permitted by the government in particular zones within its jurisdictions.

Due to substantial historical coverage gained from other sources, ECS did not review zoning records for the purpose of this assessment. Given historical information gained from other sources reviewed in this section, this is not considered to be a significant data gap that would affect our ability to render a professional opinion concerning the property's environmental quality.

6.9 Previous Reports

We have not been provided with environmental or engineering assessment reports for the subject property completed by others, nor has ECS completed similar studies or prior assessments of the subject property.

6.10 Other Historical Sources

Other credible historical sources may be reviewed to identify past uses of the subject property. These sources may include websites, county or state road maps, historical society documents, or local library information. Please find copies of correspondences in appendix ii.

6.10.1 State Environmental Agency

ECS representative Joshua Peckham contacted the Virginia Department of Environmental Quality to determine if they had historical information regarding any documented storage, spills, and/or disposals of petroleum products, chemical or hazardous substances at the site or in the immediate vicinity of the project area, or other information regarding the subject property. A Freedom of Information Act request was submitted to the Virginia DEQ on August 12, 2022. Virginia DEQ responded on August 24, 2022 confirming they had no records associated with the request.

6.10.2 Local Fire Department

ECS representative Joshua Peckham contacted the Fauquier County Department of Fire and Rescue's FOIA Representative to determine if they had historical information regarding any documented storage, spills, and/or disposals of petroleum products, chemical or hazardous substances at the site or in the immediate vicinity of the project area, or other information regarding the subject property. A Freedom of Information Act request was submitted on August 12, 2022. ECS received a response on August 8, 2018. The FOIA response detailed one incident on the adjacent property to the east on February 26, 2022 regarding a 1.5 acre brush fire caused by a utility pole surging. The report specifically states no hazardous materials were released during the incident. After a review of the records, ECS does not consider the records to show any REC for the subject property.

6.10.3 Local Health Department

ECS representative Joshua Peckham contacted the Fauquier County Department of Environmental Health to determine if they had historical information regarding any documented storage, spills, and/or disposals of petroleum products, chemical or hazardous substances at the site or in the immediate vicinity of the project area, or other information regarding the subject property. A Freedom of Information Act request was submitted on August 12, 2022. Fauquier County DEH responded on August 12, 2022 confirming they had records pertaining to the tax parcel the subject property lies on. The records pertained to a well and sewer development projects for the adjacent property to the east of the subject property. After a review of the records, ECS does not consider the records to show any REC for the subject property.

6.11 Historical Use Summary

According to historical research, the subject property has been historically used as agricultural land from at least 1927, if not earlier. Records indicate the subject parcel has been owned by Fauquier County since approximately 1993. According to historical records research and other sources, the site has historically been agricultural land. The land was partially developed starting in 2002 as a portion of the adjacent landfill. Indications of recognized environmental conditions were identified in the historical data review. The following recognized environmental conditions were identified through a review of available historical records:

The surrounding area has developed slowly from a primarily agricultural land with mixed residential homes, with increasing residential use over time. A large industrial facility was developed to the south and east around 2002. The area has remained generally consistent since the facility's construction.

- The property shares a parcel with the Fauquier County Landfill. The subject property operated as a portion of the landfill's operations as early as 2002, and the subject property was used for construction material storage by 2008 if not earlier. Records reviewed do not indicate the nature of large stockpile of materials stored on the subject property. Due to the historic use of the subject property as a part of landfill activities, and the use of the adjacent property at the times materials were stored, ECS considers the listing to be a REC for the subject property.
- Based on our review of available historical records, the adjacent facility is a landfill designated for the disposal of household trash, bulk waste and recycling, and has historically been used as such since 2002 or earlier. ECS considers the facility to represent a BER for the subject property.

7.0 SITE AND AREA RECONNAISSANCE

7.1 Methodology

Josh Peckham and Michael Bacon of ECS conducted the field reconnaissance on August 22, 2022. The weather at the time of the reconnaissance was 90 degrees Fahrenheit and sunny. Observations were made from a walking reconnaissance around the perimeter, and along several transects across the subject property. Access or visibility limitations, if any, are discussed in Section 2.6. Subject property photographs are included in Appendix V.

7.2 On-Site Features

7.2.1 Observed Geologic, Hydrogeologic, Hydrologic, and Topographic Conditions

The site generally slopes to the west. A large earthen mound rises on the east side of the property and curves across the north of the property. A tributary stream of the Mill Run stream borders the length of the western property boundary, from north to south. Groundwater flow presumably flows towards this stream. Surface flow presumable follows a similar path, but flowing slightly more south to a stormwater retention pond past the south edge of the subject property.

7.2.2 Past Site Uses

During the site reconnaissance, ECS observed the subject property for evidence of past occupancy or usage that could indicate the presence of environmental concerns. Based on current site conditions observed during the site reconnaissance, ECS presumably assumes the large mound across the property is reminiscent of former landfill operations on this portion of the parcel.

7.2.3 Current Uses

The subject property is an approximate 10 acre tract that is located in a predominantly agricultural area of Warrenton, VA. The subject property is a portion of a larger parcel currently occupied by the with similar uses. The subject property consists of a large developed earthen structure but is otherwise overgrown with herbaceous vegetation.

The table below lists pertinent features of interest that were assessed for the subject property. Relevant information regarding pertinent features is discussed further in this section. Pertinent features of environmental concern were not observed during the site reconnaissance.

Feature	Yes	No
Hazardous Substances and Petroleum Products in Connection with Identified Uses		✔
Hazardous Substance and Petroleum Product Containers Not in Connection with Identified Uses		✔
Drums, Totes, and Intermediate Bulk Containers		✔

Feature	Yes	No
Unidentified Substance Containers		✔
Underground or Aboveground Storage Tanks		✔
Strong, Pungent or Noxious Odors		✔
Standing Surface Water and Pools or Sumps Containing Liquids Likely to be Hazardous Substances or Petroleum Products		✔
Known or Suspect PCB-containing Equipment		✔
Stains or Corrosion to Floors, Walls or Ceilings		✔
Stained Soil or Pavement		✔
Floor Drains and Sump Pumps		✔
Pits, Ponds or Lagoons		✔
Stressed Vegetation		✔
Solid Waste Mounds or Non-natural Fill Materials		✔
Water/Wastewater Discharge		✔
Groundwater Wells		✔
Septic Systems or Cesspools		✔
Hydraulic Equipment (Elevators, Lifts, Compactors, Etc.)		✔
Dry Cleaning		✔
Specialized Industrial Equipment		✔
Onsite Electrical Generators		✔
Oil-water Separators		✔

Solid Waste Mounds or Non-natural Fill Materials

A large earthen mounds was observed across most of the east side of the property, extending across the north side of the property. Due to the soil surface covering of dense vegetation, ECS is not able to verify the materials buried at the subject property.

7.3 Adjoining and Nearby Properties

Contiguous and nearby properties were observed during a walking and vehicular reconnaissance of the subject property boundary and public places. The subject property is located in a rural area of Warrenton, Faquier County, Virginia.

Direction	Description	Relative Gradient	REC
North	Bingham road and a Virginia State Police station. Beyond which is a large community college complex.	Cross-gradient	No
East	Lands belonging to the Fauquier County Landfill.	Up-gradient	Yes
South	Lands belonging to the Fauquier County Landfill.	Down-gradient	No
West	Forested land containing a stream, beyond which is James Madison Highway	Down-gradient	No

Pertinent features of environmental concern were not observed on adjoining or nearby properties during the site reconnaissance.

7.4 Site and Area Reconnaissance Summary

According to our site observations and a review of adjoining and nearby properties, the subject property was used primarily as storage area for earthen material for the adjacent landfill. The subject property is located in a rural area of Fauquier County, surrounded primarily by industrial and residential land, with some commercial buildings to the north. Details pertaining to our on-site and off-site observations are referenced previously. The following RECs were identified during our on-site and off-site reconnaissance:

- A large earthen mounds was observed across most of the east side of the property, extending across the north side of the property. Due to the soil surface covering of dense vegetation, ECS is not able to verify the materials buried at the subject property. Historical records review had revealed this material originated from the adjoining landfill facilities. As ECS was not able to verify the materials at the time, ECS considers this to be a REC for the subject property.

8.0 ADDITIONAL SERVICES

ASTM guidelines identify non-scope issues, which are beyond the scope of this practice. Non-scope issues have the potential to be business environmental risks. Some of these non-scope issues include; asbestos-containing building materials, radon, lead-based paint, lead in drinking water, wetlands, and mold.

ECS was not authorized to assess non-scope issues in conjunction with this assessment.

9.0 INTERVIEWS

Copies of interview documentation are included in Appendix II.

ECS interviewed local government officials and agencies via written Freedom of Information Act requests. Information gained from such sources is included in Section 6.10.

ECS attempted to contact Katherine Roberts on August 23, 2022. At the time this report was issued, ECS had not received a response. The lack of an owner interview is considered to be a data gap for the Phase I ESA process. Based on the other information reviewed, this data gap is not expected to impact our ability to render a professional opinion regarding the subject property.

10.0 FINDINGS AND CONCLUSIONS

10.1 Findings and Opinions

The subject property is identified by the Fauquier County GIS as a portion of the parcel identified with the Property Identification Number (PIN) 6983-81-0145-000 and owned by the Board of Supervisors of Faquier County. The subject property is an approximate 10 acre tract that is located in a predominantly agricultural area of Warrenton, VA. The subject property is a portion of a much larger parcel that houses the Fauquier County Landfill facilities. The subject property consists of primarily unimproved land, with a large earthen mound rising across most of the east and north of the site. A small utility shed and some transmission lines occupy the northwest corner of the property.

The subject property is located in a rural area of Warrenton, Virginia. Based on our review of site topography and conditions observed during the site reconnaissance, it is our professional opinion that properties to the east are presumed to be hydrogeologically up-gradient of the subject property. The subject property is bound on the north by commercial facilities, on the east and south by industrial landfill facilities and on the west by undeveloped land. ECS identified the adjacent landfill operations to represent a potential BER for the subject property.

Based on the records search, site reconnaissance and interviews, it appears that the subject property has been historically used as agricultural land from at least 1952, if not earlier. Prior to 1927, it appears that the site was undeveloped. Records indicate the subject parcel has been owned by Fauquier County. Historical records prior to 1894 were not reasonably ascertainable for the subject property.

A regulatory database search report was provided by EDR. The database search involves researching a series of Federal, State, Local, and other databases for facilities and properties that are located within specified minimum search distances from the subject property. The report did not identify the subject property on the databases researched. The EDR report identified several off-site properties within the minimum ASTM search distances. Based on our review of available public records, issues associated with the the listings in the database report are not believed to represent a REC for the subject property.

ASTM E1527-21 defines a "*data gap*" as: "a lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information." A *"significant data gap"* is "a data gap that affects the ability of the environmental professional to identify a recognized environmental condition." Significant data gaps that would be expected to impact our ability to render a professional opinion concerning the subject property were not identified.

ECS was not able to conduct an interview with the property owner or someone with considerable knowledge of the property. ECS considers this to be a data gap for the assessment; however, based on conditions observed at the property and the consistent use of the property since its development, the absence of an owner interview was not considered to be a significant data gap, and was not considered likely impact our ability to render a professional opinion regarding the subject property.

ECS was not able to conduct an interview with the property owner or someone with considerable knowledge of the property. ECS considers this to be a data gap for the assessment; however, based on conditions observed at the property and the consistent agricultural use of the property that converted to a portion of a C&D landfill, the absence of an owner interview was not considered to be a significant data gap, and was not considered likely impact our ability to render a professional opinion regarding the subject property.

10.2 Significant Data Gaps

" A *"significant data gap"* is "a data gap that affects the ability of the environmental professional to identify a recognized environmental condition." Significant data gaps that would be expected to impact our ability to render a professional opinion concerning the subject property were not identified.

10.3 De Minimis Conditions

ECS did not identify *de minimis* conditions associated with the subject property during this assessment.

10.4 Conclusions

We have performed a Phase I Environmental Site Assessment in general conformance with the scope and limitations of ASTM E1527-21 of the Town of Warrenton DPW Complex Site A located at 8499 Bingham Road in Warrenton, Faquier County, Virginia, the subject property. Any exceptions to, or deletions from, this practice are described in Section 2.6 of this report. This assessment has revealed the following Recognized Environmental Conditions in relation to the subject property.

- The subject property started operating as a portion of the Fauquier County Landfill that is located on the parent parcel between 2002 and 2008. The landfill was reportedly used for storage of construction & demolition (C&D) waste material. Historical records and site visit observations revealed an earthen mound to the east of the subject property that extends to the north. Records reviewed do not indicate the nature of the material stockpiled on the subject property. Due to the historic use of the subject property as a part of C&D waste landfill activities, and the same use of the adjacent property, ECS considers the historic use to represent an REC for the subject property.
- The property shares a parcel with the Fauquier County Landfill, with several of the facilities and disposal areas adjoining the subject property to the east and south. This collection site is designated for the disposal of household trash, bulk waste and recycling as well as C&D waste. Based on our review of available historical and regulatory records, the adjacent facility was cited for violations in the past, and it is possible household waste debris may be present on the subject property, As a result of this use, ECS considers the facility to represent an REC for the subject property.

11.0 REFERENCES

ASTM E1527-21. Standard Practice for Environmental Site Assessment, Phase I Environmental Site Assessment Process.

Environmental Data Resources, Inc., Aerial Photo Decade Package, dated August 15, 2022, Inquiry Number 7085107.8.

Environmental Data Resources, Inc., Certified Sanborn Map Report (no coverage), dated August 15, 2022, Inquiry Number 7085107.3.

Environmental Data Resources, Inc., City Directory Image Report, dated August 15, 2022, Inquiry Number 7085107.5.

Environmental Data Resources, Inc., Radius Map Report, dated August 15, 2022, Inquiry Number 7085107.2s.

Historic Aerials by NETR, https://www.historicaerials.com/.

Fauquier County Parcel Search and Zoning Map, https://fauquiergis.maps.arcgis.com/apps/webappviewer/index.html?id=42c7a841c08b4f4cb11a3b2d3179e144

7.5-minute USGS Topographic Map of the Warrenton, VA Quadrangle, dated 2019. https://ngmdb.usgs.gov/topoview/.

Appendix I: Figures

Figure 1

Site Location



Figure 2

Topographical Map

Figure 3

Aerial Imagery

Appendix II: Interviews, Correspondence and User Questionnaire

ENVIRONMENTAL QUESTIONNAIRE

Environmental Questionnaire for User

Completion required for conformance with ASTM E 1527-13. Failure to provide this information may preclude CERCLA liability protections for the property purchaser. Please return answered form to ECS.

Site Name: _____

Name and Title of Person Completing Questionnaire (Please Print):

FRANK CASSIDY, DIRECTOR PUBLIC WORKS & UTILITIES

Signature of Person Completing Questionnaire:

Date: 9/9/22

Name of Your Company and Your Contact Number (Please Print):

TOWN OF WARRENTON, VA. 540-347-1101 X123

ASTM E 1527-13 indicates that, "Either the user shall make known to the environmental professional the reason why the user wants to have the Phase I Environmental Site Assessment performed or, if the user does not identify the purpose of the Phase I Environmental Site Assessment, the environmental professional shall assume the purpose is to qualify for an LLP to CERCLA liability and state this in the report." As the user of this ESA, what is the reason for conducting the Phase I ESA? If this question is unanswered, ECS will assume that the user's reason for the ESA is to qualify for landowner liability protections to CERCLA liability.

Please state reason for having ESA performed: FEASIBILITY STUDY

Will you provide Property Title Records and a Legal Description to ECS?

Please select one: **NO** ☐ **YES** ☑ AS POSSIBLE

Will you provide a 50-year chain of title abstract to ECS?

Please select one: **NO** ☑ **YES** ☐

Please Send Information Promptly

(1a.) Environmental liens that are filed or recorded against the site (40 CFR 312.25). ASTM E 1527-13 states that the user should perform a review of recorded land title records and judicial records for environmental liens or activity and use limitations for the site. Please forward the results of the land title record and judicial record review. If you would prefer, ECS can obtain this information from a third party provider for **an additional fee**. Please let ECS know if you would like to contract ECS for this service.

Please select one: **Client to Provide** ☐ **ECS to Provide for Additional Fee** ☐

(1b.) **Activity and use limitations that are in place on the site or that have been filed or recorded in a registry (40 CFR 312.26).** Are you aware of any activity and use limitations (AULs), such as engineering controls, land use restrictions or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state or local law?

Please select one: **NO** [✓] **YES** [ ]
If yes, please explain: BUT IS A LANDFILL SITE

(2.) **Specialized knowledge -** As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?

Please select one: **NO** [✓] **YES** [ ]
If yes, please explain:

(3.) **Commonly known or reasonably ascertainable information about the property (40 CFR 312.30).** Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example:

(a.) Do you know the past uses of the property?

Please select one: **NO** [ ] **YES** [✓]
If yes, please state uses: FAUQUIER COUNTY

(b.) Do you know of specific chemicals that are present or once were present at the property?

Please select one: **NO** [✓] **YES** [ ]
If yes, please explain:

(c.) Do you know of spills or other chemical releases that have taken place at the property?

Please select one: **NO** [✓] **YES** [ ]
If yes, please explain:

(d.) Do you know of any environmental cleanups that have taken place at the property?

Please select one: **NO** ☑ **YES** ☐
If yes, please explain: _____

(4.) **Relationship of the purchase price to the fair market value of the property if it were not contaminated (40 CFR 312.29).** Does the purchase price being paid for this property reasonably reflect the fair market value of the property?

Please select one: **NO** ☐ **YES** ☐ N/A
If no, please explain: _____

If you are aware that there is a difference, is the lower purchase price because contamination is known or believed to be present at the property?

Please select one: **NO** ☐ **YES** ☐ N/A
If yes, please explain: _____

(5.) **Parcel Property Owner(s) & Contact Number(s):**

A. Fauquier County
B. _____
C. _____
D. _____

Property Manager and Occupant(s) & Contact Number(s)

Property Manager: _____
Occupant/Tenant: _____
Occupant/Tenant: _____

(6.) **The degree of obviousness of the presence or likely presence of contamination at the property, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31).** As the user of this ESA, based on your knowledge and experience related to the property, are there any obvious indicators that point to the presence or likely presence of contamination at the property?

Please select one: **NO** ☐ **YES** ☐ unknown
If yes, please explain: _____

Josh Peckham

From: DEQ-NRO FOIA, rr <nrofoia@deq.virginia.gov>
Sent: Friday, August 19, 2022 5:43 PM
To: Josh Peckham; rr DEQ-NRO FOIA
Subject: [EXTERNAL] (716-23-0234) *NEW SUBMISSION* Freedom of Information Act Request

Good afternoon,

Please be advised that it is not possible to provide the requested records or determine whether they are available within the five working days required by FOIA due to technical difficulties at our Northern Regional Office. Therefore, we are invoking subsection B4 of § 2.2-3704 to provide us with seven additional working days to respond to your request. We will deliver a response on or before 8/30/22.

Thank you,
Emma

Emma Murphy (she/her/hers)
FOIA Technician
Virginia Department of Environmental Quality
Northern Regional Office
13901 Crown Court, Woodbridge, VA 22193
Main: 703-583-3800
Please submit all FOIA requests and correspondence to NROfoia@deq.virginia.gov

---------- Forwarded message ---------
From: **DEQ Website** <DEQCommunications@deq.virginia.gov>
Date: Fri, Aug 12, 2022 at 12:40 PM
Subject: *NEW SUBMISSION* Freedom of Information Act Request
To: nrofoia@deq.virginia.gov <nrofoia@deq.virginia.gov>

Freedom of Information Act Request

Submission #:	1889567
IP Address:	184.185.47.218
Submission Date:	08/12/2022
Survey Time:	12 minutes, 48 seconds

You have a new online form submission. To download a copy in PDF format, please click here.
Note: a download will promptly begin but may take up to a few minutes to complete pending the overall submission size.

Thank you,
Virginia DEQ

This is an automated message generated by Granicus. Please do not reply directly to this email.

Did you know the information you are looking for may already be online? We have compiled a list of the most frequently requested FOIA items. Please take a moment to review our online resources.

Request submitted by:

* **Name**
Joshua Peckham

* **Date**
08/12/2022

* I am a Virginia resident
Yes

* **Email**
jpeckham@ecslimited.com

Phone Number
(571) 919-0668

Information Requested

Please provide past history and current usage of property. Any information is helpful *(Example: private residence, undeveloped land, current operating business, former business, industrial property, etc)*.

* **Please be as specific as possible in describing the information you are requesting.**
ECS Mid-Atlantic, LLC (ECS) is currently conducting an environmental investigation for a portion of the referenced site. As a portion of our investigation, we are interested in obtaining any information your office may have regarding any documented storage, spills, and/or disposals of petroleum products, chemical or hazardous substances at the site or in the immediate vicinity of the project area.

Read-Only Content

Facility

Facility Name (if known)
8499 Bingham Rd. (parcel no. 6983-81-0145-000)

Former Name/Owner (if known)
BOARD OF SUPERVISORS OF FAUQUIER COUNTY

Full Address
8499 Bingham Rd.
Warrenton Virginia 20187

Additional Information
ECS is contracted to investigate an approximate 10-acre, primarily undeveloped, portion in the northwest of tax parcel number 6983-81-0145-000

* What date range is this requested for?
Other

From
08/12/1972 12:00 AM

To
08/12/2022 12:00 AM

* Add another facility?
No

Where do I send my request?

Please submit your request to the regional office that oversees the facility. Statewide requests should be sent to **Central Office**.

- Select **Blue Ridge Regional Office** if the facility is within the following counties or cities:
  - *Counties:* Alleghany, Amherst, Appomattox, Bedford, Botetourt, Campbell, Charlotte, Craig, Floyd, Franklin, Giles, Halifax, Henry, Montgomery, Patrick, Pittsylvania, Pulaski, and Roanoke
  - *Cities:* Bedford, Clifton Forge, Danville, Covington, Lynchburg, Martinsville, Radford, Roanoke and Salem

- Select **Northern Regional Office** if the facility is within the following counties or cities:
  - *Counties:* Arlington, Caroline, Culpeper, Fairfax, Fauquier, King George, Loudoun, Louisa, Madison, Orange, Prince William, Rappahannock, Spotsylvania, and Stafford
  - *Cities:* Alexandria, Fairfax, Falls Church, Fredericksburg, Manassas and Manassas Park

- Select **Piedmont Regional Office** if the facility is within the following counties or cities:
  - *Counties:* Amelia, Brunswick, Buckingham, Charles City, Chesterfield, Cumberland, Dinwiddie, Essex, Gloucester, Goochland, Greensville, Hanover, Henrico, King and Queen, King William, Lancaster, Lunenburg, Mathews, Mecklenburg, Middlesex, New Kent, Northumberland, Nottoway, Powhatan, Prince Edward, Prince George, Richmond, Surry, Sussex, and Westmoreland
  - *Cities:* Colonial Heights, Emporia, Hopewell, Petersburg, and Richmond

- Select **Southwest Regional Office** if the facility is within the following counties or cities:
  - *Counties:* Bland, Buchanan, Carroll, Dickenson, Grayson, Lee, Russell, Scott, Smyth, Tazewell, Washington, Wise, and Wythe
  - *Cities:* Bristol, Galax and Norton

- Select **Tidewater Regional Office** if the facility is within the following counties or cities:
  - *Counties:* Accomack, Isle of Wight, James City, Northampton, Southampton and York
  - *Cities:* Chesapeake, Franklin, Hampton, Newport News, Norfolk, Poquoson, Portsmouth, Suffolk, Virginia Beach, and Williamsburg

- Select **Valley Regional Office** if the facility is within the following counties or cities:
  - *Counties:* Albemarle, Augusta, Bath, Clarke, Fluvanna, Frederick, Greene, Highland, Nelson, Page, Rockbridge, Rockingham, Shenandoah, and Warren
  - *Cities:* Buena Vista, Charlottesville, Harrisonburg, Lexington, Staunton, Waynesboro, and Winchester

For Commonwealth-wide records, please select **Central Office**.

* **Regional Office**
Northern Regional Office

Josh Peckham

From: Josh Peckham
Sent: Friday, August 12, 2022 12:27 PM
To: darren.stevens@fauquiercounty.gov
Subject: Town of Warrenton DPW Complex Site A FOIA Request
Attachments: Town of Warrenton DPW Complex Site A FOIA Request.pdf

Good Afternoon,

Please see attached FOIA request on behalf of ECS Mid Atlantic LLC. Please let me know if you have questions or if I should direct my correspondence to a different contact.

Respectfully,

JOSH PECKHAM | Environmental Scientist
ECS MID-ATLANTIC, LLC
T 703.471.8400 **D** 571.919.0668 **C** 571.919.0668
14026 Thunderbolt Place, Suite 100, Chantilly, VA 20151-3232
JPeckham@ecslimited.com | www.ecslimited.com

ECS HAS LAUNCHED A PODCAST - Listen and subscribe by clicking here.

Instagram | LinkedIn | Facebook | Twitter

Confidential/proprietary message/attachments. Delete message/attachments if not intended recipient.

County of Fauquier
Department of Fire, Rescue and Emergency Management

30 John Marshall Street
Warrenton, Virginia 20186
Phone (540) 422-8800 Fax (540) 422-8813
http://www.fauquierfirerescue.org

Darren L. Stevens, MPA, CFOD
Fire Rescue Chief / Fire Marshal
darren.stevens@fauquiercounty.gov

Michael E. Gillam, MPA
Assistant Fire Rescue Chief
michael.gillam@fauquiercounty.gov

Tom Marable,
VFRA President
tom.marable@fauquiercounty.gov

August 18, 2022

Attn: Josh Peckham
ECS Mid-Atlantic, LLC
14026 Thunderbolt Place, Ste. 100
Chantilly, VA 20151

Re: PIN: 6983-81-0145-000, 199.90 Acres, 8499 Bingham Road, Warrenton, VA 20187

Dear Mr. Peckham,

This is in response to your inquiry regarding the above address. Our records department is able to search all dispatched emergency services calls in the last ten years. Information in regards to any known fires or code violations on the premises would be included in this search. There was an incident on 2/26/22. The incident report is attached.

In regards to illegal dumping or hazardous material spills on the property, these incidents would only be recorded if HazMat or other Fauquier County Emergency Services were called to the property via 911. The incident mentioned above did call HazMat, but nothing was found. That is also included in the attached report.

For records on building permits, and the use of storage tanks, wells, or septic systems on the property, please contact Fauquier County Community Development at 540-422-8200, email holly.meade@fauquiercounty.gov. In addition, we suggest that you contact the VA Department of Environmental Quality (DEQ) at 703-583-3800 to see what information they may be able to provide to help you complete your search.

If you have additional questions, please feel free to contact me at 540-422-8800 or by email at lindsay.flippo@fauquiercounty.gov.

Best Regards,

Lindsay Flippo
Fire, Rescue, & Emergency Management
Fauquier County

NFIRS-1 Basic

A

FDID	State	Month	Day	Year	Station	Number	Exposure
06100	VA	02	26	2022	Warrenton Vol. Fire & Rescue (1101)	2201600	0

B **Location Type**

Census tract:

- [x] Street Address
- [ ] Intersection
- [ ] In Front Of
- [ ] Rear Of
- [ ] Adjacent To
- [ ] Directions
- [ ] US National Grid

Number	Prefix	Street or Highway	Street Type	Suffix
8499		BINGHAM	RD-Road	

Apt./Suite/Room	City	State	Zip Code
	WARRENTON	VA	20187

Cross Street:

Additional location information for this incident is provided on the Wildland Fire Module in Section B, "Alternative Location Specification."

C **Incident Type**

141-Forest, woods or wildland fire

D **Aid Given Or Received**

- [ ] 1 Mutual Aid Received
- [ ] 2 Auto. Aid Received
- [ ] 3 Mutual Aid Given
- [ ] 4 Auto. Aid Given
- [ ] 5 Other Aid Given
- [x] None

Their FDID | Their State

Their Incident Number

E1 **Dates and Times**

Alarm	02	26	2022	13:34
Arrival	02	26	2022	13:41
Controlled	02	26	2022	16:14
Last Unit Cleared	02	26	2022	16:14

E2 **Shifts and Alarms**

Shift or Platoon	Alarms	District
A Shift		0145

E3 **Special Studies**

ID#	Value
9244	3 - No, COVID 19 was not a factor

F **Actions Taken**

11-Extinguishment by fire service personnel

Primary Action Taken

G1 **Resources**

☑ Apparatus or Personnel Module is used.

	Apparatus	Personnel
Suppression	11	19
EMS	1	3
Other	5	2

☐ Resource counts include aid received resources.

G2 **Estimated Dollar Losses and Values**

Losses: Required for all fires if known. Optional for all non-fires. None

Property: $ 2,000.00 ☐

Contents: $ 0 ☑

Pre-Incident Values: Optional None

Property: $ 2,000.00 ☐

Contents: $ ☑

Completed Modules

☐ 2 - Fire
☐ 3 - Structure Fire
☐ 4 - Civilian Fire Cas.
☐ 5 - Fire Service Cas.
☐ 6 - EMS
☐ 7 - HazMat
☐ 8 - Wildland Fire
☐ 9 - Apparatus
☐ 10 - Personnel
☐ 11 - Arson

H1 **Casualties** ☑ None

	Deaths	Injuries
Fire Service	0	0
Civilian	0	0

H2 **Detector**

Required for Confined Fires

☐ 1 - Detector Alerted Occupants
☐ 2 - Detector Did Not Alert Them
☐ 3 - Unknown

H3

Hazardous Materials Release

☐ 1 - Natural Gas
☐ 2 - Propane Gas
☐ 3 - Gasoline
☐ 4 - Kerosene
☐ 5 - Diesel Fuel / Fuel Oil
☐ 6 - Household Solvents
☐ 7 - Motor Oil
☐ 8 - Paint
☐ 0 - Other
☑ None

I **Mixed Use Property**

☐ Not Mixed
☐ 10 - Assembly Use
☐ 20 - Education Use
☐ 33 - Medical Use
☐ 40 - Residential Use
☐ 51 - Row Of Stores
☐ 53 - Enclosed Mall
☐ 58 - Business and Residential
☐ 59 - Office Use
☐ 60 - Industrial Use
☐ 63 - Military Use
☐ 65 - Farm Use
☐ 00 - Other Mixed Use

J **Property Use** ☐ None

Structures

131 ☐ Church, Place of Worship
161 ☐ Restaurant or Cafeteria
162 ☐ Bar/Tavern or Nightclub
213 ☐ Elementary School, Kindegarten
215 ☐ High School, Junior High
241 ☐ College, Adult Education
311 ☐ Nursing Home
331 ☐ Hospital
341 ☐ Clinic, Clinic-Type Infirmary
342 ☐ Doctor/Dentist Office
361 ☐ Prison or Jail, Not Juvenile
419 ☐ 1- or 2-Family Dwelling
429 ☐ MultiFamily Dwelling
439 ☐ Rooming/Boarding House
449 ☐ Commerical Hotel or Motel
459 ☐ Residential, Board and Care
464 ☐ Dormitory/Barracks
519 ☐ Food and Beverage Sales
539 ☐ Household Goods, Sales, Repairs
571 ☐ Gas or Service Station
579 ☐ Motor Vehicle/Boat Sales/Repairs
599 ☐ Business Office
615 ☐ Electric-Generating Plant
629 ☐ Laboratory/Science Laboratory
700 ☐ Manufacturing Plant
819 ☐ Livestock/Poultry Storage (Barn)
882 ☐ Non-Residential Parking Garage
891 ☐ Warehouse

Outside

124 ☐ Playground or Park
655 ☐ Crops or Orchard
669 ☐ Forest (Timberland)
807 ☐ Outdoor Storage Area
919 ☐ Dump or Sanitary Landfill
931 ☑ Open Land or Field
936 ☐ Vacant Lot
938 ☐ Graded/Cared for Plot of Land
946 ☐ Lake, River, Stream
951 ☐ Railroad Right-of-Way
960 ☐ Other Street
961 ☐ Highway/Divided Highway
962 ☐ Residential Street/Driveway
981 ☐ Construction Site
984 ☐ Industrial Plant Yard

Property Use:

Description

Look up and enter a Property Use code and description only if you have NOT checked a Property Use box.

K2

Owner

Local Option	Person/Entity Type	Business Name (if applicable)	Phone Number

Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix

Number	Prefix	Street or Highway	Street Type	Suffix

Post Office Box	Apt./Suite/Room	City

State	Zip Code

L **Remarks:**

Aos to find about an acre & 1/2 brush fire involving plastic barrels & a small gas motor machine. A 1 3/4 line was placed in service knocking the bulk of the fire quickly. Incident was scaled back to Co 1101 units, EMS1101, BC1101 & E1102. Once fire was knocked W1101 remained on scene awaiting the fire Marshall. Fire was deemed unintentional and caused by a power surge at the utility pole.

M **Authorization**

Officer In Charge ID	Signature	Position or Rank	Assignment	Date
C721	Hunter, Charles,Jr	Lieutenant		02/27/2022
Member Making Report ID	Signature	Position or Rank	Assignment	Date

NFIRS-2 Fire

A

FDID	State	Month	Day	Year	Station	Number	Exposure
06100	VA	02	26	2022	Warrenton Vol. Fire & Rescue (1101)	2201600	0

B

Property Details

B1 ☐ Not Residential

Estimated number of residential living units in the building of origin whether or not all units became involved

B2 ☐ Buildings Not Involved

Number of buildings involved

B3 1.5 ☐ None ☐ Less than 1 acre

Acres burned (outside fires)

C

On-Site Materials Or Products

On-Site Materials Storage Use

D

Ignition

D1 94-Open area, outside; included are farmland, field

Area of Fire Origin

D2 13-Electrical arcing

Heat Source

D3 72-Light vegetation - not crop, including grass

Item First Ignited

D4

Type of Material First Ignited

E1

Cause of Ignition

☐ 1 - Intentional
☐ 2 - Unintentional
☑ 3 - Failure of Equipment or Heat Source
☐ 4 - Act of Nature
☐ 5 - Cause Under Investigation
☐ U - Cause Undetermined After Investigation

E2

Factors Contributing to Ignition

33-Short-circuit arc from defective, worn insulation

Factor Contributing to Ignition

E3

Human Factors Contributing to Ignition

Check all applicable boxes

☑ None
☐ 1 - Asleep
☐ 2 - Possibly impaired by alcohol or drugs
☐ 3 - Unattended person
☐ 4 - Possibly Mentally Disabled
☐ 5 - Physically Disabled
☐ 6 - Multiple Persons Involved

☐ 7 - Age Was A Factor

Estimated Age of Person Involved

☐ Male ☐ Female

F1

Equipment Involved In Ignition

☑

Equipment Involved

Brand

Model

Serial #

Year

F2

Equipment Power Source

☑

Equipment Power Source

F3

Equipment Portability

☐ 1 - Portable
☐ 2 - Stationary

Portable equipment normally can be moved by one or two persons.

G

Fire Suppression Factors

H1

Mobile Property Involved

- [ ] 1 - Not involved in ignition, but burned
- [ ] 2 - Involved in ignition, but did not burn
- [ ] 3 - Involved in ignition and burned
- [x] None

H2

Mobile Property Type and Make

Mobile Property Type

Mobile Property Make

Mobile Property Model

Year

State

License Plate Number

VIN

Local Use

- [ ] Pre-Fire Plan Available
- [ ] Arson Report Attached
- [ ] Police Report Attached
- [ ] Coroner Report Attached
- [ ] Other Reports Attached

NFIRS-7 HazMat

A

FDID	State	Month	Day	Year	Station	Number	Exposure
06100	VA	02	26	2022	Warrenton Vol. Fire & Rescue (1101)	2201600	0

NFIRS-9 Apparatus or Resources

A

FDID	State	Month	Day	Year	Station	Number	Exposure
06100	VA	02	26	2022	Warrenton Vol. Fire & Rescue (1101)	2201600	0

B **Apparatus/Resource**	Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
ID: BC1101 Type: 92-Chief officer car	Dispatch: 02/26/2022 13:34 Arrival: Clear:	☐ Sent	0	☐ Suppression ☐ EMS ☑ Other	
ID: CF1102 Type: 92-Chief officer car	Dispatch: 02/26/2022 13:34 Arrival: Clear:	☑ Sent	1	☐ Suppression ☐ EMS ☑ Other	86-Investigate
ID: CF1102 Type: 00-Other apparatus/resource	Dispatch: 02/26/2022 13:37 Arrival: 02/26/2022 13:44 Clear: 02/26/2022 14:27	☐ Sent	0	☐ Suppression ☐ EMS ☑ Other	
ID: E1102 Type: 11-Engine	Dispatch: 02/26/2022 13:34 Arrival: Clear:	☐ Sent	3	☑ Suppression ☐ EMS ☐ Other	76-Provide water
ID: E1103 Type: 11-Engine	Dispatch: 02/26/2022 13:34 Arrival: Clear:	☐ Sent	0	☑ Suppression ☐ EMS ☐ Other	
ID: E1107 Type: 11-Engine	Dispatch: 02/26/2022 13:34 Arrival: Clear:	☑ Sent	3	☑ Suppression ☐ EMS ☐ Other	93-Cancelled en route
ID: E1107 Type: 11-Engine	Dispatch: 02/26/2022 13:39 Arrival: Clear: 02/26/2022 13:46	☐ Sent	0	☑ Suppression ☐ EMS ☐ Other	
ID: E1113 Type: 11-Engine	Dispatch: 02/26/2022 13:34 Arrival: Clear: 02/26/2022 13:40	☐ Sent	0	☑ Suppression ☐ EMS ☐ Other	
ID: ES1101 Type: 70-Medical & rescue unit, other	Dispatch: 02/26/2022 13:34 Arrival: Clear:	☐ Sent	1	☐ Suppression ☐ EMS ☑ Other	81-Incident command
ID: FM1101 Type:	Dispatch: 02/26/2022 13:56 Arrival: 02/26/2022 14:55 Clear: 02/26/2022 16:14	☐ Sent	0	☐ Suppression ☐ EMS ☐ Other	
ID: M1101	Dispatch: 02/26/2022 13:34	☐ Sent	3	☐ Suppression	

Type: 76-ALS unit

Arrival: 02/26/2022 13:42

Clear: 02/26/2022 14:27

EMS
Other

11-Extinguishment by fire service personnel

ID: RE1113

Type: 71-Rescue unit

Dispatch: 02/26/2022 13:34 Sent 3

Arrival:

Clear:

Suppression
EMS
Other

93-Cancelled en route

ID: RE1113

Type: 11-Engine

Dispatch: 02/26/2022 13:36 Sent 0

Arrival:

Clear: 02/26/2022 13:46

Suppression
EMS
Other

ID: TL1101

Type: 12-Truck or aerial

Dispatch: 02/26/2022 13:34 Sent 2

Arrival:

Clear:

Suppression
EMS
Other

ID: W1101

Type: 11-Engine

Dispatch: 02/26/2022 13:36 Sent 5

Arrival: 02/26/2022 13:41

Clear: 02/26/2022 15:01

Suppression
EMS
Other

10-Fire control or extinguishment, other

ID: W1110

Type: 11-Engine

Dispatch: 02/26/2022 13:34 Sent 3

Arrival:

Clear:

Suppression
EMS
Other

93-Cancelled en route

ID: X1101

Type: 16-Brush truck

Dispatch: 02/26/2022 13:44 Sent 0

Arrival:

Clear: 02/26/2022 13:51

Suppression
EMS
Other

NFIRS-1S Supplemental

A

FDID	State	Month	Day	Year	Station	Number	Exposure
06100	VA	02	26	2022	Warrenton Vol. Fire & Rescue (1101)	2201600	0

Apparatus Narrative for E1107:

Engine 7 responded with 3 personnel and was cancelled enroute.

Apparatus Narrative for RE1113:

Placed in service

Apparatus Narrative for W1110:

Dispatched and cancelled by command during response..


Verification

HEALTH DEPARTMENT VERIFICATION

Building Permit # _____
Health Department File # _____

Division of Zoning & Development Services
Fauquier County Department of Community Development 29
Ashby Street, Suite 310, Warrenton, Virginia 20186
Building Phone: 540-422-8230
Facsimile: 540-422-8231

Fauquier County Health Department Environmental
Health Services
98 Alexandria Pike, Suite 42, Warrenton, VA 20186
Phone: 540-347-6363
Facsimile: 540-347-6373

When constructing improvements on your property, or adding commercial uses, it is critical to avoid damaging the existing septic system and reserve area through discharge overloading or physical damage. The purpose of this form is to 1) ensure that property owners are fully aware of the potential hazards to the well, septic system and reserve area, and of their responsibility to protect these systems; and to 2) facilitate coordination between the Health Department and Zoning & Development Services.

PART 1 | **PROPERTY AND PROJECT VERIFICATION**

Property Address: 8499 Bingham Road Warrenton VA 2018 **PIN:** 6983-81-0145

Applicant Phone Number: 540-422-8835

Description of Work to be Permitted: Construct a shed 24'x 100' (maximum)

PART 2 | **SEPTIC AND WELL VERIFICATION**

For all project types listed below, PART 2A must be signed by the property owner/agent and then reviewed and approved by the Health Department prior to submission of a Building/Zoning Permit to the Building office. For project types not listed, Health Department review is not required and the property owner/agent shall complete PART 2B. **PLEASE CHECK ALL THAT APPLY:**

- ☐ Alteration or addition which increases the number of bedrooms- exceeding the current operations permit
- ☐ Geothermal system
- ☐ Abandonment of a well or septic system
- ☐ Change in Use or addition of commercial use to residential
- ☐ Any accessory structure that includes plumbing fixtures.
- ☐ Addition which increases the footprint of the home, except porches & decks
- ☑ Accessory structure larger than 256 sq. ft., including barns, sheds, and pools and pool houses that are proposed within 100' of well & septic
- ☐ Other not specified

Please fill out ONLY ONE column below:

PART 2A | **Health Department Verification -$25.00**

The County's completed Building/Zoning Permit Application shall accompany the submission to the Health Department, to include one (1) copies of a location survey or plat, drawn to scale, that shows property boundaries, all existing structures, driveways and other paving, areas of proposed grading, location of new buildings and the location of the well, drainfield, reserve drainfields and all septic system components, including tanks. The Health Department will review the application for potential impacts to the well and septic system.

I hereby give permission to the Health Department to enter onto the above referenced property for the purpose of processing this application and determining compliance with Health Department requirements.. I certify that, to the best of my knowledge, the attached application site sketch are true, correct, and complete.

Michael T. Dorsey
Owner/Agent Printed Name

Michael T. Dorsey , 11-18-16
Owner/Agent Signature **Date**

PART 2B | **Property Owner Verification**

I certify that: 1) I am not increasing the number of bedrooms with this project; 2) I know the location of the wells, drainfields, drainfield reserve areas and all septic system components, including tanks on the above referenced property; and have determined that the proposed function will not affect either system, 3) all required setbacks from such systems are being maintained and that access to the system for maintenance is not affected (see Table HD 1); and 4) I acknowledge that it is my responsibility to protect these systems.

Michael T. Dorsey
Owner/Agent Printed Name

Michael T. Dorsey , 11-18-16
Owner/Agent Signature **Date**

FOR HEALTH DEPARTMENT APPROVAL ONLY:

_____ , 11-30-16
Health Department Signature **Date**

Additional Health Department Comments:

No Plumbing Fixtures

Revised 9/20/16

Table HD 1

Minimum Separation Distances for Septic Tanks, Pretreatment Units, Pump Tanks, Conveyance Lines, and Header Lines

Structure or Topographic Feature	Minimum Horizontal Distance
Property Lines	5'
Building Foundations	10'
Basements	20'
Top edge of banks and cuts (i.e. grading)	10'
Utility Lines	10'

For a complete list see: 12 VAC5-610 and Fauquier Ordinance Chapter17

Minimum Separation Distances for Drainfield Area and Reserve Area

Structure or Topographic Feature	Minimum Horizontal Distance
Property Lines	5'
Building Foundations	10'
Basements	20'
Top edge of banks and cuts (i.e. grading)	20'
Utility Lines	10'

For a complete list see: 12 VAC5-610 and Fauquier Ordinance Chapter17

Minimum Separation Distances between a Well and a Structure or topographic feature

Structure or Topographic Feature	Class III C or IV	Class III A or B
Property Lines	10'	10'
Building Foundation	15'	15'
Building Foundation (Termite Treated)	50'	50'
House Sewer Line	50'	50'
Sewer Main / Force Main	50'	50'
Sewerage System	50'	50'
Sewage System or other contaminant source (e.g., drainfield, underground storage tank, barnyard, hog lot, etc.)	100'	50'
Cemetery	100'	50'
Sewage Dump Station	100'	50'

For a complete list see: 12 VAC5-630 and Fauquier Ordinance Chapter19

Please call the Fauquier County Health Department at 540-347-6363 if you have any questions or concerns about your project and remember that it is recommended that you have your septic tank pumped every (3) three to (5) five years.

PROPOSED EQUIPMENT STORAGE SHED

CORRAL FARM SANITARY LANDFILL

FAUQUIER COUNTY



, well

GENERAL SERVICES DEPT. RECEIVED

Sewage Disposal System Construction Permit

PAGE 1 OF 2

Commonwealth of Virginia
Department of Health
Fauquier Co Env. Health Department

Health Department Identification Number SD-93-655
Map Reference Sub1

General Information

New ☒ Repair ☐ Expanded ☐ Conditional ☐ FHA ☐ VA ☐ Case No. _____

Based on the application for a sewage disposal system construction permit filed in accordance with Section 3.13.01, a construction permit is hereby issued to:

Owner Fauquier County Sch Bd Attn Tom Telephone (703)347-6800

Address 78 W Lee St Warrenton VA 22186

For a Type I Sewage disposal system which is to be constructed on/at 7945 Old Forge Rd Lot 1 Sub1 Div

Subdivision Town of Fauquier Section/Block _____ Lot _____

Actual or estimated water use 1500 gpd 150 BR EQUIVALENT

DESIGN	NOTE: INSPECTION RESULTS
Water supply, existing: (describe) N/A signs must be posted at all spigots stating Non-Potable **To be installed:** class III B Non Potable Source cased Sch 40 to Rock grouted Sch 40 to Rock	**Water supply location:** Satisfactory yes ☐ no ☐ comments G. W. 2 Received: yes ☐ no ☐ not applicable ☐
Building sewer: Install S/S as Indicated, 4" I.D. PVC 40, or equivalent. Slope 1.25" per 10' (minimum). ☐ Other Smooth pipe to SB	**Building sewer:** yes ☐ no ☐ comments Satisfactory
Septic tank: Capacity 1500 gals. (minimum). ☒ Other No gauge Required	**Pretreatment unit:** yes ☐ no ☐ comments Satisfactory
Inlet-outlet structure: 6" in 18" out PVC 40, 4" tees or equivalent. ☒ Other Stub T's 1" Relief Lids	**Inlet-outlet structure:** yes ☐ no ☐ comments Satisfactory
Pump and pump station: No ☒ Yes ☐ describe and show design. if yes:	**Pump & pump station:** yes ☐ no ☐ comments Satisfactory
Gravity mains: 4" or larger I.D., minimum 6" fall per 100', 1500 lb/ crush strength or equivalent. ☐ Other	**Conveyance method:** yes ☐ no ☐ comments Satisfactory
Distribution box: Precast concrete with 5+ ports. ☒ Other Bed on 4" concrete PAD	**Distribution box:** yes ☐ no ☐ comments Satisfactory
Header lines: Material: 4" I.D. 1500 lb. crush strength plastic or equivalent from distribution box to 2' into absorption trench. Slope 2" minimum. ☐ Other	**Header lines:** yes ☐ no ☐ comments Satisfactory
Percolation lines: Gravity 4" plastic 1000 lb. per foot bearing load or equivalent, slope 2" 4" (min. max.) per 100'. ☐ Other	**Percolation lines:** yes ☐ no ☐ comments Satisfactory
Absorption trenches: Square ft. required 672: depth from ground surface to bottom of trench 48"; aggregate size 1½ to 1"; Trench bottom slope 2-4" per 100'; center to center spacing 9'; trench width 3 Depth of aggregate 13"; Trench length 56; Number of trenches 4	**Absorption trenches:** yes ☐ no ☐ comments Satisfactory
	Date _____ Inspected and approved by: _____ Sanitarian

C H S 202A Revised 6-84

Health Department Identification Number SD-93-655

Schematic drawing of sewage disposal system and topographic features.

PAGE 2 OF 2

Show the lot lines of the building lot and building site, sketch of property showing any topographic features which may impact on the design of the system, all existing and/or proposed structures including sewage disposal systems and wells within 100 feet of sewage disposal system and reserve area. The schematic drawing of the sewage disposal system shall show sewer lines, pretreatment unit, pump station, conveyance system, and subsurface soil absorption system, reserve area, etc. When a nonpublic drinking water supply is to be located on the same lot show all sources of pollution within 100 feet.

1 BR EQUIV; 150 gpd SEWAGE ... WELL ORGANIC FARM LANDFILL

☒ The information required above has been drawn on the attached copy of the sketch submitted with the application. Attach additional sheets as necessary to illustrate the design.

SEWAGE SYSTEM IS FOR EQUIPMENT WASH-DOWN AND RESTROOM FACILITIES ONLY. WATERLESS HAND-CLEANERS AND BOTTLED DRINKING WATER REQUIRED.

LANDFILL CELLS

THE SYSTEM TO BE INSTALLED BY THE AUTHORITY OF THIS PERMIT MUST CONFORM TO THE FAUQUIER COUNTY SANITATION AND/OR WELL ORDINANCES.



SEWAGE PERMIT REQUIREMENTS

- Drawing not to scale.
- Show ... building location ... with approved drainfield location.
- Designs for basement plumbing: YES NO
- Drainfield to be 100+' from Class I, II, III ... wells.
- Install 4-36' lines, ON CONTOUR, in 3 ... trenches, on 9' centers.
- Trench ... 48" deep.
- ... solid header pipe ... recommended.
- Set ... pipes 24" into gravel.
- Use ... single size gravel 0.5" to 1.5" dia.
- No ... or ... in drainfield system.
- Prevent ... from ... drainfield.
- No ... within 10' of ... pad.
- ... tank every 2 - 5 years.

WELL PERMIT REQUIREMENTS

- ... with 50-foot ... away from ...
- ... ground ... of ... and ...
- ... of ... contamination
- ... must ... to be witnessed by ... representative ... conditions.

- Toilet ... for equipment cleaning & toilet facilities only.

The sewage disposal system is to be constructed as specified by the permit ☐ or attached plans and specifications ☐.

This sewage disposal system construction permit is null and void if (a) conditions are changed from those shown on the application (b) conditions are changed from those shown on the construction permit.

No part of any installation shall be covered or used until inspected, corrections made if necessary, and approved, by the local health department or unless expressly authorized by the local health dept. Any part of any installation which has been covered prior to approval shall be uncovered, if necessary, upon the direction of the Department.

Date: 12/6/93 Issued by: _____ Sanitarian

Date: 12/7/93 Reviewed by: _____ Supervisory Sanitarian

This Construction Permit Valid until 12/3/94

If FHA or VA financing

Reviewed by Date _____ _____ Supervisory Sanitarian Date _____ _____ Regional Sanitarian

C.H.S. 302B Revised 5/94

Update – ES Projects

Landfill Gas
- SCS Engineers (proposal submitted for funding)
- Planning (review existing wells & production)
- New flare
- Additional wells
- Leachate recirculation coordination
- Air permit

Leachate Management
- Resource International (proposals being developed)
- Leachate sampling/analysis (annual requirement for treatment plants)
- Generator certification
- Leachate Management Plan (NOV, LF #575)
- Rebuild ponds
- Evaporation demonstration (New Waste Concepts)
- Treatment (Aqualitec, other; RFP?)
- Recirculation/Atomizing

Landfill #149 - NOV
- Joyce Engineering (waiting on Consent Order scope of work)
- Contractor estimate
- Consent Order terms
- Leachate Management Plan

Landfill #149 – Mining v. Closure Evaluation Report
- Draper Aden Associates
- Waiting on fines tests
- Mining – pros/cons; costs
- Closure/Post-Closure – costs

Transfer Construction
- Joyce Engineering
- Goal - January advertisement
- Replacement shed

|« « 1 » »| Parcel 1 of 1 Go

Back to List (/Results?page=1)

Parcel Detail for PIN 6983-81-0145-000

Street Address: 8499 BINGHAM RD

Legal Description: RESIDUE

Current Assessment Summary

Improvements Value	Land Value	Deferment	Total Taxable Value
$1,110,400	$4,645,200	$0	$5,755,600

Parcel | Improvements | Land | Transfers

Owners :	FAUQUIER COUNTY BD OF SUPERVISORS
Subdivision :	
Map Sheet :	6983.00
Landscape :	AVERAGE
Road Type :	PAVED
Topography :	ON GRADE ROLLING
Book/Page & Instrument :	869/1863DEDICATION
Ancestors :	6983-61-8156-000 (/Details/6983618156000)
Mailing Address :	40 CULPEPER ST WARRENTON, VA 20186-3206
Neighborhood :	
Neighborhood Group :	0004
Tax District :	CEDAR RUN
Class :	GOVERNMENT
Acreage :	218.2593
Utilities :	WELL WATER SEPTIC TANK View 1 more
Zoning :	AGRICULTURE DISTRICT RES, 1 DWELL/AC
Descendents :	

COMMONWEALTH of VIRGINIA

IN COOPERATION WITH THE
STATE DEPARTMENT OF HEALTH

Fauquier County Health Department
ENVIRONMENTAL HEALTH
320 HOSPITAL DRIVE - SUITE 21
WARRENTON, VIRGINIA 20186

(540) 347-6363

January 23, 2001

Mr. Roger Boswell
Building Official
40 Culpeper St
Warrenton, Va. 20186

RE: Environmental Services Offices - Waste Management - Map No. 6983-81-0145

Dear Mr. Boswell,

This letter is written in regards to a request for permission for the above referenced property to be connected onto an existing well that now serves this property to another building on the property.

This office has no objections to this connection being made.

If you have any questions please feel free to call me at 347-6375.

Sincerely,

John R. Largent

John R. Largent
Environmental Health Supervisor

6983-81-0145

VDH VIRGINIA DEPARTMENT OF HEALTH

Protecting You and Your Environment

Fauquier County Health Department
98 Alexandria PikeSuite 42
Warrenton, Virginia
20186
(540) 347-6363
(540) 347-6373

Private Well Construction Permit

Health Department ID Number: SD-12-438

Owner Information		
Fauquier County Landfill 6438 College St Warrenton VA 20187 Phone 422-8840 Fax 422-8841	Phone:	

Location Information			
Subdivision Name: Property Address: County: Directions:	8499 Bingham Rd Fauquier Off Rt. 29 left on College Street Straight on Bingham Road	Tax Map: GPIN: Legal Description:	6983-81-0145 Subdivision Section Block Lot

General Information		
Well Class: **Class IV**	Minimum Casing Depth: **20**	Minimum Grout Depth: **20**

Comments:
This proposed well is classified "Class IV" (non domestic use). The proposed use is dust supression, for the Construction and Demolition materials processing plant of the Fauquier County Landfill.

Notice: The Virginia Department of Health may revoke or modify this permit if, at a later date, it finds the conditions that formed the basis for issuing the permit do not substantially comply with the *Private Well Regulations* , 12 VAC 5-630-10 et seq., or if the well would threaten public health or the environment.

Owner Information	
Fauquier County Landfill 6438 College St Warrenton, VA 20187	Phone: (540) HD ID #: SD-12-438

Construction Drawing



Site Evaluation Conducted By: Don Jeanrenaud

Issued by: Don Jeanrenaud
Environmental Health Specialist

December 10, 2012
Issue Date

December 10, 2013
Expiration Date

Fauquier County
Department of Environmental Services

DAVINA BRATCHER
Administrative/Accounting Manager

6438 College Street
Warrenton, VA 20187

Phone: 540-422-8840
Fax: 540-422-8841
E-mail: davina.bratcher@fauquiercounty.gov
Website: www.fauquiercounty.gov

Commonwealth of Virginia

Application for: ☐ Sewage System ☒ Water Supply

VDH Use Only
Health Department ID# SD12-498
Due Date _____

Owner FAUQUIER County Landfill
Mailing Address 6438 College STREET
WARRENTON Va 20187
Agent CONTACT: Butch Grimsley
Mailing Address 6438 College STREET
WARRENTON Va 20187
Site Address 8499 BINGHAM ROAD
WARRENTON Va 20187

Phone 540-428-6171
~~Phone 540-428-8840~~
Fax 540-422-8841
Phone 540-428-6171
Phone 540-422-8840 ✓
Fax 540-422-8941

Email Butch.Grimsley@fauquiercounty.gov

Directions to Property: OFF US ROUTE 29 LEFT ON COLLEGE STREET STRAIGHT ON BINGHAM ROAD

Subdivision _____ Section _____ Block _____ Lot _____

Tax Map ~~6983-23-4168~~ 6983-81-0145 Other Property Identification _____ Dimension/Acreage of Property 218.2543

Sewage System (New Construction)

Construction permits are valid for 18-months. Owners are advised to apply for a construction permit if they intend to build within 18 months of completing this application. Certification letters do not expire, may be recorded in the land records, and transfer with a property sale. For which are you applying? ☐ Certification Letter ☐ Construction Permit

Sewage System (Existing Construction)

Check all that apply: ☐ Repair ☐ Modification ☐ Expansion ☐ Replacement ☐ Upgrade

Do you wish to apply for a betterment loan eligibility letter? _____ If yes, there is a $50.00 fee for determination of eligibility.

Sewage System (New or Existing Construction)

☐ Single Family Home (**Number of Bedrooms** ___) ☐ Multi-Family Dwelling (**Total Number of Bedrooms** ___)

☐ Other (describe) _____

Basement? Yes/No (circle one). Walk-out Basement? Yes/No (circle one) Fixtures in Basement? Yes/No (circle one).

Conditional permit desired? Yes/No (circle one). If yes, which conditions do you want?

☐ Reduced water flow ☐ Limited occupancy ☐ Intermittent of seasonal use ☐ Seasonal or temporary use not to exceed 1 year

Water Supply

Will the water supply be Public or (Private) (circle one). Is the water supply Existing or (Proposed) (circle one).

If proposed, is this a replacement well? Yes (No) (circle one). Will the old well be abandoned? Yes/No (circle one). N/A

Will any buildings within 50' of the proposed well be termite treated? Yes (No) (circle one).

Note: For sewage systems, a plat of the property may be required and a site sketch is always expected. For water supplies, a plat of the property is not required and a site sketch is always expected. The site sketch should show your property lines, actual and/or proposed buildings and the desired location of your well and/or sewage system. Your property lines, building location and the proposed well and sewage system sites must be clearly marked and sufficiently visible to see the topography.

I give permission to the Virginia Department of Health to enter onto the property during normal business hours for the purpose of processing this application and to perform quality assurance checks of evaluations and designs until an operation permit is approved.

_____
Signature of Owner/Agent

11/29/12
Date

TAG SHEET 6983-81-0145

SD- 12-438 TAX MAP ID. [illegible]

NAME: Jeffries, Hardy CC

Application For: Construction Permit X well only

Certification Letter ____

OFFICE SUPPORT	DATE	INITIALS
Application Received:	11-30-12	BY
Fee: Amount Collected:	—	BY
Receipt Number:		
Application Reviewed:	11-30-12	BM
Applicant Given Site Evaluation Info Sheet:	11-30-12	
Application Entered into VENIS:	11-30-12	
Assigned To EHS: Don	11-30-12	
ENVIRONMENTAL SPECIALIST		
Site Visit Scheduled:	12-10-12	EJ
Applicant Reminded of Site Preparation Requirements:		
Initial Site Visit Made:	12-10-12	EJ
Level I AOSE Review		
Application Deactivated:		
Purpose:		
Administrative Denial Issued:		
Revised AOSE Report Received:		
Reactivation:		
Follow Up Visit:		
Follow Up Visit:		
Follow Up Visit:		
Data Entry into VENIS:	12-10-12	EJ
Issue/Deny Drafted:	12-10-12	EJ
Issue/Deny Reviewed:		
Issue/Deny Countersigned:		
Issue/Deny Sent to Applicant:		

Mark One: Mailed ___ Faxed ___ Picked Up ___ Other Emailed to Butch, Grimsley 1:55PM

Inspection Requested		
Inspection Performed		
Alternative Insp. Fee Collected:		
Operations Permit Issued:		

Contractors Name:

License Number: _____

Water Supply, existing: (describe)

To be installed: **Class:** _____

Cased: **Grouted:**

Satisfactory: Y N

Building Sewer: **Size:** _____

Type: _____

(I.D. PVC Schedule 40, or equivalent.)

Fall: _____

(1 1/4" per 10' required)

Satisfactory: Y N

Septic Tank: **Capacity:** _____ **gals.**

Manufacturer: _____

Other Notes:

Satisfactory: Y N

Inlet-Outlet Structure: **Inlet Tee:** _____ **Outlet Tee:** _____

(1" - 2" fall req. in tees)

Effuent Filter: _____

Other Notes:

Satisfactory: Y N

Pump and Pump Station: **Capacity:** _____ **gals.**

Manufacturer: _____

Pump Size: _____

Other Notes:

Satisfactory: Y N

Gravity Mains: **Material/Size:** _____

Fall in Line: _____

Other Notes:

Satisfactory: Y N

Distribution Box: **# of Boxes:** _____ **Ports:** _____

Other Notes:

Satisfactory: Y N

Header Lines: Smooth bore pipe required for header ditches

Material: 4" I.D. 1500 lb. crush strength plastic or equivalent

2' into the absorption trench required; 2" per 100' fall req.

Satisfactory: Y N **Other Notes:** _____

Percolation Lines: **Material/Size:** _____

(slope 2" - 4" per 100' required)

Min Fall: _____ **Max Fall:** _____

Satisfactory: Y N

Absorption Trenches: **Square ft. req:** _____ **Trench Bottom:** _____ **in.**

Aggregate size/depth: _____

# of Trenches: _____ **Length:** _____

Width of Trench: _____ **Center to Center:** _____

Sidewall of ditches are consistant with soil study Y N

100% of ditches open on inspection Y N

If No, please describe:

Other Notes:

Satisfactory: Y N



NOTES:

1. TOPOGRAPHIC CONTOUR INTERVAL = 2 FEET.
2. GROUNDWATER SURFACE CONTOUR INTERVAL = 5 FEET.
3. STATIC WATER LEVELS MEASURED ON 4/02/12.
4. GROUNDWATER CONTOURS BASED ON LINEAR INTERPOLATION BETWEEN AND EXTRAPOLATION FROM KNOWN DATUM, TOPOGRAPHIC CONTOURS, AND KNOWN FIELD CONDITIONS. THEREFORE, GROUNDWATER CONTOURS MAY NOT REFLECT ACTUAL GROUNDWATER CONDITIONS.
5. TOPOGRAPHY OBTAINED FROM DRAPER ADEN ASSOCIATES. DATE OF PHOTOGRAPHY: 04/03/11. DATE OF COMPILATION: 04/13/11.
6. GROUNDWATER CONTOUR LINES SHOW THE WATER TABLE SHAPE AND ELEVATION. THESE CONTOURS ARE INFERRED LINES FOLLOWING THE GROUNDWATER SURFACE AT A CONSTANT ELEVATION ABOVE SEA LEVEL. THE GROUNDWATER FLOW DIRECTION IS GENERALLY PERPENDICULAR TO THE GROUNDWATER SURFACE CONTOURS, SIMILAR TO THE RELATIONSHIP BETWEEN SURFACE WATER FLOW AND TOPOGRAPHIC CONTOURS.

DATE	REVISIONS AND RECORD OF ISSUE	NO	BY	CK	APP	DATE	REVISIONS AND RECORD OF ISSUE	NO	BY	CK	APP
							FIRST SEMI-ANNUAL 2012 GROUNDWATER REPORT				

DESIGNED KB
DRAWN MO
CHECKED IAW
APPROVED
DATE 04/20/12

JOYCE ENGINEERING
1604 OWNBY LANE
RICHMOND, VA 23220
PHONE: (804) 355-4530
© 2012 Joyce Engineering, Inc. All rights reserved.

SCALE: 1"=100'

PROJECT NO.: 384.1201.03.03

CORRAL FARM SANITARY LANDFILL
FAUQUIER COUNTY, VIRGINIA

GROUNDWATER SURFACE CONTOUR MAP
APRIL 2, 2012
PERMIT NO. 575

DRAWING NO.: 2

My Map

Copyright 2010 Esri. All rights reserved. Mon Dec 10 2012 12:21:43 PM.

Fauquier County
Real Estate Online

Results Detail ⏮ ◀ Parcel: 1 Go ▶ ⏭ | Parcel 1 of 1 Back to List New

PIN: 6983-81-0145-000 **Street Address:** 8499 BINGHAM RD
Legal Description: RESIDUE

Parcel Improvements Land Transfers

Current Assessment Summary

Improvements Value	Land Value	Deferment	Total Taxable V
$998,000	$4,441,200	$0	$5,439,200

Owners: FAUQUIER COUNTY BD OF SUPERVISORS

Mailing Address: 40 CULPEPER ST
WARRENTON, VA 20186-3206

Subdivision:

Neighborhood: SECTION 4 SOUTHERN CENTRAL

Map Sheet: 6983.00

Tax District: CEDAR RUN

Landscape: AVERAGE

Class: GOVERNMENT

Road Type: PAVED

Acreage: 218.2593

Topography: ON GRADE
ROLLING

Utilities: WELL WATER
SEPTIC TANK

Book/Page & Instrument: 692/431 DEED
709/963 CERTIFICATE OF TAKE

Zoning: AGRICULTURE DISTRICT
RES, 1 DWELL/AC

Ancestors: 6983-61-8156-000

Descendents:

Transfer Notes: 1998-47.4176AC FROM 267.1927AC OF FAUQ CO BD OF SUP LVING 219.7751AC THEN 47.4176AC MERGED W/ ; STATE BD FOR COMM COLLEGES TO MK 50AC DB 789/1738 PL 1744 2001-PLAT RECRD WHEREAS 1.5207 AC PUBLIC STREET USE -DB 869/1863

Land Conservation Easement Summary

Virginia Outdoors Foundation (VOF)	Purchase of Development Rights (PDR)	Nature Conservancy (NC)	Open Space (OPS
☐	☐	☐	☐

Fauquier County Real Estate Online

Results Detail ⏮ ◀ Parcel: 1 Go ▶ ⏭ | Parcel 1 of 1 Back to List New

PIN: 6983-81-0145-000 **Street Address:** 8499 BINGHAM RD
Legal Description: RESIDUE

Parcel Improvements Land Transfers

⏮ ◀ Improvement: 1 Go ▶ ⏭ Improvement 1 of 15

Improvement Value Summary

Total Improvements	Undepreciated Value	Depreciated Value
15	$615,898	$998,000

Detail - Improvement 1

Undepreciated Value	Valuation Method	Depreciation Factors			Other Factors	
		Physical %	Functional %	Economic %	Market Adj.	% Complete
$176,226	COMMERCIAL	69				

Building Use: COMMERCIAL
Condition:
Grade:
Stories: 1.0
Year Built: 1930
Effective Year: 1960
Rooms:
Bedrooms:
Full Baths:
Half Baths:

Structure: 1 STY FRAME DWG
Occupancy:
Heating Type:
Heating Fuel:
Roof Style:
Roof Material:
Foundation:
% Air Conditioned:
Fireplace Opens:
Chimney Stacks:

Style:
Quality: FAIR
Fireplace Types:
Floor Cover:
Interior Walls:
Exterior Wall:

Building Sections	Square Feet	Stories
OFFICE BLDG-FRAME	2688	1.0
ENCLOSED PORCH	45	1.0
OFFICE BLDG-FRAME	444	1.0
CARPORT	444	1.0

COMMONWEALTH of VIRGINIA

IN COOPERATION WITH THE
STATE DEPARTMENT OF HEALTH

Fauquier County Health Department
ENVIRONMENTAL HEALTH
320 HOSPITAL DRIVE - SUITE 21
WARRENTON, VIRGINIA 20186

(540) 347-6363

April 18, 2002

Mr. Roger Boswell
Building Official
40 Culpeper Street
Warrenton, Va. 20186

RE: Portable Toilet Placement - Map Reference: 6983-81-0145

Dear Mr. Boswell:

This letter is written to confirm receipt of written contracts for a Portable Toilet Placement, bottled water and waterless hand cleaner to be used Habitat for Humanity.

This office hereby approves the use of this for the period of time specified by the County of Fauquier for the warehouse.

If this office can be of any further assistance, please call us at 347-6375.

Sincerely,

John R. Largent

John R. Largent
Environmental Health Supervisor

6983-81-0145

COMMONWEALTH of VIRGINIA

IN COOPERATION WITH THE
STATE DEPARTMENT OF HEALTH

Fauquier County Health Department
ENVIRONMENTAL HEALTH
320 HOSPITAL DRIVE - SUITE 21
WARRENTON, VIRGINIA 20186

(540) 347-6363

April 18, 2002

Mr. Roger Boswell
Building Official
40 Culpeper Street
Warrenton, Va. 20186

RE: Portable Toilet Placement - Map Reference: 6983-81-0145

Dear Mr. Boswell:

This letter is written to confirm receipt of written contracts for a Portable Toilet Placement, bottled water and waterless hand cleaner to be used Habitat for Humanity.

This office hereby approves the use of this for the period of time specified by the County of Fauquier for the warehouse.

If this office can be of any further assistance, please call us at 347-6375.

Sincerely,

John R. Largent

John R. Largent
Environmental Health Supervisor

Habitat for Humanity

...1991 - 2002 over a decade of service to people in need

P.O. Box 3189 Warrenton, VA 20188 (540) 341-4952

April 18, 2002

Fauquier County Health Department
Environmental Services
Warrenton Virginia 20186

Re: Portable Toilet Placement

Fauquier Habitat for Humanity is currently leasing a warehouse from the county located behind the Environmental Services Building at the landfill. We have outfitted the warehouse with electrical power for lighting and other utility use under Permit No. S02-13117. We are unable to hook into the nearby septic system due to its limited capacity or provide potable water because of the proximity of the warehouse to the county landfill.

Fauquier Habitat requests permission install bottled water for drinking and to site a portable toilet supplied by Allied Portable Toilet Rentals for the convenience of our volunteers. A copy of the Agreement to provide the portable toilet is attached.

Sincerely,

Jack Flikeid
Executive Director

C:\My Documents\Landfill Warehouse\Warehouse Toilet.doc

ALLIED PORTABLE TOILET RENTALS
1321 N. Delphine Avenue • P.O. Box 280 • Waynesboro, VA 22980
Toll Free (800) 868-8386 • Fax (540) 885-3280

Date: Feb. 12, 2002

Fauquier Habitat
P. O. Box 3189
Warrenton, VA 20188

Re: Fauquier Co. Landfill

We are pleased to quote you on your portable toilet requirements for the above referenced project as follows:

Description	Monthly Rental
Standard Polyethylene Portable Toilets w/Large Capacity Holding Tanks	$ 70.00 /EA
Same as above with Hand Washing Facilities	$ /EA
Handicap Accessible Toilets	$ /EA
140 Gallon Capacity Trailer Holding Tank	$ /EA
250 Gallon Capacity Trailer Holding Tank	$ /EA
Extra Service on Standard Toilet (in addition to your regular one (1) time weekly service)	$ EA/Week

NOTES: All units are serviced professionally on a weekly basis. Our prices are subject to Virginia Sales Tax, if applicable. Terms net 30 days. Lead time 2-3 days after receiving order.

It is the responsibility of Allied Portable Toilets to pump, haul away, and dispose of all waste from the portable toilets at an approved waste water treatment facility.

Please call Darby Boyers or Bobby Simmons at 1-800-868-8386 and allow us the opportunity to provide you with the service you deserve.

Very truly yours,

ALLIED READY MIX COMPANY

Darby G. Boyers

Darby G. Boyers

Water Supply and/or Sewage Disposal System Construction Permit

Commonwealth of Virginia
Department of Health
Fauquier County Health Department

Health Department Identification Number SD-96-386
Map Reference 6983-71-7277 91-0145

General Information

Water Supply System: New ___ Repair ___ Public ___ FHA ___ VA ___ Case No. ___
Sewage Disposal System: New ___ Repair ___ Expanded ✓ Conditional ___ Public ___
Based on the application for a sewage disposal system construction permit filed in accordance with Section 2.13 E, of the Sewage Handling and Disposal Regulations and/or Section 2.13 of the Private Well Regulations a construction permit is hereby issued to:
Owner County of Fauquier
Address c/o 223 W.Shirley Ave,Warrenton, 20186-3112 Telephone 347-6820
For a Type I Sewage Disposal System or Well to be constructed on/at 21 S (L) @ Corral farm to site straight ahead.
Subdivision ___ Section/Block ___ Lot ___ Actual or estimated water use 300 gpd equiv.
6983-71-7277

DESIGN	NOTE: SEWAGE DISPOSAL SYSTEM INSPECTION RESULTS
Water supply, existing: (describe) 3c see notes pg 2 **To be installed:** class N/A cased ___ grouted ___	**Water supply location:** Satisfactory yes ☐ no ☐ comments Completion Report G. W. 2 Received: yes ☐ no ☐ not applicable ☐
Building sewer: c/o at new Bldg Location 4" I.D. PVC Schedule 40, or equivalent. Slope 1.25" per 10' (minimum). ☑ Other smooth pipe to DB	**Building sewer:** yes ☐ no ☐ comments Satisfactory
Septic tank: Capacity 1125 gals. (minimum). ☑ Other To match ex S.T.	**Pretreatment unit:** yes ☐ no ☐ comments Satisfactory
Inlet-outlet structure: 8" in 18" out PVC Schedule 40, 4" tees or equivalent. ☑ Other Stub T's 1" Below Lid	**Inlet-outlet structure:** yes ☐ no ☐ comments Satisfactory
Pump and pump station: No ☒ Yes ☐ describe and show design. if yes: ___	**Pump & pump station:** yes ☐ no ☐ comments Satisfactory
Gravity mains: 4" or larger I.D., minimum 6" fall per 100', 1500 lb. crush strength or equivalent. ☑ Other New C/O at junction w/Ex. Conv. Line	**Conveyance method:** yes ☐ no ☐ comments Satisfactory
Distribution box: Precast concrete with ___ ports. ☐ Other ___	**Distribution box:** yes ☐ no ☐ comments Satisfactory
Header lines: Material: 4" I.D. 1500 lb. crush strength plastic or equivalent from distribution box to 2' into absorption trench. Slope 2" minimum. ☐ Other ___	**Header lines:** yes ☐ no ☐ comments Satisfactory
Percolation lines: Gravity 4" plastic 1000 lb. per foot bearing load or equivalent, slope 2" 4" (min. max.) per 100'. ☐ Other ___	**Percolation lines:** yes ☐ no ☐ comments Satisfactory
Absorption trenches: Square ft. required ___: depth from ground surface to bottom of trench ___; aggregate size ___: Trench bottom slope ___; center to center spacing ___; trench width ___ Depth of aggregate ___; Trench length ___; Number of trenches ___	**Absorption trenches:** yes ☐ no ☐ comments Satisfactory Date ___ Inspected and approved by: ___ Sanitarian

C.H.S 202A

6983-71-7277 91-0145

6983-81-0145

Health Department
Identification Number SD 96 386

Schematic drawing of sewage disposal and/or water supply system and topographic features.

Show the lot lines of the building site, sketch of property showing any topographic features which may impact on the design of the well or sewage disposal system, including existing and/or proposed structures and sewage disposal systems and wells within 200 feet. The schematic drawing of the well site or area and/or sewage disposal system shall show sewer lines, pretreatment unit, pump station, conveyance system, and subsurface soil absorption system, reserve area, etc. When a nonpublic drinking water supply is to be permitted, show all sources of pollution within 200 feet.

☒ The information required above has been drawn on the attached copy of the sketch submitted with the application. Attach additional sheets as necessary to illustrate the design.



Not to scale

PIN 6983-71-7222
"Corral Farm - Co of Fauquier"
sewage expansion only
maximum of 15 person occupancy
(20 gal pd x 15 = 300 gpd = 2 Bedroom equivalency)

A 3B well is required when there are more than two connections (for drinking water purposes), H.D. highly recommends the existing well not be used for that purpose due to proximity of new landfill. Suggest bottled water for drinking and waterless hand cleaner. Well water may be used for lavatory flushing.

This sewage disposal system and/or water supply is to be constructed as specified by the permit ___ or attached plans and specifications ___

This sewage disposal system and/or well construction permit is null and void if (a) conditions are changed from those shown on the application (b) conditions are changed from those shown on the construction permit.

No part of any installation shall be covered or used until inspected, corrections made if necessary, and approved, by the local health department or unless expressly authorized by the local health dept. Any part of any installation which has been covered prior to approval shall be uncovered, if necessary, upon the direction of the Department.

Date: 7/15/96 **Issued by:** _____ Sanitarian EHS-SR4A

Date: 7/18/96 **Reviewed by:** John K. Largent Supervisory Sanitarian

This Construction Permit Valid until 7/15/97

If FHA or VA financing

Reviewed by Date _____ _____ **Date** _____ _____

Supervisory Sanitarian Regional Sanitarian

C.H.S. 202B

299482 (cash)
Pd. 125.00
7/10/96 Rcvd

Commonwealth of Virginia
Application for a Sewage Disposal and/or Water Supply Permit

Health Department ID SD-96-386

Post-it® Fax Note 7671 | Date 7/9/96 | pages ▶ 3
To M. Billy Jenkins | From J.R. Lovano
Co./Dept. | Co. F.C.H.D.
Phone # | Phone # 347-6375
Fax # 341-0364 | Fax # 347-6373

To Be Completed By The Applicant

Type of sewage system: ___ New ___ Repair ___ Expanded ___ Conditional
PHA/VA yes ___ no ___ Case No. ___

Owner County of Fauquier Address 40 Culpeper Street

Agent Billy Jenkins, Operations & Services Address 223 W. Shirley Avenue Phone 347-6820 2nd 347-6825

Directions of Property Corral Farm large house at end of College Street

Subdivision NA Section NA Block NA Lot NA

Other Property Identification Detail drawings attached

Dimension/size of Lot/Property 6983-71-7277

Other Application Information

I. **Building/facility**	___ New	X Existing	
Intermittent Use	___ Yes	___ No	If yes, describe ___
II. **Residential Use**	___ Yes	___ No	
Termite Treatment	___ Yes	___ No	
	___ Single Family (Number of Bedrooms ___)	___ Multi-family (Number of Units ___)	
Basement	X Yes	___ No	
Fixtures in Basement	X Yes	___ No	
III. **Commerical Use**	X Yes	___ No	Describe: Office
Commerical/Wastewater	X Yes	___ No	Number of Patrons ___ Number of Employees 5

If yes, give volumes and describe ___

IV. **Water Supply:**
___ Public ___ New ___ Existing
X Private ___ New X Existing
Describe: ___

V. **Proposed Sewage Disposal Method:**
Onsite Sewage Disposal System: ___ Septic Tank Drainfield ___ LPD ___ Mound ___ Other

Public Sewerage System

Attach a site plan (rough sketch) showing dimensions of property, proposed and/or existing structures and driveways, underground utilities, adjacent soil absorption system, bodies of water, drainage ways, and wells and springs within 200 feet radius of the center of the proposed well or drainfield. Distances may be paced or estimated.

The property lines and building location are clearly marked and the property is sufficiently visible to see the topography. I give permission to the Department to enter onto the property described for the purpose of processing this application.

Billy Jenkins Supervisor, 7-9-96
Signature of Owner/Agent Date

CHS 200

OSD96 386

END

Sewage Disposal System Construction Permit

PAGE 1 OF 2

Commonwealth of Virginia
Department of Health
Fauquier Co Health Department

Health Department Identification Number SD-93-141
Map Reference 82/53

General Information

New ☐ Repair ☐ Expanded ☒ Conditional ☐ FHA ☐ VA ☐ Case No. _____

Based on the application for a sewage disposal system construction permit filed in accordance with Section 3.13.01, a construction permit is hereby issued to:

Owner B. G. Sowder, Trustee Telephone 347-1097

Address Rt. 3 Box 1320, Gainesville, Va. 22065

For a Type 1 Sewage disposal system which is to be constructed on/at 295 (L) at LFCC to Dwelling at Rear of Property

Subdivision _____ Section/Block _____ Lot _____

Actual or estimated water use ~~450 gpd 3BR Equivalent~~ ~~2 BR 300 gpd~~

DESIGN	NOTE: INSPECTION RESULTS
Water supply, existing: (describe) WELL **To be installed:** class N/A cased _____ grouted _____	**Water supply location:** Satisfactory yes ☐ no ☐ comments G. W. 2 Received: yes ☐ no ☐ not applicable ☐
Building sewer: EXISTING I.D. PVC 40, or equivalent. Slope 1.25" per 10' (minimum). ☑ Other Ferneo sch 40 pvc (4") to exist Bldg sewer	**Building sewer:** yes ☒ no ☐ comments Satisfactory SCH 40 Ferneo coupling to terra cotta sewer
Septic tank: Capacity 900 gals. (minimum). ☒ Other No Garbage Disposal	**Pretreatment unit:** yes ☒ no ☐ comments Satisfactory Tapp 1125XR C/O at inlet
Inlet-outlet structure: 8" in 18" out PVC 40, 4" tees or equivalent. ☒ Other Stub Ts 1" Below Lids	**Inlet-outlet structure:** yes ☒ no ☐ comments Satisfactory good gauge 41" 43½"
Pump and pump station: No ☑ Yes ☐ describe and show design. if yes: _____	**Pump & pump station:** yes ☐ no ☐ comments Satisfactory N/A
Gravity mains: 6" or larger I.D., minimum 6" fall per 100', 1500 lb. crush strength or equivalent. ☒ Other Sch 40 required	**Conveyance method:** yes ☒ no ☐ comments Satisfactory SCH 40.
Distribution box: Precast concrete with 6 ports. ☒ Other Bedded on 4" concrete pad	**Distribution box:** yes ☒ no ☐ comments Satisfactory dial-a-flow, hydraulic cement bedded on concrete pad
Header lines: Material: 4" I.D. 1500 lb. crush strength plastic or equivalent from distribution box to 2' into absorption trench. Slope 2" minimum. ☐ Other _____	**Header lines:** yes ☒ no ☐ comments Satisfactory SCH 40 !
Percolation lines: Gravity 4" plastic 1000 lb. per foot bearing load or equivalent, slope 2" 4" (min. max.) per 100'. ☒ Other covered w/ untreated paper	**Percolation lines:** yes ☒ no ☐ comments Satisfactory paper over
Absorption trenches: Square ft. required 1000: depth from ground surface to bottom of trench 30"; aggregate size 1" to 1½"; Trench bottom slope 2 to 4" per 100'; center to center spacing 7'; trench width 2'; Depth of aggregate 13"+; Trench length 100'; Number of trenches 5	**Absorption trenches:** yes ☒ no ☐ comments Satisfactory Depth good / soil good Date 4-13-93 Inspected and approved by: _____ + TB Sanitarian

C.H.S. 202A Revised 6/84

S. 82/53

NICE DF !

Health Department
Identification Number SD-93-141

Schematic drawing of sewage disposal system and topographic features. PAGE 2 OF 2

Show the lot lines of the building lot and building site, sketch of property showing any topographic features which may impact on the design of the system, all existing and/or proposed structures including sewage disposal systems and wells within 100 feet of sewage disposal system and reserve area. The schematic drawing of the sewage disposal system shall show sewer lines, pretreatment unit, pump station, conveyance system, and subsurface soil absorption system, reserve area, etc. When a nonpublic drinking water supply is to be located on the same lot show all sources of pollution within 100 feet.

Septic [redacted] Expansion Only & Lees Crossing -

☒ The information required above has been drawn on the attached copy of the sketch submitted with the application. Attach additional sheets as necessary to illustrate the design.



* Drawing not to scale.
* Permit void if building location interferes with approved drainfield location.
* Designed for basement plumbing? YES NO
* Drainfield to be 100+' from Class IIIC wells and 50' from all Class IIIA&B wells.
* Install 5 - 100' lines, ON CONTOUR, in 2'-wide trenches, on 7' centers.
* Install trenches 30" deep.
* Smooth-walled header pipes recommended.
* Extend header pipes 24" into gravel.
* Use single size gravel 0.5" to 1.5" diam.
* No parking or driving on drainfield system
* Divert roof drains away from drainfield.
* No trees within 10' of system.
* Pump septic tank every 3 - 5 years.

~~WELL REQUIREMENTS~~
~~* Install Class ___ well ___'+ away from drainfield, reserve, treated foundation, and all sources of contamination.~~
~~* All well grouts to be witnessed by environmental health specialist.~~
~~* Water to be tested for potability.~~

*See plat for reserve

The sewage disposal system is to be constructed as specified by the permit ☒ or attached plans and specifications ☐.

This sewage disposal system construction permit is null and void if (a) conditions are changed from those shown on the application (b) conditions are changed from those shown on the construction permit.

No part of any installation shall be covered or used until inspected, corrections made if necessary, and approved, by the local health department or unless expressly authorized by the local health dept. Any part of any installation which has been covered prior to approval shall be uncovered, if necessary, upon the direction of the Department.

Date: 4/7/93 Issued by: [redacted] EHS
Sanitarian

Date: 4/7/93 Reviewed by: John R. Sargent
Supervisory Sanitarian

This Construction Permit Valid until 4/7/94

If FHA or VA financing

Reviewed by Date _____ _____ Date _____ _____
Supervisory Sanitarian Regional Sanitarian

C.H.S. 202B Revised 6/84

ORIGINAL



County of Fauquier
Operations-Services
223 W. Shirley Ave suite 15
Warrenton, VA 22186
Phone 347-6820 FAX: 341-0364

CUSTODIAL SYSTEM TOTALS REPORT
07/01/95 thru 06/14/96

System Name	Total Cost
FAUQUIER COUNTY SCHOOLS	88,507.75
FAUQUIER COUNTY	7,385.16
	95,892.91

Completion Statement

Commonwealth of Virginia
State Department of Health

Health Department Identification Number SD 93-143

Fauquier Co. Health Department

Name of Company/Corporation/Individual: Jim Eicher

Address: Rt 1 Box 307 Bealeton, VA. Telephone: 347-2274

Owner's Name B. Sowder / trustee

Owner's Address Rt 3, Box 1320, Gainesville, VA

Location of Installation: Lot _____ Block _____

Section: 82/53 Lots 37+38 Subdivision: Corral Farm / Lee's Crossing

Other: _____

I hereby certify that the onsite sewage disposal system has been installed and completed in accordance with the construction permit issued (date) 4-7-93 and is in compliance with Part D of the Sewage Handling and Disposal Regulations and when appropriate the plans and specifications for the project.

4-13-93
Date

James L Eicher
Signature and Title

C.H.S. 203 Rev. 4/83

Soil Evaluation Form

Commonwealth of Virginia
Department of Health

Health Department
Identification Number SD 93 141
Tax Map Number subd

General Information

Date 4/6/93 Fauquier Co. Health Department

Applicant _____ Telephone No. _____

Address _____

Owner _____ Address _____

Location _____

Subdivision Subd - Lee's Crossing Block/Section II Lot _____

Soil Information Summary

1. Position in landscape satisfactory Yes ☒ No ☐ Describe sideslope (southern)

2. Slope 12-14 %

3. Depth to rock/impervious strata Max. _____ Min. _____ None X

4. Depth to seasonal water table (gray mottling or gray color) No ☒ Yes ☐ _____ inches

5. Free water present No ☒ Yes ☐ _____ range in inches

6. Soil percolation rate estimated Yes ☒ Texture group I II (III) IV
No ☐ Estimated rate 60 min/inch

7. Percolation test performed Yes ☐ Number of percolation test holes _____
No ☒ Depth of percolation test holes _____
Average percolation rate _____

Name and title of evaluator: C A Jackson JR EHS 05194

Signature: C A Jackson

Department Use

☒ Site Approved: Drainfield to be placed at 30" depth at site designated on permit.

☐ Site Disapproved:

Reasons for rejection:

1. ☐ Position in landscape subject to flooding or periodic saturation.
2. ☐ Insufficient depth of suitable soil over hard rock.
3. ☐ Insufficient depth of suitable soil to seasonal water table.
4. ☐ Rates of absorption too slow.
5. ☐ Insufficient area of acceptable soil for required drainfield, and/or Reserve Area.
6. ☐ Proposed system too close to well.
7. ☐ Other Specify _____

79" - 83"
88½" - 94"
102" - 107"
115" - 120"

78" - 81"

Date of Evaluation 4/6/93

Profile Description
SOIL EVALUATION REPORT

Health Department Identification No. SD 93 141

Page 2 of 2

Where the local health department conducts the soil evaluation the location of profile holes may be shown on the schematic drawing on the construction permit or the sketch submitted with the application. If soil evaluations are conducted by a private soil scientist, location of profile holes and sketch of the area investigated including all structural features i.e., sewage disposal systems, wells, etc., within 100 feet of site (See section 4) and reserve site shall be shown on the reverse side of this page or prepared on a separate page and attached to this form.

☐ See application sketch ☒ See construction permit ☐ See sketch on reverse side or page attached to this form.

Hole #	Horizon	Depth (Inches)	Description of, color, texture, etc.	Texture Group
1	A	0-6	5YR 3/4 Dk RBr L (old Plow Layer)	II
	B	6-40	5YR 4/4 RBr SiL/L	II
	C	40-48	5YR 4/6 4R SiL/L w/ some MN Dep at 42" + Plow 2.5YR 3/6 Dk R mottling	II
2	A	0-6	5YR 3/4 Dk R Br L (old plow layer	II
	B	6-48	5YR 4/6 4R SiL/L	II
3	A	0-4	5YR 3/4 Dk R Br SiL	IIC
	B	4-30	5YR 4/4 RBr SiL/L	II
	C	30-52	5YR 4/6 4R SiL/L w/ Mn Dep at 44"+ 2.5YR 3/6 Dk R mottling throart	III

Remarks Not to scale

TB 30"

Application for a Sewage Disposal System Construction Permit

Commonwealth of Virginia
Department of Health

For Department Use Only

Health Department Identification Number SD-93-141
Map Reference Auld.

Prince Wm. Co. Health Department ROM491

Date Received 4-6-93

To Be Completed By The Applicant

Type sewage system: ☐ New ☐ Repair ☒ Expanded ☐ Conditional
FHA/VA yes ☐ no ☐

Owner R.G. Sowden Trustee Address RT 3, Box 1320 Phone 347-1097
Gainesville VA 22065

Agent Same Address — Phone —

Directions to Property 29 S. right on College road go straight Back to Dumpster, take right Driveway to White house, site on right of house.

Subdivision Conrad Farm Section — Block — Lot —

Other Property Identification Lees Crning — 82/53

Dimensions/size of Lot/Property 2.35 acres (old lots 37 and 38)

Other Application Information

I. **Building/facility** ☐ New ☑ Existing
Intermittent Use ☐ Yes ☐ No If yes, describe: Old system, need new lines and Distribution system

II. **Residential Use** ☑ Yes ☐ No
Termite Treatment ☐ Yes ☐ No
☑ Single Family ☐ Multifamily Number of Units 0 Number of Bedrooms 2
Basement ☑ Yes ☐ No
Fixtures in Basement ☑ Yes ☐ No

III. **Commercial Use** ☐ Yes ☑ No Describe: Farm vendors and Johnson College.

Commercial/Wastewater ☐ Yes ☑ No Number of Patrons — Number of Employees —
If yes, give volumes and describe —

IV. **Water Supply:** ☐ Public ☐ New Describe: Well
☑ Private ☑ Existing

V. **Proposed Installation:** ☐ Septic tank and drainfield ☑ Other repair
If other, describe add new lines and Distribution Box possibly another Tank

SITE PLAN Attach a site plan (rough sketch) showing dimensions of property, proposed and/or existing structures and driveways, underground utilities, adjacent soil absorption systems, bodies of water, drainage ways, and wells and springs within 200 feet radius of the center of the proposed building or drainfield. Distances may be paced or estimated.

The property lines and building location are clearly marked and the property is sufficiently visible to see the topography. I give permission to the Department to enter onto the property described for the purpose of processing this application.

R G Sowden
Signature of owner/agent

4/6/93
Date

OSD93141

C.H.S. 200 Revised 4/83

ROUTE SHEET

PERMIT I.D. NO. SD-93-141

Tag Sheet

	Initials	Date
APPLICATION RECEIVED:	PCW	4-6-93
APPLICATION REVIEWED:	PCW	4-6-93
FEE DETERMINATION:	PCW	4-6-93
ASSIGNED TO:	CAS	4-6-93
SITE VISIT SCHEDULED:	CAS	4/6/93
SITE VISIT MADE:	CAS	4/6/93
FOLLOW-UP VISIT:		
ISSUE/DENY DRAFTED:	CAS	4/7/93
ISSUE/DENY REVIEWED:	JKL	4/7/93
ISSUE/DENY COUNTERSIGNED:	JKL	4/7/93
ISSUE/DENY - MAILED/PICKED UP	CAS	4/8/93

6-25-1991



911 Address

Solid Waste
6438

6438
College STREET

Water Supply and/or Sewage Disposal System Construction Permit

Commonwealth of Virginia
Department of Health
FAUQUIER CO. Health Department

Health Department
Identification Number SD-96-513
Map Reference 6984-23-9484

General Information

Water Supply System: New ✓ Repair ___ Public ___ FHA ___ VA ___ Case No. ___
Sewage Disposal System: New ✓ Repair ___ Expanded ___ Conditional ___ Public ___
Based on the application for a sewage disposal system construction permit filed in accordance with Section 2.13 E, of the Sewage Handling and Disposal Regulations and/or Section 2.13 of the Private Well Regulations a construction permit is hereby issued to:
Owner FAUQ. DEPT. SOLID WASTE MANAGEMENT Telephone 347-6812
Address 78 W. LEE ST. WARRENTON, VA. For a Type I Sewage Disposal System or Well to be constructed on/at Corrall Farm Landfill
Subdivision CORRALL FARM LANDFILL Section/Block ___ Lot 6984-23-9484 Actual or estimated water use 150 gpd / 1BR equiv.

DESIGN	NOTE: SEWAGE DISPOSAL SYSTEM INSPECTION RESULTS
Water supply, existing: (describe) N/A spout to be witnessed By HD This will be a non-potable **To be installed:** class 3B water supply. Appropriate cased 50 mm grouted 50 mm	**Water supply location:** Satisfactory yes ☐ no ☐ comments Completion Report G. W. 2 Received: yes ☐ no ☐ not applicable ☐
Building sewer: c/o FNDT 4" I.D. PVC Schedule 40, or equivalent. Slope 1.25" per 10' (minimum). ☒ Other Smooth pipe to DB	**Building sewer:** yes ☑ no ☐ comments Satisfactory Schedule 40
Septic tank: Capacity 750 gals. (minimum). ☐ Other No garbage Disposals	**Pretreatment unit:** yes ☑ no ☐ comments Satisfactory Tenn 1050 - less than 18" from surface
Inlet-outlet structure: 8" in 18" out PVC Schedule 40, 4" tees or equivalent ☒ Other Stub T's 1" Below Lids	**Inlet-outlet structure:** yes ☑ no ☐ comments Satisfactory In 8' 6" Out 8' 8"
Pump and pump station: No ☒ Yes ☐ describe and show design. if yes: ___	**Pump & pump station:** yes ☐ no ☑ comments Satisfactory
Gravity mains: 4" or larger I.D., minimum 6" fall per 100', 1500 lb. crush strength or equivalent. ☐ Other ___	**Conveyance method:** yes ☑ no ☐ comments Satisfactory Schedule 40
Distribution box: Precast concrete with 6+ ports. ☒ Other Bed w/ virgin earth	**Distribution box:** yes ☐ no ☐ comments Satisfactory 4 extra ports
Header lines: Material: 4" I.D. 1500 lb. crush strength plastic or equivalent from distribution box to 2' into absorption trench. Slope 2" minimum. ☐ Other ___	**Header lines:** yes ☑ no ☐ comments Satisfactory
Percolation lines: Gravity 4" plastic 1000 lb. per foot bearing load or equivalent, slope 2" 4" (min. max.) per 100'. ☒ Other cover w/ approved material	**Percolation lines:** yes ☑ no ☐ comments Satisfactory 10.85 / 10.95 / 10.85 / 10.85 / 10.8 11.05 / 11.15 / 11.04 / 11.18 / 11.12
Absorption trenches: Square ft. required 650 ; depth from ground surface to bottom of trench 45" ; aggregate size 1/2 to 1 1/2 SSA Trench bottom slope 2-4" per 100' ; center to center spacing 6' ; trench width 2' Depth of aggregate 13+" ; Trench length 65 ; Number of trenches 5	**Absorption trenches:** yes ☑ no ☐ comments Satisfactory liner fabric Date 1/31/97 Inspected and approved by: Helen Ralston Sanitarian

C.H.S 202A

09D4-73-9484

Health Department
Identification Number SD-96-513

Schematic drawing of sewage disposal and/or water supply system and topographic features.

Show the lot lines of the building site, sketch of property showing any topographic features which may impact on the design of the well or sewage disposal system, including existing and/or proposed structures and sewage disposal systems and wells within 200 feet. The schematic drawing of the well site or area and/or sewage disposal system shall show sewer lines, pretreatment unit, pump station, conveyance system, and subsurface soil absorption system, reserve area, etc. When a nonpublic drinking water supply is to be permitted, show all sources of pollution within 200 feet.

☒ The information required above has been drawn on the attached copy of the sketch submitted with the application. Attach additional sheets as necessary to illustrate the design.

PIN 6984-23-9484
prop 1 BR equivalent 1,150 gp
Warrenton Service District (100% Reser



SEWAGE PERMIT REQUIREMENTS

* Drawing not to scale.
* Permit void if building location interfers with approved drainfield location.
* Designed for basement plumbing YES (NO)
* Drainfield to be 100+ feet from all Class IIIA&B wells,
* Install 5 -65 feet lines, ON CONTOUR, in 2 feet-wide trenches on 6 feet centers.
* Trench bottoms installed 45" inches deep.
* Smooth-walled header pipes recommended.
* Extend header pipes 24 inches into gravel.
* Use single size gravel 0.5 to 1.5 inch diameter.
* No parking or driving on drainfield system.
* No trees within 10 feet of system.
* Pump septic tank and distribution box every 3 - 5 years.
* NO WET WEATHER CONSTRUCTION

Note: well location sited by private engineer, not Health Dept.

WELL REQUIREMENTS

* Install Class 3B well 50 + feet away from drainfield, reserve, treated foundation and all sources of contamination.
* All well grouts to be witnessed by environmental health specialist.
* Water to be tested for potability.

Power Easement

THE SYSTEM TO BE INSTALLED BY THE AUTHORITY OF THIS PERMIT MUST CONFORM TO THE FAUQUIER COUNTY SANITATION AND/OR WELL ORDINANCES

Note: No additional lots allowed in Df area

This sewage disposal system and/or water supply is to be constructed as specified by the permit ✓ or attached plans and specifications ____.

pond.

This sewage disposal system and/or well construction permit is null and void if (a) conditions are changed from those shown on the application (b) conditions are changed from those shown on the construction permit.

dam of pond.

No part of any installation shall be covered or used until inspected, corrections made if necessary, and approved, by the local health department or unless expressly authorized by the local health dept. Any part of any installation which has been covered prior to approval shall be uncovered, if necessary, upon the direction of the Department.

Class IIIB well

Date: 1/17/97 **Issued by:** drilled. ~~Sanitarian~~ EHS-RIA

Date: 1/17/97 **Reviewed by:** John L. Sargent
Supervisory Sanitarian

This Construction Permit Valid until 1/17/98

If FHA or VA financing

Reviewed by Date _____ _____ **Date** _____ _____

Supervisory Sanitarian — Regional Sanitarian

C.H.S. 2028

COMMONWEALTH of VIRGINIA

IN COOPERATION WITH THE
STATE DEPARTMENT OF HEALTH

Fauquier County Health Department
ENVIRONMENTAL HEALTH
320 HOSPITAL DRIVE · SUITE 21
WARRENTON, VIRGINIA 22186

(703) 347-6363

SEWAGE DISPOSAL SYSTEM OPERATION PERMIT

Commonwealth of Virgnia
Department of Health

Health Department ID # SD-96-513
Fauquier County Environmental Health Department

PIN# 6984-23-9484

County of Fauquier Dept of Solid Waste Mgmt is hereby granted permission to operate a Type I Sewage Disposal System having a design capacity of 150 gpd. This permit is issued in accordance with the Provisions of 32.1, Chapter 6 of the Code of Virginia as amended and Section(s) 3.22 of the Virginia Sewage Handling and Disposal Regulations of the Virginia Department of Health and any variances or conditions granted issuance of and Operating Permit does not imply or guarantee that the Sewage Disposal will function for any specified period of time.

Variance granted
✓ None ___ See Attached

Special Conditions
✓ None ___ See Attached

8/21/97
Effective Date

HEALTH OFFICIAL

VDH VIRGINIA DEPARTMENT OF HEALTH
Protecting You and Your Environment

Completion Statement

Commonwealth of Virginia
State Department of Health

Health Department Identification Number SD-96-513

Fauquier Cont Health Department

Name of Company/Corporation/Individual: R.L. Rider

Address: #30 Marshall St Warrenton VA 20186 Telephone: 347-1611

Owner's Name Faug. Dept. Solid Waste Mgt.

Owner's Address 28 W Lee St Warrenton VA

Location of Installation: Lot _____ Block _____

Section: Corall Farm Landfill Subdivision: _____

Other: 6984-23-9484

I hereby certify that the onsite sewage disposal system has been installed and completed in accordance with the construction permit issued (date) 11/7/97 and is in compliance with Part D of the Sewage Handling and Disposal Regulations and when appropriate the plans and specifications for the project.

1/31/97
Date

James E. Lee Jr.
Signature and Title

C.H.S. 203 Rev. 4/83

Record of Inspection - Private Water Supply System

Commonwealth of Virginia
Department of Health

Health Department
I.D. Number SD-96-513

F.H.A. or V.A. Case Number
If Applicable

Date 1/17/97 Local Health Department Fauquier

Owner Fauq DEPT of Solid Waste Mgm Address _____ Phone _____

Exact Location of Premises _____

Subdivision _____ Section/Block _____ Lot _____

Class of nonpublic drinking water well. 1) Class III A ___
2) Class III B ✓
3) Class III C ___
4) Other ___

Date of installation 2/27/97

CONSTRUCTION INFORMATION

If information in any item below is secured from other sources (i.e. well log, etc.), so note.

1. Water well completion report filed as required by Sec. 2.18 Yes ☑ No ☐
2. Well Location: Distances from sources of pollution (See Table 3.1, Minimum Separation Distances) and Section 3.4 of the Private Well Regulations.
   Building Sewer 50+ Pretreatment Unit 50'+
   Conveyance System 80'+ Subsurface Soil Absorption System 80'+
   (nearest point). Property Line 10'+ Other landfill = 500'+
   Site graded where necessary to divert water away from well? Yes ☐ No ☐ N/A ☐
3. Construction, General: (see Section 3.6 and 3.7 Private Well Regulations).
   Total depth of well 235 feet. Type of casing steel
   Depth of casing 15 feet. Diameter of casing 6" inches.
   Casing extends inches above ground ~12". Exterior space sealed with neat cement grout to a depth of 30 feet. Screens constructed of —
   free of rough edges and irregularities, with positive watertight seal between screen and casing?
   Yes ☐ No ☐ N/A ☑ Well head and opening to the interior protected? Yes ☑ No ☐
   Type of well seal perm. Vented Pitless adapter used? Yes ☐ No ☐ N/A ☑
   Properly installed? Yes ☐ No ☐ N/A ☑ Proper venting? Yes ☑ No ☐ N/A ☐
4. Quantity: Yield and drawdown determined by continuous pumping of 2 hours. Drawdown 15 feet. Yield 25 GPM. Type of storage wellonly.
5. Quality: Sample tap provided at entry into system? Yes ☐ No ☐ Samples(s) collected? Yes ☐ No ☐ Results of samples. Satisfactory ☐ Unsatisfactory ☐ (attach copy of results of this form)

Based on the inspection of this water supply system and the information contained on the water well completion report attached, this water supply meets ☑ does not meet ☐ the requirements of the Private Well Regulations.

Remarks: Grout approved using neat cement grout. Well approved on construction only on basis of driller's GW-2. Layne Bailey Inc. - LH. 3/1/97.

Date 3/1/97 Signed _____ Sanitarian

Date 3/1/97 Signed _____ Supervisory Sanitarian

Date _____ Signed _____ Regional Sanitarian (If V.A. or F.H.A.)

C.H.S. 204 Revised 9/90

PROPOSED Septic DRAINFIELD		
A	12397.6136	10586.5121
B	12448.1897	10602.9207
C	12451.2932	10550.4539
D	12404.0255	10546.5536
LF#1	12445.4520	10547.3052
LF#2	12468.1234	10551.3740
LF#3	12422.3530	10617.3063

PROPOSED 100% Reserve DRAINFIELD		
E	12541.6692	10363.1460
F	12492.1112	10374.7653
G	12474.9762	10330.4128
H	12525.1473	10307.7891
LF#4	12507.9472	10368.5943
LF#5	12523.7243	10312.0004



1" = 100'

PROPOSED Septic DRAINFIELD		
A	12397.6136	10586.5121
B	12448.1887	10602.9207
C	12451.2932	10550.4538
D	12404.0255	10546.5336
LF#1	12446.4520	10547.3052
LF#2	12468.1234	10556.3740
LF#3	12422.3530	10617.3063

PROPOSED 100% Reserve DRAINFIELD		
E	12541.6602	10363.1460
F	12492.1112	10374.7653
G	12474.9762	10330.4128
H	12525.1473	10307.7291
LF#4	12507.9472	10368.5943
LF#5	12523.7243	10312.0004



1" = 100'

Health Department
Identification Number SD-96-513

matic drawing of sewage disposal and/or water supply system and topographic features.

Show the lot lines of the building site, sketch of property showing any topographic features which may impact on the design of the well or sewage disposal system, including existing and/or proposed structures and sewage disposal systems and wells within 200 feet. The schematic drawing of the well site or area and/or sewage disposal system shall show sewer lines, pretreatment unit, pump station, conveyance system, and subsurface soil absorption system, reserve area, etc. When a nonpublic drinking water supply is to be permitted, show all sources of pollution within 200 feet.

☒ The information required above has been drawn on the attached copy of the sketch submitted with the application.
Attach additional sheets as necessary to illustrate the design.

PIN 6984-23-9484
prop 1 BR equivalent 1,150 gpd
Warrenton Service District (100% Reserve)



Power Easement

THE SYSTEM TO BE INSTALLED BY THE AUTHORITY OF THIS PERMIT MUST CONFORM TO THE FAUQUIER COUNTY SANITATION AND/OR WELL ORDINANCES

SEWAGE PERMIT REQUIREMENTS

* Drawing not to scale.
* Permit void if building location interfers with approved drainfield location.
* Designed for basement plumbing YES (NO)
* Drainfield to be 100+ feet from all Class IIIA&B wells,
* Install 5 -65 feet lines, ON CONTOUR, in 2 feet-wide trenches on 6 feet centers.
* Trench bottoms installed 45" inches deep.
* Smooth-walled header pipes recommended.
* Extend header pipes 24 inches into gravel.
* Use single size gravel 0.5 to 1.5 inch diameter.
* No parking or driving on drainfield system.
* No trees within 10 feet of system.
* Pump septic tank and distribution box every 3 - 5 years.
* NO WET WEATHER CONSTRUCTION

Note: well location sited by private engineer, not Health Dept.

WELL REQUIREMENTS

* Install Class 3B well 50 + feet away from drainfield, reserve, treated foundation and all sources of contamination.
* All well grouts to be witnessed by environmental health specialist.
* Water to be tested for potability.

Note: No additional cuts allowed in Df area

This sewage disposal system and/or water supply is to be constructed as specified by the permit ✓ or attached plans and specifications ____.

This sewage disposal system and/or well construction permit is null and void if (a) conditions are changed from those shown on the application (b) conditions are changed from those shown on the construction permit.

No part of any installation shall be covered or used until inspected, corrections made if necessary, and approved, by the local health department or unless expressly authorized by the local health dept. Any part of any installation which has been covered prior to approval shall be uncovered, if necessary, upon the direction of the Department.

Date: 1/17/97 **Issued by:** Class IIIB well drilled. Sanitarian EHS-SRIA

Date: 1/17/97 **Reviewed by:** John K. Sargent Supervisory Sanitarian

This Construction Permit Valid until 1/17/98

If FHA or VA financing

Reviewed by Date _____ _____ **Date** _____ _____
Supervisory Sanitarian Regional Sanitarian

C.H.S. 2028

COMMONWEALTH of VIRGINIA

IN COOPERATION WITH THE
STATE DEPARTMENT OF HEALTH

Fauquier County Health Department
ENVIRONMENTAL HEALTH
320 HOSPITAL DRIVE - SUITE 21
WARRENTON, VIRGINIA 22186

(703) 347-6363

SEWAGE DISPOSAL SYSTEM OPERATION PERMIT

Commonwealth of Virgnia
Department of Health

Health Department ID # SD-96-513
Fauquier County Environmental Health Department

PIN# 6984-23-9484

Fauquier County Dept of Solid Waste mgmt is hereby granted permission to operate a Type I Sewage Disposal System having a design capacity of 150 gpd. This permit is issued in accordance with the Provisions of 32.1, Chapter 6 of the Code of Virginia as amended and Section(s) 3.22 of the Virginia Sewage Handling and Disposal Regulations of the Virginia Department of Health and any variances or conditions granted issuance of and Operating Permit does not imply or guarantee that the Sewage Disposal will function for any specified period of time.

Variance granted
✓ None ___ See Attached

Special Conditions
___ None ✓ See Attached

3/11/97
Effective Date

HEALTH OFFICIAL

Conditions

① Operation permit limited to 60 days from 3/11/97 to allow permit holder to secure monitoring well permits and data to be delivered to health department. Failure to deliver will void this OP and all activities connected with this permit must cease.

VDH VIRGINIA DEPARTMENT OF HEALTH
Protecting You and Your Environment

growth and development edging in our direction.

We look with pity and disappointment on the once lovely counties of Loudoun and Prince William, now far down the path to overgrowth, over-development and overpopulation.

Did anyone happen to read the front page story in *The Washington Post* a few weeks ago that focused on writers of this letter are "elitist no-growthers."

The question back is: "Why are we elitist just because we want to save our way of life?" We're not wealthy. We have full-time jobs — in Bethesda, Md. But that commute is worth the trip just to escape the might be stating that the County.

We've been where over-development takes you and we don't ever want to go there again.

Nancy Browning Premen
Andre J. Premen
Warrenton

Landfill concerns

Today we are crying for help. There isn't a day in our family's life that the landfill isn't staring us straight in the face. There is a 200-foot mountain of waste reaching into every aspect of our lives. Our water is polluted; we don't dare drink it. Our property has been inundated with landfill run-off, methane gas has invaded our home. The thought alone is enough to invoke fear.

The landfill has removed so many trees from behind our home that we can now count the number of methane vents that are present there. The methane levels alone at the landfill are cause for sheer terror. It is a fact that methane can migrate 2,000 feet from its source. It has already been in our home. Did anyone know that the methane probes on the west side of the landfill have shown levels at 50 times the explosive limit every month for the last 2 1/2 years? Now probes on the south side are active. The methane is rampant, always has been, always will be. And here we are, just feet away, possibly minutes away from a methane explosion.

The county constructed a pond 150 feet from our well that collects stormwater run-off from the landfill. This pond has levels of contaminants in it that would scare you. The water from this pond has been routed to flow directly through the middle of our property. The entire topography of the land behind us has been changed, making our property an extension of the landfill.

Perhaps no one is aware that the landfill has operated in blatant violation of its permit for over a year. In December 1995, the landfill submitted a proposal to the Virginia Department of Environmental Quality to amend its permit. This permit amendment proposed changes in the way the landfill would monitor the groundwater for pollutants. By state law, these changes are not to be placed in effect without approval or consent from the director of DEQ. Yet, without approval or consent, two wells have ceased to have the water from them tested for over a year. These two wells are highly polluted and located directly behind our home. The water that is supposed to be tested from these wells is the same water that flows into our well. Also without DEQ approval or consent, the landfill constructed two new wells, 300 feet down from the old ones and completely off the permitted landfill area. These new wells are fully operational and are being tested in place of the two polluted, permitted wells.

Any changes in the permitted groundwater monitoring system constitutes a major permit amendment, and according to state law, the landfill cannot make any major permit amendments without DEQ approval or consent. Also, the landfill is required to inform the citizens of its proposals within 14 days of submission to DEQ by way of publication in a local paper and a public hearing. This has not been done and the landfill continues to operate in direct violation of its permit, the state law, and without regard to us.

Not once have we received as much as a phone call from our supervisors to check on our concerns or well-being. They know we are here. They have not made any effort to inspect our property, which has been destroyed by landfill run-off. They have never bothered to ask us about the pollution in our water, knowing we live downhill from the landfill and the water from the landfill flows into our well. They have not even inquired whether or not our two small children are well. Not once did any of them call when the evacuation from methane was ordered by the county's hazardous materials response team. We are out here in harm's way and our board of supervisors could care less.

Today we are crying because we are left to live next to a landfill where the county government does everything it can to promote the landfill's longevity, prosperity and security. The things we thought it was supposed to work toward for its citizens.

Bruce W. Casner
Sonya L. Sanchez
Warrenton

Sewer and money

I was at the House of Delegates subcommittee hearing Feb. 10 when attorney Ben Jones, who works for the developers of Waterfield, testified for the board of supervisors and the Fauquier County Water and Sanitation Authority against Sen. Edd Houck's (D-Spotsylvania) bill.

Mr. Jones told the legislators that he was putting his money where his mouth is: "I own a place where I hope to retire to down in Lancaster County, down on the Rappahannock River. And I own a stream, and the stuff that comes down the river comes right up to my house, my front yard. And I crab there and I eat the oysters from there, so I'm, I'm not worried about this. I know there's not — there's nothing wrong with interbasin transfer and there's nothing wrong with standards that the Water Control Board uses."

Mr. Jones is presently in Fauquier County and will make the money from this county and its citizens to retire to the house of his dreams somewhere else. Fauquier and its citizens, who would like to spend the rest of their lives here, are left to pay for the disasters he helps to create.

Is he putting his money or Fauquier County taxpayers money where his mouth is?

Denise R. Williams
Warrenton

Tim Bridges
3/3/97
9:50 AM

Requested apps + all pertinent info.

Completion Statement

Commonwealth of Virginia
State Department of Health

Health Department Identification Number SD-96-573

Fauquier Co't Health Department

Name of Company/Corporation/Individual: R L [redacted] R. Lee

Address: #30 Marshall St Warrenton VA 20186 Telephone: 347-1611

Owner's Name Faug Dept Solid Waste Mgt.

Owner's Address 78 W Lee St Warrenton VA

Location of Installation: Lot _____ Block _____

Section: Corral Farm Landfill Subdivision: _____

Other: 6984-23-9484

I hereby certify that the onsite sewage disposal system has been installed and completed in accordance with the construction permit issued (date) 1/17/97 and is in compliance with Part D of the Sewage Handling and Disposal Regulations and when appropriate the plans and specifications for the project.

1/31/97
Date

James E. Lee Jr.
Signature and Title

C.H.S. 203 Rev. 4/83

Commonwealth of Virginia
Application for a Sewage Disposal and/or Water Supply Permit

Health Department ID SD-96-513

To Be Completed By The Applicant

Type of sewage system: ___ New ___ Repair ___ Expanded ___ Conditional
FHA/VA yes ___ no ___ Case No ___

Owner Fauq. Co. Dept. of Solid Waste Management Address 78 W Lee St. Warrenton, Va. Phone (347-6812

Agent ___ Address ___ Phone ___

Directions of Property 295 (L) LFCC/GCC entrance to landfill bldg

Subdivision Corral Farm Landfill Section ___ Block — Lot —

Other Property Identification ___

Dimension/size of Lot/Property 6984-23-9484

Other Application Information

I. Building/facility ✓ New ___ Existing
Intermittent Use ___ Yes ✓ No If yes, describe ___

II. Residential Use ___ Yes ✓ No Equip Shed
Termite Treatment ___ Yes ✓ No
___ Single Family (Number of Bedrooms ___) ___ Multi-family (Number of Units ___)

Basement ___ Yes ✓ No
Fixtures in Basement ___ Yes ✓ No

III. Commerical Use ___ Yes ___ No Describe: ___

Commerical/Wastewater ___ Yes ___ No Number of Patrons ___
Number of Employees ___

If yes, give volumes and describe ___

IV. Water Supply: ___ Public ___ New ___ Existing
✓ Private ✓ New ___ Existing
Describe: Private

V. Proposed Sewage Disposal Method:
Onsite Sewage Disposal System: ✓ Septic Tank Drainfield ___ LPD ___ Mound ___ Other

Public Sewerage System

Attach a site plan (rough sketch) showing dimensions of property, proposed and/or existing structures and driveways, underground utilities, adjacent soil absorption system, bodies of water, drainage ways, and wells and springs within 200 feet radius of the center of the proposed well or drainfield. Distances may be paced or estimated.

The property lines and building location are clearly marked and the property is sufficiently visible to see the topography.
I give permission to the Department to enter onto the property described for the purpose of processing this application.

[signature] 9/25/96
Signature of Owner/Agent Date

CHS 200

SD96513

6984-23-9484

COMMONWEALTH OF VIRGINIA
Department of Health

Z100231

PCMS Pt. # _____

Fauquier Co. Health Department Date: 9-25-96

Received of: Faug. Co. Dept of Solid Waste

Two hundred-Ninety Dollars 00/100 Dollars $ 290.00 CASH ☐ C

For: Septic + Well Permit Local Use: _____ CHECK ☑ # 046449

Services Given For: Carroll Farm Landfill MONEY ORDER ☐

Received By: J. Brown

Codes	Amt.	Codes	Amt.
_____	$ _____	02116	$ 10.00
_____	$ _____	02119	$ 40.00
02116	$ 65.00	02345	$ 175.00

ADM-1304 REV. 10/91

County of Fauquier

Department of Solid Waste Management

Ellis D. Bingham
Solid Waste Manager

Benji Brackman
Recycling Coordinator
(703) 347-6830

78 W. Lee Street (Suite 100)
Warrenton, Virginia 22186
(703) 347-6810
Fax: (703) 341-7129

Jill Genco
Accounting

Lori Shremshock
Support Services

September 11, 1996

SPECIAL CHECK REQUEST

DATE: September 11, 1996

DEPARTMENT: Solid Waste Management

PAYEE: Commonwealth of Virginia, Department of Health

AMOUNT: $290.00

CHARGE CODE: 4-513-42710-6055 (Permitting Fees)

PURPOSE: (Please list why a special check is needed versus the next available A/P Bill Run)

Drainfield permit renewall.

Permit is needed ASAP to continue construction of operations building and recycling building at new landfill.

SEND THE CHECK TO:
NAME & ADDRESS:

Call Jill (x 6813). Department of Solid Waste Management will pick up to mail with required forms.

(Original Invoice Must Accompany This Request)

V22056
912968

Director, Solid Waste Managment

GENERAL SERVICES DEPT.
RECEIVED
OCT 0 1993

Sewage Disposal System Construction Permit

PAGE 1 OF 2

Commonwealth of Virginia
Department of Health
Fauquier Co Env. Health Department

Health Department Identification Number SD-93-655
Map Reference 9ubd

General Information

New ☒ Repair ☐ Expanded ☐ Conditional ☐ FHA ☐ VA ☐ Case No. _____

Based on the application for a sewage disposal system construction permit filed in accordance with Section 3.13.01, a construction permit is hereby issued to:

Owner Fauquier County Solid Waste Telephone (703)347-6800
Address 78 W Lee St. Ste 100, Warrenton VA 22186
For a Type I Sewage disposal system which is to be constructed on/at 295 @ LFCC/gcc entrance to landfill Bldg.
Subdivision Carroll Farm Landfill Bldg. Section/Block _____ Lot _____
Actual or estimated water use 150gpd 1BR EQUIVALENT

DESIGN	NOTE: INSPECTION RESULTS
Water supply, existing: (describe) N/A signs must be posted at all spigots stating Non-Potable **To be installed:** class III B Non Potable, grout to be witnessed by HD cased 50' min to Rock grouted 50' min to Rock	**Water supply location:** Satisfactory yes ☐ no ☐ comments G. W. 2 Received: yes ☐ no ☐ not applicable ☐
Building sewer: Install c/o at Endt. 4" I.D. PVC 40, or equivalent. Slope 1.25" per 10' (minimum). ☐ Other smooth pipe to DB	**Building sewer:** yes ☐ no ☐ comments Satisfactory
Septic tank: Capacity 1000 gals. (minimum). ☒ Other No garbage Disposals	**Pretreatment unit:** yes ☐ no ☐ comments Satisfactory
Inlet-outlet structure: 8" in 18" out PVC 40, 4" tees or equivalent. ☒ Other Stub T's 1" Relay Lids	**Inlet-outlet structure:** yes ☐ no ☐ comments Satisfactory
Pump and pump station: No ☒ Yes ☐ describe and show design. If yes: _____	**Pump & pump station:** yes ☐ no ☐ comments Satisfactory
Gravity mains: 4" or larger I.D., minimum 6" fall per 100', 1500 lb/ crush strength or equivalent. ☐ Other _____	**Conveyance method:** yes ☐ no ☐ comments Satisfactory
Distribution box: Precast concrete with 5± ports. ☒ Other Bed on 4" concrete PAD	**Distribution box:** yes ☐ no ☐ comments Satisfactory
Header lines: Material: 4" I.D. 1500 lb. crush strength plastic or equivalent from distribution box to 2' into absorption trench. Slope 2" minimum. ☐ Other _____	**Header lines:** yes ☐ no ☐ comments Satisfactory
Percolation lines: Gravity 4" plastic 1000 lb. per foot bearing load or equivalent, slope 2" 4" (min. max.) per 100'. ☐ Other _____	**Percolation lines:** yes ☐ no ☐ comments Satisfactory
Absorption trenches: Square ft. required 672 : depth from ground surface to bottom of trench 48" ; aggregate size 1½ to 1½: Trench bottom slope 2-4" per 100' ; center to center spacing 9' ; trench width 3 Depth of aggregate 13+" ; Trench length 56 ; Number of trenches 4	**Absorption trenches:** yes ☐ no ☐ comments Satisfactory
	Date 10 SD 93 Inspected and approved by: _____ Sanitarian

C.H.S. 202A Revised 6/84

Health Department Identification Number SD-93-65

Schematic drawing of sewage disposal system and topographic features. PAGE 2 OF 2

Show the lot lines of the building lot and building site, sketch of property showing any topographic features which may impact on the design of the system, all existing and/or proposed structures including sewage disposal systems and wells within 100 feet of sewage disposal system and reserve area. The schematic drawing of the sewage disposal system shall show sewer lines, pretreatment unit, pump station, conveyance system, and subsurface soil absorption system, reserve area, etc. When a nonpublic drinking water supply is to be located on the same lot show all sources of pollution within 100 feet.

1BR EQUIV, 150gpd SEWAGE + NON-POTABLE WELL - CORRAL FARM LANDFILL

☒ The information required above has been drawn on the attached copy of the sketch submitted with the application. Attach additional sheets as necessary to illustrate the design.

SEWAGE SYSTEM IS FOR EQUIPMENT WASH-DOWN AND RESTROOM FACILITIES ONLY. WATERLESS HAND-CLEANERS AND BOTTLED DRINKING WATER REQUIRED.

LANDFILL CELLS

THE SYSTEM TO BE INSTALLED BY THE AUTHORITY OF THIS PERMIT MUST CONFORM TO THE FAUQUIER COUNTY SANITATION AND/OR WELL ORDINANCES.



SEWAGE PERMIT REQUIREMENTS

* Drawing not to scale
* Permit void if building location interferes with approved drainfield location
* Designed for basement plumbing? YES NO
* Drainfield to be 100+' from Class I/II wells and 50' from all Class III/IV wells
* Install 4 56' lines, IN CONTOUR, in 3' wide trenches, on 9' centers.
* Install trenches 48" deep.
* Smooth-walled header pipes recommended.
* Extend header pipes 24" into gravel.
* Use single size gravel 0.5" to 1.5" dia.
* No parking or driving on drainfield system
* Divert roof drains away from drainfield.
* No trees within 10' of system.
* Pump septic tank every 2 - 5 years

WELL PERMIT REQUIREMENTS

* Install Class III-B well 50-feet + away from drainfield, reserve, treated foundation and all sources of contamination
* All well grouts to be witnessed by environmental health specialist
* [redacted]
* water is for equipment cleaning + toilet-flushing only.

The sewage disposal system is to be constructed as specified by the permit ☒ or attached plans and specifications ☐.

This sewage disposal system construction permit is null and void if (a) conditions are changed from those shown on the application (b) conditions are changed from those shown on the construction permit.

No part of any installation shall be covered or used until inspected, corrections made if necessary, and approved, by the local health department or unless expressly authorized by the local health dept. Any part of any installation which has been covered prior to approval shall be uncovered, if necessary, upon the direction of the Department.

Date: 12/7/93 Issued by: [signature] Sanitarian II

Date: 12/7/93 Reviewed by: [signature] Supervisory Sanitarian

This Construction Permit Valid until 12/3/94

If FHA or VA financing

Reviewed by Date _____ Supervisory Sanitarian Date _____ Regional Sanitarian

C.H.S. 202B Revised 6/84

II-2A

FILE COPY


376
752
8
50 | 376
400
7x6=42+3=45
50'
Row
50'
50'
15'
4L

Soil Evalution Form

Commonwealth of Virginia
Department of Health

Health Department Identification Number
Tax Map Number Land Fill

General Information

Date # 11/1/96 Fauquier County Health Department

Applicant Fauquier County Board of Supervisors Telephone No. (703) 347-8660

Address 40 Culpeper Street, Warrenton, VA 22186

Owner same Address

Location

Subdivison N/A Block/Section Lot

Soil Information Summary

1. Position in landscape satisfactory Yes [X] No [ ] Describe Man-made Ridgetop (profiles 1.2.3) and Sideslope (profiles 4.5)
2. Slope Original-3%; Reserve-8%
3. Depth to rock/impervious strata Max >60" Min. ____ None ____
4. Depth to seasonal water table (gray mottling or gray color) No [X] Yes [ ]
5. Free Water present No [X] Yes [ ] ____ range in inches
6. Soil percolation rate estimated Yes [X] Texture group I II (III) IV
   No [ ] Estimated rate 45 min/inch
7. Percolation test performed Yes [ ] Number of percolation test holes ____
   No [X] Depth of percolation test holes ____
   Average percolation rate ____

Name and title of evaluator: Danny R. Hatch VCPSS: Fauquier County Soil Scientist + C A Jackson Jr EHS-SR IA

Signature: Danny R Hatch

Department Use

[✓] Site Approved: Drainfield to be placed at 45" depth at site designated on permit.

[ ] Site Disaproved:

Reasons for rejection:

1. [ ] Position in landscape subject to flooding or periodic saturation.
2. [ ] Insufficient depth of suitable soil over hard rock.
3. [ ] Insufficient depth of suitable soil to seasonal water table.
4. [ ] Rates of absorption too slow.
5. [ ] Insufficient area of acceptable soil for required drainfield, and/or Reserve Area.
6. [ ] Proposed system too close to well.
7. [ ] Other Specify

Date of Evaluation 10/30/96

Health Department Identification No. _____

Profile Description

SOIL EVALUATION REPORT

Where the local health department conducts the soil evaluation the location of profile holes may be shown on the schematic drawing on the construction permit or the sketch submitted with the application. If soil evaluations are conducted by a private soil scientist, locations of profile holes and sketch of the area investigated including all structural features i.e., sewage disposal systems, wells, ect., within 100 feet of site (See section 4) and reserve site shall be shown on the reverse side of this page or prepared on a separate page and attached to this form.

☐ See application sketch ☐ See construction permit ☐ See sketch on reverse side or page attached to this form.

Hole #	Horizon	Depth (Inches)	Description of, color, texture, etc.	Texture Group
1	Fill	0-20		
	Bt	20-41	Red (10R4/6) silty clay loam+, moderate medium subangular blocky structure; friable; few faint clay films	III
	C	41-60	Red (2.5YR4/6) loam, structureless massive; friable	II
2	Ap	0-7	Brown to dark brown (7.5YR4/4) loam, compacted; firm	II
	Bt	7-22	Red (2.5YR4/6) silty clay loam, compacted; firm	III
	BC	22-33	Red (2.5YR4/6) loam+, weak medium subangular blocky structure; friable	II
	C	33-60	Red (2.5YR4/8) loam with common medium distinct brownish yellow (10YR6/8) mottles, structureless massive; friable; few manganese stains	II
3	Bt	0-14	Red (2.5YR4/6) silty clay loam+, compacted; firm; common manganese stains	III
	C	14-60	Strong brown (7.5YR5/6) loam with few coarse prominent red (10R4/6) mottles, structureless massive; friable; common manganese stains	II
4	A	0-5	Reddish brown (5YR4/4) silt loam; friable	II
	Bt	5-30	Red (2.5YR4/8) clay-, moderate medium subangular blocky structure; friable; few faint clay films	IV
	BC	30-40	Mottled red (2.5YR5/8) and reddish yellow (7.5YR6/8) clay loam, weak medium subangular blocky structure; friable; few manganese stains	III
	C	40-60	Mottled red (2.5YR5/8) and reddish yellow (7.5YR6/8) loam+, structureless massive; friable; few manganese stains	II
5	A	0-6	Reddish brown (5YR4/4) silt loam; friable	II
	Bt	6-30	Red (2.5YR4/8) clay, moderate medium subangular blocky structure; friable; few faint clay films	IV
	BC	30-42	Mottled red (2.5YR4/8) and brownish yellow (10YR6/8) clay loam; friable	III
	C	40-60	Mottled red (2.5YR5/8) and reddish yellow (7.5YR6/8) loam+, structureless massive; friable; few manganese stains	II

Remarks: Trench bottom should be 30" to 45" deep

Not to scale TB=45"

A - D
12404
12397
7

B - C
12451
12448
3

MORTON BUILDINGS, INC.
18478 Industrial Rd. • Culpeper, Virginia 22701-4114
540/825-3633
Fax: 540/825-3699

DEPARTMENT OF COMMUNITY DEVELOPMENT
ZONING OFFICE
40 CULPEPER STREET
WARRENTON, VA 22186
(540) 347-8674

RECEIVED
JAN 27 1997
FAUQUIER COUNTY
BUILDING

SUBJECT: 2500 Gallon Tank

Zoning Permit 40801NF Storage Building / Landfill Recycling
(Building Permit S96-05487)

Fauquier Board of Supervisors, Owner

Tank shown on plans should have been identified as a "pump and haul" tank.
See notation below clarifying location of installed tank.

Mike Martin Mgr.
Signature

1-28-97
Date

North ←



Excellence – Since 1903

6984-23-9484

1/3/17 As Built — Fauquier County Land Fill
Carroll Farm



AC = 64.5'
BC = 99'

AD = 51'
BD = 84.5'

Commonwealth of Virginia
Uniform Water Well Completion Report

Owner Riverr Coast Co. Inc
Address
Warrenton, Va. 20186
Phone
Location

Tax Map ID
VDH Permit SO-96-513
VWCB Permit
VWCB ID 6926239484
County Fauq -
Class III 13

* Well Data *

General Information
Drilling Method Rotary
Depth to Bedrock 63
Static Water Level 15
Well Disinfected (Y or N) Y

Date Completed 2/27/97
Yield 25 (GPM)
Stabilized Water Level
Disinfectant Used HTH

Total Depth of Well 235
Length of Test 2 hours
Natural Flow (Rate)
Amount Used 1 Ft.

Casing
From 0 to 75
Size 6 1/4 Material Steel
Weight/Schedule 13.188 Wall

From _____ to _____
Size _____ Material _____
Weight/Schedule _____

From _____ to _____
Size _____ Material _____
Weight/Schedule _____

Gravel Pack
From _____ to _____

From _____ to _____

From _____ to _____

Grout
From 0 to 50
Bore Hole Size 10"-0-75
Type
Method Cement pressure

From _____ to _____
Bore Hole Size 6.75-235
Type
Method

From _____ to _____
Bore Hole Size
Type
Method

Water Zones or Screened Intervals
From 80 to 92
Mesh Size _____ Diam. ___
From _____ to _____
Mesh Size _____ Diam. ___

From 130 to 133
Mesh Size _____ Diam. ___
From _____ to _____
Mesh Size _____ Diam. ___

From 218 to 220
Mesh Size _____ Diam. ___
From _____ to _____
Mesh Size _____ Diam. ___

* Use Data *

Private Well: Domestic _____ Agricultural _____ Industrial _____ Monitoring —
Public Well: Community _____ Non Community _____

Drillers Log
(Use additional sheets if necessary)

Depth	Description of Formation or Sediment	Remarks
0-63	Overburden	
63-235	Rock	

I certify that the information contained here is true and that this well was installed and constructed in accordance with the permit and further that the well complies with all applicable state and local regulations, ordinances and laws.

Drilling Contractor Layne Drilling Co. Inc.
Address P.O. Box 385 Remington, Va. 22734

Phone 439-3050

Drillers Signature [signature] Date 2/28/97
Representing Layne
Virginia Contractors License Number 020-358

COMMONWEALTH of VIRGINIA

IN COOPERATION WITH THE
STATE DEPARTMENT OF HEALTH

Fauquier County Health Department
ENVIRONMENTAL HEALTH
320 HOSPITAL DRIVE - SUITE 21
WARRENTON, VIRGINIA 22186

(703) 347-6363

March 27, 1997

Ms. Val Negley
County of Fauquier Building Office
40 Culpeper Street
Warrenton, Virginia 20186

RE: Potable Water Status of Well at Corrall Farm Landfill

Dear Ms. Negley:

This letter is written per your request for verification that the new well drilled at the above referenced landfill as described on SD96-513 was changed by this office from a non-potable well to a Class 3B potable water supply and that it meets all the criteria set forth in the Private Well Regulations. If this office can be of further assistance, please call (540) 347-6369.

Sincerely,

C.A. Jackson Jr.
EHS-Senior/A

Pin No. 6984-23-9484

Subd. _____

Old tax Map _____

TAG SHEET

NAME Dept of Waste Mgt.

Construction Permit ✓ Lot Certification _____
Remodeling _____ Repair _____

	INITIALS	DATE
Application Received	9/25/96	GB
Application Reviewed	9/25/96	GB
Fee Determination	9/25/96	GB
E.H.S. assigned to		
Site visit scheduled		
Site visit made	11/1/96	CDJ
Follow-up visit		
Issue/Deny Drafted	1/17/97	CDJ
Issue/Deny Reviewed	1/17/97	JMS
Issue/Deny Countersigned	1/17/97	DJB
Lot Cert placed in pending		
E.H.S. signing plat		
Lot Cert and/or permit picked up/mailed	1/17/97	PCT

FAUQUIER COUNTY SANITARY LANDFILL
FAUQUIER COUNTY, VIRGINIA

WELL COMPLETION REPORT

DAA PROJECT NO. 5308.28

Prepared for:

FAUQUIER COUNTY
Fauquier County, Virginia

Prepared by:

DRAPER ADEN ASSOCIATES
Glen Allen, Virginia

December, 1995

FAUQUIER COUNTY SANITARY LANDFILL
FAUQUIER COUNTY, VIRGINIA

WELL COMPLETION REPORT

DAA PROJECT NO. 5308.28

This document, including all attachments, was prepared by Draper Aden Associates in accordance with a contract between Draper Aden Associates and Fauquier County. This document has been prepared by Draper Aden Associates in accordance with generally accepted standards of environmental practice for the exclusive use of Fauquier County for specific application to the referenced site. No other warranty is either expressed or implied.

Any reuse of this document by other parties, or for purposes other than those specified, without written authorization from Draper Aden Associates, will be at the sole risk of the party or parties utilizing this document. Draper Aden Associates shall incur no liability resulting from any and all claims, damages, losses, and expenses that might arise from unauthorized use of this document.

Donna Lancaster
Project Geologist

Leonard N. Ford, Jr. (PhD, PG)
Project Manager

TABLE OF CONTENTS

1.0 SUMMARY

2.0 DRILLING

3.0 SOIL AND ROCK SAMPLING

4.0 WELL CONSTRUCTION

5.0 ANCILLARY REQUIREMENTS

6.0 WELL DEVELOPMENT

7.0 SURVEY DATA

8.0 LIMITATIONS

APPENDICES

1.0 TABLES

2.0 GEOLOGIC BORING LOGS

FAUQUIER COUNTY SANITARY LANDFILL
FAUQUIER COUNTY, VIRGINIA

WELL COMPLETION REPORT

DAA PROJECT NO. 5308.28

1.0 SUMMARY

On September 14, and September 15, 1995, Badger Drilling, Inc., advanced two borings at the subject site and constructed two groundwater monitoring wells (MW-13, MW-14) within the boreholes. Draper Aden personnel documented all well drilling and well construction procedures.

The monitoring wells were constructed in general accordance with the specifications outlined in the *Invitation For Bids: Drilling and Well Construction*, as prepared by Draper Aden Associates (dated September, 1995).

On September 21, 1995, Draper Aden personnel obtained static water levels and measured construction parameters in each of the monitoring wells. On September 21, 1995, Draper Aden personnel developed the two new monitoring wells. On November 8, 1995, Draper Aden personnel surveyed the locations and elevations of the groundwater monitoring wells and other relevant site features.

Well locations are shown on SHEET 1 (in pocket at back of report). Well specifications are presented in TABLE 1 (APPENDIX 1). Survey data are presented in TABLE 2 (APPENDIX 1). Static water level data are shown in TABLE 3 (APPENDIX 1). Geologic boring logs, which also illustrate monitoring well as-built data, are presented in APPENDIX 2.

2.0 DRILLING

2.1 Nominal Borehole Diameter

All boreholes were approximately 9.5 to 10 inches in diameter in order to help ensure that, when using 2-inch wellpipe, the minimum width of the annulus around the wellpipe would be greater than 2 inches.

2.2 Drilling Methods

Each boring was advanced using hollow stem auger drilling methods. The depth of each boring is listed on TABLE 1.

2.3 Cuttings

Drilling was performed in a manner that minimized the spreading of soil cuttings.

3.0 SOIL AND ROCK SAMPLING

3.1 Split Spoon Sampling

During drilling, soil materials were obtained using standard split-spoon samplers. In general, split-spoon samples were obtained at 5.0 foot intervals between the surface and the bottom of the borehole.

3.2 Cuttings

Cuttings were generally kept clear of the borehole and were stockpiled near the borehole upon completion of the monitoring well.

3.3 Continuous Coring

Not applicable.

3.4 Sample Disposition

After describing the contents of the split-spoon samplers, Draper Aden personnel placed the soil samples in plastic bags. The samples are archived at the offices of Draper Aden Associates, Glen Allen, Virginia.

4.0 WELL CONSTRUCTION

4.1 Construction Method

All wells were constructed within the hollow stem augers. The filter sand and the bentonite seal were not placed by the tremie pipe method; however, the depth from the ground surface to the top of each layer was carefully measured using a 100 foot tape (graduated in tenths of a foot). The observed procedure appeared to ensure that the filter sand and the bentonite seal were placed at the appropriate depths. A tremie pipe was used to place the cement-bentonite backfill.

4.2 Wellpipe and Screen

Each monitoring well was constructed of pre-cleaned Schedule 40 PVC pipe having an inner diameter of 2 inches.

The base of each well terminates with a factory-slotted PVC screen having a length of 10 feet and threaded PVC plug. Slots in the screen are 0.01 inch in width.

The driller wore clean, surgical-type gloves whenever handling PVC wellpipe, and the pipe was maintained in a clean manner.

In order to provide a smooth cut, a PVC pipe-cutter was used wherever it was necessary to shorten sections of PVC wellpipe.

4.3 Sandpack

The filter sand (No. 2, Drillers Service, Inc.) appeared to be a clean sand, with no fraction exceeding a nominal diameter of approximately 0.25 inches.

Filter sand was placed in the annulus around the well riser to a point approximately 2 feet above the top of the screen in the monitoring well.

4.4 Bentonite Seal

The annulus around the wellpipe was sealed with a layer of bentonite pellets, which was placed directly above the sand filter pack. The minimum thickness of the bentonite layer in each monitoring well is two (2) feet.

4.5 Grout

Following hydration of the bentonite seal, each boring was sealed with a Portland Type I bentonite/cement slurry, using the tremie-pipe method.

4.6 Surface Completion

Each well was completed with a concrete apron, capped PVC well riser, and outer protective casing.

The outer protective casing is constructed of steel, is square in cross-section, has a hinged lid (that can be lifted upward, then to either side, to gain access to the well), and has a diagonal dimension of not less than 8 inches.

Each concrete apron has the following approximate dimensions: 3 feet x 3 feet x 3.5 inches. A form was used in constructing each apron. The form was approximately centered with respect to the protective steel casing.

A spike was placed into each concrete apron for surveying purposes.

A vent hole was drilled through the PVC riser at a point approximately 2 inches (± 1 inch) below its top.

A drain hole was drilled through each outer protective casing just above the surface of the concrete apron.

The outer protective casings are lockable. The driller provided a lock for each protective casing cap. Both locks are keyed identically.

5.0 ANCILLARY REQUIREMENTS

5.1 Extraneous Material

The driller took reasonable care to help ensure that each boring was free from all materials other than those required for well construction. "Materials required for well construction" is defined in the specification to include polyvinyl chloride (PVC), sand, bentonite, Portland cement, and natural soil materials.

5.2 Decontamination

All drilling equipment (drillsteel, bits, casing materials), and any additional equipment that contacts subsurface formations, was decontaminated prior to on-site use and between consecutive well installations.

Steam cleaning with potable hot water and biodegradable detergent (Alconox) was used to clean the equipment and was conducted in a manner that appeared to minimize overspray and runoff.

5.3 Disposition of Waste Water

Not applicable.

5.4 Cleanup

The driller removed all refuse from each well site.

5.5 Health and Safety

Smoking was not permitted within 100 feet of the borehole.

6.0 WELL DEVELOPMENT

On September 21, 1995, Draper Aden personnel developed the two new monitoring wells to remove fine sediment by repeatedly surging and purging groundwater from the well. At a minimum, three well volumes of groundwater were removed from each monitoring well during well development.

7.0 SURVEY DATA

On November 8, 1995, Draper Aden personnel surveyed the locations and elevations of the groundwater monitoring wells and other relevant site features. In order to relate water levels to elevation, a reference point having a known elevation was selected as a bench mark.

Four points were surveyed at each monitoring well location: ground surface, the spike in the concrete pad, the top of the open protective steel casing, and the top of the PVC wellpipe. The surveyed points are presented on TABLE 2 (APPENDIX 1).

8.0 LIMITATIONS

This report has been prepared for the exclusive use of the referenced client for specific application to the subject site. This report should in no way be construed as our recommendation to either purchase, sell, or develop the project site. This report represents a statement of observations and shall not be regarded as certification of the presence of contamination or lack thereof.

The report was prepared in accordance with generally accepted standards of practice for environmental and geological services as conducted by engineering firms of similar size and having similar resources. No other warranty, either expressed or implied, is made.

Our conclusions and recommendations are based upon information provided to us by others, our observations, and professional judgement. To the best of our knowledge, information provided by others is true and correct, unless otherwise noted; however, Draper Aden Associates is not responsible for the verification of information provided by others.

Our on-site observations pertain only to specific locations at specific times on specific dates. Our observations and conclusions do not reflect variations in subsurface conditions that may exist between sampling locations, in unexplored areas of the site, or at times other than those represented by our observations.

It is the responsibility of the client to notify the appropriate government agencies of our findings, as may be required by law. It is not the responsibility of Draper Aden Associates to report these findings to any federal, state and/or local agency, including such conditions as may present a potential danger to public health, safety, or the environment.

APPENDIX 1

TABLES

TABLE 1

CLIENT: FAUQUIER COUNTY SANITARY LANDFILL
PROJECT: WELL COMPLETION REPORT

WELL SPECIFICATIONS

WELL	TYPE	NORTHING	EASTING	D_b	TD_b	SAND	BNT	$DEPTH_m$	STICKUP	$DEPTH_c$	$ELEV_{gs}$	$ELEV_{mp}$
MW-1	2MW10	12388.44	10744.15	9.25	30	17	15	31.98	1.98	30	535.72	537.70
MW-2	2MW10	11106.81	10898.34	9.25	25	12	10	26.98 \28.27	1.98 \3.27	25	515.05 \516.92	517.03 \520.19
MW-3	2MW10	10761.46	11060.80	9.25	20	7	5	21.17	1.17	20	500.68	501.85
MW-4	2MW10	12055.70	9811.25	9.25	20	7.5	5.5	22.53	2.53	20	512.25	514.78
MW-5	2MW10	10198.48	10621.36	9.25	30	18	16	30.86	0.86	30	512.96	513.82
MW-6	2MW10	11642.43	9895.39	9.25	50	37.5	35.5	49.90	-0.10	50	547.90	547.80
MW-7	2MW10	12091.41	10503.4	9.25	25	12	10.7	26.92	1.92	25	539.49	541.41
MW-12	2MW10	10774.60	10503.40	7.2	39	27	25	41.15	2.15	39	527.26	529.41
MW-13♦	2MW10	10574.21	10688.00	9.25	42.0	27	25	41.80	1.58	40.22	522.50	524.44
MW-14♣	2MW10	10847.99	10951.50	9.25	37.0	20	17	35.0	1.82	33.18	505.28	507.23

NOTES:

MW - monitoring well (prefix = pipe diameter, suffix = screen length)
D_b - borehole diameter
TDb - total depth of borehole
SAND - top of sandpack
BNT - top of bentonite seal
$DEPTH_m$ - measured well depth (relative to measuring point)
$DEPTH_c$ - corrected well depth (relative to ground surface) = $depth_m$ - stickup
$ELEV_{gs}$ - elevation: ground surface
$ELEV_{mp}$ - elevation: measuring point (top PVC)
♦ - replaces monitoring well MW-12
♣ - replaces monitoring well MW-2

1.98 \ 3.27 - original \ adjusted

Elevation in feet.

TABLE 2

CLIENT: FAUQUIER COUNTY SANITARY LANDFILL
PROJECT: WELL COMPLETION REPORT

SURVEY DATA

WELL	NORTHING	EASTING	$ELEV_{gs}$	$ELEV_{cp}$	$ELEV_{oc}$	$ELEV_{mp}$
MW-1	12388.44	10744.15	535.72	■	■	537.70
MW-2	11106.81	10898.34	516.92♠	517.12♠	520.91♠	520.19♠
MW-3	10761.46	9642.93	500.68	■	■	501.85
MW-4	12055.70	11060.80	512.25	■	■	514.78
MW-5	10198.48	9811.25	512.96	■	■	513.82
MW-6	11642.43	10621.36	547.90	■	■	547.80
MW-7	12091.41	9895.39	539.49	■	■	541.41
MW-12	10774.60	10503.40	527.26	■	■	529.41
MW-13♦	10574.21	10688.00	522.50	522.87	524.49	524.44
MW-14♣	10847.99	10951.50	505.28	505.42	506.84	507.23

NOTES:

$ELEV_{gs}$ - elevation of the ground surface
$ELEV_{cp}$ - elevation of concrete pad or nail (spike) set in pad
$ELEV_{oc}$ - elevation of the open protective casing
$ELEV_{mp}$ - elevation of the measuring point (top PVC wellpipe)
■ - elevation data unavailable

All measurements in feet.

♠ - new data: well has been modified
♦ - replaces monitoring well MW-12
♣ - replaces monitoring well MW-2

survey.308

TABLE 3

CLIENT: FAUQUIER COUNTY SANITARY LANDFILL
PROJECT: WELL COMPLETION REPORT

STATIC WATER LEVELS

DATE: 09-21-95

WELL	$ELEV_{mp}$	DTW	STICKUP	DTW_c	$ELEV_{gs}$	$ELEV_{gw}$
MW-13♦	524.44	24.85	1.58	23.27	522.50	499.59
MW-14♣	507.23	7.85	1.82	6.03	505.28	499.38

NOTES:

$ELEV_{mp}$	- elevation of measuring reference point (top of PVC wellpipe)
DTW	- depth to water (relative to reference point)
DTW_c	- depth to water (relative to ground surface)
$ELEV_{gs}$	- elevation of the ground surface
$ELEV_{gw}$	- elevation of the groundwater table
♦	- replaces existing monitoring well MW-12
♣	- replaces existing monitoring well MW-2

sw092195.308

APPENDIX 2

GEOLOGIC BORING LOGS

DRAPER ADEN ASSOCIATES
Engineers • Geologists • Hydrologists

LOG OF: **MW-13**
(1 of 2)

Project Number: **5308.28**

Client: **Fauquier County**	Drilling Company: **Badger Drilling**
Project: **Fauquier County Landfill**	Driller: **J. Davis**
Location: **Rt. 674**	Boring Method: **6.25" HSA**
North: **10574.2** East: **10688.0**	Logged by: **D. Lancaster**
Total Depth **42.0'** Elev GS: **522.5**	Reference: **ground surface** Completion Date: **September 13, 1995**

Samp ID	Blow Counts	N Value	Depth Scale	SOIL DESCRIPTION (ASTM)	Stratum Elev	PID (ppm)	WELL LOG	H2O	REMARKS
S1	6 7 13 14	20	2 4	V stiff, red-brown, CLAY, trace gravel (quartz, angular), plant fragments; moist. (CL)					RESIDUAL SOIL.
S2	8 8 9 8	17	6 8	Increasing sand.					
S3	3 5 7 10	12	10 12 14	MnOx-staining.					Grout.
S4	3 5 8 9	13	16 18	Stiff, red-yellow (layered), SILT, trace sand, extensive MnOx-staining, relict texture present; v moist. (ML)	507.5				SAPROLITE. Parent = gneiss.
S5	6 10 13 17	23	20 22	Becoming v stiff.				500.2 ▼	SWE: 09-15-95.

DRAPER ADEN ASSOCIATES
Engineers • Geologists • Hydrologists

LOG OF: **MW-13** (2 of 2)

Project Number: 5308.28

Client: Fauquier County	Drilling Company: Badger Drilling
Project: Fauquier County Landfill	Driller: J. Davis
Location: Rt. 674	Boring Method: 6.25" HSA
North: 10574.2 East: 10688.0	Logged by: D. Lancaster
Total Depth 42.0' Elev GS: 522.5 Reference: ground surface	Completion Date: September 13, 1995

Samp ID	Blow Counts	N Value	Depth Scale	SOIL DESCRIPTION (ASTM)	Stratum Elev	PID (ppm)	WELL LOG	H2O	REMARKS
				SILT.					Cuttings + bentonite.
S6	6 7 12 17	19	26	Becoming wet.				497.5	DDW: 09-14-95.
									Bentonite.
								495.5	
			28						Sandpack.
								493.5	
S7	6 12 18 10	30	30						
			32						
			34						
S8	4 14 20 31	34	36	Becoming hard, yellow-brown.					Screen: 0.01" slotted, 2" Sch 40 PVC. Cuttings.
			38					483.6	
								483.5	
								482.5	
S9	5 5 4 14	9	40	Becoming stiff.					
			42		480.5			480.5	
				Boring terminated at 42 feet. Groundwater encountered. Well MW-13 constructed at 39.5 feet.					
			44						
			46						

DRAPER ADEN ASSOCIATES
Engineers • Geologists • Hydrologists

LOG OF: **MW-14** (1 of 2)

Project Number: **5308.28**

Client: **Fauquier County**	Drilling Company: **Badger Drilling**
Project: **Fauquier County Landfill**	Driller: **J.. Davis**
Location: **Rt. 674**	Boring Method: **6.25" HSA**
North: **10848.0** East: **10951.5**	Logged by: **C. Campana**
Total Depth **37.0'** Elev GS: **505.3**	Reference: **ground surface** Completion Date: **September 14, 1995**

Samp ID	Blow Counts	N Value	Depth Scale	SOIL DESCRIPTION (ASTM)	Stratum Elev	PID (ppm)	WELL LOG	H2O	REMARKS
S1	8 9 7 5	16	2 4	V stiff, red-brown, SILT with v fine sand, trace gravel (quartz, angular), root fragments; moist. (ML)					RESIDUAL SOIL.
S2	1 2 3 4	5	6 8	Becoming mottled (lt gr, y, r-br, br) with MnOx-filled joints.				▼	SWE: 09-15-95. Grout.
S3	3 9 10 14	19	10 12 14	Becoming mottled (r-br, br) with extensive MnOx-stained joints.	490.3				
S4	5 9 10 13	19	16 18	V stiff, mottled (y-br, r-br, r-blk), micaceous, fine sandy SILT with MnOx-filled joints (< 2 mm) and MnOx-staining; moist. (SM)				488.3	SAPROLITE. Parent = schist. Bentonite.
S5	6 7 8 8	15	20 22	Becoming stiff, mottled (or-br, y-br, tan) with MnOx planes, indistinct relict texture; wet.				485.3 ▼ 482.3	DDW: 09-15-95. Sandpack.

DRAPER ADEN ASSOCIATES
Engineers • Geologists • Hydrologists

LOG OF: **MW-14** (2 of 2)

Project Number: **5308.28**

Client: **Fauquier County**	Drilling Company: **Badger Drilling**
Project: **Fauquier County Landfill**	Driller: **J. Davis**
Location: **Rt. 674**	Boring Method: **6.25" HSA**
North: **10848.0** East: **10951.5**	Logged by: **C. Campana**
Total Depth **37.0'** Elev GS: **505.3**	Reference: **ground surface** Completion Date: **September 14, 1995**

Samp ID	Blow Counts	N Value	Depth Scale	SOIL DESCRIPTION (ASTM)	Stratum Elev	PID (ppm)	WELL LOG	H2O	REMARKS
				Sandy SILT.					
S6	12 18 28 43	46	26	Becoming hard, increasing gravel (angular, > 5 mm).					Screen: 0.01" slotted, 2" Sch 40 PVC.
			28						
S7	12 16 18 19	34	30						
			32					472.4 472.3	Sandpack.
			34						
S8	12 16 16 20	32	36					470.3	Cuttings.
					468.3			468.3	
			38	Boring terminated at 37 feet. Groundwater encountered. Well MW-14 constructed at 33 feet.					
			40						
			42						
			44						
			46						

COMMONWEALTH of VIRGINIA

IN COOPERATION WITH THE
STATE DEPARTMENT OF HEALTH

Fauquier County Health Department
ENVIRONMENTAL HEALTH
320 HOSPITAL DRIVE - SUITE 21
WARRENTON, VIRGINIA 20186

(540) 347-6363

May 30, 2007

Mr. Charles Cooper
Building Official
40 Culpeper Street
Warrenton, Va. 20186

RE: Temporary Pit Privy – Map Reference 6983-81-0145 – 6438 College St., Warrenton, Va.

Dear Sir :

This letter is written to confirm receipt of written contracts for a temporary privy, bottled water and waterless hand cleaner to be used by C & D Recycle Center.

This office hereby approves the use of the temporary trailer for the period of time specified by the County of Fauquier.

If this office can be of any further assistance, please call us at 347-6375.

Sincerely,

John R. Largent

John R. Largent
Environmental Health Supervisor

FAUQUIER CO ENVIRONMENTAL HEALTH DEPT.

TEMPORARY PRIVY APPLICATION

Name of ~~Event~~ or Project: C + D RECYCLE CENTER

Coordinator's Name: Dow Nuckols

Coordinator's Address: 6438 COLLEGE ST, WARRENTON, VA 20187

P.I.N. # 6983-81-0145

Name of Privy Company: ACTON MOBIL INDUSTRIES

Number of Privies: (1)

(Va Regs require 1 Privy per 100 people for Mass Gathering)
1 Privy per 25 People for Construction Site)

Fees:
Administrative fee: $35.00-includes 1st Privy

$15.00 each for Privies 2-20 (Maximum of $100.00)
$15.00 each for Privies 21 and Greater

Signature of Property Owner: _____ Date:

Signature of Coordinator-Agent: Dwight C. Nuckols Date: 5/17/07

Date Application Evaluated and approved: _____

EHS Supervisor John R. Lorzert

FAUQUIER CO ENVIRONMENTAL HEALTH DEPT.

TEMPORARY PRIVY APPLICATION

Name of ~~Event~~ or Project: C & D RECYCLE CENTER

Coordinator's Name: Dow Nuckols (cell) 540-270-5575

Coordinator's Address: 6438 COLLEGE ST, WARRENTON, VA 20187

P.I.N. # 6983-81-0145

Name of Privy Company: ACTON MOBIL INDUSTRIES

Number of Privies: (1)

(Va Regs require 1 Privy per 100 people for Mass Gathering)
1 Privy per 25 People for Construction Site)

Fees:
Administrative fee: $35.00-includes 1st Privy

$15.00 each for Privies 2-20 (Maximum of $100.00)
$15.00 each for Privies 21 and Greater

Signature of Property Owner: _____ Date:

Signature of Coordinator-Agent: Dale L. Nuckols Date: 5/17/07

Date Application Evaluated and approved: _____

EHS Supervisor _____

4-13-93

Memo to file on one bedroom cottage -

building sewer exits back of cottage and does not appear to head towards old cesspool. Apparently, it is served by a system on the other side of the two houses.

MLC

COMMONWEALTH OF VIRGINIA
DEPARTMENT OF HEALTH

MEMO SHEET

Date _____

Time: _____

To _____

_____

☐ Initial and return	☐ Please call	☐ Information
☐ Handle	☐ Reply for Sig.	☐ Comments
☐ File	☐ As discussed	☐ Approval
☐ Discuss with me	☐ As requested	☐ Signature

_____

_____

_____

_____

_____

N13800000
Rev 2/90

_____
Signature

10D 4/8/93

Chuck,

Mr. Escher called - He said he can get drainfield in the right place but may have to move septic tank on cottage to ② hand side instead of ① hand side because of plumbing in house and therefore would have to move dis box to ② on instead of ① cottage and that would be ok if all regs are met. Thanks John

Application for a Sewage Disposal (Repair) System Construction Permit

Commonwealth of Virginia
Department of Health

For Department Use Only

Health Department Identification Number SD-93-[redacted] 143
Map Reference Subd.

Fauquier County Health Department

Date Received 4-6-93

To Be Completed By The Applicant

Type sewage system: ☐ New ☒ Repair ☐ Expanded ☐ Conditional
FHA/VA yes ☐ no ☐

Owner B G Souder Trustee Address Rt 3 Box 1320 Phone 347-1097
Gainesville VA 22065

Agent _____ Address _____ Phone _____

Directions to Property 29 S (L) College Road, to back of property

Subdivision Coral Farm Section _____ Block _____ Lot _____

Other Property Identification (Lee's Crossing) 82/53

Dimensions/size of Lot/Property 2.35 Acres (old lots 37 & 38)

Other Application Information

I. **Building/facility** ☐ New ☑ Existing
Intermittent Use ☐ Yes ☐ No If yes, describe: _____

II. **Residential Use** ☑ Yes ☐ No
Termite Treatment ☐ Yes ☐ No
☑ Single Family ☐ Multifamily Number of Units 1 Number of Bedrooms 1
Basement ☐ Yes ☑ No
Fixtures in Basement ☐ Yes ☑ No

III. **Commercial Use** ☐ Yes ☑ No Describe: _____

Commercial/Wastewater ☐ Yes ☐ No Number of Patrons ___ Number of Employees ___
If yes, give volumes and describe _____

IV. **Water Supply:** ☐ Public ☐ New Describe: _____
☑ Private ☑ Existing

V. **Proposed Installation:** ☑ Septic tank and drainfield ☐ Other
If other, describe _____

SITE PLAN Attach a site plan (rough sketch) showing dimensions of property, proposed and/or existing structures and driveways, underground utilities, adjacent soil absorption systems, bodies of water, drainage ways, and wells and springs within 200 feet radius of the center of the proposed building or drainfield. Distances may be paced or estimated.

The property lines and building location are clearly marked and the property is sufficiently visible to see the topography. I give permission to the Department to enter onto the property described for the purpose of processing this application.

_____ 4/6/93
Signature of owner/agent Date

C.H.S. 200 Revised 4/83

SD93143

Application for a Sewage Disposal System Construction Permit

Commonwealth of Virginia
Department of Health

For Department Use Only

Health Department Identification Number SD-93-[redacted] 143
Map Reference Subd.

Fauquier County Health Department

Date Received 4-6-93

To Be Completed By The Applicant

Type sewage system: ☐ New ☒ Repair ☐ Expanded ☐ Conditional
FHA/VA yes ☐ no ☐

Owner B G Sauder Trustee Address Rt 3 Box 1320 Phone 347-1097
Gainesville VA 22065

Agent _____ Address _____ Phone _____

Directions to Property 29 S (L) College Road, to back of property

Subdivision Canal Farm Section _____ Block _____ Lot _____

Other Property Identification (Lee's Crossing) 82/53

Dimensions/size of Lot/Property 7.35 Acres (old lots 39 & 38)

Other Application Information

I. **Building/facility** ☐ New ☑ Existing
Intermittent Use ☐ Yes ☐ No If yes, describe: _____

II. **Residential Use** ☑ Yes ☐ No
Termite Treatment ☐ Yes ☐ No
☑ Single Family ☐ Multifamily Number of Units 1 Number of Bedrooms 1
Basement ☐ Yes ☑ No
Fixtures in Basement ☐ Yes ☑ No

III. **Commercial Use** ☐ Yes ☑ No Describe: _____

Commercial/Wastewater ☐ Yes ☐ No Number of Patrons ____ Number of Employees ____
If yes, give volumes and describe _____

IV. **Water Supply:** ☐ Public ☐ New Describe: _____
☑ Private ☑ Existing

V. **Proposed Installation:** ☑ Septic tank and drainfield ☐ Other
If other, describe _____

SITE PLAN Attach a site plan (rough sketch) showing dimensions of property, proposed and/or existing structures and driveways, underground utilities, adjacent soil absorption systems, bodies of water, drainage ways, and wells and springs within 200 feet radius of the center of the proposed building or drainfield. Distances may be paced or estimated.

The property lines and building location are clearly marked and the property is sufficiently visible to see the topography. I give permission to the Department to enter onto the property described for the purpose of processing this application.

_____ 4/6/93
Signature of owner/agent Date

C.H.S. 200 Revised 4/89

SD93143

Application for a Sewage Disposal System Construction Permit

Commonwealth of Virginia
Department of Health

For Department Use Only

Health Department Identification Number SD-93-[redacted] 143
Map Reference Subd.

Fauquier County Health Department

Date Received 4-6-93

To Be Completed By The Applicant

Type sewage system: ☐ New ☒ Repair ☐ Expanded ☐ Conditional
FHA/VA yes ☐ no ☐

Owner R G Sauder Trustee Address Rt 3 Box 1320 Phone 347-1097
Gainesville VA 22065

Agent _____ Address _____ Phone _____

Directions to Property 29 S (L) College Road, to back of property

Subdivision Canal Farm Section _____ Block _____ Lot _____

Other Property Identification (Lee's Crossing) 32/53

Dimensions/size of Lot/Property 7.35 Acres (old lots 37 & 38)

Other Application Information

I. **Building/facility** ☐ New ☑ Existing
Intermittent Use ☐ Yes ☐ No If yes, describe: _____

II. **Residential Use** ☑ Yes ☐ No
Termite Treatment ☐ Yes ☐ No
☑ Single Family ☐ Multifamily Number of Units 1 Number of Bedrooms 1
Basement ☐ Yes ☑ No
Fixtures in Basement ☐ Yes ☑ No

III. **Commercial Use** ☐ Yes ☑ No Describe: _____

Commercial/Wastewater ☐ Yes ☐ No Number of Patrons ____ Number of Employees ____
If yes, give volumes and describe _____

IV. **Water Supply:** ☐ Public ☐ New Describe: _____
☑ Private ☑ Existing

V. **Proposed Installation:** ☑ Septic tank and drainfield ☐ Other
If other, describe _____

SITE PLAN Attach a site plan (rough sketch) showing dimensions of property, proposed and/or existing structures and driveways, underground utilities, adjacent soil absorption systems, bodies of water, drainage ways, and wells and springs within 200 feet radius of the center of the proposed building or drainfield. Distances may be paced or estimated.

The property lines and building location are clearly marked and the property is sufficiently visible to see the topography. I give permission to the Department to enter onto the property described for the purpose of processing this application.

_____ 4/6/93
Signature of owner/agent Date

C.H.S. 200 Revised 4/89

(SD 93 143

Sewage Disposal System Construction Permit

Commonwealth of Virginia
Department of Health
Fauquier Health Department

Health Department Identification Number SD 93 143
Map Reference subd

General Information

New ☐ Repair ☒ Expanded ☐ Conditional ☐ FHA ☐ VA ☐ Case No. _____

Based on the application for a sewage disposal system construction permit filed in accordance with Section 3.13.01, a construction permit is hereby issued to:

Owner BJ Sonder Trustee Telephone _____

Address _____

For a Type I Sewage disposal system which is to be constructed on/at 295 (L) @ LFCC

Subdivision Reed's Crossing ~~Section/Block~~ _____ Lot _____

Actual or estimated water use 150 gpd 1 BR

DESIGN	NOTE: INSPECTION RESULTS
Water supply, existing: (describe) III C **To be installed:** class N/A cased _____ grouted _____	**Water supply location:** Satisfactory yes ☐ no ☐ comments G. W. 2 Received: yes ☐ no ☐ not applicable ☐
Building sewer: EXISTING I.D. PVC 40, or equivalent. Slope 1.25" per 10' (minimum). ☒ Other sch 40 to DB Box	**Building sewer:** yes ☐ no ☐ comments Satisfactory
Septic tank: Capacity 750 gals. (minimum). ☒ Other Neoplanbrige Disposals	**Pretreatment unit:** yes ☐ no ☐ comments Satisfactory
Inlet-outlet structure: 8" in 18" out PVC 40, 4" tees or equivalent. ☒ Other STUBS 1" Below Lids	**Inlet-outlet structure:** yes ☐ no ☐ comments Satisfactory
Pump and pump station: No ☒ Yes ☐ describe and show design. if yes: _____	**Pump & pump station:** yes ☐ no ☐ comments Satisfactory
Gravity mains: 4" or larger I.D., minimum 6" fall per 100', 1500 lb. crush strength or equivalent. ☐ Other _____	**Conveyance method:** yes ☐ no ☐ comments Satisfactory
Distribution box: Precast concrete with 4+ ports. ☒ Other Bedded on 4" concrete pad	**Distribution box:** yes ☐ no ☐ comments Satisfactory
Header lines: Material: 4" I.D. 1500 lb. crush strength plastic or equivalent from distribution box to 2' into absorption trench. Slope 2" minimum. ☐ Other _____	**Header lines:** yes ☐ no ☐ comments Satisfactory
Percolation lines: Gravity 4" plastic 1000 lb. per foot bearing load or equivalent, slope 2" 4" (min. max.) ~~per 100'~~. ☒ Other Cover w/ untreated paper	**Percolation lines:** yes ☐ no ☐ comments Satisfactory
Absorption trenches: Square ft. required 600: depth from ground surface to bottom of trench 30"; aggregate size 1 2 to 1 1/2 Trench bottom slope 2 to 4 inches per 100'; center to center spacing 7'; trench width 2' Depth of aggregate 13"; Trench length 100; Number of trenches 3	**Absorption trenches:** yes ☐ no ☐ comments Satisfactory Date _____ Inspected and approved by: _____ Sanitarian

C.H.S. 202A Revised 6/84

Health Department
Identification Number SD 93 143

Schematic drawing of sewage disposal system and topographic features. PAGE 2 OF 2

Show the lot lines of the building lot and building site, sketch of property showing any topographic features which may impact on the design of the system, all existing and/or proposed structures including sewage disposal systems and wells within 100 feet of sewage disposal system and reserve area. The schematic drawing of the sewage disposal system shall show sewer lines, pretreatment unit, pump station, conveyance system, and subsurface soil absorption system, reserve area, etc. When a nonpublic drinking water supply is to be located on the same lot show all sources of pollution within 100 feet.

Sec 82 Pcl 53

☒ The information required above has been drawn on the attached copy of the sketch submitted with the application. Attach additional sheets as necessary to illustrate the design.



* Drawing not to scale.
* Permit void if building location interferes with approved drainfield location.
* Designed for basement plumbing? YES NO
* Drainfield to be 100+' from Class IIIC wells and 50' from all Class IIIA&B wells.
* Install 3 - 100 lines, ON CONTOUR, in 2'-wide trenches, on 7' centers.
* Install trenches 30 " deep.
* Smooth-walled header pipes recommended.
* Extend header pipes 24" into gravel.
* Use single size gravel 0.5" to 1.5" diam.
* No parking or driving on drainfield system
* Divert roof drains away from drainfield.
* No trees within 10' of system.
* Pump septic tank every 3 - 5 years.

~~WELL REQUIREMENTS~~
~~* Install Class ___ well ___ '+ away from drainfield, reserve, treated foundation, and all sources of contamination.~~
~~* All well grouts to be witnessed by environmental health specialist.~~
~~* Water to be tested for potability.~~

* see plat for reserve

The sewage disposal system is to be constructed as specified by the permit ☒ or attached plans and specifications ☐.

This sewage disposal system construction permit is null and void if (a) conditions are changed from those shown on the application (b) conditions are changed from those shown on the construction permit.

No part of any installation shall be covered or used until inspected, corrections made if necessary, and approved, by the local health department or unless expressly authorized by the local health dept. Any part of any installation which has been covered prior to approval shall be uncovered, if necessary, upon the direction of the Department.

Date: 4/7/93 Issued by: [signature] EHS

Date: 4/7/93 Reviewed by: John K. Sargent
Supervisory Sanitarian

This Construction Permit Valid until 4/7/94

If FHA or VA financing

Reviewed by Date _____ _____ Date _____ _____
Supervisory Sanitarian Regional Sanitarian

C.H.S. 2028 Revised 6/84

II-2A

ORIGINAL

Sewage Disposal System Construction Permit

Commonwealth of Virginia
Department of Health
Fauquier Health Department

Health Department Identification Number SD93 141
Map Reference 51-66

General Information

New ☐ Repair ☒ Expanded ☐ Conditional ☐ FHA ☐ VA ☐ Case No. _____

Based on the application for a sewage disposal system construction permit filed in accordance with Section 3.13.01, a construction permit is hereby issued to:

Owner BJ Sowder Trustee Telephone _____

Address _____

For a Type I Sewage disposal system which is to be constructed on/at 295 Old Calfee

Subdivision Rock Class Section/Block _____ Lot _____

Actual or estimated water use 150 gpd 1 BR

DESIGN	NOTE: INSPECTION RESULTS
Water supply, existing: (describe) III C **To be installed:** class N/A cased _____ grouted _____	**Water supply location:** Satisfactory yes ☐ no ☐ comments G. W. 2 Received: yes ☐ no ☐ not applicable ☐
Building sewer: EXISTING I.D. PVC 40, or equivalent. Slope 1.25" per 10' (minimum). ☒ Other sch. 40 to DB Box	**Building sewer:** yes ☐ no ☐ comments Satisfactory
Septic tank: Capacity 750 gals. (minimum). ☒ Other Negative Pressure	**Pretreatment unit:** yes ☐ no ☐ comments Satisfactory
Inlet-outlet structure: 8" in 18" out PVC 40, 4" tees or equivalent. ☒ Other Stub T's 1" Below Lids	**Inlet-outlet structure:** yes ☐ no ☐ comments Satisfactory
Pump and pump station: No ☒ Yes ☐ describe and show design. if yes: _____	**Pump & pump station:** yes ☐ no ☐ comments Satisfactory
Gravity mains: 6" or larger I.D., minimum 6" fall per 100', 1500 lb. crush strength or equivalent. ☐ Other _____	**Conveyance method:** yes ☐ no ☐ comments Satisfactory
Distribution box: Precast concrete with 4 ports. ☒ Other Bedded on 4" concrete pad	**Distribution box:** yes ☐ no ☐ comments Satisfactory
Header lines: Material: 4" I.D. 1500 lb. crush strength plastic or equivalent from distribution box to 2' into absorption trench. Slope 2" minimum. ☐ Other _____	**Header lines:** yes ☐ no ☐ comments Satisfactory
Percolation lines: Gravity 4" plastic 1000 lb. per foot bearing load or equivalent, slope 2" 4" (min. max.) per 100'. ☒ Other Cover w/ Geotextile paper	**Percolation lines:** yes ☐ no ☐ comments Satisfactory
Absorption trenches: Square ft. required 600: depth from ground surface to bottom of trench 30"; aggregate size 1/2 to 1 1/2" Trench bottom slope 2 to 4 inches per 100'; center to center spacing 7'; trench width 2' Depth of aggregate 13"; Trench length 100; Number of trenches 3	**Absorption trenches:** yes ☐ no ☐ comments Satisfactory
	Date _____ Inspected and approved by: _____ Sanitarian

C.H.S. 202A Revised 6/84

Health Department
Identification Number SD 93 141

Schematic drawing of sewage disposal system and topographic features.

PAGE 2 OF 2

Show the lot lines of the building lot and building site, sketch of property showing any topographic features which may impact on the design of the system, all existing and/or proposed structures including sewage disposal systems and wells within 100 feet of sewage disposal system and reserve area. The schematic drawing of the sewage disposal system shall show sewer lines, pretreatment unit, pump station, conveyance system, and subsurface soil absorption system, reserve area, etc. When a nonpublic drinking water supply is to be located on the same lot show all sources of pollution within 100 feet.

Sec 82 Res 93

☒ The information required above has been drawn on the attached copy of the sketch submitted with the application. Attach additional sheets as necessary to illustrate the design.



* Drawing not to scale.
* Permit void if building location interferes with approved drainfield location.
* Designed for basement plumbing: YES NO
* Drainfield to be 100+' from Class IIIC wells and 50' from all Class IIIA&B wells.
* Install 3 - 100 lines, ON CONTOUR, in 2'-wide trenches, on 7' centers.
* Install trenches 30 " deep.
* Smooth-walled header pipes recommended.
* Extend header pipes 24" into gravel.
* Use single size gravel 0.5" to 1.5" diam.
* No parking or driving on drainfield system.
* Divert roof drains away from drainfield.
* No trees within 10' of system.
* Pump septic tank every 3 - 5 years.

~~WELL REQUIREMENTS~~

~~* Install Class ___ well ___' from drainfield, reserve, treated foundation, and all sources of contamination.~~
~~* All well grouts to be witnessed by environmental health specialist.~~
~~* Water to be tested for potability.~~

* see plat for reserve

The sewage disposal system is to be constructed as specified by the permit ☒ or attached plans and specifications ☐.

This sewage disposal system construction permit is null and void if (a) conditions are changed from those shown on the application (b) conditions are changed from those shown on the construction permit.

No part of any installation shall be covered or used until inspected, corrections made if necessary, and approved, by the local health department or unless expressly authorized by the local health dept. Any part of any installation which has been covered prior to approval shall be uncovered, if necessary, upon the direction of the Department.

Date: 4/7/93 Issued by: _____ Sanitarian EHS

Date: 4/7/93 Reviewed by: _____ Supervisory Sanitarian

This Construction Permit Valid until 4/7/94

If FHA or VA financing

Reviewed by Date _____ _____ Supervisory Sanitarian Date _____ _____ Regional Sanitarian

C.H.S. 202B Revised 6/84

II-2A

FILE COPY

ROUTE SHEET

PERMIT I.D. NO. SD-93-143

Tag Sheet	Initials	Date
APPLICATION RECEIVED:	ASC	4/7/93
APPLICATION REVIEWED:	ASC	4/7/93
FEE DETERMINATION:	ASC	4/7/93
ASSIGNED TO:	CAJ	4/7/93
SITE VISIT SCHEDULED:	CAJ	4/6/93
SITE VISIT MADE:	CAJ	4/6/93
FOLLOW-UP VISIT:		
ISSUE/DENY DRAFTED:	CAJ	4/7/93
ISSUE/DENY REVIEWED:	JRY	4/14/93
ISSUE/DENY COUNTERSIGNED:	JRY	4/14/93
ISSUE/DENY - MAILED/PICKED UP	CAJ	4/8/93


COTTAGE
Bldg sewer
Front
PATIO
60'
45'
77'
99'

Sewage Disposal System Construction Permit

Commonwealth of Virginia
Department of Health
Fauquier Co Env. Health Department

Health Department Identification Number SD-93-655
Map Reference Subd.

General Information

New ☒ Repair ☐ Expanded ☐ Conditional ☐ FHA ☐ VA ☐ Case No. _____

Based on the application for a sewage disposal system construction permit filed in accordance with Section 3.13.01, a construction permit is hereby issued to:

Owner Fauquier County Solid Waste Telephone (703) 347-6800
Address 78 W Lee St., Ste 100, Warrenton VA 22186
For a Type I Sewage disposal system which is to be constructed on/at 295 @ LFCC/QCC entrance to landfill Bldg.
Subdivision Conrad Farm Landfill Section/Block — Lot —
Actual or estimated water use 150 gpd 1 BR EQUIVALENT

DESIGN	NOTE: INSPECTION RESULTS
Water supply, existing: (describe) N/A signs must be posted at all spigots stating Non-Potable **To be installed:** class IIIB Non Potable grout to be witnessed by H cased 50' min to Rock grouted 50' min to Rock	**Water supply location:** Satisfactory yes ☐ no ☐ comments G. W. 2 Received: yes ☐ no ☐ not applicable ☐
Building sewer: Install c/o at Fndt. 4" I.D. PVC 40, or equivalent. Slope 1.25" per 10' (minimum). ☐ Other smooth pipe to DB	**Building sewer:** yes ☐ no ☐ comments Satisfactory
Septic tank: Capacity 1000 gals. (minimum). ☒ Other No garbage Disposals	**Pretreatment unit:** yes ☐ no ☐ comments Satisfactory
Inlet-outlet structure: 8" in 8" out PVC 40, 4" tees or equivalent. ☒ Other Stub T's 1" Below Lids	**Inlet-outlet structure:** yes ☐ no ☐ comments Satisfactory
Pump and pump station: No ☒ Yes ☐ describe and show design. if yes:	**Pump & pump station:** yes ☐ no ☐ comments Satisfactory
Gravity mains: 4" or larger I.D., minimum 6" fall per 100', 1500 lb. crush strength or equivalent. ☐ Other	**Conveyance method:** yes ☐ no ☐ comments Satisfactory
Distribution box: Precast concrete with 5+ ports. ☒ Other Bed on 4" concrete PAD	**Distribution box:** yes ☐ no ☐ comments Satisfactory
Header lines: Material: 4" I.D. 1500 lb. crush strength plastic or equivalent from distribution box to 2' into absorption trench. Slope 2" minimum. ☐ Other	**Header lines:** yes ☐ no ☐ comments Satisfactory
Percolation lines: Gravity 4" plastic 1000 lb. per foot bearing load or equivalent, slope 2" 4" (min. max.) per 100'. ☐ Other	**Percolation lines:** yes ☐ no ☐ comments Satisfactory
Absorption trenches: Square ft. required 672: depth from ground surface to bottom of trench 48"; aggregate size 1/2 to 1 1/2: Trench bottom slope 2-4" per 100'; center to center spacing 9'; trench width 3 Depth of aggregate 13+"; Trench length 56; Number of trenches 4	**Absorption trenches:** yes ☐ no ☐ comments Satisfactory Date _____ Inspected and approved by: _____ Sanitarian

Health Department Identification Number SD-93-65-5

Schematic drawing of sewage disposal system and topographic features. PAGE 2 OF 2

Show the lot lines of the building lot and building site, sketch of property showing any topographic features which may impact on the design of the system, all existing and/or proposed structures including sewage disposal systems and wells within 100 feet of sewage disposal system and reserve area. The schematic drawing of the sewage disposal system shall show sewer lines, pretreatment unit, pump station, conveyance system, and subsurface soil absorption system, reserve area, etc. When a nonpublic drinking water supply is to be located on the same lot show all sources of pollution within 100 feet.

1BR EQUIV., 150gpd SEWAGE + NON-POTABLE WELL CORRAL FARM LANDFILL

☒ The information required above has been drawn on the attached copy of the sketch submitted with the application. Attach additional sheets as necessary to illustrate the design.

SEWAGE SYSTEM IS FOR EQUIPMENT WASH-DOWN AND RESTROOM FACILITIES ONLY. WATERLESS HAND-CLEANERS AND BOTTLED DRINKING WATER REQUIRED.

LANDFILL CELLS

THE SYSTEM TO BE INSTALLED BY THE AUTHORITY OF THIS PERMIT MUST CONFORM TO THE FAUQUIER COUNTY SANITATION AND/OR WELL ORDINANCES.



SEWAGE PERMIT REQUIREMENTS

* Drawing not to scale.
* Permit void if building location interferes with approved drainfield location.
* Designed for basement plumbing? YES NO
* Drainfield to be 100+' from Class IIIC wells and 50' from all Class IIIA&B wells.
* Install 4-56' lines, ON CONTOUR, in 3'-wide trenches, on 9' centers.
* Install trenches 48" deep.
* Smooth-walled header pipes recommended.
* Extend header pipes 24" into gravel.
* Use single size gravel 0.5" to 1.5" diam.
* No parking or driving on drainfield system
* Divert roof drains away from drainfield.
* No trees within 10' of system.
* Pump septic tank every 3 - 5 years.

WELL PERMIT REQUIREMENTS

* Install Class III B well 50-feet + away from drainfield, reserve, treated foundation and all sources of contamination.
* All well grouts to be witnessed by environmental health specialist.
* [redacted]
* water is for equipment cleaning + toilet-flushing only.

The sewage disposal system is to be constructed as specified by the permit ☒ or attached plans and specifications ☐.

This sewage disposal system construction permit is null and void if (a) conditions are changed from those shown on the application (b) conditions are changed from those shown on the construction permit.

No part of any installation shall be covered or used until inspected, corrections made if necessary, and approved, by the local health department or unless expressly authorized by the local health dept. Any part of any installation which has been covered prior to approval shall be uncovered, if necessary, upon the direction of the Department.

Date: 12/7/93 Issued by: [redacted] EHS John R. Largent Supervisory Sanitarian

Date: 12/7/93 Reviewed by:

This Construction Permit Valid until 12/7/94

If FHA or VA financing

Reviewed by Date _____ _____ Date _____ _____

Supervisory Sanitarian Regional Sanitarian

C.H.S. 202B Revised 6/84

II-2A

ORIGINAL

Commonwealth of Virginia
Application for a Sewage Disposal and/or Water Supply Permit

Health Department ID SD-93-655

To Be Completed By The Applicant

Type of sewage system: X New ___ Repair ___ Expanded ___ Conditional
FHA/VA yes ___ no X Case No ___

Owner Fauquier County Solid Waste Mgt. Address 70 W. Lee St Warrenton VA 22186 Phone 703-347-6500

Agent Ellis D. Bingham Solid Waste Manager Address same as above Phone 347-6120

Directions of Property Rt 29 S Council Town Landfill

Subdivision ___ Section ___ Block ___ Lot ___

Other Property Identification Council Town Landfill

Dimension/size of Lot/Property N/A

Other Application Information

I. **Building/facility** X New ___ Existing
Intermittent Use ___ Yes ___ No If yes, describe ___

II. **Residential Use** ___ Yes X No
Termite Treatment ___ Yes X No
___ Single Family (Number of Bedrooms ___) ___ Multi-family (Number of Units ___)

Basement ___ Yes X No
Fixtures in Basement ___ Yes X No

III. **Commerical Use** ___ Yes ___ No Describe: ___

Commerical/Wastewater X Yes ___ No Number of Patrons ___ Number of Employees 7

If yes, give volumes and describe Toilet facilities + equip. washing

IV. **Water Supply:** ___ Public ___ New ___ Existing
X Private X New ___ Existing
Describe: Non-Potable Well

V. **Proposed Sewage Disposal Method:**
Onsite Sewage Disposal System: X Septic Tank Drainfield ___ LPD ___ Mound ___ Other

Public Sewerage System

Attach a site plan (rough sketch) showing dimensions of property, proposed and/or existing structures and driveways, underground utilities, adjacent soil absorption system, bodies of water, drainage ways, and wells and springs within 200 feet radius of the center of the proposed well or drainfield. Distances may be paced or estimated.

The property lines and building location are clearly marked and the property is sufficiently visible to see the topography. I give permission to the Department to enter onto the property described for the purpose of processing this application.

Signature of Owner/Agent 11/12/93 Date

CHS 200

(A) SD 93 655

Soil Evaluation Form

PAGE 1 OF 4

Commonwealth of Virginia
Department of Health

Health Department
Identification Number SD-93-655
Tax Map Number subd.

General Information

Date 6/3/93 Fauquier Co Env Health Department

Applicant Draper Aden Associates Telephone No.

Address

Owner County of Fauquier Address Solid Waste Dept. 78 E Lee St. Warrenton VA

Location

Subdivision Carroll Farm Landfill Block/Section Lot

Soil Information Summary

1. Position in landscape satisfactory Yes ☒ No ☐ Describe sloping Ridgetop

2. Slope 2-3 %

3. Depth to rock/impervious strata Max. ____ Min. ____ None X

4. Depth to seasonal water table (gray mottling or gray color) No ☒ Yes ☐ ____ inches

5. Free water present No ☒ Yes ☐ ____ range in inches

6. Soil percolation rate estimated Yes ☒ Texture group I (II) (III) IV
No ☐ Estimated rate 45-55 min/inch

7. Percolation test performed Yes ☐ Number of percolation test holes ____
No ☒ Depth of percolation test holes ____
Average percolation rate ____

Name and title of evaluator: CA Jackson Jr EHS 05194 w/ Glen McCleary S.S.

Signature:

Department Use

☒ Site Approved: Drainfield to be placed at 48" depth at site designated on permit.

☐ Site Disapproved:

Reasons for rejection:

1. ☐ Position in landscape subject to flooding or periodic saturation.
2. ☐ Insufficient depth of suitable soil over hard rock.
3. ☐ Insufficient depth of suitable soil to seasonal water table.
4. ☐ Rates of absorption too slow.
5. ☐ Insufficient area of acceptable soil for required drainfield, and/or Reserve Area.
6. ☐ Proposed system too close to well.
7. ☐ Other Specify

Date of Evaluation 6/3/93

Profile Description
SOIL EVALUATION REPORT

Health Department Identification No. SD 93 655

Where the local health department conducts the soil evaluation the location of profile holes may be shown on the schematic drawing on the construction permit or the sketch submitted with the application. If soil evaluations are conducted by a private soil scientist, location of profile holes and sketch of the area investigated including all structural features i.e., sewage disposal systems, wells, etc., within 100 feet of site (See section 4) and reserve site shall be shown on the reverse side of this page or prepared on a separate page and attached to this form.

☐ See application sketch ☐ See construction permit ☐ See sketch on reverse side or page attached to this form.

Hole #	Horizon	Depth (Inches)	Description of, color, texture, etc.	Texture Group
			See attached consultants Report	

Remarks

Not to scale
TB = 48"

Soil Evaluation Form

Tax Map Number:_____ Health Department I.D. Number:_____

General Information

Date: *June 3, 1993* *Fauquier County* Health Department

Applicant: *Draper Aden Associates* Telephone Number: *(804) 870-7675*
Address: *4136 Innslake Driave, Glen Allen, Virginia 23060*
Owner: *Same* Address:_____

Location: *The Coral Farm, Route 29/15, Near Warrenton*

Subdivision:_____ Block/Section:_____ Site # *1*

Soil Information Summary

1. Position in landscape satisfactory Yes ☑ No ☐ Describe: *Sloping Ridgetop*

2. Slope *2-3* %

3. Depth to rock/inpervious strata Max. Min. None ☑

4. Depth to seasonal water table No ☑ Yes ☐ ____inches

5. Free water present No ☑ Yes ☐ range in inches:_____

6. Soil percolation rate estimated Yes ☑ Texture Group *II & III*
No ☐ Estimated Rate 35-40 minutes per inch

7. Percolation test performed Yes ☐ Number of percolation holes: n/a
No ☑ Depth of percolation test holes: n/a
Average percolation rate: n/a

Name and Title of Evaluators: Glen McClenny, VCPSS #3401-0049; Curtis Moore,Soil Scientist

Signatures: Glen E McClenny Curtis W. Moore

Department Use

☐ Site Approved: Drainfield to be placed at ____depth at site designated on permit.

☐ Site Disapproved:
Reasons for rejection:
1. ☐ Position in landscape subject to flooding or periodic saturation.
2. ☐ Insufficent depth to suitable soil over hard rock.
3. ☐ Insufficent depth to suitable soil to seasonal water table.
4. ☐ Rates of absorption too slow.
5. ☐ Insufficent area of acceptable soil for required drainfield, and/or Reserve Area.
6. ☐ Proposed system too close to well.
7. ☐ Other Specify_____

Date of Evaluation: *June 3, 1993*

Profile Descriptions

SOIL EVALUATION REPORT

Fauquier Landfill, Site #1

Where the local health department conducts the soil evaluation the location of profile holes may be shown on the schematic drawing on the construction permit or the sketch submitted with the application. If soil evaluations are conducted by a private soil scientist, location of profile notes and sketch of the area investigated including all structural features i.e., sewage disposal systems, wells, etc., within 100 feet of site (See section 4) and reserve site shall be shown on the reverse side of this page or prepared on a separate page and attached to this form.

☑ See sketch on page attached to this form.

HOLE #	HORIZON	DEPTH	DESCRIPTION OF COLOR, TEXTURE, ETC.	GROUP
1	A	0-6	5YR 3/4 Silt Loam, Friable	III
	Bt	6-26	2.5YR 4/6 Silty Clay Loam, Firm	III
	C	26-72	Mixed 2.5YR 4/8, 5/8, 6/8, 5YR 6/8, 6/6, 7/8 with few prominent 10YR 7/8, 2/1 mottles; Very Fine Sandy Loam, Very Friable	II
2	A	0-7	5YR 3/4 Silt Loam, Friable	III
	Bt	7-22	2.5YR 4/6 Light Silty Clay Loam, Friable to Firm	III
	BC	22-36	2.5YR 4/8, 5YR 5/8 Silt Loam, Friable	III
	C	36-72	5YR 5/6, 6/8, 7/8, 7.5YR 6/8, 7/8 Micaceous Fine Sandy Loam, Very Friable; few quartz gravel 54-60"	II
3	A	0-6	5YR 3/4 Silt Loam, Friable	III
	Bt	6-28	2.5YR 4/6 Light Silty Clay Loam, Friable to Firm	III
	C	28-72	5YR 5/8, 6/8, 7/8, 7.5YR 6/8, 7/8 Silt Loam to Very Fine Sandy Loam, Very Friable	II/III
4	A	0-5	5YR 3/3, 3/4 Silt Loam, Friable	III
	Bt	5-24	2.5YR 5/6, 5/8, 4/6 Light Silty Clay Loam to Clay Loam, Friable to Firm	III
	BC	24-36	2.5YR 4/6, 4/8, 5/8, 5YR 5/6, 5/8 Silt Loam, Friable	III
	C	36-72	2.5YR 4/8, 5/8, 6/8 with few prominent 10YR 7/8, 2/1, 2.5Y 4/4 parent mottles; Micaceous Silt Loam, Very Friable	III
5	A	0-6	5YR 3/4 Silt Loam, Friable	III
	Bt	6-24	5YR 5/6 Silty Clay Loam, Firm	III
	C	24-72	Mixed 2.5YR 4/6, 4/8, 5YR 5/6, 5/8, 6/8, 7/8 with few prominent 10YR 2/1, 7/8 parent mottles; Micaceous Fine Sandy Loam, Very Friable	II

REMARKS:

Trench Bottom: 48"

Area: 56' X 65'; Install 4, 56 foot lines on 9 foot centers, using 3 foot wide trenches, to yield enough drainfield for 320 gallons per day usage (based on a 40 mpi). The reserve shall be the remaining 4, 56 foot lines. Service District (100% Reserve)

COMMONWEALTH OF VIRGINIA
Department of Health

T 029179

PCMS Pt. # _____

Health Department Date: 12/2/93

Received of: Doe Co. County of Hanover
Four Hundred Dollars $ 400.00 CASH ☐

For: Lot Cert + Inspect Local Use: _____ CHECK ☑

Services Given For: Conrad Farm MONEY ORDER ☐

Received By: P. Ramey

Codes	Amt.	Codes	Amt.
116	$ 50.00		$
119	$ 25.00		$
345	$ 325.00		$

ADM-1304 REV. 10/91



COMMONWEALTH of VIRGINIA

IN COOPERATION WITH THE
STATE DEPARTMENT OF HEALTH

Fauquier County Health Department
ENVIRONMENTAL HEALTH
320 HOSPITAL DRIVE - SUITE 21
WARRENTON, VIRGINIA 22186

November 9, 1993

Mr. Ellis Bingham, Solid Waste Manager
County of Fauquier
78 W. Lee Street
Warrenton, Virginia 22186

RE: Sewage Disposal Permit - Corral Farm Sanitary Landfill

Dear Mr. Bingham:

This letter is written in response to your permit for the above referenced proposal. This office has approved the site plan which included the lot certification for the sewage disposal system and non-potable water supply on 11/8/93. However, before we can issue a permit for the above, your office needs to submit the following fees ($150, lot certification and $250, well and septic) and the enclosed (completed) application.

Once this has been done, this office will proceed with the issuance of the permit as expeditiously as possible. In the interim, if this office can be of further assistance, please call (703) 347-6369.

Sincerely,

C.A. Jackson Jr.
Environmental Health Specialist

INSERT OVERSIZED HERE

FIELD OFFICE: FAUQUIER

BOX #: 114

TAX MAP #: 6983-81-0145

MAP SEQUENCE #: 001

Appendix III: Regulatory Records Documentation

8499 BINGHAM RD
8499 BINGHAM RD
WARRENTON, VA 20187

Inquiry Number: 7085107.2s
August 12, 2022

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	220
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527-21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

8499 BINGHAM RD
WARRENTON, VA 20187

COORDINATES

Latitude (North):	38.6804930 - 38ˆ 40' 49.77''
Longitude (West):	77.7866350 - 77ˆ 47' 11.88''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	257591.7
UTM Y (Meters):	4284800.0
Elevation:	531 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	13911450 WARRENTON, VA
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20140816
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
8499 BINGHAM RD
WARRENTON, VA 20187

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	FAUQUIER COUNTY HHW	6438 COLLEGE ST	PA MANIFEST	Higher	682, 0.129, East
A2	CORRAL FARM WASTE MA	6438 COLLEGE ST	VA SWF/LF, VA SPILLS, VA ENF, VA Financial...	Higher	682, 0.129, East
A3	FAUQUIER COUNTY HHW	6438 COLLEGE STREET	RCRA-VSQG	Higher	682, 0.129, East

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Lists of Federal RCRA generators

RCRA-LQG ---------- RCRA - Large Quantity Generators
RCRA-SQG ---------- RCRA - Small Quantity Generators

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

EXECUTIVE SUMMARY

Federal ERNS list

ERNS ---------- Emergency Response Notification System

Lists of state- and tribal hazardous waste facilities

VA SHWS ---------- This state does not maintain a SHWS list. See the Federal CERCLIS list and Federal NPL list.

Lists of state and tribal leaking storage tanks

VA LUST ---------- Leaking Underground Storage Tank Tracking Database
INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
VA LTANKS ---------- Leaking Petroleum Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ---------- Underground Storage Tank Listing
VA UST ---------- Registered Petroleum Storage Tanks
VA AST ---------- Registered Petroleum Storage Tanks
INDIAN UST ---------- Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

VA ENG CONTROLS ---------- Engineering Controls Sites Listing
VA INST CONTROL ---------- Voluntary Remediation Program Database

Lists of state and tribal voluntary cleanup sites

VA VCP ---------- Voluntary Remediation Program
INDIAN VCP ---------- Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

VA BROWNFIELDS ---------- Brownfields Site Specific Assessments

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
ODI ---------- Open Dump Inventory
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register
US CDL ---------- National Clandestine Laboratory Register

EXECUTIVE SUMMARY

Local Land Records

LIENS 2 ---------- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---------- Hazardous Materials Information Reporting System
VA SPILLS 90 ---------- SPILLS 90 data from FirstSearch

Other Ascertainable Records

RCRA NonGen / NLR ---------- RCRA - Non Generators / No Longer Regulated
FUDS ---------- Formerly Used Defense Sites
DOD ---------- Department of Defense Sites
SCRD DRYCLEANERS ---------- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---------- Financial Assurance Information
EPA WATCH LIST ---------- EPA WATCH LIST
2020 COR ACTION ---------- 2020 Corrective Action Program List
TSCA ---------- Toxic Substances Control Act
TRIS ---------- Toxic Chemical Release Inventory System
SSTS ---------- Section 7 Tracking Systems
ROD ---------- Records Of Decision
RMP ---------- Risk Management Plans
RAATS ---------- RCRA Administrative Action Tracking System
PRP ---------- Potentially Responsible Parties
PADS ---------- PCB Activity Database System
ICIS ---------- Integrated Compliance Information System
FTTS ---------- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---------- Material Licensing Tracking System
COAL ASH DOE ---------- Steam-Electric Plant Operation Data
COAL ASH EPA ---------- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---------- PCB Transformer Registration Database
RADINFO ---------- Radiation Information Database
HIST FTTS ---------- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---------- Incident and Accident Data
CONSENT ---------- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---------- Indian Reservations
FUSRAP ---------- Formerly Utilized Sites Remedial Action Program
UMTRA ---------- Uranium Mill Tailings Sites
LEAD SMELTERS ---------- Lead Smelter Sites
US AIRS ---------- Aerometric Information Retrieval System Facility Subsystem
US MINES ---------- Mines Master Index File
ABANDONED MINES ---------- Abandoned Mines
FINDS ---------- Facility Index System/Facility Registry System
DOCKET HWC ---------- Hazardous Waste Compliance Docket Listing
ECHO ---------- Enforcement & Compliance History Information
UXO ---------- Unexploded Ordnance Sites
FUELS PROGRAM ---------- EPA Fuels Program Registered Listing
VA AIRS ---------- Permitted Airs Facility List
VA NPDES ---------- Comprehensive Environmental Data System
VA COAL ASH ---------- Coal Ash Disposal Sites
VA DRYCLEANERS ---------- Drycleaner List
VA TIER 2 ---------- Tier 2 Information Listing

VA UIC ---------- Underground Injection Control Wells
MINES MRDS ---------- Mineral Resources Data System

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP ---------- EDR Proprietary Manufactured Gas Plants
EDR Hist Auto ---------- EDR Exclusive Historical Auto Stations
EDR Hist Cleaner ---------- EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

VA RGA LF ---------- Recovered Government Archive Solid Waste Facilities List
VA RGA LUST ---------- Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal RCRA generators

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 06/20/2022 has revealed that there is 1 RCRA-VSQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FAUQUIER COUNTY HHW EPA ID:: VAR000517722	6438 COLLEGE STREET	E 1/8 - 1/4 (0.129 mi.)	A3	209

Lists of state and tribal landfills and solid waste disposal facilities

VA SWF/LF: The Solid Waste Management Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Department of Environmental Quality's Permitted Facilities list.

A review of the VA SWF/LF list, as provided by EDR, and dated 02/25/2022 has revealed that there is 1 VA SWF/LF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CORRAL FARM WASTE MA	***6438 COLLEGE ST***	***E 1/8 - 1/4 (0.129 mi.)***	***A2***	***10***
Permit Number: PBR625 Permit Number: SWP149 Permit Number: SWP575 Permit Number: PBR528 pmt_stat: Permitted pmt_stat: Revoked				

ADDITIONAL ENVIRONMENTAL RECORDS

Other Ascertainable Records

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there is 1 PA MANIFEST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FAUQUIER COUNTY HHW Generator EPA Id: VAR000517722	6438 COLLEGE ST	E 1/8 - 1/4 (0.129 mi.)	A1	8

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 1 records.

Site Name	Database(s)
NEW BALTIMORE FIRE DEPT (COMPANY 1	VA LUST

OVERVIEW MAP - 7085107.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites

0 1/4 1/2 1 Miles

- Indian Reservations BIA
- Power transmission lines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	8499 BINGHAM RD	CLIENT:	ECS Mid Atlantic, LLC
ADDRESS:	8499 BINGHAM RD WARRENTON VA 20187	CONTACT:	Joshua Allen Peckham
LAT/LONG:	38.680493 / 77.786635	INQUIRY #:	7085107.2s
		DATE:	August 12, 2022 11:54 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 7085107.2S

0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 8499 BINGHAM RD	CLIENT: ECS Mid Atlantic, LLC
ADDRESS: 8499 BINGHAM RD WARRENTON VA 20187	CONTACT: Joshua Allen Peckham
LAT/LONG: 38.680493 / 77.786635	INQUIRY #: 7085107.2s DATE: August 12, 2022 11:54 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		0	0	NR	NR	NR	0
RCRA-VSQG	0.250		0	1	NR	NR	NR	1
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
VA SHWS	N/A		N/A	N/A	N/A	N/A	N/A	N/A
Lists of state and tribal landfills and solid waste disposal facilities								
VA SWF/LF	0.500		0	1	0	NR	NR	1
Lists of state and tribal leaking storage tanks								
VA LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
INDIAN LUST	0.500		0	0	0	NR	NR	0
VA LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
VA UST	0.250		0	0	NR	NR	NR	0
VA AST	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
VA ENG CONTROLS	0.500		0	0	0	NR	NR	0
VA INST CONTROL	0.500		0	0	0	NR	NR	0
Lists of state and tribal voluntary cleanup sites								
VA VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
VA BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
VA SPILLS	TP		NR	NR	NR	NR	NR	0
VA SPILLS 90	TP		NR	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		0	0	NR	NR	NR	0
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
VA AIRS	TP		NR	NR	NR	NR	NR	0
VA NPDES	TP		NR	NR	NR	NR	NR	0
VA COAL ASH	0.500		0	0	0	NR	NR	0
VA DRYCLEANERS	0.250		0	0	NR	NR	NR	0
VA ENF	TP		NR	NR	NR	NR	NR	0
VA Financial Assurance	TP		NR	NR	NR	NR	NR	0
PA MANIFEST	0.250		0	1	NR	NR	NR	1
VA TIER 2	TP		NR	NR	NR	NR	NR	0
VA UIC	TP		NR	NR	NR	NR	NR	0
MINES MRDS	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
VA RGA LF	TP		NR	NR	NR	NR	NR	0
VA RGA LUST	TP		NR	NR	NR	NR	NR	0
- Totals --		0	0	3	0	0	0	3

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

N/A = This State does not maintain a SHWS list. See the Federal CERCLIS list.

A1
East
1/8-1/4
0.129 mi.
682 ft.

FAUQUIER COUNTY HHW
6438 COLLEGE ST
WARRENTON, VA 20187

Site 1 of 3 in cluster A

PA MANIFEST **S123094923**
N/A

Relative:
Higher

Actual:
579 ft.

Manifest Details:

Year:	2017
Manifest Number:	015831253JJK
Manifest Type:	TSD Copy
Generator EPA Id:	VAR000517722
Generator Date:	10/21/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D004
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	70
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

Year:	2017
Manifest Number:	015831253JJK
Manifest Type:	TSD Copy
Generator EPA Id:	VAR000517722
Generator Date:	10/21/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	P037
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	70
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822

FAUQUIER COUNTY HHW (Continued) **S123094923**

Date TSP Sig:	Not reported
Year:	2017
Manifest Number:	015831253JJK
Manifest Type:	TSD Copy
Generator EPA Id:	VAR000517722
Generator Date:	10/21/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	P044
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	70
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported
Year:	2017
Manifest Number:	015831253JJK
Manifest Type:	TSD Copy
Generator EPA Id:	VAR000517722
Generator Date:	10/21/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D020
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	70
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

A2
East
1/8-1/4
0.129 mi.
682 ft.

CORRAL FARM WASTE MANAGEMENT FACILITY
6438 COLLEGE ST
WARRENTON, VA 20187

Site 2 of 3 in cluster A

VA SWF/LF **S107678802**
VA SPILLS **N/A**
VA ENF
VA Financial Assurance

Relative:
Higher

Actual:
579 ft.

SWF/LF:

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Permit Number:	PBR625
Unit Name:	Transfer Station
Unit Status Code:	Not reported
Deq Region:	Northern Regional Office
Mailing Address:	6438 College St
Mailing Address 2:	Not reported
Mailing Address 3:	Not reported
Mailing City,St,Zip:	Warrenton, VA 20187
Facility Telephone:	Not reported
Decimal Longitude:	Not reported
Lat/Long (dms):	38 40 48.86 / -77 46 45.65
Owner Name:	Not reported
Operator Name:	Not reported
Unit Status Description:	Transfer Station - Active
Payment ID:	Not reported

Permit:

Permit Number:	PBR625
Unit Description:	Corral Farm Transfer Station
FIC Description:	Fauquier County
Permit Event Desc:	Financial Assurance Compliance Letter Issued
Permit Event Complete Date:	1/24/2019

Permit Number:	PBR625
Unit Description:	Corral Farm Transfer Station
FIC Description:	Fauquier County
Permit Event Desc:	Financial Assurance Annual Update Submitted
Permit Event Complete Date:	1/4/2021

Permit Number:	PBR625
Unit Description:	Corral Farm Transfer Station
FIC Description:	Fauquier County
Permit Event Desc:	Financial Assurance Annual Update Submitted
Permit Event Complete Date:	12/12/2017

Permit Number:	PBR625
Unit Description:	Corral Farm Transfer Station
FIC Description:	Fauquier County
Permit Event Desc:	Financial Assurance Annual Update Submitted
Permit Event Complete Date:	12/26/2019

Permit Number:	PBR625
Unit Description:	Corral Farm Transfer Station
FIC Description:	Fauquier County
Permit Event Desc:	Financial Assurance Annual Update Submitted
Permit Event Complete Date:	12/28/2018

Permit Number:	PBR625

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Unit Description: Corral Farm Transfer Station
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/12/2018

Permit Number: PBR625
Unit Description: Corral Farm Transfer Station
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/5/2020

Permit Number: PBR625
Unit Description: Corral Farm Transfer Station
FIC Description: Fauquier County
Permit Event Desc: Notice of Intent received
Permit Event Complete Date: 7/31/2017

Permit Number: PBR625
Unit Description: Corral Farm Transfer Station
FIC Description: Fauquier County
Permit Event Desc: Application received
Permit Event Complete Date: 8/16/2017

Permit Number: PBR625
Unit Description: Corral Farm Transfer Station
FIC Description: Fauquier County
Permit Event Desc: Completeness Review
Permit Event Complete Date: 8/23/2017

Permit Number: PBR625
Unit Description: Corral Farm Transfer Station
FIC Description: Fauquier County
Permit Event Desc: Application revision received
Permit Event Complete Date: 8/29/2017

Permit Number: PBR625
Unit Description: Corral Farm Transfer Station
FIC Description: Fauquier County
Permit Event Desc: Application revision received
Permit Event Complete Date: 9/12/2017

Permit Number: PBR625
Unit Description: Corral Farm Transfer Station
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Cost Estimate Approved
Permit Event Complete Date: 9/18/2017

Permit Number: PBR625
Unit Description: Corral Farm Transfer Station
FIC Description: Fauquier County
Permit Event Desc: Permit issued
Permit Event Complete Date: 9/22/2017

Permit Number: PBR625
Unit Description: Corral Farm Transfer Station
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Event Complete Date: 9/25/2017

Name: CORRAL FARM WASTE MANAGEMENT FACILITY
Address: 6438 COLLEGE ST
Address 2: Not reported
Address 3: Not reported
City,State,Zip: WARRENTON, VA 20187
Permit Number: SWP149
Unit Name: Sanitary Landfill
Unit Status Code: Not reported
Deq Region: Northern Regional Office
Mailing Address: 6438 College St
Mailing Address 2: Not reported
Mailing Address 3: Not reported
Mailing City,St,Zip: Warrenton, VA 20187
Facility Telephone: Not reported
Decimal Longitude: Not reported
Lat/Long (dms): 38 40 54.16 / -77 46 48.58
Owner Name: Not reported
Operator Name: Not reported
Unit Status Description: Sanitary Landfill - Inactive
Payment ID: Not reported

Permit:
Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Response Received
Permit Event Complete Date: 1/10/2008

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/11/2008

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 1/16/2007

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/16/2014

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/17/2007

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Event Desc: Financial Assurance Cost Estimate Sent to Region
Permit Event Complete Date: 1/17/2007

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/19/2006

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Mechanism Submitted
Permit Event Complete Date: 1/2/2003

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Finalizing permit,respond to comments
Permit Event Complete Date: 1/23/2001

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW monitoring report received
Permit Event Complete Date: 1/24/2003

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/24/2019

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Cost Estimate Sent to Region
Permit Event Complete Date: 1/25/2010

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/30/2009

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 1/4/2021

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/5/2015

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Cost Estimate Sent to Region
Permit Event Complete Date: 11/16/2005

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Technically adequate,drafting permit
Permit Event Complete Date: 11/3/2000

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Public notice-draft permit issued
Permit Event Complete Date: 11/9/2000

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/12/2017

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/13/2012

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Mechanism Submitted
Permit Event Complete Date: 12/16/2009

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/18/2015

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 12/18/2015

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/19/2011

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 12/2/2012

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/22/2008

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/26/2019

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/27/2004

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/27/2007

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/27/2010

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/28/2016

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/28/2018

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 12/29/2004

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/29/2014

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 12/29/2016

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/30/2013

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/31/2003

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: PUBLIC HEARING DATE
Permit Event Complete Date: 12/7/2000

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/9/2005

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/1/2011

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Mechanism Submitted
Permit Event Complete Date: 2/10/2003

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/12/2018

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Ten year permit review completed
Permit Event Complete Date: 2/14/2001

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Event Desc: Annual GW monitoring report received
Permit Event Complete Date: 2/17/2006

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW monitoring report received
Permit Event Complete Date: 2/20/2007

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Permit issued
Permit Event Complete Date: 2/4/1974

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/5/2010

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/5/2020

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual Groundwater Report Acknowledgement
Permit Event Complete Date: 2/7/2008

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 3/7/2003

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW monitoring report received
Permit Event Complete Date: 4/4/2000

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 4/4/2012

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Approved
Permit Event Complete Date: 5/15/2008

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Review Letter Sent
Permit Event Complete Date: 5/15/2008

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 6/14/2004

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Approved
Permit Event Complete Date: 6/20/2006

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Review Letter Sent
Permit Event Complete Date: 6/20/2006

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Approved
Permit Event Complete Date: 8/1/2007

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Review Letter Sent
Permit Event Complete Date: 8/1/2007

Permit Number: SWP149
Unit Description: Fauquier County Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 8/6/2013

Name: CORRAL FARM WASTE MANAGEMENT FACILITY
Address: 6438 COLLEGE ST
Address 2: Not reported
Address 3: Not reported
City,State,Zip: WARRENTON, VA 20187
Permit Number: SWP575
Unit Name: Sanitary Landfill
Unit Status Code: Not reported
Deq Region: Northern Regional Office
Mailing Address: 6438 College St
Mailing Address 2: Not reported
Mailing Address 3: Not reported
Mailing City,St,Zip: Warrenton, VA 20187
Facility Telephone: Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Decimal Longitude: Not reported
Lat/Long (dms): 38 40 38.99 / -77 46 44.58
Owner Name: Not reported
Operator Name: Not reported
Unit Status Description: Sanitary Landfill - Active
Payment ID: Not reported

Permit:

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Response Received
Permit Event Complete Date: 1/10/2008

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/11/2008

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 1/16/2007

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/16/2014

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/17/2007

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Cost Estimate Sent to Region
Permit Event Complete Date: 1/17/2007

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/19/2006

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Mechanism Submitted
Permit Event Complete Date: 1/2/2003

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

FIC Description: Fauquier County
Permit Event Desc: Annual GW monitoring report received
Permit Event Complete Date: 1/24/2003

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/24/2019

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Cost Estimate Sent to Region
Permit Event Complete Date: 1/25/2010

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: CTO inspection conducted
Permit Event Complete Date: 1/27/2006

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/30/2009

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 1/4/2021

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/5/2015

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Cost Estimate Sent to Region
Permit Event Complete Date: 11/16/2005

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/12/2017

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/13/2012

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/16/2009

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/18/2015

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 12/18/2015

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/19/2011

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/22/2008

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: CQA report review
Permit Event Complete Date: 12/26/2002

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/26/2019

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: CTO issued
Permit Event Complete Date: 12/27/2002

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/27/2004

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/27/2007

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/27/2010

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 12/27/2012

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/28/2016

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/28/2018

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 12/29/2004

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: CQA report received
Permit Event Complete Date: 12/29/2005

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/29/2014

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 12/29/2016

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/30/2013

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/31/2003

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/9/2005

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/1/2011

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Mechanism Submitted
Permit Event Complete Date: 2/10/2003

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/12/2018

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW monitoring report received
Permit Event Complete Date: 2/17/2006

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: CTO issued
Permit Event Complete Date: 2/2/2006

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW monitoring report received
Permit Event Complete Date: 2/20/2007

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/5/2010

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/5/2020

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Installation report received
Permit Event Complete Date: 2/8/2002

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW monitoring report received
Permit Event Complete Date: 2/8/2008

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Ten year permit review completed
Permit Event Complete Date: 3/16/2004

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 3/7/2003

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: CQA report received
Permit Event Complete Date: 4/29/2013

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 4/4/2012

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: OWP Acknowledgement Letter Sent
Permit Event Complete Date: 4/9/2002

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: CTO inspection conducted
Permit Event Complete Date: 5/17/2013

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: CTO issued
Permit Event Complete Date: 5/22/2013

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 6/14/2004

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Approved
Permit Event Complete Date: 7/26/2006

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Review Letter Sent
Permit Event Complete Date: 7/26/2006

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Approved
Permit Event Complete Date: 7/9/2008

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Review Letter Sent
Permit Event Complete Date: 7/9/2008

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Approved
Permit Event Complete Date: 8/1/2007

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Annual GW Report Review Letter Sent
Permit Event Complete Date: 8/1/2007

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 8/6/2013

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: CTO inspection conducted
Permit Event Complete Date: 9/12/2002

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Event Desc: CQA report received
Permit Event Complete Date: 9/17/2002

Permit Number: SWP575
Unit Description: Corral Farm Sanitary Landfill
FIC Description: Fauquier County
Permit Event Desc: Permit issued
Permit Event Complete Date: 9/23/1994

Name: CORRAL FARM WASTE MANAGEMENT FACILITY
Address: 6438 COLLEGE ST
Address 2: Not reported
Address 3: Not reported
City,State,Zip: WARRENTON, VA 20187
Permit Number: PBR528
Unit Name: Materials Recovery Facility
Unit Status Code: Not reported
Deq Region: Northern Regional Office
Mailing Address: 6438 College St
Mailing Address 2: Not reported
Mailing Address 3: Not reported
Mailing City,St,Zip: Warrenton, VA 20187
Facility Telephone: Not reported
Decimal Longitude: Not reported
Lat/Long (dms): 38 40 40.85 / -77 46 55.89
Owner Name: Not reported
Operator Name: Not reported
Unit Status Description: Materials Recovery Facility - Clean Closed
Payment ID: Not reported

Permit:
Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Response Received
Permit Event Complete Date: 1/10/2008

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/11/2008

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Permit revoked
Permit Event Complete Date: 1/13/2022

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/16/2014

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/24/2019

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Cost Estimate Sent to Region
Permit Event Complete Date: 1/25/2010

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Cost Estimate Sent to Region
Permit Event Complete Date: 1/29/2009

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/30/2009

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 1/4/2021

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 1/5/2015

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Permit issued
Permit Event Complete Date: 11/29/2006

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/12/2017

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/13/2012

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Mechanism Submitted
Permit Event Complete Date: 12/16/2009

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/18/2015

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 12/18/2015

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/19/2011

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/22/2008

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/26/2019

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/27/2010

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 12/27/2012

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/28/2016

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/28/2018

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/29/2014

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 12/29/2016

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 12/30/2013

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/1/2011

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/12/2018

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Annual Update Submitted
Permit Event Complete Date: 2/27/2007

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/5/2010

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 2/5/2020

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 4/4/2012

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Application received
Permit Event Complete Date: 7/27/2006

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Application revision received
Permit Event Complete Date: 8/28/2006

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Financial Assurance Compliance Letter Issued
Permit Event Complete Date: 8/6/2013

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: OWP Acknowledgement Sent
Permit Event Complete Date: 8/9/2006

Permit Number: PBR528
Unit Description: Fauquier County CDD MRF
FIC Description: Fauquier County
Permit Event Desc: Review-1
Permit Event Complete Date: 8/9/2006

SPILLS:
Name: FAQUIER COUNTY SOLID WASTE MANAGMENT FACILITY '
Address: 6438 COLLEGE ST.
City,State,Zip: WARRENTON, VA 20187
City,State,Zip: WARRENTON, VA 20187
Fips City/County: 061/Fauquier County
Status: Closed
Reference Id: 66774
IR Number: 2017-N-0363
Associated IR: Not reported
Incident Date: 07/12/2016
Call Received Date: 07/13/2016
Closure Comments: Spill Cleaned up, material taken to Reco for disposal
Threat To: Not reported
Terrorism (Y/N): N
Characterize Incident: Accidental
Incident Type: Petroleum(Petroleum), Surface Spill(Petroleum)
Incident Subtype: Petroleum * Surface Spill
Materials: Not reported
Effect To Receptor: Not reported
Water Body: Not reported
Low Quantity To Water: Not reported
High Quantity To Water: Not reported
Quantity Units: Not reported
Other Receptors: Not reported
RP Company: Fauquier County Solid Waste Managment Facility
RP Name: Not reported
Property Owner: Not reported
Property Company: Not reported
Duration Of Event (Hrs): 0
Impacts: Not reported
Other Impacts: Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Steps Taken:	Not reported
Steps Taken Description:	Not reported
System Components:	Not reported
Other System Components:	Not reported
Cause Of Event:	Not reported
Corrective Action Taken:	Not reported
Weather Status:	No
Precipitation (Wet):	0
Discharge Type:	Not reported
Discharge Volume:	0
Unknown Discharge (Y/N):	N
Site Name:	FAUQUIER LANDFILL-DIESEL SPILL
Closure Date:	08/01/2016
Orig. Call Incident Description:	A truck hit a rock and spill 75 gallons of diesel in Cell 1 of the Landfill
Original Call Material Description:	Diesel
Original Call Location Description:	SWP575 6438 College St. Warrenton, 20187
Incident Ongoing at time of Call:	No
Agencies Notified (Y/N):	Not reported
Other Agencies:	Not reported
Permitted (Y/N):	Yes
Call Reported By Company Name:	Fauquier County Solid Waste Managment Facility
Call Property Owner Company Name:	Not reported
Call Property Owner Name:	Not reported
Site Summary:	A truck hit a rock and spill 75 gallons of diesel in Cell 1 of the Landfill

ENFORCEMENT:

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Not reported
Location Address:	Not reported
Location Address 2:	Not reported
Location City,St,Zip:	Not reported
Solid Waste Facility Region:	Not reported
CEDS Site Id:	Not reported
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Not reported
Inspection Date:	Not reported
Inspection Event Code:	Not reported
Inspection Event Complete Date:	Not reported
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	VAR051470
Enforcement Action Number:	NR18-1209
Action:	NOTICE OF VIOLATION/NOV
Action Date:	12/13/2018
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	WATER

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	1/8/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	1/8/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	1/8/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	1/15/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	10/24/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/24/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Date:	10/24/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	11/2/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	10/9/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/9/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	10/9/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	10/17/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	12/6/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	12/6/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	12/6/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	12/13/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	2/13/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	2/13/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/14/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	8/28/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/28/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	8/28/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/31/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	8/8/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/8/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	8/8/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/23/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Ac
Inspection Date:	10/27/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/27/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Ac
Inspection Date:	10/27/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	11/4/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Ac
Inspection Date:	7/19/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	7/19/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Ac
Inspection Date:	7/19/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	7/26/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill
Inspection Date:	10/27/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/27/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill
Inspection Date:	7/19/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	7/19/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill
Inspection Date:	7/19/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	7/25/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	Northern Regional Office
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Sanitary Landfill [SW]
Inspection Date:	3/9/2010
Inspection Event Code:	SWLWCIR
Inspection Event Complete Date:	4/21/2010
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	Northern Regional Office
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Sanitary Landfill [SW]
Inspection Date:	12/10/2009
Inspection Event Code:	SWLWCIR
Inspection Event Complete Date:	1/21/2010
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Send warning letter w/CIR to facility
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	Northern Va. Regional Office
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Sanitary Landfill [S
Inspection Date:	05/15/06
Inspection Event Code:	SNOVWCIR
Inspection Event Complete Date:	Not reported
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Send NOV w/ CIR to facility
Flag:	WASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	Northern Va. Regional Office
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Sanitary Landfill [S
Inspection Date:	05/16/06
Inspection Event Code:	SNOVWCIR
Inspection Event Complete Date:	Not reported
Solid Waste Enf Effective Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Send NOV w/ CIR to facility
Flag:	WASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	ROUTE 29 TO COLLEGE STREET
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 2018
Solid Waste Facility Region:	Northern Va. Regional Office
CEDS Site Id:	522
Site Location:	Route 29 to College St
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Sanitary Landfill [S
Inspection Date:	02/08/06
Inspection Event Code:	SNOVWCIR
Inspection Event Complete Date:	Not reported
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Solid Waste Full Permit
Solid Waste Unit Name:	Fauquier County Landfill
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Send NOV w/ CIR to facility
Flag:	WASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	ROUTE 29 TO COLLEGE STREET
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 2018
Solid Waste Facility Region:	Northern Va. Regional Office
CEDS Site Id:	522
Site Location:	Route 29 to College St
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Sanitary Landfill [S
Inspection Date:	02/08/06
Inspection Event Code:	SNOVWCIR
Inspection Event Complete Date:	Not reported
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Solid Waste Full Permit
Solid Waste Unit Name:	Corral Farm Sanitary Landfill
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Send NOV w/ CIR to facility
Flag:	WASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Not reported
Location Address:	Not reported
Location Address 2:	Not reported
Location City,St,Zip:	Not reported
Solid Waste Facility Region:	Not reported
CEDS Site Id:	Not reported
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Not reported
Inspection Date:	Not reported
Inspection Event Code:	Not reported
Inspection Event Complete Date:	Not reported
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	VAR051470
Enforcement Action Number:	NR18-1209
Action:	NOTICE OF VIOLATION/NOV
Action Date:	12/13/2018
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	WATER
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	625
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	10/24/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/24/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	625
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	10/24/2018
Inspection Event Code:	SNDL

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Complete Date:	11/2/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	625
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	12/6/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	12/6/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	625
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	12/6/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	12/13/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	625
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	2/13/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	625
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	2/13/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/14/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	625
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Date:	6/11/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/11/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	625
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	6/11/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/19/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	625
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	8/8/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/8/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	625
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	8/8/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/15/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/24/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/24/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/24/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	10/31/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/3/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/3/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/3/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	10/4/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	2/13/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	2/13/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/20/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	6/11/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/11/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	6/11/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	6/27/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/27/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	6/27/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/28/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	8/28/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/28/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	8/28/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/29/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	8/8/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/8/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	PBR
Solid Permit Id (numeric Suffix):	528
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	8/8/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/14/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	Northern Regional Office
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Landfill Mining [SW]
Inspection Date:	2/10/2016
Inspection Event Code:	SNOVWCIR
Inspection Event Complete Date:	2/19/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	Northern Regional Office
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Sanitary Landfill [SW]
Inspection Date:	2/10/2016
Inspection Event Code:	SNOVWCIR
Inspection Event Complete Date:	2/19/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	Northern Regional Office
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Sanitary Landfill [SW]
Inspection Date:	5/30/2013
Inspection Event Code:	SWLWCIR
Inspection Event Complete Date:	6/12/2013
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Send warning letter w/CIR to facility
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	Northern Regional Office
CEDS Site Id:	522
Site Location:	Route 29 to College Street
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Sanitary Landfill [SW]
Inspection Date:	9/5/2012
Inspection Event Code:	SWLWCIR
Inspection Event Complete Date:	11/1/2012
Solid Waste Enf Effective Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Send warning letter w/CIR to facility
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	10/3/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/3/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	10/3/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	10/5/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	12/29/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	12/29/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	12/29/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	1/3/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	12/6/2017
Inspection Event Code:	INSPFAC

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Complete Date:	12/6/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	12/6/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	12/13/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	2/10/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/10/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	2/10/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/15/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	2/13/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Date:	2/13/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/20/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	4/10/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/10/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	4/10/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	4/17/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	4/26/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/26/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	4/26/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	5/5/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	6/27/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/27/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	6/27/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/29/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	8/28/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/28/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Active
Inspection Date:	8/28/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	9/6/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	10/24/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/24/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	10/24/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	11/5/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	6/11/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/11/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	6/11/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	8/8/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/8/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	149
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	8/8/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/27/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/24/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/24/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/24/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	11/7/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/27/2016
Inspection Event Code:	SWL
Inspection Event Complete Date:	3/31/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/3/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/3/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/3/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	10/6/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	12/29/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	12/29/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	12/29/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	1/3/2017
Solid Waste Enf Effective Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	12/6/2017
Inspection Event Code:	DATERESP
Inspection Event Complete Date:	1/3/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	12/6/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	12/6/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	12/6/2017
Inspection Event Code:	SDL
Inspection Event Complete Date:	1/22/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	2/10/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/10/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	2/10/2017
Inspection Event Code:	SNDL

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Complete Date:	2/21/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	2/13/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	2/13/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/22/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	4/10/2018
Inspection Event Code:	DATERESP
Inspection Event Complete Date:	4/24/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	4/10/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/10/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Date:	4/10/2018
Inspection Event Code:	SWL
Inspection Event Complete Date:	4/24/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	4/26/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/26/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	4/26/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	4/28/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	6/11/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/11/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	6/11/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/15/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	6/27/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/27/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	FAUQUIER COUNTY SOLID WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	SWP
Solid Permit Id (numeric Suffix):	575
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	6/27/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/29/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	6/27/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/27/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	6/27/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/29/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	7/19/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	7/19/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	7/19/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	7/25/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	7/2/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	7/2/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	7/2/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	7/8/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	8/28/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/28/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	8/28/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/31/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	8/8/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/8/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	8/8/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/23/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	1/8/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	1/8/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	1/8/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	1/25/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	10/24/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/24/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	10/24/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	11/5/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	10/27/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/27/2016
Solid Waste Enf Effective Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	10/27/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	11/15/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	10/3/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/3/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	10/3/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	10/5/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	10/9/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/9/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	10/9/2019
Inspection Event Code:	SNDL

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Complete Date:	10/18/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	12/29/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	12/29/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	12/29/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	1/3/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	12/6/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	12/6/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	12/6/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	12/13/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Date:	2/10/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/10/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	2/10/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/15/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	2/13/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	2/13/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/20/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	4/10/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/10/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	4/10/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	4/17/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	4/17/2019
Inspection Event Code:	DATERESP
Inspection Event Complete Date:	6/28/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	4/17/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/17/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	4/17/2019
Inspection Event Code:	SWL
Inspection Event Complete Date:	5/13/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	4/26/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/26/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	4/26/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	5/5/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	6/11/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/11/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	6/11/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	6/27/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/27/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	6/27/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/29/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	7/19/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	7/19/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	7/19/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	7/26/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	7/2/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	7/2/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	7/2/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	7/9/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	8/28/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/28/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	8/28/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	9/6/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	8/8/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/8/2018
Solid Waste Enf Effective Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	8/8/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/27/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	4/17/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/17/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	4/17/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	4/25/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	6/11/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/11/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	6/11/2018
Inspection Event Code:	SNDL

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Complete Date:	6/19/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	7/2/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	7/2/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	7/2/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	7/9/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	8/8/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/8/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Facility ID:	Not reported
Facility Name:	Corral Farm Transfer Station
Location Address:	8499 Bingham Road
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2189
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Transfer Station - Transfer Station - Active
Inspection Date:	8/8/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/15/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Date:	1/8/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	1/8/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	1/8/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	1/10/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/24/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/24/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/24/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	10/31/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/26/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/26/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/26/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	11/1/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/3/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/3/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/3/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	10/4/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/9/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/9/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	10/9/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	10/17/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	2/10/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/10/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	2/10/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/14/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	2/13/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	2/13/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/20/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	4/17/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/17/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	4/17/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	4/22/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	4/26/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/26/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	4/26/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	4/27/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	6/11/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/11/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	6/11/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	6/27/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/27/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	6/27/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/28/2017
Solid Waste Enf Effective Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	7/19/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	7/19/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	7/19/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	7/25/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	7/2/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	7/2/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	7/2/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	7/3/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	8/28/2017
Inspection Event Code:	INSPFAC

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Complete Date:	8/28/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	8/28/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/31/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	8/8/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	8/8/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County CDD MRF
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	2039
Site Location:	Adjacent to Corral Farm SLF #575
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County CDD MRF - Materials Recovery Facility - Active
Inspection Date:	8/8/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	8/14/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive
Inspection Date:	2/10/2016
Inspection Event Code:	Notice of
Inspection Event Complete Date:	2/19/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Fauquier County Landfill - Sanitary Landfill - Inactive

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Date:	2/10/2016
Inspection Event Code:	Notice of
Inspection Event Complete Date:	2/19/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	1/8/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	1/8/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	1/8/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	1/15/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/24/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/24/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/24/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	11/7/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/27/2016
Inspection Event Code:	DATERESP
Inspection Event Complete Date:	10/27/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/27/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/27/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/27/2016
Inspection Event Code:	SWL
Inspection Event Complete Date:	3/31/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/3/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/3/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/3/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	10/6/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/9/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	10/9/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	10/9/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	10/18/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	12/29/2016
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	12/29/2016
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	12/29/2016
Inspection Event Code:	SNDL
Inspection Event Complete Date:	1/3/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	12/6/2017
Inspection Event Code:	DATERESP
Inspection Event Complete Date:	1/3/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	12/6/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	12/6/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	12/6/2017
Inspection Event Code:	SDL
Inspection Event Complete Date:	1/22/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	2/10/2017
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/10/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	2/10/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/21/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	2/13/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	2/13/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	2/13/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	2/22/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	4/10/2018
Inspection Event Code:	DATERESP
Inspection Event Complete Date:	4/24/2018
Solid Waste Enf Effective Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	4/10/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/10/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	4/10/2018
Inspection Event Code:	SWL
Inspection Event Complete Date:	4/24/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	4/17/2019
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	4/17/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE
Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	4/17/2019
Inspection Event Code:	SNDL
Inspection Event Complete Date:	4/25/2019
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	4/26/2017
Inspection Event Code:	INSPFAC

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Inspection Event Complete Date:	4/26/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	4/26/2017
Inspection Event Code:	SNDL
Inspection Event Complete Date:	4/28/2017
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	6/11/2018
Inspection Event Code:	INSPFAC
Inspection Event Complete Date:	6/11/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
Address 2:	Not reported
Address 3:	Not reported
City,State,Zip:	WARRENTON, VA 20187
Facility ID:	Not reported
Facility Name:	Fauquier County Solid Waste Management Facility
Location Address:	6438 College Street
Location Address 2:	Not reported
Location City,St,Zip:	Warrenton, VA 20187
Solid Waste Facility Region:	NVRO
CEDS Site Id:	522
Site Location:	Not reported
Solid Permit Id (alpha Prefix):	Not reported
Solid Permit Id (numeric Suffix):	Not reported
Solid Waste Unit Type:	Corral Farm Sanitary Landfill - Sanitary Landfill - Active
Inspection Date:	6/11/2018
Inspection Event Code:	SNDL
Inspection Event Complete Date:	6/15/2018
Solid Waste Enf Effective Date:	Not reported
Solid Waste Enf Penalty Type:	Not reported
Solid Waste Enf Penalty Amount:	Not reported
Solid Waste Enf Type Desc:	Not reported
Solid Waste Unit Type:	Not reported
Solid Waste Unit Name:	Not reported
Haz. Waste Facility Region:	Not reported
Haz. Waste Facility Epaid:	Not reported
Haz. Waste Enforcement Date:	Not reported
Haz. Waste Enforcement Type:	Not reported
Haz. Waste Enforcement Agency:	Not reported
Haz. Waste Enf RCRIS Comments:	Not reported
Haz. Waste Penalty Type:	Not reported
Haz. Waste Enf Order Dt. Signed:	Not reported
Haz. Waste Enf Order Type:	Not reported
Haz. Waste Penalty Amount:	Not reported
Type Of Permit:	Not reported
Permit No:	Not reported
Enforcement Action Number:	Not reported
Action:	Not reported
Action Date:	Not reported
Civil Charges Assessed:	Not reported
Solid Waste Facility Description:	Not reported
Inspection Event Completed Dt:	Not reported
Inspection Event Description:	Not reported
Flag:	SOLIDWASTE

Financial Assurance 2:

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
City,State,Zip:	WARRENTON, VA 20187
Latitude:	38.68024

CORRAL FARM WASTE MANAGEMENT FACILITY (Continued) **S107678802**

Longitude:	-77.779348
Permit:	PBR625
Closure Estimate:	58104
Post Closure Estimate:	0
Corrective Action Estimate:	0
Total Estimate:	58104
Solid Waste Financial Mechanism Name:	Local Government Financial Test
Solid Permit Status:	Active
Permit Operating Status:	P
POS Effective Date:	09/22/2017
Solid Waste Facility Region:	Northern Virginia Regional Office

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
City,State,Zip:	WARRENTON, VA 20187
Latitude:	38.68171153
Longitude:	-77.78016278
Permit:	SWP149
Closure Estimate:	12089687
Post Closure Estimate:	11449100
Corrective Action Estimate:	85035
Total Estimate:	23623822
Solid Waste Financial Mechanism Name:	Local Government Financial Test
Solid Permit Status:	Inactive
Permit Operating Status:	P
POS Effective Date:	02/04/1974
Solid Waste Facility Region:	Northern Virginia Regional Office

Name:	CORRAL FARM WASTE MANAGEMENT FACILITY
Address:	6438 COLLEGE ST
City,State,Zip:	WARRENTON, VA 20187
Latitude:	38.677499
Longitude:	-77.779052
Permit:	SWP575
Closure Estimate:	7403140
Post Closure Estimate:	4959272
Corrective Action Estimate:	0
Total Estimate:	12362412
Solid Waste Financial Mechanism Name:	Local Government Financial Test
Solid Permit Status:	Active
Permit Operating Status:	P
POS Effective Date:	09/23/1994
Solid Waste Facility Region:	Northern Virginia Regional Office

---

A3 **FAUQUIER COUNTY HHW** **RCRA-VSQG** **1012189076**
East **6438 COLLEGE STREET** **VAR000517722**
1/8-1/4 **WARRENTON, VA 20187**
0.129 mi.
682 ft. **Site 3 of 3 in cluster A**

Relative: RCRA-VSQG:
Higher

Date Form Received by Agency:		20090710
Handler Name:	FAUQUIER COUNTY HHW	
Handler Address:		6438 COLLEGE STREET
Handler City,State,Zip:		WARRENTON, VA 20187
EPA ID:		VAR000517722
Contact Name:		MIKE DORSEY
Contact Address:		Not reported

Actual:
579 ft.

FAUQUIER COUNTY HHW (Continued) **1012189076**

Contact City,State,Zip:		Not reported
Contact Telephone:		540-347-6811
Contact Fax:		Not reported
Contact Email:		MIKE.DORSEY@FAUQUIERCOUNTY.GOV
Contact Title:		Not reported
EPA Region:		03
Land Type:		County
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		VA
State District:		4
Mailing Address:		6438 COLLEGE STREET
Mailing City,State,Zip:		WARRENTON, VA 20187
Owner Name:	FAUQUIER COUNTY	
Owner Type:		County
Operator Name:	POLLUTION CONTROL INDUSTRIES, INC.	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No

FAUQUIER COUNTY HHW (Continued) **1012189076**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: FAUQUIER COUNTY	
Legal Status:	County
Date Became Current:	19940923
Date Ended Current:	Not reported
Owner/Operator Address:	6438 COLLEGE STREET
Owner/Operator City,State,Zip:	WARRENTON, VA 20187
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: POLLUTION CONTROL INDUSTRIES, INC.	
Legal Status:	Private
Date Became Current:	20090708
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20051006
Handler Name: FAUQUIER CO. LANDFILL-DEPT.OF ENV. SERV.	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	VA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

FAUQUIER COUNTY HHW (Continued) **1012189076**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090710
Handler Name: FAUQUIER COUNTY HHW
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: VA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 562111
NAICS Description: SOLID WASTE COLLECTION

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - General
Date Violation was Determined: 20050909
Actual Return to Compliance Date: 20051214
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Y01
Date of Enforcement Action: 20051109
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INSPECTOR FACT FINDING LETTER - Warning letter
Enforcement Responsible Person: R4MNR
Enforcement Responsible Sub-Organization: NR
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported

FAUQUIER COUNTY HHW (Continued) **1012189076**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - General
Date Violation was Determined: 20050909
Actual Return to Compliance Date: 20051214
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Y01
Date of Enforcement Action: 20051109
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INSPECTOR FACT FINDING LETTER - Warning letter
Enforcement Responsible Person: R4MNR
Enforcement Responsible Sub-Organization: NR
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - General
Date Violation was Determined: 20050909
Actual Return to Compliance Date: 20051214
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Y01
Date of Enforcement Action: 20051109
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

FAUQUIER COUNTY HHW (Continued) **1012189076**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INSPECTOR FACT FINDING LETTER - Warning letter
Enforcement Responsible Person: R4MNR
Enforcement Responsible Sub-Organization: NR
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - General
Date Violation was Determined: 20050909
Actual Return to Compliance Date: 20051214
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Y01
Date of Enforcement Action: 20051108
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INSPECTOR FACT FINDING LETTER - Warning letter
Enforcement Responsible Person: R4MNR
Enforcement Responsible Sub-Organization: NR
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported

FAUQUIER COUNTY HHW (Continued) **1012189076**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20050909
Actual Return to Compliance Date: 20051214
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Y01
Date of Enforcement Action: 20051108
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INSPECTOR FACT FINDING LETTER - Warning letter
Enforcement Responsible Person: R4MNR
Enforcement Responsible Sub-Organization: NR
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - General
Date Violation was Determined: 20050909
Actual Return to Compliance Date: 20051214
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Y01
Date of Enforcement Action: 20051108
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

FAUQUIER COUNTY HHW (Continued) **1012189076**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INSPECTOR FACT FINDING LETTER - Warning letter
Enforcement Responsible Person: R4MNR
Enforcement Responsible Sub-Organization: NR
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - General
Date Violation was Determined: 20050909
Actual Return to Compliance Date: 20051214
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Y01
Date of Enforcement Action: 20051108
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INSPECTOR FACT FINDING LETTER - Warning letter
Enforcement Responsible Person: R4MNR
Enforcement Responsible Sub-Organization: NR
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported

FAUQUIER COUNTY HHW (Continued) **1012189076**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20050909
Actual Return to Compliance Date: 20051214
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Y01
Date of Enforcement Action: 20051109
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INSPECTOR FACT FINDING LETTER - Warning letter
Enforcement Responsible Person: R4MNR
Enforcement Responsible Sub-Organization: NR
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20050909
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R4MNR
Evaluation Responsible Sub-Organization: NR
Actual Return to Compliance Date: 20051214
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20050909
Evaluation Responsible Agency: State

FAUQUIER COUNTY HHW (Continued) **1012189076**

Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R4MNR
Evaluation Responsible Sub-Organization:	NR
Actual Return to Compliance Date:	20051214
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20050909
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R4MNR
Evaluation Responsible Sub-Organization:	NR
Actual Return to Compliance Date:	20051214
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20050909
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R4MNR
Evaluation Responsible Sub-Organization:	NR
Actual Return to Compliance Date:	20051214
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20050909
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R4MNR
Evaluation Responsible Sub-Organization:	NR
Actual Return to Compliance Date:	20051214
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20050909
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R4MNR
Evaluation Responsible Sub-Organization:	NR
Actual Return to Compliance Date:	20051214

FAUQUIER COUNTY HHW (Continued) **1012189076**

Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20050909
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R4MNR
Evaluation Responsible Sub-Organization:	NR
Actual Return to Compliance Date:	20051214
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20050909
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R4MNR
Evaluation Responsible Sub-Organization:	NR
Actual Return to Compliance Date:	20051214
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Count: 1 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
FAUQUIER	S104407569	NEW BALTIMORE FIRE DEPT (COMPANY 1	5303 JAMES MADISON HIGHWAY	20187	VA LUST

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/31/2022
Number of Days to Update: 26

Source: EPA
Telephone: N/A
Last EDR Contact: 08/02/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/31/2022
Number of Days to Update: 26

Source: EPA
Telephone: N/A
Last EDR Contact: 08/02/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/31/2022
Number of Days to Update: 26

Source: EPA
Telephone: N/A
Last EDR Contact: 08/02/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 06/24/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 06/27/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/31/2022
Number of Days to Update: 26

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 08/02/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/31/2022
Number of Days to Update: 26

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 08/02/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/16/2022
Date Data Arrived at EDR: 05/19/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 71

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 08/03/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 05/16/2022
Date Data Arrived at EDR: 05/24/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 66

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/24/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 05/16/2022
Date Data Arrived at EDR: 05/24/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 66

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/04/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/14/2022
Date Data Arrived at EDR: 06/15/2022
Date Made Active in Reports: 06/21/2022
Number of Days to Update: 6

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/15/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: This state does not maintain a SHWS list. See the Federal CERCLIS list and Federal NPL list.

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: Department of Environmental Quality
Telephone: 804-698-4236
Last EDR Contact: 06/09/2022
Next Scheduled EDR Contact: 09/26/2022
Data Release Frequency: N/A

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Solid Waste Management Facilities

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 02/25/2022
Date Data Arrived at EDR: 02/28/2022
Date Made Active in Reports: 05/26/2022
Number of Days to Update: 87

Source: Department of Environmental Quality
Telephone: 804-698-4238
Last EDR Contact: 05/26/2022
Next Scheduled EDR Contact: 09/12/2022
Data Release Frequency: Semi-Annually

Lists of state and tribal leaking storage tanks

LUST REG TD: Leaking Underground Storage Tank Sites

Leaking underground storage tank site locations. Includes: counties of Accomack, Isle of Wight, James City, Northampton, Southampton, York; cities of Chesapeake, Franklin, Hampton, Newport News, Norfolk, Poquoson, Portsmouth, Suffolk, Virginia Beach, Williamsburg.

Date of Government Version: 06/30/2013
Date Data Arrived at EDR: 07/05/2013
Date Made Active in Reports: 09/16/2013
Number of Days to Update: 73

Source: Department of Environmental Quality Tidewater Regional Office
Telephone: trofoia@deq.vir
Last EDR Contact: 09/26/2016
Next Scheduled EDR Contact: 01/09/2017
Data Release Frequency: Quarterly

LUST REG PD: Leaking Underground Storage Tank Sites

Leaking underground storage tank site locaitons. Includes: counties of Amelia, Brunswick, Charles City, Chesterfield, Dinwiddie, Essex, Gloucester, Goochland, Greensville, Hanover, Henrico, King and Queen, King William, Lancaster, Mathews, Middlesex, New Kent, Northumberland, Powhatan, Prince George, Richmond, Surry, Sussex, Westmoreland; cities of Colonial Heights, Emporia, Hopewell, Petersburg.

Date of Government Version: 12/02/2014
Date Data Arrived at EDR: 12/04/2014
Date Made Active in Reports: 01/16/2015
Number of Days to Update: 43

Source: Department of Environmental Quality Piedmont Regional Office
Telephone: 804-527-5020
Last EDR Contact: 08/29/2016
Next Scheduled EDR Contact: 12/12/2016
Data Release Frequency: Quarterly

LUST REG SC: Leaking Underground Storage Tanks

Leaking underground storage tank site locations. Includes: counties of Amherst, Appomattox, Buckingham, Campbell, Charlotte, Cumberland, Halifax, Lunenburg, Mecklenburg, Nottoway, Pittsylvania, Prince Deward; cities of Danville, Lynchburg.

Date of Government Version: 09/06/2013
Date Data Arrived at EDR: 09/06/2013
Date Made Active in Reports: 09/17/2013
Number of Days to Update: 11

Source: Department of Environmental Quality, South Central Region
Telephone: 434-582-5120
Last EDR Contact: 08/29/2016
Next Scheduled EDR Contact: 12/12/2016
Data Release Frequency: Semi-Annually

LUST REG WC: Leaking Underground Storage Tank List

Leaking underground storage tank site locations. Includes: counties of Alleghany, Bedford, Botetourt, Craig, Floyd, Franklin, Giles, Henry, Montgomery, Patrick, Pulaski, Roanoke; cities of Bedford, Clifton Forge, Covington, Martinsville, Radford, Roanoke, Salem.

Date of Government Version: 06/04/2015
Date Data Arrived at EDR: 06/05/2015
Date Made Active in Reports: 07/07/2015
Number of Days to Update: 32

Source: Department of Environmental Quality West Central Regional Office
Telephone: 540-562-6700
Last EDR Contact: 08/29/2016
Next Scheduled EDR Contact: 12/12/2016
Data Release Frequency: No Update Planned

LUST REG VA: Leaking Underground Storage Tank List

Leaking underground storage tank site locations. Includes: counties of Albemarle, Augusta, Bath, Clarke, Fluvanna, Frederick, Greene, Highland, Nelson, Page, Rockbridge, Rockingham, Shenandoah, Warren; cities of Buena Vista, Charlottesville, Harrisonburg, Lexington, Staunton, Waynesboro, Winchester.

Date of Government Version: 12/06/2011
Date Data Arrived at EDR: 12/08/2011
Date Made Active in Reports: 01/16/2012
Number of Days to Update: 39

Source: Department of Environmental Quality Valley Regional Office
Telephone: 540-574-7800
Last EDR Contact: 08/29/2016
Next Scheduled EDR Contact: 12/12/2016
Data Release Frequency: No Update Planned

LUST REG NO: Leaking Underground Storage Tank Tracking Database

Leaking underground storage tank site locations. Includes: counties of Arlington, Caroline, Culpeper, Fairfax, Fauquier, King George, Loudoun, Louisa, Madison, Orange, Prince William, Rappahannock, Spotsylvania, Stafford; cities of Alexandria, Fairfax, Falls Church, Fredericksburg, Manassas, Manassas Park.

Date of Government Version: 05/18/2004
Date Data Arrived at EDR: 05/22/2004
Date Made Active in Reports: 07/09/2004
Number of Days to Update: 48

Source: Department of Environmental Quality Northern Regional Office
Telephone: 703-583-3800
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

LUST REG SW: Leaking Underground Storage Tank Database

Leaking underground storage tank site locations. Includes: counties of Bland, Buchanan, Carroll, Dickenson, Grayson, Lee, Russell, Scott, Smyth, Tazewell, Washington, Wise, Wythe; cities of Bristol, Galax, Norton.

Date of Government Version: 07/15/2013
Date Data Arrived at EDR: 07/18/2013
Date Made Active in Reports: 09/16/2013
Number of Days to Update: 60

Source: Department of Environmental Quality Southwest Regional Office
Telephone: 276-676-4800
Last EDR Contact: 10/11/2016
Next Scheduled EDR Contact: 01/23/2017
Data Release Frequency: No Update Planned

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 06/22/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 90
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

LTANKS: Leaking Petroleum Storage Tanks
Includes releases of petroleum from underground storage tanks and aboveground storage tanks.

Date of Government Version: 02/03/2022
Date Data Arrived at EDR: 02/24/2022
Date Made Active in Reports: 05/23/2022
Number of Days to Update: 88

Source: Department of Environmental Quality
Telephone: 804-698-4010
Last EDR Contact: 05/25/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Quarterly

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 10/14/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 02/01/2022
Number of Days to Update: 88

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 06/29/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Varies

UST: Registered Petroleum Storage Tanks
Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 02/02/2022
Date Data Arrived at EDR: 02/24/2022
Date Made Active in Reports: 05/23/2022
Number of Days to Update: 88

Source: Department of Environmental Quality
Telephone: 804-698-4010
Last EDR Contact: 05/25/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Quarterly

AST: Registered Petroleum Storage Tanks
Registered Aboveground Storage Tanks.

Date of Government Version: 02/02/2022
Date Data Arrived at EDR: 02/24/2022
Date Made Active in Reports: 05/23/2022
Number of Days to Update: 88

Source: Department of Environmental Quality
Telephone: 804-698-4010
Last EDR Contact: 05/25/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Quarterly

INDIAN UST R4: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 06/22/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 90

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/06/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/14/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/12/2021
Date Data Arrived at EDR: 11/15/2021
Date Made Active in Reports: 02/08/2022
Number of Days to Update: 85

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 06/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Engineering Controls Sites Listing

A listing of sites with Engineering Controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 03/30/2022
Date Data Arrived at EDR: 04/05/2022
Date Made Active in Reports: 06/30/2022
Number of Days to Update: 86

Source: Department of Environmental Quality
Telephone: 804-698-4228
Last EDR Contact: 06/29/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Quarterly

INST CONTROL: Voluntary Remediation Program Database

Sites included in the Voluntary Remediation Program database that have deed restrictions.

Date of Government Version: 03/30/2022
Date Data Arrived at EDR: 04/05/2022
Date Made Active in Reports: 06/30/2022
Number of Days to Update: 86

Source: Department of Environmental Quality
Telephone: 804-698-4228
Last EDR Contact: 06/29/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VRP: Voluntary Remediation Program

The Voluntary Cleanup Program encourages owners of elected contaminated sites to take the initiative and conduct voluntary cleanups that meet state environmental standards.

Date of Government Version: 03/30/2022
Date Data Arrived at EDR: 04/05/2022
Date Made Active in Reports: 06/30/2022
Number of Days to Update: 86

Source: Department of Environmental Quality
Telephone: 804-698-4228
Last EDR Contact: 06/29/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Quarterly

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/15/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site Specific Assessments

To qualify for Brownfields Assessment, the site must meet the Federal definition of a Brownfields and should have contaminant issues that need to be addressed and a redevelopment plan supported by the local government and community. Virginia's Department of Environmental Quality performs brownfields assessments under a cooperative agreement with the U.S. Environmental Protection Agency at no cost to communities, property owners or, prospective purchasers. The assessment is an evaluation of environmental impacts caused by previous site uses similar to a Phase II Environmental Assessment.

Date of Government Version: 04/19/2022
Date Data Arrived at EDR: 04/20/2022
Date Made Active in Reports: 07/14/2022
Number of Days to Update: 85

Source: Department of Environmental Quality
Telephone: 804-698-4207
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/10/2022
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 0

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 09/26/2022
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/21/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/12/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 07/21/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 04/30/2022
Date Data Arrived at EDR: 05/24/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 66

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/24/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: No Update Planned

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 04/30/2022
Date Data Arrived at EDR: 05/24/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 66

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/24/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Quarterly

PFAS: Per- and Polyfluoroalkyl Substances

PFOS and PFOA stand for perfluorooctane sulfonate and perfluorooctanoic acid, respectively. Both are fluorinated organic chemicals, part of a larger family of compounds referred to as perfluoroalkyl substances (PFASs).

Date of Government Version: 03/16/2022
Date Data Arrived at EDR: 04/05/2022
Date Made Active in Reports: 06/30/2022
Number of Days to Update: 86

Source: Department of Environmental Quality
Telephone: 804-698-4336
Last EDR Contact: 06/29/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Varies

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/31/2022
Number of Days to Update: 26

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 08/02/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/21/2022
Date Data Arrived at EDR: 03/21/2022
Date Made Active in Reports: 06/14/2022
Number of Days to Update: 85

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

SPILLS BRL: Prep/Spills Database Listing

A listing of spills locations located in the Blue Ridge Regional area, Lynchburg.

Date of Government Version: 09/18/2009
Date Data Arrived at EDR: 09/18/2009
Date Made Active in Reports: 10/06/2009
Number of Days to Update: 18

Source: DEQ, Blue Ridge Regional Office
Telephone: 434-582-6218
Last EDR Contact: 11/28/2011
Next Scheduled EDR Contact: 03/12/2012
Data Release Frequency: Varies

SPILLS VA: PREP Database

The Department of Environmental Quality's POLLUTION RESPONSE PROGRAM, known as PREP, provides for responses to air, water, and waste pollution incidents in order to protect human health and the environment.

Date of Government Version: 08/08/2012
Date Data Arrived at EDR: 08/09/2012
Date Made Active in Reports: 10/05/2012
Number of Days to Update: 57

Source: Department of Environmental Quality, Valley Regional Office
Telephone: 540-574-7800
Last EDR Contact: 05/06/2013
Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Quarterly

SPILLS TD: PREP Database

The Department of Environmental Quality's POLLUTION RESPONSE PROGRAM, known as PREP, provides for responses to air, water, and waste pollution incidents in order to protect human health and the environment.

Date of Government Version: 09/17/2009
Date Data Arrived at EDR: 09/23/2009
Date Made Active in Reports: 10/06/2009
Number of Days to Update: 13

Source: Department of Environmental Quality, Tidewater Region
Telephone: trofoia@deq.vir
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: Quarterly

SPILLS: Prep/Spills Database Listing

The Department of Environmental Quality's POLLUTION RESPONSE PROGRAM, known as PREP, provides for responses to air, water, and waste pollution incidents in order to protect human health and the environment. PREP staff often work to assist local emergency responders, other state agencies, federal agencies, and responsible parties, as may be needed, to manage pollution incidents. Oil spills, fish kills, and hazardous materials spills are examples of incidents that may involve the DEQ's PREP Program.

Date of Government Version: 02/03/2022
Date Data Arrived at EDR: 02/10/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 89

Source: Department of Environmental Quality
Telephone: 804-698-4287
Last EDR Contact: 05/25/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Quarterly

SPILLS SW: Reportable Spills

The Department of Environmental Quality's POLLUTION RESPONSE PROGRAM, known as PREP, provides for responses to air, water, and waste pollution incidents in order to protect human health and the environment.

Date of Government Version: 01/21/2010
Date Data Arrived at EDR: 01/22/2010
Date Made Active in Reports: 02/16/2010
Number of Days to Update: 25

Source: Department of Environmental Quality, Southwest Region
Telephone: 276-676-4839
Last EDR Contact: 07/13/2012
Next Scheduled EDR Contact: 10/29/2012
Data Release Frequency: No Update Planned

SPILLS PD: PREP Database

The Department of Environmental Quality's POLLUTION RESPONSE PROGRAM, known as PREP, provides for responses to air, water, and waste pollution incidents in order to protect human health and the environment.

Date of Government Version: 10/20/2009
Date Data Arrived at EDR: 10/29/2009
Date Made Active in Reports: 12/03/2009
Number of Days to Update: 35

Source: Department of Environmental Quality, Piedmont Region
Telephone: 804-527-5020
Last EDR Contact: 02/06/2012
Next Scheduled EDR Contact: 05/21/2012
Data Release Frequency: Quarterly

SPILLS NO: PREP Database

The Department of Environmental Quality's POLLUTION RESPONSE PROGRAM, known as PREP, provides for responses to air, water, and waste pollution incidents in order to protect human health and the environment.

Date of Government Version: 09/23/2009
Date Data Arrived at EDR: 09/29/2009
Date Made Active in Reports: 10/30/2009
Number of Days to Update: 31

Source: Department of Environmental Quality, Northern Region
Telephone: 703-583-3864
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

SPILLS PC: Pollution Complaint Database

Pollution Complaints Database. The pollution reports contained in the PC database include the initial release reporting of Leaking Underground Storage Tanks and all other releases of petroleum to the environment as well as releases to state waters. The database is current through 12/1/93. Since that time, all spill and pollution reporting information has been collected and tracked through the DEQ regional offices.

Date of Government Version: 06/01/1996
Date Data Arrived at EDR: 10/22/1996
Date Made Active in Reports: 11/21/1996
Number of Days to Update: 30

Source: Department of Environmental Quality
Telephone: 804-698-4287
Last EDR Contact: 03/08/2010
Next Scheduled EDR Contact: 06/21/2010
Data Release Frequency: No Update Planned

SPILLS WC: Prep Database

The Department of Environmental Quality's POLLUTION RESPONSE PROGRAM, known as PREP, provides for responses to air, water, and waste pollution incidents in order to protect human health and the environment.

Date of Government Version: 09/21/2009
Date Data Arrived at EDR: 09/29/2009
Date Made Active in Reports: 10/30/2009
Number of Days to Update: 31

Source: Department of Environmental Quality, West Central Region
Telephone: 540-562-6700
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 09/01/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/15/2013
Number of Days to Update: 43

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 05/11/2022
Date Data Arrived at EDR: 05/17/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 73

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 08/11/2022
Next Scheduled EDR Contact: 11/28/2022
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/13/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/08/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/03/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/21/2022
Date Data Arrived at EDR: 03/21/2022
Date Made Active in Reports: 06/14/2022
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 07/29/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 08/04/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/14/2022
Next Scheduled EDR Contact: 09/26/2022
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/11/2022
Next Scheduled EDR Contact: 11/28/2022
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 07/18/2022
Date Data Arrived at EDR: 07/18/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 11

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/18/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/31/2022
Number of Days to Update: 26

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 08/02/2022
Next Scheduled EDR Contact: 09/12/2022
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/14/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 01/25/2022
Date Data Arrived at EDR: 02/03/2022
Date Made Active in Reports: 02/25/2022
Number of Days to Update: 22

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 08/02/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 01/20/2022
Date Data Arrived at EDR: 01/20/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 64

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/08/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 06/28/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/11/2022
Date Data Arrived at EDR: 03/15/2022
Date Made Active in Reports: 06/14/2022
Number of Days to Update: 91

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 07/13/2022
Next Scheduled EDR Contact: 10/31/2022
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 84

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 06/02/2022
Next Scheduled EDR Contact: 09/12/2022
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 05/25/2022
Next Scheduled EDR Contact: 09/12/2022
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 08/04/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 06/23/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data
Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/21/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees
Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2022
Date Data Arrived at EDR: 04/14/2022
Date Made Active in Reports: 07/12/2022
Number of Days to Update: 89

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 06/29/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 23

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 06/21/2022
Next Scheduled EDR Contact: 10/03/2022
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/08/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 07/26/2021
Date Data Arrived at EDR: 07/27/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 87

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/26/2022
Next Scheduled EDR Contact: 11/14/2022
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/10/2022
Next Scheduled EDR Contact: 11/28/2022
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/31/2022
Number of Days to Update: 26

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 08/01/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/02/2022
Date Data Arrived at EDR: 05/25/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 65

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 05/25/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 03/21/2022
Date Data Arrived at EDR: 03/22/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 3

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 08/02/2022
Next Scheduled EDR Contact: 09/12/2022
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/27/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/27/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 03/10/2022
Date Data Arrived at EDR: 03/10/2022
Date Made Active in Reports: 06/14/2022
Number of Days to Update: 96

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 06/14/2022
Next Scheduled EDR Contact: 09/19/2022
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 05/13/2022
Date Data Arrived at EDR: 05/18/2022
Date Made Active in Reports: 05/31/2022
Number of Days to Update: 13

Source: EPA
Telephone: (215) 814-5000
Last EDR Contact: 05/18/2022
Next Scheduled EDR Contact: 09/12/2022
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 05/19/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 01/11/2022
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 34

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/07/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 04/02/2022
Date Data Arrived at EDR: 04/05/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 07/01/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/16/2022
Date Data Arrived at EDR: 05/17/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 73

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/11/2022
Next Scheduled EDR Contact: 11/28/2022
Data Release Frequency: Quarterly

AIRS: Permitted Airs Facility List

A listing of permitted Airs facilities.

Date of Government Version: 06/14/2022
Date Data Arrived at EDR: 06/15/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 13

Source: Department of Environmental Quality
Telephone: 804-698-4000
Last EDR Contact: 06/09/2022
Next Scheduled EDR Contact: 09/26/2022
Data Release Frequency: Annually

CEDS: Comprehensive Environmental Data System

Virginia Water Protection Permits, Virginia Pollution Discharge System (point discharge) permits and Virginia Pollution Abatement (no point discharge) permits.

Date of Government Version: 05/31/2022
Date Data Arrived at EDR: 06/01/2022
Date Made Active in Reports: 06/13/2022
Number of Days to Update: 12

Source: Department of Environmental Quality
Telephone: 804-698-4077
Last EDR Contact: 05/26/2022
Next Scheduled EDR Contact: 09/12/2022
Data Release Frequency: Quarterly

COAL ASH: Coal Ash Disposal Sites

A listing of facilities with coal ash impoundments.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 05/26/2021
Date Made Active in Reports: 08/18/2021
Number of Days to Update: 84

Source: Department of Environmental Protection
Telephone: 804-698-4285
Last EDR Contact: 05/26/2022
Next Scheduled EDR Contact: 09/12/2022
Data Release Frequency: Varies

DRYCLEANERS: Drycleaner List

A listing of registered drycleaners.

Date of Government Version: 04/11/2022
Date Data Arrived at EDR: 04/12/2022
Date Made Active in Reports: 04/13/2022
Number of Days to Update: 1

Source: Department of Environmental Quality
Telephone: 804-698-4407
Last EDR Contact: 06/29/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Varies

ENFORCEMENT: Enforcement Actions Data

A listing of enforcement actions.

Date of Government Version: 04/04/2022
Date Data Arrived at EDR: 04/05/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 84

Source: Department of Environmental Quality
Telephone: 804-698-4031
Last EDR Contact: 06/23/2022
Next Scheduled EDR Contact: 10/10/2022
Data Release Frequency: Quarterly

Financial Assurance 1: Financial Assurance Information Listing

A listing of financial assurance information for underground storage tank facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 01/24/2022
Date Data Arrived at EDR: 04/21/2022
Date Made Active in Reports: 07/15/2022
Number of Days to Update: 85

Source: Department of Environmental Quality
Telephone: 804-698-4205
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information listing

Solid waste financial assurance information.

Date of Government Version: 04/26/2022
Date Data Arrived at EDR: 04/27/2022
Date Made Active in Reports: 07/20/2022
Number of Days to Update: 84

Source: Department of Environmental Quality
Telephone: 804-698-4123
Last EDR Contact: 07/19/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Varies

TIER 2: Tier 2 Information Listing

A listing of facilities which store or manufacture hazardous materials and submit a chemical inventory report.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 01/04/2022
Date Made Active in Reports: 03/21/2022
Number of Days to Update: 76

Source: Department of Environmental Quality
Telephone: 804-698-4159
Last EDR Contact: 06/23/2022
Next Scheduled EDR Contact: 09/26/2022
Data Release Frequency: No Update Planned

UIC: Underground Injection Control Wells

A listing of underground injection controls wells.

Date of Government Version: 04/19/2022
Date Data Arrived at EDR: 04/20/2022
Date Made Active in Reports: 07/14/2022
Number of Days to Update: 85

Source: Department of Mines, Minerals and Energy
Telephone: 276-415-9700
Last EDR Contact: 07/26/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Quarterly

PCS INACTIVE: Listing of Inactive PCS Permits

An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 06/28/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Semi-Annually

MINES MRDS: Mineral Resources Data System

Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 05/27/2022
Next Scheduled EDR Contact: 09/05/2022
Data Release Frequency: Varies

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 06/28/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 06/28/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Semi-Annually

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Virgina.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/20/2014
Number of Days to Update: 203

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Virgina and at the Regional VA Levels.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/15/2014
Number of Days to Update: 198

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 05/08/2022
Date Data Arrived at EDR: 05/09/2022
Date Made Active in Reports: 07/28/2022
Number of Days to Update: 80

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/08/2022
Next Scheduled EDR Contact: 11/21/2022
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/28/2022
Next Scheduled EDR Contact: 10/17/2022
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/29/2022
Next Scheduled EDR Contact: 11/07/2022
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/06/2022
Next Scheduled EDR Contact: 10/24/2022
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/10/2022
Next Scheduled EDR Contact: 11/28/2022
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/03/2022
Next Scheduled EDR Contact: 09/19/2022
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Licensed Facilities
Source: Department of Social Services
Telephone: 804-692-1900

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

8499 BINGHAM RD
8499 BINGHAM RD
WARRENTON, VA 20187

TARGET PROPERTY COORDINATES

Latitude (North):	38.680493 - 38ˆ 40’ 49.77’’
Longitude (West):	77.786635 - 77ˆ 47’ 11.89’’
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	257591.7
UTM Y (Meters):	4284800.0
Elevation:	531 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	13911450 WARRENTON, VA
Version Date:	2019

EDR’s GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General SSE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES





Target Property Elevation: 531 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
51061C0325C	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
51061C0308C	FEMA FIRM Flood data
51061C0309C	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
WARRENTON	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Triassic
Series:	Triassic mafic intrusives
Code:	Tri *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Plutonic and Intrusive Rocks

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name:	CATOCTIN
Soil Surface Texture:	extremely stony - silt loam
Hydrologic Group:	Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.
Soil Drainage Class:	Well drained. Soils have intermediate water holding capacity. Depth to water table is more than 6 feet.

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel:	HIGH
Depth to Bedrock Min:	> 20 inches
Depth to Bedrock Max:	> 40 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	10 inches	extremely stony - silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 6.00 Min: 2.00	Max: 6.50 Min: 5.10
2	10 inches	22 inches	channery - silt loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 6.00 Min: 2.00	Max: 6.50 Min: 5.10
3	22 inches	28 inches	very channery - silt loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 6.00 Min: 2.00	Max: 7.30 Min: 5.60
4	28 inches	32 inches	unweathered bedrock	Not reported	Not reported	Max: 0.06 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
unweathered bedrock
flaggy - silt loam

Surficial Soil Types: silt loam
unweathered bedrock
flaggy - silt loam

Shallow Soil Types: silty clay loam
silt loam
very channery - silt loam

Deeper Soil Types: weathered bedrock
loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

PHYSICAL SETTING SOURCE MAP - 7085107.2s



County Boundary
Major Roads
Contour Lines
Earthquake epicenter, Richter 5 or greater
Water Wells
Public Water Supply Wells
Cluster of Multiple Icons

0 1/4 1/2 1 Miles

Groundwater Flow Direction
GI Indeterminate Groundwater Flow at Location
GV Groundwater Flow Varies at Location
HD Closest Hydrogeological Data
Oil, gas or related wells

N

SITE NAME:	8499 BINGHAM RD	CLIENT:	ECS Mid Atlantic, LLC
ADDRESS:	8499 BINGHAM RD WARRENTON VA 20187	CONTACT:	Joshua Allen Peckham
LAT/LONG:	38.680493 / 77.786635	INQUIRY #:	7085107.2s
		DATE:	August 12, 2022 11:55 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for FAUQUIER County: 2

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for FAUQUIER COUNTY, VA

Number of sites tested: 6

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	4.450 pCi/L	50%	50%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	1.800 pCi/L	100%	0%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Virginia Public Water Supplies
Source: Department of Health, Office of Water Programs
Telephone: 804-786-1756

OTHER STATE DATABASE INFORMATION

Virginia Oil and Gas Wells
Source: Department of Mines, Minerals and Energy
Telephone: 804-692-3200
A listing of oil and gas well locations.

RADON

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

EPA Region 3 Statistical Summary Readings
Source: Region 3 EPA
Telephone: 215-814-2082
Radon readings for Delaware, D.C., Maryland, Pennsylvania, Virginia and West Virginia.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Appendix IV: Historical Research Documentation

8499 BINGHAM RD
8499 BINGHAM RD
WARRENTON, VA 20187

Inquiry Number: 7085107.5
August 16, 2022

The EDR-City Directory Image Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by
infoUSA®
Copyright©2008
All Rights Reserved

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2017	☐	☐	EDR Digital Archive
2014	☐	☐	EDR Digital Archive
2010	☐	☐	EDR Digital Archive
2005	☐	☐	EDR Digital Archive
2000	☐	☐	EDR Digital Archive
1995	☐	☐	EDR Digital Archive
1992	☐	☐	EDR Digital Archive
1988	☐	☐	Polk's City Directory
1983	☐	☐	Polk's City Directory
1978	☐	☐	Hill's City Directory
1974	☐	☐	Hill's City Directory
1970	☐	☐	Hill's City Directory
1966	☐	☐	Hill's City Directory
1963	☐	☐	Hill's City Directory

EXECUTIVE SUMMARY

Year	Target Street	Cross Street	Source

FINDINGS

TARGET PROPERTY STREET

8499 BINGHAM RD
WARRENTON, VA 20187

Year	*CD Image*	*Source*	
BINGHAM RD			
2017	-	EDR Digital Archive	Street not listed in Source
2014	-	EDR Digital Archive	Street not listed in Source
2010	-	EDR Digital Archive	Street not listed in Source
2005	-	EDR Digital Archive	Street not listed in Source
2000	-	EDR Digital Archive	Street not listed in Source
1995	-	EDR Digital Archive	Street not listed in Source
1992	-	EDR Digital Archive	Street not listed in Source
1988	-	Polk's City Directory	Street not listed in Source
1983	-	Polk's City Directory	Street not listed in Source
1978	-	Hill's City Directory	Street not listed in Source
1974	-	Hill's City Directory	Street not listed in Source
1970	-	Hill's City Directory	Street not listed in Source
1966	-	Hill's City Directory	Street not listed in Source
1963	-	Hill's City Directory	Street not listed in Source

FINDINGS

CROSS STREETS

No Cross Streets Identified

8499 BINGHAM RD

8499 BINGHAM RD

WARRENTON, VA 20187

Inquiry Number: 7085107.8

August 15, 2022

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

08/15/22

Site Name:

8499 BINGHAM RD
8499 BINGHAM RD
WARRENTON, VA 20187
EDR Inquiry # 7085107.8

Client Name:

ECS Mid Atlantic, LLC
14026 Thunderbolt Place
Chantilly, VA 20151
Contact: Joshua Allen Peckham

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2016	1"=500'	Flight Year: 2016	USDA/NAIP
2012	1"=500'	Flight Year: 2012	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2005	1"=500'	Flight Year: 2005	USDA/NAIP
1994	1"=500'	Acquisition Date: March 12, 1994	USGS/DOQQ
1980	1"=500'	Flight Date: March 27, 1980	USDA
1977	1"=500'	Flight Date: March 02, 1977	USGS
1970	1"=500'	Flight Date: September 25, 1970	USGS
1966	1"=500'	Flight Date: January 09, 1966	USGS
1960	1"=500'	Flight Date: April 11, 1960	USGS
1952	1"=500'	Flight Date: March 18, 1952	USGS

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

INQUIRY #: 7085107.8
YEAR: 2016
= 500'
N
EDR

INQUIRY #: 7085107.8
YEAR: 2012
= 500'
N
EDR

INQUIRY #: 7085107.8
YEAR: 2009
= 500'
N
EDR

INQUIRY #: 7085107.8
YEAR: 2005
= 500'
N
EDR



INQUIRY #: 7085107.8

YEAR: 1994

= 500'

N

EDR

INQUIRY #: 7085107.8
YEAR: 1980
= 500'
N
EDR

INQUIRY #: 7085107.8

YEAR: 1977

= 500'

N

EDR

Subject boundary not shown because it exceeds image extent or image is not georeferenced.


INQUIRY #: 7085107.8
YEAR: 1970
= 500'
N
EDR

INQUIRY #: 7085107.8

YEAR: 1966

= 500'

N

EDR

Subject boundary not shown because it exceeds image extent or image is not georeferenced.

INQUIRY #: 7085107.8
YEAR: 1960
= 500'
N
EDR

INQUIRY #: 7085107.8

YEAR: 1952

= 500'

N

EDR

Subject boundary not shown because it exceeds image extent or image is not georeferenced.

8499 BINGHAM RD

8499 BINGHAM RD

WARRENTON, VA 20187

Inquiry Number: 7085107.3

August 12, 2022

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

08/12/22

Site Name:

8499 BINGHAM RD
8499 BINGHAM RD
WARRENTON, VA 20187
EDR Inquiry # 7085107.3

Client Name:

ECS Mid Atlantic, LLC
14026 Thunderbolt Place
Chantilly, VA 20151
Contact: Joshua Allen Peckham

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by ECS Mid Atlantic, LLC were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 777A-415A-8241

PO # 47 13457-A

Project Town of Warrenton DPW Complex

UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.

Sanborn® Library search results

Certification #: 777A-415A-8241

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

ECS Mid Atlantic, LLC (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Appendix V: Site Photographs

1 - East view across site

2 - Geotech boring on west of site

3 - Non-pcb transformers on northwestern portion of site

4 - North view across site

5 - North view offsite w/ Police Station

6 - Northeast offsite from top of hill

7 - Propane tank adjacent to utility building

8 - Rear of utility shed

9 - Small pond on southern portion of site

10 - Small utility shed/pumping station on northwest portion of site

11 - South view across western portion of the site

12 - Southwest view offsite from Northwest corner

13 - Stream offsite on west property

14 - View of Northern landscaped area of site

15 - View of northwest adjacent property

16 - View of southeast adjacent property

17 - View of stormwater pond located to the southwest of the site

18 - West view offsite

Appendix VI: Statement of Qualifications

Engineering Consulting Services

Statement of Qualifications

2020

GUTS

INITIATIVE

CONSTRUCTION MATERIALS

FACILITIES

GEOTECHNICAL

RESILIENCE

ENVIRONMENTAL

TENACITY

COMPANY OVERVIEW

2,000
employees

65+
locations

30+
years' experience

ABOUT OUR COMPANY

Engineering Consulting Services (ECS) is one of the largest and most rapidly growing engineering and consulting companies in the US. Founded in 1988, ECS is a leader in geotechnical, environmental, construction materials and facilities engineering. We are currently ranked 69 in *Engineering News-Record's* Top 500 Design Firms (April 2020) and 52 in Zweig Group's 2020 Hot Firms (June 2020).

ECS CORE SERVICES

- Geotechnical
- Construction Materials
- Environmental
- Facilities

ECS FOOTPRINT

Whether your project requires local project management, specialty expertise or both, we have you covered. ECS provides the best of both worlds - the attention your projects deserve from our local team, coupled with abundant staffing and technical resources. With 2,000 employees, ECS has grown to more than 65 locations spread across the Mid-Atlantic, Midwest, Southeast and Southwest.

WHY ECS? WE HAVE GRIT.

What does that mean for you? That one descriptive word defines our company culture. It sets just the right tone for what our clients can expect our team to deliver each and every day. At ECS, GRIT is made up of four characteristics: guts, resilience, initiative and tenacity. Our boots are made for working. Click here for an inside look at what we do, who we are and why we have GRIT.

As a culture of doers, we roll up our sleeves and use our skills to help solve problems. We hustle.

WHEREVER YOUR PROJECT TAKES YOU, ECS HAS...

BOOTS ON THE GROUND.



SERVICES KEY

- Environmental & Facilities
- Geotechnical, Environmental, Materials Testing & Facilities
- Geotechnical, Environmental & Facilities

OFFICES KEY

- Full Service Office
- Testing Services Only
- Corporate Headquarters

Materials Testing Service Area is approximately a 75-mile radius around each office.

DUE DILIGENCE

As part of typical commercial, industrial and residential real estate transactions, many services need to be completed prior to closing that should not be overlooked. ECS provides environmental and engineering due diligence services common to real estate transaction-driven work, including:

Environmental Due Diligence Services:

- Phase I Environmental Site Assessments (ESAs)
- Wetland and Stream Determination and Delineation Services
- Phase II Environmental Site Assessments (ESAs)
- Underground Storage Tank (UST) Assessments and Closures
- Environmental Transaction Screens (ETS)
- Regulatory Record Reviews
- HUD Assessments
- Endangered Species Assessments
- Historical and Cultural Surveys/Assessments
- Radon Assessment
- Asbestos Surveys and Abatement Design
- Lead-Based Paint Surveys and Abatement Design
- Microbial and Indoor Air Quality Assessments
- Vapor Intrusion Assessments
- Fannie Mae and Freddie Mac Assessments
- Contaminated soil management plans

Facilities Due Diligence Services:

- Accessibility Consulting
- Bank Draw Review
- Pre and Post Construction Surveys
- Property Condition Assessments (PCAs)
- Forensic Investigations
- GPR Surveys
- EIFS Services

Engineering Due Diligence Services:

- Subsurface Geotechnical Explorations
- Test Pit Evaluations
- Seismic Studies
- Cost estimating for construction
- Geologic Assessments

Joshua Peckham

ENVIRONMENTAL SCIENTIST

CERTIFICATIONS

OSHA 40 Hour Hazardous Waste Operations TrainingCertification (HAZWOPER)

8-Hour Hazardous Waste and Emergency Response Refresher

38-Hour Army Corps of Engineers Wetland Delineation Training program

Provisional Virginia DEQ Erosion & Sediment Control inspector

Provisional Virginia DEQ Storm Water Management Inspector

American Concrete Institute Inspector Certification

SKILLS

Phase I Assessments

Phase II Remediation Activities

Wetland Delineation, permitting

Construction Materials Testing

EDUCATION

Bachelor of Science, 2017, Environmental Science with Wetland Science minor

Virginia Polytechnic Institute and State University, Blacksburg, VA

YEARS OF EXPERIENCE

Environmental Scientist
2021-present
Environmental Technician
2017, 2018-2021
Construction Material Technician
2018

PROFESSIONAL PROFILE

Mr. Peckham is an Environmental Scientist with five years of experience with ECS Mid-Atlantic, LLC. Duties as an environmental scientist include developing Phase I Site Assessments; Wetland delineation and permit compliance monitoring; Virginia stormwater and erosion and sediment control (SWPPP) inspections; and performing a variety of Phase II remediation activities.

PROJECT EXPERIENCE

- *Dominion Liberty Rail Spur*, Manassas, VA – Wetland permit compliance monitoring, SWPPP inspections and permitting.
- *Dominion Possum Point Power Station*, Dumfries, VA – Phase II water treatment remediation, coal ash dewatering treatment system operation and maintenance.
- *Dominion Chesterfield Power Station*, Chesterfield, VA – Phase II water treatment remediation, coal ash dewatering treatment system operation and maintenance.
- *The Wharf phase II*, Washington, DC. Phase II excavation monitoring
- *Hanover Pike Phase 1 ESA,* Hanover, Maryland. Phase 1 report generation
- *Potomac Creek*, Fredericksburg, VA, materials testing
- *Montross Solar Project*, Montross, VA, materials testing
- Field screening and sampling of petroleum impacted materials.
- Excavation and remediation of contaminated materials support
- Wetland delineation, flagging, and mapping
- Wetland impact permitting and compliance monitoring
- Soil boring, sampling, well installation, and related sub-surface work
- Dewatering system construction, operation, maintenance, and sampling.
- Wetland and SWPPP permit monitoring proposal generation
- Sub-slab and soil vapor sampling
- Soil and asphalt compaction testing
- ACI & WACEL concrete inspection and testing
- Nuclear gauge use and radiation safety training
- On-site dust and air monitoring for safety compliance
- Ground Penetrating Radar survey assistance
- Air emission permitting work



Ryan J. Croyle, REM

Regional Environmental Manager

Education

Bachelor of Science, 1998, Environmental Science/Biology, Edinboro University, Edinboro, PA

Certifications

National Registry of Environmental Professionals, Registered Environmental Manager

38-Hour Army Corps of Engineers Wetland Delineation Training Program

OSHA HAZWOPER 40 Hour Certification & Refreshers

New Jersey DEP Subsurface Evaluator License, Reg. No. 207176

EPA AHERA Asbestos Building Inspector Certification (Multiple states)

NIOSH 582 Certification (Collecting and Analyzing Asbestos Air Samples)

Mr. Croyle is the Regional Environmental Manager/ Principal Reviewer for the ECS Mid-Atlantic Northern Region. His responsibilities include managing the environmental staff, as well as coordinating, preparing, and reviewing environmental programs and services.

Environmental Manager – Mr. Croyle provides principal review of Phase I and II Environmental Site Assessments, site characterization and remedial investigation reports, underground storage tank removal and remediation, State Voluntary Cleanup Programs, wetland determinations, risk assessments and hazardous materials surveys, health and safety plans (HASPs) environmental impact statements, and wetlands delineation studies.

Sample Project Experience

- Department of the Navy, Polychlorinated Biphenyl (PCB) Impacted Soil Removal, Mechanicsburg, PA
- Fairpoint Communications, Bentleyville, PA
- MD State Highways Environmental Contract, Multiple Locations, MD
- Direct To You Gas, Adams County, PA
- Queensgate Plaza, York, PA
- Tanger Property, Hanover PA
- PNC Financial Services Group, Environmental, National Account Manager, Multiple Locations, US
- PNC Financial Services Group, Mercantile Bank, MD and PA
- Commercial Shopping Center, Brewers Hill, MD
- Cintas West Philadelphia Brownfields Redevelopment, Philadelphia, PA
- Center Point Baltimore, MD
- Bank of America, Environmental, Multiple Locations, PA
- Broadway Arts, Long Branch, NJ
- Bell Telephone Laboratory Consultation, Chester, NJ
- Broadway Arts Redevelopment, Long Branch, NJ
- Tractor Supply Company, Multiple Locations, MD, PA, NJ, MA
- AutoZone, Multiple Locations, PA, NJ, NH, MA, ME
- Millersville University, Millersville, PA
- BELCO Corporate Headquarters, Harrisburg, PA

Appendix VII: Acronyms

List of Common Acronyms

AULs	Activity and Use Limitations
AST	Aboveground Storage Tank
ASTM	American Society for Testing and Materials
ACM	Asbestos Containing Materials
BER	Business Environmental Risk
CORRACTS	CERCLA Corrective Action List
NPL	CERCLA National Priorities List
NFRAP	CERCLA No Further Remedial Action Planned
CERCLA	Comprehnsive Environmental Response Cleanup Liability Act
CESQG	Conditionally Exempt Small Quantity Generator
CREC	Controlled Recognized Environmental Condition
ERNS	Emergency Response Notification System
EC	Engineering Controls
HIST LF	Historical Landfill
HREC	Historical Recognized Environmental Condition
IC	Institutional Controls
LQG	Large Quantity Generator
LBP	Lead Based Paint
LTANKS	Leaking Tanks
LUST	Leaking Underground Storage Tank
REC	Recognized Environmental Condition
RCRA	Resource Conservation and Recovery Act
RCRIS	Resource Conservation and Recovery Information System
SQG	Small Quantity Generator
SWF/LF	Solid Waste Facility/Landfill
SHWS	State Hazardous Waste Sites
UST	Underground Storage Tank
USGS	United States Geological Survey