

Department Reports
5.16.2025

ELECTRIC DISTRIBUTION

Tickets, locates

POWER PLANT

Rounds

It's been a couple very wild weeks at the lake with all the different schools using the facilities and lake area for end of year activities.

Lots and lots of mowing, trimming and trash picking up.

Been working on the dog park filling in holes and getting it sprayed for stickers on the second round.

New camp host have got started and are seaming to like the challenge so far.

Been working on getting the kayak building all ready for the folks to open, we still need to put concrete underneath the overhead doors but having trouble finding time for everything.

Normal maintenance on plant and substations, we will be doing oil samples on every piece of electrical equipment once we get past Memorial Day weekend.

NC has been keeping the power plant mowed and then bringing the mower to the lake to help because one machine is not working.

LB has been attending weekly SPP market meetings and trying to stay on top of what the power market is doing daily.

STREET

Regular Mowing

Grading

Spread sand on West Garfield and East Hayes

Pulled shoulder on East Hayes (needs more work)

Picked up tree limbs 200 blk West Steadman 200 blk N Jennings

Cleaned up after Balloon Fest

Cleaned around court house for car show

Helped line crew at Sunrise 2nd

WATER/WASTEWATER

Rounds, tickets, locates

Mow sewer plant

Weed rocks

Grout wells

Clean lift stations

Mow water plant

Repaired 2 service lines

MECHANIC

PICKED UP APPROVED TIRE QUOTES FOR #5 AND #12

LET GATES REPAIR KNOW THEY WON TIRE BID TO ORDER IN TIRES

TALKED TO COOP AND PRONTO TO LET THEM KNOW THE OUTCOME OF TIRE BID

#21 MH NOT TAKING FUEL EASY, LEAKING FUEL ON GROUND WHEN TRYING TO FILL. FOUND BOTTOM OF FILLER NECK ROTTED WITH BIG HOLE TO RUBBER LINE THAT GOES TO TANK, REPLACED WITH NEW FILLER NECK. REPLACED BROKEN PARKING LIGHT HOUSING ON DRIVER FRONT

CLEANED WASH BAY

WORKED ON UPDATING VEHICLE CHECK LISTS

#75 S DEWEZE MOWER BLEW HYDRAULIC, REPLACED WITH CUSTOM HOSE MADE AT NAPA. REPLACED DECK RAISE BOLT THAT WAS MISSING.

LOOKED OVER OLD FILES IN COMPUTER, UPDATED AS I SEEN NEEDED

#14 E OIL LEAK ISSUE. LOOKING OVER TRUCK AND FOUND CRANK CASE BREATHER/FILTER HASN'T BEEN CHANGED, NEEDS CHANGED EVERY 50,000 MILES. IF IT PLUGS UP CAUSES OIL LEAKS. ORDERED FROM RUSTY ECK AND INSTALLED CRANK CASE BREATHER. CHANGED OIL AND FILTER, UPPER FUEL FILTER, NEW DRAIN PLUG, NEW OIL AND FILTER, TIRE ROTATION & BRAKE CHECK, FOUND MISSING SHOCK BOLT AND REPLACED WITH NEW BOLT. ADDED UV LEAK DETECTION OIL TO ENGINE OIL TO MAKE SURE OIL LEAK IS FIXED. TEST DRIVE RAN OVER BOLT ON TEST DRIVE AND TOOK FRONT TIRE TO COOP FOR REPAIR. CHECKING OIL LEAK WITH UV DYE LIGHT, FOUND SMALL DRIP AT OIL PAN. GOING TO ORDER LOWER BOTTOM PLASTIC OIL PAN TO REPLACE.

#75 S SERVICE CALL TO CHANGE RUINED TIRE ON MOWER

#5 W TOOK TO GATES TO HAVE TIRES INSTALLED. ALIGNMENT WAS ALSO NEEDED ON THIS TRUCK NEEDS REAR BRAKES, ORDERED BRAKE PADS AND WILL REPLACE SOON

#12 S TOOK TO GATES TO HAVE TIRE INSTALLED, FOUND BAD TIE ROD ORDERED PART AND WILL REPLACE SOON

#30 S TRANS LIGHT ON IN DASH, CHECKED FLUID AND TRIED TO SCAN COMPUTER BUT SCAN TOOL WILL NOT READ, AFTER SHUT OFF AND RESTARTED LIGHT IS NOW OFF. AJ REPAIR CAN READ CODES IF LIGHT COMES BACK ON.

WHAT A WEEK !