| Museum & Visitor Center Capital | Needs | Critical Path | | | |
|---|---------------|----------------------|---------------------|-------------------|--------|
| Maintenance Need | Est Cost | Year | Safety of People | Safety of Objects | Maint. |
| 1 Replace leaking roof with bitumen | \$20,720 | 1 | х | х | х |
| 2 Repair exterior door- parking | \$860 | 1 | х | х | х |
| 3 Replace rotten wood-ceiling supports | \$2,165 | 1 | х | х | х |
| 4 Repair water damaged drywall-exhibit closet | \$810 | 1 | х | х | х |
| 5 Replace & expand VC work area for safety ex | it \$18,500 | 1 | х | | |
| 6 Install safety railing at exterior ramp | \$3,330 | 1 | х | | |
| Duct modification and relocation of leaking | | | | | |
| 7 dehumidifer | \$4,355 | 1 | | х | |
| 8 Replace 4 ton AC unit- theatre | \$10,667 | 1 | х | х | х |
| 9 Paint exterior | \$8,220 | 1 | | | х |
| 0 Repair plumbing leaks | \$1,140 | 1 | х | | х |
| 1 Replace dead electric plugs | \$414 | 1 | х | | х |
| 2 Replace broken outside signage | \$6,050 | 1 | | | х |
| 3 Relocate fire truck | \$20,000 | 1 | | | х |
| 4 Install fire suppression | \$120,000 | 2 | х | х | |
| 5 Replace water heater | \$1,480 | 2 | | | х |
| 6 Replace discontinued & damaged ceiling tile | s \$26,000 | 2 | | | х |
| 7 Duct cleaning/sanitizing of existing mold | \$1,890 | 3 | х | х | х |
| 8 Install electronic rekey building | \$55,000 | 3 | х | Х | х |
| 9 Replace archival lighting system | \$25,000 | 3 | | х | х |
| 0 Bathroom sink replacement | \$700 | 3 | х | | х |
| 1 Install mini split AC unit- VC bathrooms | \$11,455 | 3 | х | | х |
| 2 Replace discontinued and damaged carpet | \$14,050 | 3 | | х | х |
| 3 Grout visitor center floor | \$3,000 | 3 | | | х |
| Universal Project Costs | | | | | |
| 4 Project Manager (part time- three years) | \$150,000 | | | | |
| 5 Contigency- 15% | \$75,871 | | | | |
| TOTAL ESTIMATE O | OST \$505,806 | | | | |