

Unit # 674 – 2004 Cat Hydraulic Excavator

Department: Street & Bridge

Vehicle Age: 16 years old

Hours: 8,802.1

Upon inspection by the Equipment Maintenance Lead Mechanic, the following was found.

- Is operable. Serviced every 300 hours.
- Engine has oil leaks and gets hot.
- Radiator is plugged and needs to be replaced.
- Thermostat needs to be replaced.
- Transmission is operable.
- A/C compressor and belt are missing. Not operable.
- Top inside cab panel is missing – wires are hanging down from wiper motor.
- Front bucket hydraulic cylinder is leaking.
- Three of the top idle rollers are worn down and needs to be replaced. Condition of bottom track rollers is unknown.
- Front windshield is cracked.
- Rear right and left side access panel doors are dented.
- Bushings on boom section of the bucket need to be replace.
- Out of service since October 2019.

The repair cost for this unit can range from \$10,000 and up.

