

## **Parker Estates Storm Facility Restoration**

	MacKay Sposito Inc.  Staff Role/Title: Fully Burdened Rate:										Subconsultant Fee	Expenses	TOTALS
		SR PM/PIC \$227.00	Construction Manager \$160.00	Sr. Permit Specialist \$135.00	Environmental Construction Inspector \$134.00	Construction Inspector I \$102.00	Engineer III \$130.00	PM - Survey \$158.00	Land Surveyor III \$129.00	Survey Technician III \$99.00	Beaver State		
Task ID	Task Description		,	,	, , , , , ,	,	,	,		,			
	Basic Services and Deliverables	Hrs	Hrs	Hrs	Hrs	Hrs	Hrs	Hrs	Hrs	Hrs	\$	\$	
1.0	Pre-Construction												
1.1	Project Setup												
1.1.1	Setup Sharepoint site		4										\$640
1.1.2	Prepare & distribute Contact list		2										\$320
1.1.3	Prepare & coordinate submittal list		2										\$320
1.1.4	Review pre-construction submittals		8										\$1,280
													\$0
1.2	Pro Construction Meeting												\$0
	Pre-Construction Meeting												\$0 \$320
1.2.1 1.2.2	Prepare meeting agenda Schedule Pre-Con		2										\$320
1.2.3	Attend / Lead Pre-con meeting	2	2										\$774
1.2.4	Prepare & distribute minutes		2										\$320
1.2.4	r repare & distribute minutes												\$0
1.3	Document Pre-Construction Site Conditions												\$0
1.3.1	Site visit / Photos		2										\$320
			_										\$0
2.0	Beaver State Services												\$0
2.1.1	Review materials, direct assembly, and assist in installation of beaver devices										\$ 8,000		\$8,000
2.1.2	Final Inspection / closeout										\$ 4,100		\$4,100
	Tindi mopodion / Globoodi										Ψ,100		\$0
3.0	Construction												\$0
	Construction Management	6	24		4		12						\$7,298
3.1		0			4		12						
3.2	Construction Inspection		24									\$ 250	\$4,090
3.3	Construction Progress meetings		16		2								\$2,828
													\$0
4.0	Post Construction												\$0
4.1	Punch list / Closeout	1	8		2		1						\$1,905
7.1	i diloit list / Oloscout	I					I						
													\$0 \$0
	Sub-Consultant Markup (10%)											\$ 1,210	\$1,210
	ous sonsultant markap (1070)											Ψ 1,∠10	\$1,210
													10.0
	Design Tasks Summary of Hours	9	98	C	8	0	13		0	0	-		128
												Total	\$34,