

**Odyssey Shankle Bus and Truck  
Repair**

5200 46th Avenue  
Hyattsville, MD 20781  
servicemngr@odyshank.com  
(301) 699-8500

**Estimate**                      **2848**  
**Date:**                      **2/10/2025**

**Bill To**  
TOWN OF COTTAGE CITY  
3820 40TH AVENUE  
BRENTWOOD, MD 20722  
P: 240-461-3835

**Remit Payment To**  
Primary  
5200 46th Avenue  
Hyattsville, MD 20781

Service Order		Purchase Order	Authorizer		
2848					
Item	Description	Quantity	Rate	Amount	
<b>Complaint:</b> INSPECT SALT SPREADER CUTS OFF AFETR 10 SECONDS OF STARTING AND SALT SPREADER CONTROL HAS POWER BUT NOT SENDING POWER TO THE AUGER SALT SPREADER					
<b>Cause:</b>					
Labor	<b>Recommended Correction:</b> Chassis / Chassis /	1.00000	\$170.00	\$170.00	
			<b>Subtotal</b>	\$170.00	
<b>Complaint:</b> REPLACE SERVICE KIT, AUGER SHORT AND BEARING					
<b>Cause:</b> Customer request (Inspection)					
Labor	<b>Recommended Correction:</b> Chassis / Chassis / REPLACE SERVICE KIT, AUGER SHORT AND BEARING	7.00000	\$170.00	\$1,190.00	
Parts	AUGER 5"X66" VMAXX	1	\$1,576.296	\$1,576.30	
Parts	2-BOLT FLANGE BEARING	2	\$74.175	\$148.35	
Parts	1/4"-20X3/4" SERRATED BOLT	1	\$17.96	\$17.96	
Parts	3/8"- 16 SERRATED NUT	1	\$4.425	\$4.43	
Parts	SHIPPING	1	\$174.21	\$174.21	
Parts	AUGER BIT - A	1	\$63.00	\$63.00	
Parts	FLAT WASHER - A	2	\$20.965	\$41.93	
Parts	3/8 X 1 1/2 BOLT - A	20	\$6.375	\$127.50	
Parts	3/8 X 1 1/2 NUT - A	20	\$3.75	\$75.00	
			<b>Subtotal</b>	\$3,418.68	

**Complaint:** REMOVE AND REPLACE MAXX SPREADER CONTROL UNIT, MOTOR AND HARNESS

**Cause:** Customer request (Inspection)

Item	Description	Quantity	Rate	Amount
Labor	<b>Recommended Correction:</b> Chassis / Chassis / REMOVE AND REPLACE MAXX SPREADER CONTROL	8.00000	\$170.00	\$1,360.00
Parts	SPREADER CONTROL - A	1	\$1,448.436	\$1,448.44
Parts	MOTOR - A	1	\$564.187	\$564.19
Parts	HARNESS - A	1	\$243.292	\$243.29
<b>Subtotal</b>				\$3,615.92
HAZ MAT				1.500%
Credit Card Pass-Through fee				3.000%
Shop Supplies				

**Unit:** mes-13989 **VIN:** 1FTWF31578EC87954  
**License Plate:** md83815  
2008FordF-350  
**Chassis:** 47,503 Miles

<b>Labor</b>	\$2,720.00
<b>Parts</b>	\$4,484.60
<b>HAZ MAT(1.50% of \$7,340.60)</b>	\$110.11
<b>Subtotal</b>	\$7,450.71
<b>Exempt (0% of \$0.00)</b>	\$0.00
<b>Credit Card Pass-Through fee (3.000% of \$7,450.71)</b>	\$223.52
<b>Total</b>	\$7,674.23

\*: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.

The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

**Customer Signature:** \_\_\_\_\_

**Printed Name:** \_\_\_\_\_ **Date:** \_\_\_\_\_