



## CITY COUNCIL ITEM SUMMARY

<b>MEETING DATE:</b>	March 18, 2021
<b>SUBCATEGORY:</b>	Bid Award/Purchase
<b>DEPARTMENT NAME:</b>	Water Department
<b>AGENDA ITEM TITLE:</b>	WPCP Pre-Mixer Repair
<b>DEPARTMENT SUMMARY RECOMMENDATION:</b>	<p>One submersible Flygt mixer in the pre-mix tank at the Water Pollution Control Plant is failing.</p> <p>We've requested quotes from the manufacturer for both repair and replacement of this mixer. The repair quote is \$9,527.91, and the replacement cost is \$18,576.32 for an identical mixer.</p> <p>Your approval is recommended to repair the mixer at a cost of \$9,527.91. This will be paid from account 505-3330-52-2361, and is a budgeted item.</p>
<b>LEGAL:</b>	N/A