

# Dalton Fire Department

Dalton, GA

This report was generated on 3/8/2022 9:16:34 AM



## Incident Statistics

Zone(s): All Zones | Start Date: 02/01/2022 | End Date: 02/28/2022

INCIDENT COUNT			
INCIDENT TYPE		# INCIDENTS	
EMS		198	
FIRE		97	
TOTAL		295	
TOTAL TRANSPORTS (N2 and N3)			
APPARATUS	# of APPARATUS TRANSPORTS	# of PATIENT TRANSPORTS	TOTAL # of PATIENT CONTACTS
TOTAL			
PRE-INCIDENT VALUE		LOSSES	
\$420,359,896.00		\$116,420.00	
CO CHECKS			
TOTAL			
MUTUAL AID			
Aid Type		Total	
Aid Given		14	
Aid Received		1	
OVERLAPPING CALLS			
# OVERLAPPING		% OVERLAPPING	
92		31.19	
LIGHTS AND SIREN - AVERAGE RESPONSE TIME (Dispatch to Arrival)			
Station	EMS	FIRE	
Station 1	0:04:34	0:04:20	
Station 2	0:04:57	0:06:08	
Station 3	0:04:50	0:05:02	
Station 4	0:04:19	0:04:46	
Station 5	0:05:20	0:05:48	
AVERAGE FOR ALL CALLS		0:04:41	
LIGHTS AND SIREN - AVERAGE TURNOUT TIME (Dispatch to Enroute)			
Station	EMS	FIRE	
Station 1	0:01:07	0:01:24	
Station 2	0:01:08	0:01:26	
Station 3	0:01:17	0:01:07	
Station 4	0:01:05	0:01:25	
Station 5	0:00:46	0:01:10	

Only Reviewed Incidents included. EMS for Incident counts includes only 300 to 399 Incident Types. All other incident types are counted as FIRE. CO Checks only includes Incident Types: 424, 736 and 734. # Apparatus Transports = # of incidents where apparatus transported. # Patient Transports = All patients transported by EMS. # Patient Contacts = # of PCR contacted by apparatus. This report now returns both NEMSIS 2 & 3 data as appropriate. For overlapping calls that span over multiple days, total per month will not equal Total count for year.

AVERAGE FOR ALL CALLS		0:01:09
AGENCY	AVERAGE TIME ON SCENE (MM:SS)	
Dalton Fire Department	26:31	

Only Reviewed Incidents included. EMS for Incident counts includes only 300 to 399 Incident Types. All other incident types are counted as FIRE. CO Checks only includes Incident Types: 424, 736 and 734. # Apparatus Transports = # of incidents where apparatus transported. # Patient Transports = All patients transported by EMS. # Patient Contacts = # of PCR contacted by apparatus. This report now returns both NEMSIS 2 & 3 data as appropriate. For overlapping calls that span over multiple days, total per month will not equal Total count for year.

# Dalton Fire Department

Dalton, GA

This report was generated on 3/8/2022 9:17:18 AM



## Monthly Incident Hydrant and Fire Marshal Services Report

Start Date: 02/01/2022 | End Date: 02/28/2022

### Average Response Time - 1st arriving Unit

Structure Fires	4:36
Other Fires	4:46
MVAs	3:59
All EMS	4:44
All Incidents	4:20

### Incident Count by Type

<b>Fires (100-199)</b>	<b>Total: 15</b>
Total Structure Fires (111,112)	6
Structure Fires (111,112) w/Hose Deployment	0
Other Fires (100, 113 – 173)	9
Total Water Usage for all Fires	0

<b>EMS (300-399)</b>	<b>Total: 198</b>
Medical Assist, Assist EMS Crew (311)	170
EMS call, excluding vehicle accident with injury (321)	0
Motor Vehicle Accidents (322,323,324)	28
Rescue (350 – 372)	0
All other EMS (300, 320, 331, 340-343, 381)	0
<b>Specialized Responses (400-499)</b>	<b>Total: 12</b>
<b>Service Calls (500-599)</b>	<b>Total: 9</b>
Lockouts (511)	1
Public Service (550 - 555)	2

<b>All Other Incidents (200s, 600s – 900s)</b>	<b>Total: 61</b>
<b>Total Calls for Date Range (100 - 999)</b>	<b>Total: 295</b>

### Mutual and Automatic Aid

Total Mutual and Automatic Aid Given for Fire (100s)	3
Total Mutual and Automatic Aid Received for Fire (100s)	0
Total Mutual and Automatic Aid Given for EMS (300s)	5

Only Completed and Reviewed Primary Exposure Reports are in calculations.



emergencyreporting.com  
Doc Id: 1718  
Page # 1 of 2

# Dalton Fire Department

Dalton, GA

This report was generated on 3/8/2022 9:17:18 AM



Total Mutual and Automatic Aid Received for EMS (300s)	1
--	---

## Hydrants

Hydrants Tested	0
-----------------	---

## Fire Marshal Services

Alcohol	1
Annual	71
Annual Apartment	1
Complaint	1
Fireworks	1
Kitchen Hood Installation	2
New Construction	1
OTC	15
Plan Review	7
Site Visit	61
Unsafe Building	1

Only Completed and Reviewed Primary Exposure Reports are in calculations.



emergencyreporting.com  
Doc Id: 1718  
Page # 2 of 2

# Dalton Fire Department


Dalton, GA

This report was generated on 3/8/2022 9:18:14 AM



## Incidents by Day of the Week for Date Range

Start Incident Type: 100 | End Incident Type: 911 | Start Date: 2/1/2022 | End Date: 2/28/2022



DAY OF THE WEEK	# INCIDENTS
Sunday	36
Monday	37
Tuesday	53
Wednesday	53
Thursday	44
Friday	39
Saturday	33
TOTAL	295

Only Reviewed incidents included.

# Dalton Fire Department


Dalton, GA

This report was generated on 3/8/2022 9:18:42 AM



## Incidents per Zone per Shift for Date Range

Start Date: 02/01/2022 | End Date: 02/28/2022



SHIFT	ZONE	# INCIDENTS
A	District 1	31
	District 2	22
	District 3	12
	District 4	18
	District 5	5
	Out of District WCDF ST1	1
	Whitfield county	5
B	District 1	37
	District 2	13
	District 3	17
	District 4	8
	District 5	12
	Whitfield county	6
C	District 1	40
	District 2	20
	District 3	22
	District 4	10
	District 5	5
	Whitfield county	11

**TOTAL: 295**

The totals reflect the # INCIDENTS each STATION was assigned. Only REVIEWED incidents included.



emergencyreporting.com  
Doc Id: 1285  
Page # 1 of 1

# Dalton Fire Department


Dalton, GA

This report was generated on 3/8/2022 9:19:31 AM



## Incidents per Hour for Incident Type Range for Date Range

Start Incident Type: 100 | End Incident Type: 911 | Start Date: 02/01/2022 | End Date: 02/28/2022



Hour	# of CALLS
00:00 - 00:59	5
01:00 - 01:59	9
02:00 - 02:59	7
03:00 - 03:59	9
04:00 - 04:59	3
05:00 - 05:59	5
06:00 - 06:59	12
07:00 - 07:59	11
08:00 - 08:59	10
09:00 - 09:59	9
10:00 - 10:59	13
11:00 - 11:59	22
12:00 - 12:59	11
13:00 - 13:59	19
14:00 - 14:59	15
15:00 - 15:59	13
16:00 - 16:59	17
17:00 - 17:59	22
18:00 - 18:59	21
19:00 - 19:59	21
20:00 - 20:59	11
21:00 - 21:59	7
22:00 - 22:59	10
23:00 - 23:59	13
TOTAL:	295

Only REVIEWED incidents included.



emergencyreporting.com  
Doc Id: 898  
Page # 1 of 1

# Dalton Fire Department

Dalton, GA

This report was generated on 3/8/2022 9:44:38 AM



## Incident Type Count per Station for Date Range

Start Date: 02/01/2022 | End Date: 02/28/2022

INCIDENT TYPE	# INCIDENTS
<b>Station: 1 - STATION 1</b>	
111 - Building fire	4
113 - Cooking fire, confined to container	1
115 - Incinerator overload or malfunction, fire confined	1
131 - Passenger vehicle fire	1
311 - Medical assist, assist EMS crew	81
322 - Motor vehicle accident with injuries	8
324 - Motor vehicle accident with no injuries.	2
442 - Overheated motor	1
444 - Power line down	1
445 - Arcing, shorted electrical equipment	1
461 - Building or structure weakened or collapsed	3
500 - Service Call, other	3
611 - Dispatched & cancelled en route	4
622 - No incident found on arrival at dispatch address	1
651 - Smoke scare, odor of smoke	1
733 - Smoke detector activation due to malfunction	1
735 - Alarm system sounded due to malfunction	1
743 - Smoke detector activation, no fire - unintentional	4
744 - Detector activation, no fire - unintentional	1
745 - Alarm system activation, no fire - unintentional	1

**# Incidents for 1 - Station 1:**

**121**

<b>Station: 2 - STATION 2</b>	
111 - Building fire	1
113 - Cooking fire, confined to container	1
131 - Passenger vehicle fire	1
142 - Brush or brush-and-grass mixture fire	1
311 - Medical assist, assist EMS crew	23
322 - Motor vehicle accident with injuries	3
324 - Motor vehicle accident with no injuries.	2
412 - Gas leak (natural gas or LPG)	1
500 - Service Call, other	1
520 - Water problem, other	1
551 - Assist police or other governmental agency	1
611 - Dispatched & cancelled en route	7
651 - Smoke scare, odor of smoke	1

Only REVIEWED incidents included.



emergencyreporting.com

Doc Id: 857

Page # 1 of 3



INCIDENT TYPE	# INCIDENTS
652 - Steam, vapor, fog or dust thought to be smoke	1
671 - HazMat release investigation w/no HazMat	1
735 - Alarm system sounded due to malfunction	5
741 - Sprinkler activation, no fire - unintentional	2
743 - Smoke detector activation, no fire - unintentional	1
745 - Alarm system activation, no fire - unintentional	3

**# Incidents for 2 - Station 2:**

**57**

#### Station: 3 - STATION 3

118 - Trash or rubbish fire, contained	1
132 - Road freight or transport vehicle fire	1
311 - Medical assist, assist EMS crew	31
322 - Motor vehicle accident with injuries	3
324 - Motor vehicle accident with no injuries.	2
413 - Oil or other combustible liquid spill	2
440 - Electrical wiring/equipment problem, other	1
441 - Heat from short circuit (wiring), defective/worn	1
444 - Power line down	1
553 - Public service	1
561 - Unauthorized burning	1
611 - Dispatched & cancelled en route	2
622 - No incident found on arrival at dispatch address	1
714 - Central station, malicious false alarm	1
735 - Alarm system sounded due to malfunction	1
741 - Sprinkler activation, no fire - unintentional	1
743 - Smoke detector activation, no fire - unintentional	2
745 - Alarm system activation, no fire - unintentional	3

**# Incidents for 3 - Station 3:**

**56**

#### Station: 4 - STATION 4

142 - Brush or brush-and-grass mixture fire	1
311 - Medical assist, assist EMS crew	24
322 - Motor vehicle accident with injuries	4
323 - Motor vehicle/pedestrian accident (MV Ped)	1
511 - Lock-out	1
611 - Dispatched & cancelled en route	3
622 - No incident found on arrival at dispatch address	1
743 - Smoke detector activation, no fire - unintentional	4
745 - Alarm system activation, no fire - unintentional	2

**# Incidents for 4 - Station 4:**

**41**

#### Station: 5 - STATION 5

111 - Building fire	1
311 - Medical assist, assist EMS crew	11

Only REVIEWED incidents included.

INCIDENT TYPE	# INCIDENTS
322 - Motor vehicle accident with injuries	2
324 - Motor vehicle accident with no injuries.	1
611 - Dispatched & cancelled en route	5
# Incidents for 5 - Station 5:	
20	

Only REVIEWED incidents included.

# Dalton Fire Department



Dalton, GA

This report was generated on 3/8/2022 9:45:16 AM



## Major Incident Types by Month for Date Range

Start Date: 02/01/2022 | End Date: 02/28/2022



INCIDENT TYPE	FEB	TOTAL
False Alarm & False Call	33	33
Fire	15	15
Good Intent Call	28	28
Hazardous Condition (No Fire)	12	12
Rescue & Emergency Medical Service Incident	198	198
Service Call	9	9
<b>Total</b>	<b>295</b>	<b>295</b>

Only REVIEWED incidents included



emergencyreporting.com

Doc Id: 495

Page # 1 of 1

# Dalton Fire Department


Dalton, GA

This report was generated on 3/8/2022 9:45:39 AM



## Count of Aid Given and Received for Incidents for Date Range

Start Date: 02/01/2022 | End Date: 02/28/2022



AID TYPE	TOTAL	% of TOTAL
Automatic aid received	1	0.3%
Mutual aid given	1	0.3%
Automatic aid given	13	4.4%
None	280	94.9%

Only REVIEWED incidents included



# Dalton Fire Department

Dalton, GA

This report was generated on 3/8/2022 9:46:05 AM



## Detailed Fire Losses per Incident Type for Date Range

Start Date: 02/01/2022 | End Date: 02/28/2022

INCIDENT TYPE	COUNT	% OF INCIDENTS	TOTAL LOSSES (Sum of Property and Content Loss)	% OF TOTAL
111 - Building fire	5	55.56 %	\$110,500.00	94.91 %
113 - Cooking fire, confined to container	1	11.11 %	\$20.00	0.02 %
131 - Passenger vehicle fire	2	22.22 %	\$5,500.00	4.72 %
142 - Brush or brush-and-grass mixture fire	1	11.11 %	\$400.00	0.34 %

Only REVIEWED incidents included.



emergencyreporting.com

Doc Id: 1238

Page # 1 of 1

# Dalton Fire Department

Dalton, GA

This report was generated on 3/8/2022 9:46:28 AM



## Detailed Property And Contents Saved for Date Range

Start Date: 02/01/2022 | End Date: 02/28/2022

INCIDENT #	DATE	TYPE	LOCATION	PRE-INCIDENT PROPERTY	PRE-INCIDENT CONTENTS	PRE-INCIDENT TOTAL	PROP. SAVED	CONT. SAVED	TOTAL SAVED
2022-00509	02/15/2022	142 - Brush or brush-and-grass mixture fire	1002 ROCKDALE DR Dalton	\$3,000.00	\$0.00	\$3,000.00	\$2,600.00	\$0.00	\$2,600.00
2022-00529	02/16/2022	131 - Passenger vehicle fire	1329 E Walnut AVE Dalton	\$15,000.00	\$0.00	\$15,000.00	\$14,500.00	\$0.00	\$14,500.00
2022-00540	02/17/2022	111 - Building fire	601 Luckie ST Dalton	\$75,000.00	\$25,000.00	\$100,000.00	\$70,000.00	\$24,500.00	\$94,500.00
2022-00587	02/23/2022	113 - Cooking fire, confined to container	108 W Waterworks ST Dalton	\$125,000.00	\$20.00	\$125,020.00	\$125,000.00	\$0.00	\$125,000.00
2022-00618	02/25/2022	131 - Passenger vehicle fire	2000 Chattanooga RD Dalton	\$11,726.00	\$150.00	\$11,876.00	\$6,726.00	\$150.00	\$6,876.00
2022-00623	02/25/2022	111 - Building fire	1000 Vista DR Dalton	\$250,000,000.00	\$20,000,000.00	\$270,000,000.00	\$250,000,000.00	\$19,995,000.00	\$269,995,000.00
2022-00627	02/26/2022	111 - Building fire	209 Fields AVE Dalton	\$60,000.00	\$20,000.00	\$80,000.00	\$20,000.00	\$5,000.00	\$25,000.00
2022-00633	02/27/2022	111 - Building fire	209 Fields AVE Dalton	\$20,000.00	\$5,000.00	\$25,000.00	\$0.00	\$0.00	\$0.00
2022-00651	02/28/2022	111 - Building fire	2305 Abutment RD Dalton	\$125,000,000.00	\$25,000,000.00	\$150,000,000.00	\$125,000,000.00	\$24,980,000.00	\$149,980,000.00

TOTAL PRE-INCIDENT PROPERTY	TOTAL PRE-INCIDENT CONTENT	TOTAL PRE-INCIDENT	TOTAL PROP. SAVED	TOTAL CONT. SAVED	TOTAL SAVED
\$375,309,726.00	\$45,050,170.00	\$420,359,896.00	\$375,238,826.00	\$45,004,650.00	\$420,243,476.00

Only REVIEWED incidents included



emergencyreporting.com

Doc Id: 1834

Page # 1 of 2

# INCIDENTS	AVG. VAL.	AVERAGE SAVED
9	\$46,706,655.00	\$46,693,719.00

Only REVIEWED incidents included



emergencyreporting.com

Doc Id: 1834

Page # 2 of 2

# **Training Division Monthly Report**

## **February 2022**

### **Overview**

The department delivered a 40-hour Trench Rescue Technician certification course for a total of 25 students. Six attendees from Catoosa and Whitfield County Fire Departments completed the course along with 19 members of DFD's technical rescue team. Hazardous materials and confined space rescue refresher training was delivered to all suppression personnel at Cargill on Brookhollow Industrial Boulevard. This training included a site tour of the Cargill facility and 2 tabletop scenarios involving a chemical release with fire and a confined space rescue simulated using an on-site reactor. Monthly training included territory familiarization, pre-fire training, core competency check-offs, special operations training, and company level drills chosen by company officers. Training hours during the month of February totaled 3,619.

### **Outside Schools**

1 prospective fire investigator attended the 80-hour Fire Investigator Module 1 course at GPSTC.

7 members of the department's technical rescue team attended Structural Collapse Rescue Technician at GPSTC. All 7 members attained national certification through the National Board on Fire Service Professional Qualifications.

6 firefighters attended County Fire Tactics Leadership and Tactics Conference in Pensacola Beach, FL.



# Dalton Fire Department

Dalton, GA

This report was generated on 3/8/2022 8:06:43 AM



## Completed Inspections per Inspection Type for Date Range

Occupancy Status: All | Start Date: 02/01/2022 | End Date: 02/28/2022

ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: Alcohol</b>						
10423 - 2	Super Mercado La Escondida	532 Underwood ST Dalton, GA 30721	02/16/2022	Hearn, Scott Raymond	Passed	

Total # Inspections for Alcohol:

1

<b>Inspection Type: Annual</b>						
10988	Dorsett	1318 May ST Dalton, GA 30720	02/01/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov
10984	Dorsett	1218 May ST Dalton, GA 30720	02/01/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to: dstratton@daltonga.gov
10986	Dorsett Industries	1305 May ST Dalton, GA 30720	02/01/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to: dstratton@daltonga.gov
10987	Dorsett Carpet	1304 May ST Dalton, GA 30720	02/01/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
10958	Synthetic Turf Resources	809 Kenner ST Dalton, GA 30720	02/03/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to: dstratton@daltonga.gov
10765	Shaw Plant 21	330 Brickyard RD Dalton, GA 30720	02/03/2022	Hearn, Scott Raymond	Passed	
11428	TK Wingz	700 Martin Luther King Jr BLVD Dalton, GA 30721	02/03/2022	Blankenship, Donnie	Corrective Action Plan Given	
10846	Engineered Floors	607 Fifth AVE Dalton, GA 30720	02/04/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to: dstratton@daltonga.gov
10769	Sanco	207 Brookhollow Ind. BLVD Dalton, GA 30720	02/04/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add Knox Box to building.
10768	Sanco Inc.	205 Brookhollow Ind. BLVD Dalton, GA 30720	02/04/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add Knox Box to building. Add riser room signage.
11030	Dorsett	1130 Richards ST Dalton, GA 30720	02/04/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.

Includes LOCKED inspections for both archived and unarchived occupancy records.



emergencyreporting.com  
Doc Id: 1026  
Page # 1 of 12

ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: Annual</b>						
10850	Dorsett # 5	911 Mattie DR Dalton, GA 30721	02/04/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
11111	Mohawk	405 Virgil DR Dalton, GA 30720	02/07/2022	Hearn, Scott Raymond	Passed	Add Knox Box to building.
11112	Mohawk (County)	406 Virgil DR Dalton, GA 30720	02/07/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add Knox Box to building.
11247	Vacant	407 Sheridan AVE Dalton, GA 30720	02/08/2022	Stratton, Dale Lee	Passed with Comments	The building is vacant but secured. A site visit was conducted in lieu of an annual inspection. 20220208
11113	First Source Worldwide	413 Virgil DR Dalton, GA 30720	02/08/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add Knox Box to building.
11115	Paradigm Printing	429 Virgil DR Dalton, GA 30720	02/08/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add Knox Box to building, repair or replace emergency lighting.
10818	Ultrasonic Composites	421 Eleventh AVE Dalton, GA 30720	02/08/2022	Stratton, Dale Lee	Corrective Action Plan Given	A corrective action plan has been provided.
10078	Dalton Print Shop	118 W Cuyler ST Dalton, GA 30720	02/08/2022	Blankenship, Donnie	Passed	
10816	Ultrasonic Composites	503 Eleventh AVE Dalton, GA 30720	02/08/2022	Stratton, Dale Lee	Failed	A corrective action plan has been provided.
10339	Murrell S. Tull Jr. D.D.S/ Dalton Dental Assistant School	1017 Riverburch PKY Dalton, GA 30721	02/09/2022	Blankenship, Donnie	Corrective Action Plan Given	
10989	The Pillow Company	1411 May ST Dalton, GA 30720	02/09/2022	Stratton, Dale Lee	Corrective Action Plan Given	A corrective action plan has been provided. A reinspection will be scheduled 30 days from the date of inspection. Email photos of corrected actions to dstratton@daltonga.gov
11272	E.H. Garage	417 Sheridan AVE Dalton, GA 30720	02/09/2022	Blankenship, Donnie	Corrective Action Plan Given	
11299	Clayton Miller Hospitality Carpets	2304 Dalton Industrial CT Dalton, GA 30720	02/09/2022	Blankenship, Donnie	Corrective Action Plan Given	
11306	Mapei	2308 Dalton Industrial CT Dalton, GA 30720	02/09/2022	Blankenship, Donnie	Corrective Action Plan Given	
11107	Shaw Plant # 72	900 V.D.Parrott PKY Dalton, GA 30720	02/10/2022	Blankenship, Donnie	Corrective Action Plan Given	
11433	Shaw Plant T 7	2226 S Hamilton Street EXT Dalton, GA 30721	02/10/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add signage to fire alarm control panel. Add smoke detector above alarm panel. Add Knox Box to building.
11032 - 2	Mannington Mills	950 Riverbend DR Dalton, GA 30721	02/10/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Have risers inspected. Add Knox Box to building.
11434	Shaw Industries Plant 19	1010 V.D. Parrott Jr. PKY Dalton , GA 30720	02/10/2022	Blankenship, Donnie	Corrective Action Plan Given	

Includes LOCKED inspections for both archived and unarchived occupancy records.

ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: Annual</b>						
11150	Shaw Industries #61	616 Walnut (East) AVE Dalton, GA 30720	02/10/2022	Blankenship, Donnie	Passed with Comments	Email a copy of your current inspection reports for fire safety systems.
11116	Corinthian Textiles	441 Virgil DR Dalton, GA 30720	02/10/2022	Hearn, Scott Raymond	Passed with Comments	Add sprinklers to storage racks. Add Knox Box to building. Repair or replace emergency lighting and exit signs.
11435	Frankie's Feed and Seed	203 W Morris ST Dalton, GA 30720	02/10/2022	Blankenship, Donnie	Failed	
10760	Vacant	235 Brickyard RD Dalton, GA 30720	02/10/2022	Hearn, Scott Raymond	Passed with Comments	Vacant
10921	Dryden Oil Company	1221 S Hamilton ST Dalton, GA 30720	02/10/2022	Hearn, Scott Raymond	Passed with Comments	Vacant
11410 - 1	La Esperanza Apartments	1702 E Morris ST Dalton, GA 30720	02/10/2022	Blankenship, Donnie	Corrective Action Plan Given	Progress is being made to become code compliant.
11436	R' and S' Auto Repair	403 Eleventh AVE Dalton, GA 30721	02/10/2022	Stratton, Dale Lee	Passed	
11158	Department of Community Supervision	230 Brickyard RD Dalton, GA 30720	02/11/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Have sprinkler system inspected.
11432	Wacker	2124 S Hamilton ST Dalton, GA 30720	02/11/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add Knox Box to building.
10981	Perpetual Macine Company	1810 Lessco DR Dalton, GA 30720	02/11/2022	Hearn, Scott Raymond	Passed with Comments	Add Knox Box to building.
10815	Mohawk	506 Eleventh AVE Dalton, GA 30720	02/11/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltoga.gov
10852	Hill & Williams Brothers Inc.	434 Fourth AVE Dalton, GA 30720	02/14/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov. A follow up inspection will be conducted in 90 days.
10766	MFG Chemical	1200 Brooks RD Dalton, GA 30720	02/15/2022	Hearn, Scott Raymond	Passed	
11045	Manufacturing Polymer Products	1224 Riverbend RD Dalton, GA 30720	02/15/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Knox Box, FDC sign, sprinkler service.
10983	Postons of Dalton	1311 Ludie ST Dalton, GA 30720	02/15/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov
11028	Cope Brothers Construction	1007 Richards ST Dalton, GA 30720	02/15/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov

Includes LOCKED inspections for both archived and unarchived occupancy records.

ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: Annual</b>						
11048	Garland Sales	415 Sheridan AVE Dalton, GA 30720	02/15/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov
11036	Preferred Tufters	1135 Riverbend DR Dalton, GA 30720	02/16/2022	Hearn, Scott Raymond	Corrective Action Plan Given	
10791	Fabric Sources International	2305 Dalton Industrial CT Dalton, GA 30720	02/16/2022	Blankenship, Donnie	Corrective Action Plan Given	
11007	SAI Resources	1002 E Morris ST Dalton, GA 30720	02/16/2022	Stratton, Dale Lee	Failed	A corrective action plan has been provided. A re-inspection has been scheduled.
10789	Fabric Sources International	2309 Dalton Industrial CT Dalton, GA 30720	02/16/2022	Blankenship, Donnie	Corrective Action Plan Given	
11164	Apollo Textiles	2312 Dalton Industrial CT Dalton, GA 30720	02/16/2022	Blankenship, Donnie	Corrective Action Plan Given	
10792	Capel Inc.	2316 Dalton Industrial CT Dalton, GA 30720	02/16/2022	Blankenship, Donnie	Corrective Action Plan Given	
10929	Harrell Machine Sales	1818 S Hamilton ST Dalton, GA 30720	02/17/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov
11437	Performance Fabric Technology	302 Brickyard RD Dalton, GA 30720	02/18/2022	Hearn, Scott Raymond	Passed	
10762	Premise Health	304 Brickyard RD Dalton, GA 30720	02/18/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add exit signs and emergency lighting.
10940	Dynasty Carpet & Rug Co. Inc.	2210 S Hamilton EXT Dalton, GA 30721	02/18/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add Knox Box to building. Repair one exit sign.
10092	Polyventive	1202 Dozier ST Dalton, GA 30720	02/18/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
11272	E.H. Garage	417 Sheridan AVE Dalton, GA 30720	02/18/2022	Blankenship, Donnie	Corrective Action Plan Given	
10764	Floor Productions Inc.	324 Brickyard RD Dalton, GA 30720	02/21/2022	Hearn, Scott Raymond	Corrective Action Plan Given	
10937	Mayberry Rug	2120 S Hamilton ST Dalton, GA 30720	02/21/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add Knox Box to building.
11212	Mayberry Carpet and Rug	2116 S Hamilton ST Dalton, GA 30720	02/21/2022	Hearn, Scott Raymond	Passed	
10936	Mayberry Rug	2112 S Hamilton ST Dalton, GA 30720	02/21/2022	Hearn, Scott Raymond	Passed	
10758	Display Craft	233 Brickyard RD Dalton, GA 30720	02/21/2022	Hearn, Scott Raymond	Passed with Comments	Add Knox Box to building.
10931	Chem Tech Finishers	1904 S Hamilton ST Dalton, GA 30721	02/22/2022	Stratton, Dale Lee	Passed with Comments	Email photos of corrected actions to dstratton@daltonga.gov

Includes LOCKED inspections for both archived and unarchived occupancy records.

ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: Annual</b>						
10142	Global Textile Services	124 Global DR Dalton, GA 30720	02/22/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov
10957	Daltonian Flooring	131 Global DR Dalton, GA 30720	02/24/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
10371	Supreme Restaurant Supply	401 E Morris ST Dalton, GA 30720	02/24/2022	Hearn, Scott Raymond	Passed	
10948	Universal Textile Technologists	204 W Industrial BLVD Dalton, GA 30720	02/24/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
10947	Emerald Carpets	200 W Industrial BLVD Dalton, GA 30720	02/25/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.
10932	Manly Steel	1907 S Hamilton ST Dalton, GA 30720	02/28/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Update extinguishers.
10946	Tuftco Finishing Systems Inc.	100 W Industrial BLVD Dalton, GA 30720	02/28/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided.

Total # Inspections for Annual: 71

<b>Inspection Type: Annual Apartment</b>						
10671	Mountain Woods Apartments	1000 Cartwright PL Dalton, GA 30720	02/14/2022	Stratton, Dale Lee	Passed with Comments	Repair all fire breaks/smoke stops in the attic spaces.

Total # Inspections for Annual Apartment 1

<b>Inspection Type: Complaint</b>						
11205 - 9	Delicias Reinita Restaurante y Buffet Mexicano	101 W Walnut AVE #19 Dalton, GA 30720	02/10/2022	Stratton, Dale Lee	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov

Total # Inspections for Complaint: 1

<b>Inspection Type: Fireworks</b>						
10380	Cross Pointe Christian Center	2681 Underwood ST Dalton, GA 30720	02/11/2022	Blankenship, Donnie	Passed	

Total # Inspections for Fireworks: 1

<b>Inspection Type: Kitchen Hood Installation</b>						
10351	El Milagro #2	101 E Long ST Dalton, GA 30720	02/11/2022	Hearn, Scott Raymond	Passed	
10344 - 1	Tocayos Mexican Grill LLC	904 S Thornton AVE Dalton, GA 30720	02/14/2022	Hearn, Scott Raymond	Passed	

Total # Inspections for Kitchen Hood Installation: 2

Includes LOCKED inspections for both archived and unarchived occupancy records.



ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: New Construction</b>						
11070	State Farm	1904 Shields RD Dalton, GA 30720	02/08/2022	Blankenship, Donnie	Passed	

Total # Inspections for New Construction: 1

<b>Inspection Type: OTC</b>						
10100 - 3	All-In Counseling	200 W Emery ST #Suite 4 Dalton, GA 30720	02/02/2022	Hearn, Scott Raymond	Passed with Comments	Add extinguisher and ensure exit signs and lights are working.
10121	Helton Tire LLC	212 N Glenwood AVE Dalton, GA 30721	02/02/2022	Blankenship, Donnie	Corrective Action Plan Given	
10318 - 1	Northwest Georgia Mobility	1225 Coronet DR #Suite 3 Dalton, GA 30720	02/04/2022	Hearn, Scott Raymond	Passed	
10387	Ravaa Gowns	927 E Morris ST Dalton, GA 30720	02/04/2022	Blankenship, Donnie	Corrective Action Plan Given	
10321	Antojo Cocina y Cantina	116 W King ST Dalton, GA 30720	02/07/2022	Blankenship, Donnie	Corrective Action Plan Given	
11427	Smoking Bunny	320 W Walnut AVE Dalton, GA 30720	02/07/2022	Blankenship, Donnie	Corrective Action Plan Given	
10620	Whimsy in White	334 S Hamilton ST Dalton, GA 30720	02/07/2022	Hearn, Scott Raymond	Passed	
11351	Quick Stop	304 N Thornton AVE Dalton, GA 30720	02/08/2022	Blankenship, Donnie	Corrective Action Plan Given	
11149 - 3	Hot Spot Laundry	1101 New Doris ST #3 Dalton, GA 30721	02/08/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add suite 3
11431	GSH Properties	101 S Glenwood AVE Dalton, GA 30721	02/08/2022	Blankenship, Donnie	Corrective Action Plan Given	
11348	Affordable Moto Service	710 N Hamilton ST #A Dalton, GA 30720	02/15/2022	Hearn, Scott Raymond	Passed	
10738	Fairfield Inn & Suites	786 College DR Dalton, GA 30720	02/21/2022	Hearn, Scott Raymond	Passed	
10330 - 2	Tienda Jissels	616 Fourth AVE #Suite 2 Dalton, GA 30720	02/21/2022	Hearn, Scott Raymond	Passed	
10651	Green Door General Store	248 N Hamilton ST Dalton, GA 30720	02/24/2022	Blankenship, Donnie	Corrective Action Plan Given	
10719	Akkaya	800 Abutment RD Dalton, GA 30720	02/24/2022	Hearn, Scott Raymond	Corrective Action Plan Given	Add sprinkler system to racks.

Total # Inspections for OTC: 15

Includes LOCKED inspections for both archived and unarchived occupancy records.





ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: Plan Review</b>						
10191	Jeffersons	200 N Hamilton ST Dalton, GA 30720	02/01/2022	Hearn, Scott Raymond	Passed	
10648	Creative Plastics	1409 Coronet DR Dalton, GA 30720	02/08/2022	Daniel, Matthew T.	Passed	Fire alarm plan review.
11326	Blanca's Venue	Pleasant Grove DR NE Dalton, GA 30721	02/14/2022	Blankenship, Donnie	Passed with Comments	Initiated plan review on new construction.
10191	Jeffersons	200 N Hamilton ST Dalton, GA 30720	02/17/2022	Daniel, Matthew T.	Passed	
10643	QEP	1505 Coronet DR Dalton, GA 30720	02/18/2022	Daniel, Matthew T.	Passed	
11326	Blanca's Venue	Pleasant Grove DR NE Dalton, GA 30721	02/21/2022	Blankenship, Donnie	Corrective Action Plan Given	
10610	Tandus	1210 Royal DR Dalton, GA 30720	02/24/2022	Daniel, Matthew T.	Passed	Sprinkler plan review.

Total # Inspections for Plan Review:

7

<b>Inspection Type: Site Visit</b>						
11075 - 7	Just Jump	1423 W Walnut AVE Dalton, GA 30720	02/01/2022	Hearn, Scott Raymond	Passed with Comments	Change of address notification.
11075 - 6	Planet Fitness	1423 W Walnut AVE Dalton, GA 30720	02/01/2022	Hearn, Scott Raymond	Passed with Comments	Delivered change of address notification.
11075 - 5	Buff City Soap	1423 E Walnut AVE #Suite5 Dalton, GA 30721	02/01/2022	Hearn, Scott Raymond	Passed with Comments	Delivered change of address notification.
11075 - 3	Atlas Total Health	1423 W Walnut AVE #Suite3 Dalton, GA 30720	02/01/2022	Hearn, Scott Raymond	Passed with Comments	Delivered address change notification.
11075 - 1	Affordable Dentures and Implants	1423 W Walnut AVE #Suite1 Dalton, GA 30720	02/01/2022	Hearn, Scott Raymond	Passed with Comments	Delivered address change notification.
11075 - 8	Moe's	1419 W Walnut AVE #Suite1 Dalton, GA 30720	02/01/2022	Hearn, Scott Raymond	Passed with Comments	Delivered address change notification.
11075 - 10	United States Navy Recruiting	1419 W Walnut AVE #Suite3 Dalton, GA 30720	02/01/2022	Hearn, Scott Raymond	Passed with Comments	Delivered address change notification.
11075 - 11	United States Marine Corp Recruiting	1419 W Walnut AVE #Suite4 Dalton, GA 30720	02/01/2022	Hearn, Scott Raymond	Passed with Comments	Delivered address change notification.
11075 - 12	United States Army Recruiting	1419 W Walnut AVE #Suite5 Dalton, GA 30720	02/01/2022	Hearn, Scott Raymond	Passed with Comments	Delivered address change notification.

Includes LOCKED inspections for both archived and unarchived occupancy records.



ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: Site Visit</b>						
10456 - 1	Ollie's	1205 N Glenwood AVE #Suite 1 Dalton, GA 30721	02/01/2022	Stratton, Dale Lee	Passed with Comments	System services Ollie's and Roses. Repairs are projected to be completed by February 5, 2022
10456 - 2	Roses	1205 N Glenwood AVE #Suite 3 Dalton, GA 30721	02/01/2022	Stratton, Dale Lee	Passed with Comments	The sprinkler system services Ollie's and Roses. Repairs are projected to be completed by February 5, 2022.
10196 - 2	Apartments @ 222 N Hamilton Street	222 N Hamilton ST Dalton, GA 30720	02/01/2022	Blankenship, Donnie	Failed	
11430	Jesus Believers	508 Sheridan AVE Dalton, GA 30721	02/02/2022	Stratton, Dale Lee	Passed	
10196 - 1	Baja Coop	222 N Hamilton ST Dalton, GA 30720	02/02/2022	Blankenship, Donnie	Passed with Comments	Installed key in Knox Box.
10196	E & D Legacy LLC	222 N Hamilton ST Dalton, GA 30720	02/02/2022	Blankenship, Donnie	Passed with Comments	Install door code in Knox Box.
10943	Shaw Plant # 80	2230 S Hamilton EXT Dalton, GA 30721	02/03/2022	Hearn, Scott Raymond	Passed with Comments	Looking at hydrant info.
10998 - 1	Champion Green	409 North Park DR #Suite A Dalton, GA 30720	02/03/2022	Stratton, Dale Lee	Passed with Comments	Installed Knox Box keys.
10092	Polyventive	1202 Dozier ST Dalton, GA 30720	02/03/2022	Stratton, Dale Lee	Passed with Comments	Site visit was conducted to remove the door of the Knox box so it could be sent back to Knox to be re-keyed for The City of Dalton.
11121	Vacant	455 Virgil DR Dalton, GA 30720	02/03/2022	Hearn, Scott Raymond	Passed with Comments	Vacant as of 2/1/22
11117	Vacant	139 Blacksmith WAY Dalton, GA 30721	02/03/2022	Hearn, Scott Raymond	Passed with Comments	Vacant as of 2/1/2022
11428	TK Wingz	700 Martin Luther King Jr BLVD Dalton, GA 30721	02/03/2022	Stratton, Dale Lee	Passed with Comments	2/3/2022. Assisted Inspector Blankenship with reinspection of the facility.
11244	Dalton Beverages	1007 S Thornton AVE Dalton, GA 30720	02/07/2022	Hearn, Scott Raymond	Passed with Comments	Check on step in bathroom.
10265 - 1	Crescent City Tavern	324 S Depot ST Dalton, GA 30720	02/07/2022	Hearn, Scott Raymond	Passed with Comments	Sent requirements.
11140	Dalton Collision Center	927 S Hamilton ST Dalton, GA 30720	02/08/2022	Stratton, Dale Lee	Passed with Comments	Site visit conducted to assess progress on paint booth suppression system installation and completion of the mixing room wall assemblies.

Includes LOCKED inspections for both archived and unarchived occupancy records.



ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: Site Visit</b>						
10816	Ultrasonic Composites	503 Eleventh AVE Dalton, GA 30720	02/09/2022	Stratton, Dale Lee	Passed with Comments	Site visit was conducted to familiarize Inspector Blankenship with the building discrepancies noted in the annual inspection conducted on 20220802.
10816	Ultrasonic Composites	503 Eleventh AVE Dalton, GA 30720	02/09/2022	Blankenship, Donnie	Passed with Comments	Performed a walk through with Inspector Stratton.
11272	E.H. Garage	417 Sheridan AVE Dalton, GA 30720	02/09/2022	Stratton, Dale Lee	Passed with Comments	Assisted with Inspector Blankenship with a site visit. Occupants were illegally living in a commercial structure.
10958	Synthetic Turf Resources	809 Kenner ST Dalton, GA 30720	02/10/2022	Stratton, Dale Lee	Passed with Comments	Site visit conducted to update contact information and exchange building access keys in the Knox Box.
10794	Synthetic Turf Resources	421 Callahan RD SE Dalton, GA 30720	02/10/2022	Stratton, Dale Lee	Passed with Comments	Site visit conducted to update contact information and exchange building access keys in the Knox Box.
11091	STR	2670 Abutment RD Dalton, GA 30720	02/10/2022	Stratton, Dale Lee	Passed with Comments	Site visit conducted to update contact information and exchange building access keys in the Knox Box.
10979	STR	2680 Abutment RD Dalton, GA 30720	02/10/2022	Stratton, Dale Lee	Passed with Comments	Site visit conducted to update contact information and exchange building access keys in the Knox Box.
10772	STR	310 Brookhollow Ind. BLVD Dalton, GA 30720	02/10/2022	Stratton, Dale Lee	Passed with Comments	Site visit conducted to update contact information and exchange building access keys in the Knox Box.
11145	Little Tokyo	2113 E Walnut AVE Dalton, GA 30721	02/10/2022	Hearn, Scott Raymond	Passed	
10958	Synthetic Turf Resources	809 Kenner ST Dalton, GA 30720	02/11/2022	Stratton, Dale Lee	Passed with Comments	Meeting conducted with a representative from ASA to discuss the fire doors in the structure. Specifically, if the doors could be removed or, would they have to be repaired/replaced.
10671	Mountain Woods Apartments	1000 Cartwright PL Dalton, GA 30720	02/14/2022	Blankenship, Donnie	Passed with Comments	Assisted Inspector Stratton with an annual inspection.
11032	Pollard Properties	950 Riverbend DR Dalton, GA 30721	02/14/2022	Hearn, Scott Raymond	Passed with Comments	Have sprinkler system inspected. Add gate in separation.

Includes LOCKED inspections for both archived and unarchived occupancy records.



ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: Site Visit</b>						
10456 - 2	Roses	1205 N Glenwood AVE #Suite 3 Dalton, GA 30721	02/14/2022	Stratton, Dale Lee	Passed with Comments	I conducted a follow up inspection at Ollie's and Roses to assess repairs and serviceability of the sprinkler system. The initial inspection was conducted on 2-1-2022. As of 2-14-2022, the repairs have not been completed and the system is still offline. The sprinkler repair technician informed the manager that the repairs may be more extensive than previously expected. The repair completion date is tentative.
10456 - 1	Ollie's	1205 N Glenwood AVE #Suite 1 Dalton, GA 30721	02/14/2022	Stratton, Dale Lee	Passed with Comments	Follow up inspection conducted to assess repairs and serviceability of the sprinkler system. As of this date, the repairs have not been completed and the system is still offline. The sprinkler repair technician informed the manager that the repairs may be more extensive than previously expected.
10344 - 1	Tocayos Mexican Grill LLC	904 S Thornton AVE Dalton, GA 30720	02/14/2022	Hearn, Scott Raymond	Passed	
10211	Stay Lodge of Dalton	1116 Willowdale RD Dalton, GA 30720	02/15/2022	Stratton, Dale Lee	Passed with Comments	A site visit was conducted to update contact information.
11396	Dalton Animal Care	1022 S Hamilton ST Dalton, GA 30720	02/15/2022	Blankenship, Donnie	Passed with Comments	I met with the construction manager in regards to fire department requirements for the remodel currently underway.
10008	Westwood Apartments	721 Skylark PL #Office Dalton, GA 30720	02/17/2022	Stratton, Dale Lee	Failed	Site visit conducted to assess progress on the provided corrective action plan. No apparent actions have been taken on the provided corrective action plan. (Reference site visit conducted on 1/18/2022). Inspector Stratton placed a phone call to David Lands to find out why no corrective actions have been addressed. Mr. Lands stated that parts for the hand rails have been ordered. A 30 day extension has been granted.
11435	Frankie's Feed and Seed	203 W Morris ST Dalton, GA 30720	02/17/2022	Hearn, Scott Raymond	Corrective Action Plan Given	
10942	Shaw Plant # 4	2225 S Hamilton EXT Dalton, GA 30721	02/18/2022	Hearn, Scott Raymond	Passed	
11130 - 2	Bargain Hunt	2121 E Walnut AVE Dalton, GA 30720	02/18/2022	Hearn, Scott Raymond	Passed with Comments	Reset alarm.
11130 - 3	Harbor Freight Tools	2125 E Walnut AVE Dalton, GA 30720	02/18/2022	Hearn, Scott Raymond	Passed with Comments	Separate alarm panels.

Includes LOCKED inspections for both archived and unarchived occupancy records.

ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: Site Visit</b>						
10388 - 5	New restaurant	301 E Morris ST Dalton, GA 30720	02/21/2022	Hearn, Scott Raymond	Passed with Comments	Exhaust duct
10100 - 3	All-In Counseling	200 W Emery ST #Suite 4 Dalton, GA 30720	02/21/2022	Hearn, Scott Raymond	Passed	
10784 - 9	Bobbie's Florist	100 W Walnut AVE #Suite 110 Dalton, GA 30720	02/21/2022	Stratton, Dale Lee	Passed with Comments	The tentative date for the firewall repair is April. The corrective action plan has been re-emailed. A 30 day extension has been granted.
10956 - 16	Balance Food Co.	509 Benjamin WAY #500 Dalton, GA 30721	02/21/2022	Hearn, Scott Raymond	Passed	
11007	SAI Resources	1002 E Morris ST Dalton, GA 30720	02/23/2022	Stratton, Dale Lee	Passed with Comments	Site visit conducted to discuss and explain the inspection report to Jackie Poag, the maintenance personnel representing the building owner. Site visit further included ensuring the sprinkler system inspection had been conducted. The system was yellow tagged and a 5 year internal inspection is overdue. Mr. Poag stated that he would inform the building owner and have the inspection scheduled.
11135 - 2	Supreme Spa	2708 Airport RD #suite 3 Dalton, GA 30720	02/24/2022	Blankenship, Donnie	Passed with Comments	The document had requested OTC inspection. There is still work being done in the building. I advised them that once the work is near completion to contact me for the OTC inspection.
00001 - 8	Single Family Dwelling	522 Straight ST Dalton, GA 30721	02/25/2022	Daniel, Matthew T.	Passed	Structure is secure.
10289 - 1	The Gallant Goat	307 S Hamilton ST Dalton, GA 30721	02/25/2022	Blankenship, Donnie	Passed with Comments	The business owner had applied for an occupational tax certificate from the city however there was still a large amount of work needed to be done before the business is ready to open. I advise the owner to contact me once they were ready to open the business.
10336	DPS-Park Creek Elementary School	1500 Hale-Bowen DR Dalton, GA 30720	02/25/2022	Hearn, Scott Raymond	Passed	Delivered educational material.
10440	DPS-Roan Street Elementary School	1116 Roan ST Dalton, GA 30720	02/25/2022	Hearn, Scott Raymond	Passed	Delivered educational material.

Includes LOCKED inspections for both archived and unarchived occupancy records.

ID	OCCUPANCY	ADDRESS	DATE	INSPECTOR	RESULT	NOTES
<b>Inspection Type: Site Visit</b>						
10687	DPS-Blue Ridge Elementary Schools	100 S Bogle ST Dalton, GA 30721	02/25/2022	Hearn, Scott Raymond	Passed	Delivered educational material.
10809	DPS-Brookwood Elementary School	501 Central AVE Dalton, GA 30720	02/25/2022	Hearn, Scott Raymond	Passed	Delivered educational material.
10070	DPS-City Park School	405 School ST Dalton, GA 30720	02/25/2022	Hearn, Scott Raymond	Passed	Delivered educational material.
10524	DPS-Westwood Elementary School	708 Trammell ST Dalton, GA 30720	02/25/2022	Hearn, Scott Raymond	Passed	Delivered educational material.
10332	Christian Heritage Elementary School	1600 MLK Jr. BLVD Dalton, GA 30720	02/25/2022	Hearn, Scott Raymond	Passed	Delivered educational material.

Total # Inspections for Site Visit: 61

<b>Inspection Type: Unsafe Building</b>						
00001 - 10	1404 Belton Avenue	1404 Belton AVE Dalton, GA 30720	02/17/2022	Daniel, Matthew T.	Failed	Parcel# 12-184-01-006 All utilities appear to be disconnected from the structure. The exterior of the structure allows for visual identification of several hazardous conditions. The structure is unfit for human habitation, easily accessible to vagrants and poses an immediate threat to life safety. It is my recommendation that the structure be condemned and demolished.

Total # Inspections for Unsafe Building: 1

**TOTAL # INSPECTIONS: 162**

Includes LOCKED inspections for both archived and unarchived occupancy records.



emergencyreporting.com  
Doc Id: 1026  
Page # 12 of 12

# Dalton Fire Department

Dalton, GA

This report was generated on 3/8/2022 8:06:04 AM



## Occupancy Inspection History per Occupancy with Violations

Inspection Observations: CORRECTIVE ACTION PLAN, FAIL | Occupancy Categories: All Categories | Start Date: 02/01/2022 | End Date: 02/28/2022

INSPECTION DATE	INSPECTION TYPE	RESULT	NOTES	QUESTION	REMARKS	OBSERVATION
Engine 1 A Shift						
Apartments @ 222 N Hamilton Street - 222 N Hamilton ST						
02/01/2022	Site Visit	Failed		If a change of occupancy has occurred, does the building comply with current code requirements?	I performed a site visit based on information that construction was taking place at the building. While on site I observed new construction on division 1 behind Baja Coop. I was advised by workers on site that they were constructing a new apartment in a space that was previously used as a business occupancy. After speaking with Chief Daniel, and Building Official Michael Fowler, I advised the workers that they had to stop work based on the fact that there were no plans submitted or permits pulled to perform the work. I contacted the owner of the building Misty Williams via phone and advised her of the situation. I also spoke later on with Rod Adams whom the owner had hired to oversee the work and advised him of the proper procedures required to perform the work.	FAIL
Dalton Print Shop - 118 W Cuyler ST - 706.226.1624						
02/08/2022	Annual	Passed		Has a Knox Box containing the property access keys been installed?	Install Knox Box on the building.	FAIL

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 1 of 38

**Department of Community Supervision - 230 Brickyard RD - 706.272.2306**

02/11/2022	Annual	Corrective Action Plan Given	Have sprinkler system inspected.	Have sprinklers been maintained and in operational condition?	Have system inspected by a licensed contractor.	CORRECTIVE ACTION PLAN
------------	--------	------------------------------	----------------------------------	---	---	------------------------

**Green Door General Store - 248 N Hamilton ST - 706-980-3884**

02/24/2022	OTC	Corrective Action Plan Given		Are there any identifiable electrical hazards?	Remove combustibles near electrical panels. Install covers on electrical outlets.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Correct address is 248 N Hamilton Street. Change address signage to correct address. Suite number for Green Door is suite 101.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Have fire extinguishers serviced by a GA licensed fire extinguisher contractor. Hang fire extinguisher.	CORRECTIVE ACTION PLAN

**Polyventive - 1202 Dozier ST - 706.226.7028**

02/18/2022	Annual	Passed with Comments	A corrective action plan has been provided.	Is required emergency lighting in place?	Install emergency lighting.	CORRECTIVE ACTION PLAN
				Have sprinklers been maintained and in operational condition?	Installed sprinkler system must operate as designed.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Installed sprinkler system must operate as designed.	CORRECTIVE ACTION PLAN

**Smoking Bunny - 320 W Walnut AVE**

02/07/2022	OTC	Corrective Action Plan Given		Are there any identifiable electrical hazards?	Install covers on electrical outlets.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install code compliant address signage.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 2 of 38

# TK Wingz - 700 Martin Luther King Jr BLVD

02/03/2022	Annual	Corrective Action Plan Given		Are there any identifiable electrical hazards?	1) Extension cords shall not be plugged into multiplug adapters. 2) Junction box covers must be installed on all junction boxes containing electrical wire splices. Complete on 2-3-2022 3) All electrical wire splices must be installed in a covered junction box. Complete on 2-3-2022 4) Install covers on all electrical outlets and switch plate covers on all electrical switches. Complete on 2-3-2022 5) Extension cords shall not substitute permanent electrical wiring.	CORRECTIVE ACTION PLAN
				Has equipment been maintained in proper working condition?	Install listed grease filters in hood system.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 3 of 38

**Westwood Apartments - 721 Skylark PL #Office- 706.537.6584**

02/17/2022	Site Visit	Failed	Site visit conducted to assess progress on the provided corrective action plan. No apparent actions have been taken on the provided corrective action plan. (Reference site visit conducted on 1/18/2022). Inspector Stratton placed a phone call to David Lands to find out why no corrective actions have been addressed. Mr. Lands stated that parts for the hand rails have been ordered. A 30 day extension has been granted.	Have all applicable code requirements been met?	<ol style="list-style-type: none"><li>1) Remove all outdated address signs.</li><li>2) Install address signs reflecting the current assigned address. (use the attached PDF as a guideline)</li><li>3) Repair or replace all handrails.</li><li>4) All fire extinguishers must be operable and require a current annual inspection. The inspection must be conducted by a Georgia licensed contractor.</li><li>5) Repair all overhead hazards.</li></ol> <p>20220217-Site visit conducted to assess progress on the provided corrective action plan. No apparent actions have been taken on the provided corrective action plan. (Reference site visit conducted on 1/18/2022). Inspector Stratton placed a phone call to David Lands to find out why no corrective actions have been addressed. Mr. Lands stated that parts for the hand rails have been ordered. A 30 day extension has been granted.</p>	FAIL
------------	------------	--------	--	---	---	------

**Engine 1 B Shift**

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 4 of 38



**Chem Tech Finishers - 1904 S Hamilton ST - 706-278-8312**

02/22/2022	Annual	Passed with Comments	Email photos of corrected actions to dstratton@daltonga.gov	Is required emergency lighting in place?	Install emergency lighting throughout the building, to include office spaces, and stairwells.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace all exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN
				Is a detector present at the location of each control unit(s), notification appliance circuit power extender(s) and supervising station transmitting equipment of the fire alarm to provide notification?	Install a smoke detector above the Fire Alarm Control Panel.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Multi plug adapters shall be mounted according to manufacturers recommended specifications.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Ensure all doors in means of egress operate as designed.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Install sprinklers in carpet racks. Install sprinklers in the inspection area prior to roll up.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Install sprinkler head wrenches inside the sprinkler cabinets. Install an FDC sign at the Fire Department Connection.	CORRECTIVE ACTION PLAN

**Shaw Industries Plant 19 - 1010 V.D. Parrott Jr. PKY**

02/10/2022	Annual	Corrective Action Plan Given		Are there any identifiable electrical hazards?	Keep combustibles a minimum of 3 feet away from electrical panels. Mark electrical rooms.	CORRECTIVE ACTION PLAN
------------	--------	------------------------------	--	--	---	------------------------

**Engine 1 C Shift****Manly Steel - 1907 S Hamilton ST - (706) 278-3347**

02/28/2022	Annual	Corrective Action Plan Given	Update extinguishers.	Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Update extinguishers.	CORRECTIVE ACTION PLAN
------------	--------	------------------------------	-----------------------	---	-----------------------	------------------------

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 5 of 38

**Quick Stop - 304 N Thornton AVE**

02/08/2022	OTC	Corrective Action Plan Given		Are there any identifiable electrical hazards?	Exposed electrical wiring should be in conduit. Install covers on electrical junction boxes.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install code compliant address signage.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Remove items blocking fire extinguishers.	CORRECTIVE ACTION PLAN

**Engine 2 A Shift****Mannington Mills - 950 Riverbend DR**

02/10/2022	Annual	Corrective Action Plan Given	Have risers inspected. Add Knox Box to building.	Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
				Have sprinklers been maintained and in operational condition?	System out of date.	CORRECTIVE ACTION PLAN

**Performance Fabric Technology - 302 Brickyard RD**

02/18/2022	Annual	Passed		Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
------------	--------	--------	--	--	---------------------------	------------------------

**Sanco - 207 Brookhollow Ind. BLVD - 7062793773**

02/04/2022	Annual	Corrective Action Plan Given	Add Knox Box to building.	Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
------------	--------	------------------------------	---------------------------	--	---------------------------	------------------------

**Sanco Inc. - 205 Brookhollow Ind. BLVD - 706.279.3773**

02/04/2022	Annual	Corrective Action Plan Given	Add Knox Box to building. Add riser room signage.	Have all applicable code requirements been met?	Add riser room sign to door.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN

**Engine 2 B Shift**

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 6 of 38

**Display Craft - 233 Brickyard RD - 706-277-2209**

02/21/2022	Annual	Passed with Comments	Add Knox Box to building.	Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
------------	--------	----------------------	---------------------------	--	---------------------------	------------------------

**Engineered Floors - 607 Fifth AVE - 7062786666**

02/04/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to: dstratton@daltonga.gov	Are exit signs visible?	Relocate exit sign. Exit shall not lead into areas of hire hazard.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Gate code at rear entrance.	CORRECTIVE ACTION PLAN
				Is a fire alarm installed where required by the Code?	Install FACP sign above the door concealing the Fire Alarm Control Panel.  Corrective action completed on 20220204.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	1)Multi plug adapters shall be mounted according to manufacturers recommended specifications. 2) Junction boxes containing electrical wire splices have a junction box cover.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Have sprinklers been maintained and in operational condition?	Ensure sprinkler wrenches have been installed in all sprinkler cabinets.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Ensure proper mounting of all fire extinguishers.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 7 of 38

**Fabric Sources International - 2305 Dalton Industrial CT**

02/16/2022	Annual	Corrective Action Plan Given		Is required emergency lighting in place?	Install emergency lighting as required. Repair or replace emergency lighting.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Install approved exit signage throughout building. Repair or replace exit signage.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Remove items blocking the fire sprinkler riser. Add riser room signage.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install address signage at the road.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Remove obstructions from egress path.	CORRECTIVE ACTION PLAN
				Have sprinklers been maintained and in operational condition?	Remove items blocking fire sprinklers.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install additional fire extinguishers in office area. Hang fire extinguishers. Do not block fire extinguishers.	CORRECTIVE ACTION PLAN

**Hot Spot Laundry - 1101 New Doris ST #3- 7068475208**

02/08/2022	OTC	Corrective Action Plan Given	Add suite 3	Is address signage correct and in place?	Add correct suite number to door.	CORRECTIVE ACTION PLAN
------------	-----	------------------------------	-------------	--	-----------------------------------	------------------------

**R' and S' Auto Repair - 403 Eleventh AVE**

02/10/2022	Annual	Passed		Are there any identifiable electrical hazards?	A junction box cover must be installed on junction boxes containing electrical wire splices.	CORRECTIVE ACTION PLAN
------------	--------	--------	--	--	--	------------------------

**Shaw Plant T 7 - 2226 S Hamilton Street EXT**

02/10/2022	Annual	Corrective Action Plan Given	Add signage to fire alarm control panel. Add smoke detector above alarm panel. Add Knox Box to building.	Have all applicable code requirements been met?	Add smoke detector above FACP. Add FACP signage at door to panel.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN

**Engine 2 C Shift**

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 8 of 38

**All-In Counseling - 200 W Emery ST #Suite 4- +17062266028**

02/02/2022	OTC	Passed with Comments	Add extinguisher and ensure exit signs and lights are working.	Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Add fire extinguisher inspected by licensed Georgia contractor.	CORRECTIVE ACTION PLAN
------------	-----	----------------------	--	---	---	------------------------

**Apollo Textiles - 2312 Dalton Industrial CT - +17062772622**

02/16/2022	Annual	Corrective Action Plan Given		Is required emergency lighting in place?	Add additional emergency lighting as discussed. Repair or replace emergency lighting.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace exit signage. Add additional exit signage as discussed.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Engrave or stamp hydraulic calculation plate.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Keep combustibles a minimum of 3 feet away from electrical panels.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Add code compliant address signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Install sprinkler head in paint booth.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Keep storage a minimum of 18 inches below sprinkler heads.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 9 of 38

**Capel Inc. - 2316 Dalton Industrial CT - 706-277-0967**

02/16/2022	Annual	Corrective Action Plan Given		Is required emergency lighting in place?	Repair or replace emergency lighting.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace exit signage.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Install FDC signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Install sprinklers in all areas of the building.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Install a sprinkler head cabinet with required wrench and heads.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Remove items blocking fire extinguishers.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 10 of 38

**Clayton Miller Hospitality Carpets - 2304 Dalton Industrial CT - 706-281-4501**

02/09/2022	Annual	Corrective Action Plan Given		Is required emergency lighting in place?	Install additional emergency lights as discussed.	CORRECTIVE ACTION PLAN
				Are exits, other than main exits properly marked?	Install exit signage in isle ways.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Have hydraulic call plate stamped or engraved. Install FDC signage.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Remove combustibles near electrical panels.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Replace faded address signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Keep egress paths clear.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Contact a GA licensed fire sprinkler contractor to ensure all areas of the building are properly covered.	CORRECTIVE ACTION PLAN

**Dynasty Carpet & Rug Co. Inc. - 2210 S Hamilton EXT - 706-529-3336**

02/18/2022	Annual	Corrective Action Plan Given	Add Knox Box to building. Repair one exit sign.	Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
------------	--------	------------------------------	--	--	---------------------------	------------------------

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 11 of 38

**Fabric Sources International - 2309 Dalton Industrial CT - 706-226-7333**

02/16/2022	Annual	Corrective Action Plan Given		Is required emergency lighting in place?	Add additional emergency lighting as discussed.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Add additional exit signage as discussed.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Secure compressed gas cylinders. Mark door as not an exit.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Secure electrical panels.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install code compliant address signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Remove items blocking egress paths a minimum of 10 feet back and the width of the egress door.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Ensure all areas of the building required to be sprinklers are properly protected.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Remove items blocking fire sprinkler riser.	CORRECTIVE ACTION PLAN

**Floor Productions Inc. - 324 Brickyard RD - 706-217-6462**

02/21/2022	Annual	Corrective Action Plan Given		Have all applicable code requirements been met?	Remove bucket and other items from sprinkler lines.	CORRECTIVE ACTION PLAN
				Components required to be fire or smoke resistant are properly maintained?	Maintain fire wall integrity. Roll up fire door must be maintained.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Begin a plan to have sprinkler system protection for entire building.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 12 of 38



**Hill & Williams Brothers Inc. - 434 Fourth AVE**

02/14/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov. A follow up inspection will be conducted in 90 days.	Is address signage correct and in place?	Install address signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Has equipment been maintained in proper working condition?	Install a residential hood vented to the exterior of the structure or remove the residential stove.	CORRECTIVE ACTION PLAN

**La Esperanza Apartments - 1702 E Morris ST - 706-270-0178**

02/10/2022	Annual	Corrective Action Plan Given	Progress is being made to become code compliant.	Is required emergency lighting in place?	Add emergency lighting.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Add lighted exit signage.	CORRECTIVE ACTION PLAN
				Are required smoke detectors for elevators installed correctly?	Smoke detectors should be interconnected within the apartment in which they service.	CORRECTIVE ACTION PLAN
				Is the number of means of egress correct?	All bedrooms shall have an approved secondary means of escape.	FAIL

**Mapei - 2308 Dalton Industrial CT - 706-277-7095**

02/09/2022	Annual	Corrective Action Plan Given		Is required emergency lighting in place?	Install additional emergency lights as discussed.	CORRECTIVE ACTION PLAN
				Are exits, other than main exits properly marked?	Install additional exit signage as discussed.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Install FDC signage. Engrave or stamp hydraulic calculation plates.	CORRECTIVE ACTION PLAN
				Is a detector present at the location of each control unit(s), notification appliance circuit power extender(s) and supervising station transmitting equipment of the fire alarm to provide notification?	Email a copy of the current fire alarm inspection report.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Keep storage a minimum of 18 inches below sprinkler heads.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 13 of 38

**Premise Health - 304 Brickyard RD - 706-876-1870**

02/18/2022	Annual	Corrective Action Plan Given	Add exit signs and emergency lighting.	Is required emergency lighting in place?	Add exit sign and emergency lighting.	CORRECTIVE ACTION PLAN
				Are exits, other than main exits properly marked?		CORRECTIVE ACTION PLAN
				Are exit signs visible?		CORRECTIVE ACTION PLAN
				Are doors, passages, or stairways that could be mistaken as an exit marked NO EXIT?	Mark as not an exit.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN

**Wacker - 2124 S Hamilton ST**

02/11/2022	Annual	Corrective Action Plan Given	Add Knox Box to building.	Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
------------	--------	------------------------------	---------------------------	--	---------------------------	------------------------

**Engine 4 A Shift****Dorsett - 1218 May ST - 706-279-3359**

02/01/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to: dstratton@daltonga.gov	Is address signage correct and in place?	Install address sign indicating the correct address.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 14 of 38

**Dorsett - 1318 May ST - 706-278-6711**

02/01/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov	Are exits, other than main exits properly marked?	Install lighted exit sign at the exit.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace all exit lighting that does not operate as designed.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Residential dryer must be vented to the exterior of the structure.	CORRECTIVE ACTION PLAN
				Components required to be fire or smoke resistant are properly maintained?	Fire doors require a current inspection. The inspection must be conducted by a Georgia licensed contractor.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Are proper clearances of combustible materials from ignition sources being maintained?	LP bottles must be stored 10' from the exit.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Remove all impediments from means of egress.	CORRECTIVE ACTION PLAN
				Have sprinklers been maintained and in operational condition?	Install FDC sign at the Fire Department Connection. Install a sprinkler head wrench in the sprinkler box.	CORRECTIVE ACTION PLAN

**Dorsett # 5 - 911 Mattie DR - 7062781961**

02/04/2022	Annual	Passed with Comments	A corrective action plan has been provided.	Have all applicable code requirements been met?	Install panic hardware on egress door.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Repair or replace lighting.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install address sign in an unobstructed location.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	1) Install FDC sign at the Fire Department Connection. 2) Install a sprinkler wrench in the sprinkler cabinet.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 15 of 38

**Dorsett Carpet - 1304 May ST - 706-278-1961**

02/01/2022	Annual	Passed with Comments	A corrective action plan has been provided.	Are exit signs visible?	Install exit signs in the office area as discussed.	CORRECTIVE ACTION PLAN
				Are doors, passages, or stairways that could be mistaken as an exit marked NO EXIT?	Install NO EXIT sign on doorway leading into the warehouse.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Multi plug adapters shall be mounted according to manufacturers recommended specifications. Extension cords shall not be plugged into multi plug adapters. Install blanks in open spaces in electrical panels.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install Knox Box.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Install a RISER ROOM sign on the door concealing the riser. Install sprinkler heads and a sprinkler wrench in the sprinkler cabinet.	CORRECTIVE ACTION PLAN

**Dorsett Industries - 1305 May ST - 706-278-1961**

02/01/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to: dstratton@daltonga.gov	Is required emergency lighting in place?	Install emergency lighting.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace all exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install address sign on the front of the building.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install Knox Box.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Place a sprinkler wrench in the sprinkler cabinet.	CORRECTIVE ACTION PLAN

**Perpetual Macine Company - 1810 Lessco DR - 706-278-0272**

02/11/2022	Annual	Passed with Comments	Add Knox Box to building.	Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
------------	--------	----------------------	---------------------------	--	---------------------------	------------------------

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 16 of 38

**Synthetic Turf Resources - 809 Kenner ST - 706-272-4200**

02/03/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to: dstratton@daltonga.gov	Components required to be fire or smoke resistant are properly maintained?	Fire doors require a current annual inspection.	CORRECTIVE ACTION PLAN
------------	--------	----------------------	--	--	---	------------------------

**The Pillow Company - 1411 May ST - 706-277-3178**

02/09/2022	Annual	Corrective Action Plan Given	A corrective action plan has been provided. A reinspection will be scheduled 30 days from the date of inspection. Email photos of corrected actions to dstratton@daltonga.gov	Is required emergency lighting in place?	Install emergency lighting.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	1) Remove exit signs that do not lead to an exit. 2) Repair or replace all exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	1) Extension cords shall not substitute permanent electrical wiring. 2) Maintain 36" clearance around electrical panels. 3) Repair or replace all damaged electrical fixtures. 4) Install blanks in open spaces in electrical panels. 5) Junction boxes containing electrical wire splices must be covered with a junction box cover. 6) Ensure electrical outlets are properly mounted. 7) Extension cords shall not be plugged into extension cords. Multiplug adapters shall not be plugged into multiplug adapters. Extension cords shall not be plugged into multiplug adapters. 8) Multiplug adapters shall be mounted according to manufacturer's recommended specifications.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Replace faded address signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 17 of 38

			Are proper clearances of combustible materials from ignition sources being maintained?	LP gas cylinders must not be stored inside the structure. LP storage must be relocated to the exterior of the structure and a minimum of 10' from means of egress.	CORRECTIVE ACTION PLAN
			Are the installed sprinkler systems code compliant?	1) Install sprinkler wrenches in the sprinkler cabinets. 2) Install RISER ROOM signage on doors concealing risers. 3) No foreign objects shall be hung or suspended from sprinkler system components. 4) Install FDC sign at the Fire Department Connection.	CORRECTIVE ACTION PLAN
			Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Fire extinguishers must remain free of obstructions and foreign objects.	CORRECTIVE ACTION PLAN

#### Engine 4 B Shift

#### Cope Brothers Construction - 1007 Richards ST

02/15/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov	Are exit signs visible?	Install exit signs.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Replace missing ceiling tiles to complete the ceiling assembly.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Multi plug adapters shall be mounted according to manufacturers recommended specifications.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox box.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	The upper office area requires installation of sprinkler heads.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Install FDC sign at the Fire Department Connection. Install an FDC sign with an indicator arrow on the left side of the building.	CORRECTIVE ACTION PLAN

#### Garland Sales - 415 Sheridan AVE

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 18 of 38

02/15/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov	Is required emergency lighting in place?	Install emergency lighting throughout.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace all exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Install blanks in the open spaces in the electrical panels. Install a cover on the electrical panel. Repair or remove all damaged electrical fixtures. Electrical wiring must be installed in conduit or properly covered with the appropriate materials.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Replace faded FDC sign at the Fire Department Connection. Maintain a clear path to the sprinkler riser. All components of fire suppression systems must be accessible.	CORRECTIVE ACTION PLAN
				Manufacturing Polymer Products - 1224 Riverbend RD		
02/15/2022	Annual	Corrective Action Plan Given	Knox Box, FDC sign, sprinkler service.	Have all applicable code requirements been met?	Add FDC signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
				Have sprinklers been maintained and in operational condition?	Have sprinkler inspection.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



### Postons of Dalton - 1311 Ludie ST

02/15/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov	Are exit signs visible?	Repair or replace all exit lights that do not operate as designed.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Extension cords shall not be plugged into extension cords. Extension cords shall not be plugged into multi plug adapters. Multi plug adapters shall not be plugged into multi plug adapters. Install junction box covers on all junction boxes containing electrical wire splices. Install outlet covers and light switch covers on all electrical outlets and electrical switches.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Replace faded address signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Are proper clearances of combustible materials from ignition sources being maintained?	LP gas cylinder storage must be a minimum of 10' away from exits. LP gas cylinders must be stored outside of the structure.	CORRECTIVE ACTION PLAN

### Preferred Tufters - 1135 Riverbend DR

02/16/2022	Annual	Corrective Action Plan Given		Are exit signs visible?	Repair or replace emergency lighting.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Maintain 3 feet of clearance from electrical panel.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Clear out exits.	CORRECTIVE ACTION PLAN

### SAI Resources - 1002 E Morris ST

02/16/2022	Annual	Failed	A corrective action plan has been provided. A re-inspection has been scheduled.	Is required emergency lighting in place?	Install emergency lighting.	FAIL
				Are exits, other than main exits properly marked?	Install exit signs in the office area.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 20 of 38



				Are exit signs visible?	Install exit signs in the warehouse.	FAIL
				Are there any identifiable electrical hazards?	<p>1) Multi plug adapters shall be mounted according to manufacturers recommended specifications. Extension cord shall not be plugged into extension cords. Extension cord shall not be plugged in multiplug adapters. Multi plug adapters shall not be plugged into multiplug adapters.</p> <p>2) Install junction box covers on all junction boxes containing electrical wire splices.</p> <p>3) Electrical wiring must be installed in conduit or properly covered with the appropriate materials.</p> <p>4) Replace all damaged extension cords.</p> <p>5) Maintain 36" clearance around electrical panels.</p> <p>6) Install blanks in open spaces in electrical panels.</p> <p>7) Properly mount all electrical fixtures.</p> <p>8) Replace damaged electrical wiring</p> <p>9) Extension cords shall not substitute permanent electrical wiring.</p> <p>10) Electrical wire splices shall be installed in a covered and mounted junction box.</p>	FAIL
				Has a Knox Box containing the property access keys been installed?	Install Knox Box.	CORRECTIVE ACTION PLAN
				Are proper clearances of combustible materials from ignition sources being maintained?	<p>1) LP cylinders must be stored outside of the structure.</p> <p>2) Remove all foreign attachments from natural gas supply lines.</p>	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.

				Are the means of egress free of obstructions or impediments?	1) Maintain clear paths of travel. 2) Exit doors shall require no special knowledge to operate and shall be free of obstructions and ready for immediate use. Exit doors shall swing outward. 3) Secure handrail at the emergency exit. 4) Repair exit stairs.	FAIL
				Have sprinklers been maintained and in operational condition?	1) Remove or secure insulation. 2) Sprinkler systems require a current annual inspection. The inspection must be conducted by a Georgia licensed contractor. 3) Repair ceiling assembly in the rear office area.	FAIL
				Are the installed sprinkler systems code compliant?	Remove all foreign attachments from the sprinkler system supply piping. Maintain 18" clearance from sprinkler heads.	FAIL

#### Engine 4 C Shift

#### Corinthian Textiles - 441 Virgil DR - 706-529-9400

02/10/2022	Annual	Passed with Comments	Add sprinklers to storage racks. Add Knox Box to building. Repair or replace emergency lighting and exit signs.	Are exit signs visible?	Repair or replace emergency licensed guts and exit signs.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Add sprinklers to rack storage areas.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN

#### First Source Worldwide - 413 Virgil DR - 706-278-4054

02/08/2022	Annual	Corrective Action Plan Given	Add Knox Box to building.	Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
------------	--------	------------------------------	---------------------------	--	---------------------------	------------------------

#### Mohawk - 405 Virgil DR - 706-278-8000

02/07/2022	Annual	Passed	Add Knox Box to building.	Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
------------	--------	--------	---------------------------	--	---------------------------	------------------------

#### Mohawk (County) - 406 Virgil DR - 706-277-1100

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 22 of 38

02/07/2022	Annual	Corrective Action Plan Given	Add Knox Box to building.	Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN
<b>Paradigm Printing - 429 Virgil DR - 706-226-7474</b>						
02/08/2022	Annual	Corrective Action Plan Given	Add Knox Box to building, repair or replace emergency lighting.	Is required emergency lighting in place?	Repair or replace emergency lighting.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Battery backup not working.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Add Knox Box to building.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 23 of 38

**Shaw Plant # 72 - 900 V.D.Parrott PKY - 706-532-1215**

02/10/2022	Annual	Corrective Action Plan Given		Have all applicable code requirements been met?	Ensure heaters are listed with tilt protection. Maintain 3' clearance from combustibles around heaters. Install riser room signage.	CORRECTIVE ACTION PLAN
				Is a fire alarm installed where required by the Code?	Email a copy of the fire alarm inspection report.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Mount multiplug adapters. Maintain 3' clearance from combustibles in electrical rooms. Mark electrical rooms with signage.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Remove obstructions in egress paths.	CORRECTIVE ACTION PLAN
				Has the fire-extinguishing system and the listed exhaust hood been inspected by a Georgia licensed contractor at least every 6 months?	Have the kitchen suppression system serviced by a GA licensed contractor.	CORRECTIVE ACTION PLAN
				Has the appropriately scheduled inspection of the entire exhaust system for grease buildup been conducted by a Georgia licensed contractor?	Have hood system inspected and cleaned if needed every 6 months.	CORRECTIVE ACTION PLAN
				Have fire hydrants been maintained in proper working condition according to manufacturer's recommended specifications?	Email a copy of the fire hydrant flow inspection report.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Install escutcheon plates as needed.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Fire extinguisher needed in risk management area.	CORRECTIVE ACTION PLAN

**Engine 5 A Shift**

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



**Blanca's Venue - Pleasant Grove DR NE**

02/21/2022	Plan Review	Corrective Action Plan Given		Have all applicable code requirements been met?	Numerous code discrepancies were found during plan review. Comments were left of the plan review and the plan was failed.	CORRECTIVE ACTION PLAN
------------	-------------	------------------------------	--	---	---	------------------------

**Mohawk - 506 Eleventh AVE - 7062771100**

02/11/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov	Is required emergency lighting in place?	Repair or replace all emergency lighting that does not operate as designed	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace all exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Replace missing ceiling tiles in the office area.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Install junction box covers on all junction boxes that contain electrical splices. Install blanks in open spaces in electrical panels.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Relocate the building address numeric to a location they will no be obstructed.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Ensure all exit doors operate as designed. Ensure all exit doors are equipped with panic hardware.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	1) Install FDC sign at the Fire Department Connection. 2) Install Sprinkler cabinet complete with sprinkler heads and sprinkler wrenches, at the riser.	CORRECTIVE ACTION PLAN

**Engine 5 B Shift**

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 25 of 38

**Delicias Reinita Restaurante y Buffet Mexicano - 101 W Walnut AVE #19- 706-529-9641**

02/10/2022	Complaint	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov	Are exit signs visible?	Repair or replace all exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN
				If a change of occupancy has occurred, does the building comply with current code requirements?	Business name does not match the name on the Occupational Tax Certificate. City hall must be contacted to correct this discrepancy.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	All means of egress must remain readily operable and free obstructions. Repair all damaged egress components.	CORRECTIVE ACTION PLAN

**E.H. Garage - 417 Sheridan AVE**

02/09/2022	Annual	Corrective Action Plan Given		Have all applicable code requirements been met?	Occupant is living at the business and has been advised to stop living here immediately.	FAIL
				Are there any identifiable electrical hazards?	Install covers on electrical boxes.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install code compliant address signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Have fire extinguishers serviced by a ga licensed fire extinguisher contractor.	CORRECTIVE ACTION PLAN
02/18/2022	Annual	Corrective Action Plan Given		Are there any identifiable electrical hazards?	Install covers on electrical boxes.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install code compliant address signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 26 of 38

**Murrell S. Tull Jr. D.D.S/ Dalton Dental Assistant School - 1017 Riverburch PKY - 706-226-6153**

02/09/2022	Annual	Corrective Action Plan Given		Is required emergency lighting in place?	Repair or replace emergency lighting.	CORRECTIVE ACTION PLAN
				Are exits, other than main exits properly marked?	Repair or replace exit signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN

**Ladder 3 A Shift****Mountain Woods Apartments - 1000 Cartwright PL - 706-226-2718**

02/14/2022	Annual Apartment	Passed with Comments	Repair all fire breaks/smoke stops in the attic spaces.	Components required to be fire or smoke resistant are properly maintained?	Repair all fire/smoke partitions in the attic space.	CORRECTIVE ACTION PLAN
------------	------------------	----------------------	---	--	--	------------------------

**Squad 1 A Shift****Antojo Cocina y Cantina - 116 W King ST - 571-250-9229**

02/07/2022	OTC	Corrective Action Plan Given		Have all applicable code requirements been met?	Install a carbon monoxide detector in the kitchen area.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Secure electrical panel.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Once the Knox Box is installed contact the fire inspector to secure it.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 27 of 38

**Emerald Carpets - 200 W Industrial BLVD - 706-277-5018**

02/25/2022	Annual	Passed with Comments	A corrective action plan has been provided.	Is required emergency lighting in place?	Install emergency lighting throughout the warehouse.	CORRECTIVE ACTION PLAN
				Is a detector present at the location of each control unit(s), notification appliance circuit power extender(s) and supervising station transmitting equipment of the fire alarm to provide notification?	Install a smoke detector above the fire alarm control panel.	CORRECTIVE ACTION PLAN
				Is a fire alarm installed where required by the Code?	Install breaker lock on breaker servicing the fire alarm control panel.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Install blanks in open spaces in electrical panels.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install Knox Box.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Install sprinklers in the carpet racks.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Replace missing ceiling tiles to maintain ceiling assembly continuity. Install FDC sign on the Fire Department Connection. Install sprinkler head and a sprinkler wrench in the sprinkler cabinets. Remove all foreign attachments and objects from sprinkler piping. Install RISER ROOM sign on door concealing the riser.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install a fire extinguisher in the break room.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 28 of 38



**Frankie's Feed and Seed - 203 W Morris ST**

02/10/2022	Annual	Failed		Is required emergency lighting in place?	Install emergency lighting.	CORRECTIVE ACTION PLAN
				Are exits, other than main exits properly marked?	Install exit signage.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Install code compliant stairs at the rear exit. Contact City Hall for an OTC.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Extension cords should only be used for temporary power. Remove electrical wiring from sprinkler pipe. Exposed electrical wiring should be in conduit. Install covers on electrical outlets. Install covers on electrical boxes. Correct all electrical issues.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install code compliant address signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Doors shall swing in the direction of travel in a means of egress.	CORRECTIVE ACTION PLAN
				Have sprinklers been maintained and in operational condition?	Have sprinkler system inspected and brought up to be code compliant.	FAIL
				Are all required areas of the building sprinkled?	Install sprinkler head in restroom.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install code compliant fire extinguishers. Ensure they have been tagged by a GA licensed fire extinguisher contractor.	CORRECTIVE ACTION PLAN
02/17/2022	Site Visit	Corrective Action Plan Given		Have all applicable code requirements been met?	Repair or replace sprinkler system. Repair or replace rear steps.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 29 of 38

**Harrell Machine Sales - 1818 S Hamilton ST - 706-278-1511**

02/17/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstraton@daltonga.gov	Is required emergency lighting in place?	Install emergency lighting.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Sprinkle office spaces and warehouse lavatory.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Install an FDC sign at the Fire Department Connection.	CORRECTIVE ACTION PLAN

**Helton Tire LLC - 212 N Glenwood AVE**

02/02/2022	OTC	Corrective Action Plan Given		Have all applicable code requirements been met?	Install a properly rated fire door to separate the buildings as discussed.	CORRECTIVE ACTION PLAN
				Is address signage correct and in place?	Install code compliant address signage.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN

**Mayberry Rug - 2120 S Hamilton ST - 706-226-4484**

02/21/2022	Annual	Corrective Action Plan Given	Add Knox Box to building.	Has a Knox Box containing the property access keys been installed?	Add 1 Knox Box at gate.	CORRECTIVE ACTION PLAN
------------	--------	------------------------------	---------------------------	--	-------------------------	------------------------

**Supreme Restaurant Supply - 401 E Morris ST - 706-370-5754**

02/24/2022	Annual	Passed		Is required emergency lighting in place?	Add emergency lighting.	CORRECTIVE ACTION PLAN
				Are exits, other than main exits properly marked?	Add "NOT AN EXIT" on front door..	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Add exit sign to doorway at ramp.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Add an exit doorway in upper section of building.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 30 of 38

# Ultrasonic Composites - 421 Eleventh AVE

02/08/2022	Annual	Corrective Action Plan Given	A corrective action plan has been provided.	Is required emergency lighting in place?	Install emergency lighting in the warehouse area.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace all exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN
				Are doors, passages, or stairways that could be mistaken as an exit marked NO EXIT?	Install a NO EXIT sign on the door in the break room.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Relocate LP cylinder storage a minimum of 10' from exits.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	1) Install switch plate covers and outlet covers on all electrical outlets and switches. 2) Extension cords shall not be plugged into extension cords. Extension cords shall not be plugged into multiplug adapters. Multiplug adapter shall not be plugged into multiplug adapters. 3) Extension cords shall not substitute permanent electrical wiring. 4) Install blanks in open spaces in electrical panels. 5) Install a junction box cover on junction boxes containing electrical wire splices. 6) Electrical wire splices must be installed in a covered and mounted junction box.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Mean of egress must remain readily accessible and free of obstructions.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install two fire extinguishers in the office area. One at the front exit and one at the break room. Install mounted fire extinguishers throughout the warehouse. Fire extinguishers must remain free of obstructions.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



**Ultrasonic Composites - 503 Eleventh AVE - 706-259-3303**

02/08/2022	Annual	Failed	A corrective action plan has been provided.	Is required emergency lighting in place?	Repair or replace all emergency lighting that does not operate as designed. Install emergency lighting throughout the warehouse.	CORRECTIVE ACTION PLAN
				Is a detector present at the location of each control unit(s), notification appliance circuit power extender(s) and supervising station transmitting equipment of the fire alarm to provide notification?	Install a smoke detector above the fire alarm panel.	FAIL
				Is a fire alarm installed where required by the Code?	Installed fire protection devices must be maintained and operate as designed.	FAIL
				Are there any identifiable electrical hazards?	1) Maintain 36" clearance around all electrical panels. 2) Install blanks in open spaces in electrical panels. 3) Extension cords shall not substitute permanent electrical wiring. 4) Repair or remove damaged electrical connections.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box.	CORRECTIVE ACTION PLAN
				Are proper clearances of combustible materials from ignition sources being maintained?	Maintain proper clearance of combustible materials from ignition sources.	FAIL
				Are the means of egress free of obstructions or impediments?	Means of egress must remain free of obstructions and ready for immediate use. Egress doors must remain unlocked while the building is occupied.	FAIL
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install fire extinguishers throughout the building. Fire extinguishers must be inspected and tagged by a Georgia licensed contractor.	FAIL

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 32 of 38

**Universal Textile Technologist - 204 W Industrial BLVD - 706-277-3778**

02/24/2022	Annual	Passed with Comments	A corrective action plan has been provided.	Is required emergency lighting in place?	Install emergency lighting throughout the warehouse. Install emergency lighting in office stairwells.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace all exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Ensure compressed gas cylinders are properly secured.	CORRECTIVE ACTION PLAN
				Is a detector present at the location of each control unit(s), notification appliance circuit power extender(s) and supervising station transmitting equipment of the fire alarm to provide notification?	Install a smoke detector above the fire alarm control panel.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Multi plug adapters shall be mounted according to manufacturers recommended specifications. Repair or replace all damaged electrical fixtures. Remove abandoned electrical wiring and fixtures. Install junction box covers on open junction boxes containing electrical wire splices.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Sprinkle carpet racks.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Install RISER ROOM sign on the door concealing the riser.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install fire extinguishers in the office area. Fire extinguishers must be mounted.	CORRECTIVE ACTION PLAN

**Squad 1 B Shift**

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 33 of 38

**Akkaya - 800 Abutment RD - 706.532.1342**

02/24/2022	OTC	Corrective Action Plan Given	Add sprinkler system to racks.	Have all applicable code requirements been met?	Ensure all exit signs and emergency lighting are working.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	All electrical panel and connections shall be in proper working condition.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Develop plan to add sprinkler protection to rack storage areas.	CORRECTIVE ACTION PLAN

**Daltonian Flooring - 131 Global DR**

02/24/2022	Annual	Passed with Comments	A corrective action plan has been provided.	Is required emergency lighting in place?	Repair or replace all emergency lighting that does not operate as designed.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace exit signs that do not operate as designed.	CORRECTIVE ACTION PLAN
				Is a detector present at the location of each control unit(s), notification appliance circuit power extender(s) and supervising station transmitting equipment of the fire alarm to provide notification?	Install a smoke detector above the fire alarm panel.	CORRECTIVE ACTION PLAN
				Is a fire alarm installed where required by the Code?	Address system trouble alert. Install breaker lock on the breaker servicing the FACP.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Install blanks in open spaces in electrical panels.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Install a sprinkler head wrench in the sprinkler cabinet.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 34 of 38

# Global Textile Services - 124 Global DR

02/22/2022	Annual	Passed with Comments	A corrective action plan has been provided. Email photos of corrected actions to dstratton@daltonga.gov	Is required emergency lighting in place?	Install emergency lighting throughout the warehouse.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Repair or replace all exit signs that do not operate as designed. Install exit signs throughout the warehouse.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Remove residential stove.	CORRECTIVE ACTION PLAN
				Are there any identifiable electrical hazards?	Multi plug adapters shall be mounted according to manufacturers recommended specifications. Install outlet covers on all electrical outlets. Install junction box covers on all junction boxes containing electrical wire splices. Install blanks in open spaces in electrical panels. Maintain 36" clearance around electrical panels. Install the appropriate electrical panel cover.	CORRECTIVE ACTION PLAN
				Are proper clearances of combustible materials from ignition sources being maintained?	LP cylinders must not be stored within 10' of any means of egress. Remove flammable products from under stairwells	CORRECTIVE ACTION PLAN
				Are the means of egress free of obstructions or impediments?	Remove hasp on office space. Exits must remain free of obstructions and ready for immediate use.	CORRECTIVE ACTION PLAN
				Are all required areas of the building sprinkled?	Install sprinklers in the carpet racks.	CORRECTIVE ACTION PLAN
				Are the installed sprinkler systems code compliant?	Replace faded FDC sign at the Fire Department Connction. Install sprinkler wrenches in sprinkler head cabinets.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install fire extinguisher in trucker's lounge.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



**GSH Properties - 101 S Glenwood AVE**

02/08/2022	OTC	Corrective Action Plan Given		Is required emergency lighting in place?	Install emergency lighting through out building.	CORRECTIVE ACTION PLAN
				Are exits, other than main exits properly marked?	Repair or replace exit signage.	CORRECTIVE ACTION PLAN
				Have all applicable code requirements been met?	Replace expired smoke detectors.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install appropriate fire extinguishers. Ensure they have been tagged by a GA licensed fire extinguisher contractor.	CORRECTIVE ACTION PLAN

**Squad 1 C Shift****Ravaa Gowns - 927 E Morris ST**

02/04/2022	OTC	Corrective Action Plan Given		Is required emergency lighting in place?	Install emergency lighting.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Install exit signage as discussed.	CORRECTIVE ACTION PLAN
				Has a Knox Box containing the property access keys been installed?	Install a Knox Box on the building.	CORRECTIVE ACTION PLAN
				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install code compliant fire extinguishers.	CORRECTIVE ACTION PLAN

**Tuftco Finishing Systems Inc. - 100 W Industrial BLVD - (706) 277-1110**

02/28/2022	Annual	Passed with Comments	A corrective action plan has been provided.	Is required emergency lighting in place?	Repair or a place emergency lighting that does not operate as designed. Install emergency lighting throughout the warehouse.	CORRECTIVE ACTION PLAN
				Are exit signs visible?	Install exit signs throughout the office area. Repair or replace all exit signs that do not operate as designed. Install exit signs throughout the warehouse.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.



emergencyreporting.com

Doc Id: 1362

Page # 36 of 38



Are doors, passages, or stairways that could be mistaken as an exit marked NO EXIT?	Repair or replace NO EXIT SIGN.	CORRECTIVE ACTION PLAN
Components required to be fire or smoke resistant are properly maintained?	Installed fire doors require a current annual inspection. The inspection must be conducted by a Georgia licensed contractor.	CORRECTIVE ACTION PLAN
Is a detector present at the location of each control unit(s), notification appliance circuit power extender(s) and supervising station transmitting equipment of the fire alarm to provide notification?	Install a smoke detector above the fire alarm control panel.	CORRECTIVE ACTION PLAN
Is a fire alarm installed where required by the Code?	1) Fire alarm requires a current annual inspection. 2) Install FACP sign above the door concealing the fire alarm control panel. 3) Install a breaker lock on the breaker servicing the fire alarm control panel.	CORRECTIVE ACTION PLAN
Are there any identifiable electrical hazards?	Install junction box covers on junction boxes containing electrical wire splices. Install outlet covers on electrical outlets. Install blanks in open spaces in electrical panels. Electrical fixtures must be properly mounted. Electrical wiring must be installed in conduit or covered with the appropriate materials.	CORRECTIVE ACTION PLAN
Is address signage correct and in place?	Install address signage.	CORRECTIVE ACTION PLAN
Has a Knox Box containing the property access keys been installed?	Install Knox Box.	CORRECTIVE ACTION PLAN
Are the means of egress free of obstructions or impediments?	Ensure all means of egress are free of obstructions.	CORRECTIVE ACTION PLAN

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.

				Does the selection, distribution, installation, and maintenance of portable fire extinguishers comply with NFPA 10?	Install fire extinguishers where indicated.	CORRECTIVE ACTION PLAN
--	--	--	--	---	---	------------------------

Occupancy Inspection History per Occupancy with Violations where Remarks are recorded on Page 2 of Inspection.

