

INVOICE

PLEASE REMIT TO

RASMUSSEN MECHANICAL SERVICES
 3211 NEBRASKA AVE.
 COUNCIL BLUFFS, IA 51501
 Phone: (712) 323-0541



INVOICE NUMBER SRV085519
 INVOICE DATE 12/21/2021
 PO NUMBER
TOTAL DUE \$7,627.26

BILL TO

CITY OF DEADWOOD
 67 DUNLOP AVENUE
 DEADWOOD, SD 57732

LOCATION

ADAMS HOUSE
 22 VAN BUREN STREET
 DEADWOOD, SD 57732

Service Call 210614-0033

Customer Number	Called In By	Payment Terms
0002547	LANCE	Net 30

Description 6/23/21 5 TON A/C UNIT REPLACEMENT: BEGAN THE CONDENSER AND EVAP CHANGE OUT.

7/1/21 RECOVERED REFRIGERANT IN OLD SYSTEM. RAN NEW LINE SET, TESTED FOR LEAKS. INSTALLED A NEW A/C UNIT EVAP COIL AND LINE SET. VACUUM PUMP IS ON UNIT.

7/2/21 FINISHED INSTALL AND PERFORMED START UP.

7/5/21 FIXED THREE CRACKS IN THE EVAPORATOR CONDENSATE PAN THAT WERE NOT NOTICED AT INSTALL.

7/12/21 REPLACED A CRACKED DRAIN PAN ON THE COIL OF THE A/C. PUMPED DOWN THE CONDENSER. CUT THE LINE SET NEXT TO THE COIL. CUT THE CONDENSATE LINE AND PULLED OUT THE COIL. A COIL IS HELD IN PLACE BY 6-8 PLASTIC TABS. BROKE THE TABS TO GET THE COIL OUT. PUT THE COIL IN THE NEW DRAIN PAN, PUT THE COIL AND DRAIN PAN BACK IN THE UNIT. HOOKED UP THE LNE SET AND CONDENSATE. PRESSURE TESTED AND RAN VACUUM PUMP. RAN AND TESTED. ADDED REFRIGERANT. WILL ORDER NEW DRAIN PAN.

8/17/21 SHUT THE UNIT DOWN AND TOOK PANELS OFF. CUT THE DRAIN LINE FREE FROM THE COIL. PULLED THE COIL AND PAN OUT FROM THE UNIT AND TOOK THE OLD PAN OFF OF THE COIL. PUT THENEW PAN ON COIL AND SLID IT BACK IN THE FURNACE. RECONNECTED THE DRAIN. STARTED THE UNIT BACK UP AND VERIFIED IT WAS CONDENSATING AND FILLING THE DRAIN AND NOT LEAKING ANYWHERE ELSE.

Detail of Charges

Charges	Description	Quantity	Total
LABOR			\$3,472.00
		Subtotal	\$7,627.26
		Total Tax	\$0.00
		Amount Paid	\$0.00
		Total	\$7,627.26