



# PinPoint PDR

Shop: 1528 North Canyon Street, Spearfish, South Dakota, 57783  
 Mailing: 1528 North Canyon Street, Spearfish, South Dakota, 57783  
 www.pinpointpdr.com | slade@pinpointpdr.com  
 Phone: 6056457812 | Tax ID: 92-0452284

**Invoice# 1318**  
 Date Created: 11/14/2024  
 P.O.#: \_\_\_\_\_

## City Of Lead Deadwood

| lornie@cityofdeadwood.com

*Trent's vehicle*

### 2018 Chevrolet Colorado, White

VIN: 1GCHTBEA6J1171581  
 Odometer: 12012

Stock/RO#: \_\_\_\_\_  
 License: \_\_\_\_\_

Vehicle Owner: Deadwood Planning And Zoning

#### Services Summary:

**Hail:** \$4,400.00 - **Hood:** Conventional Repair, **LT Fender:** \$250.00, **RT Fender:** \$175.00, **LT Front Door:** \$175.00, **RT Front Door:** \$175.00, **LT Rear Door:** \$175.00, **RT Rear Door:** \$125.00, **Roof:** \$1,875.00, **LT Roof Rail:** \$312.50, **RT Roof Rail:** \$562.50, **LT Bedside:** \$400.00, **RT Bedside:** \$175.00

**R&I/R&R:** \$1,246.00 - **Front Bumper:** \$126.00, **Hood:** \$63.00, **LT Fender:** \$84.00, **RT Fender:** \$84.00, **LT Front Door:** \$98.00, **RT Front Door:** \$189.00, **LT Rear Door:** \$49.00, **RT Rear Door:** \$49.00, **Roof:** \$301.00, **LT Bedside:** \$49.00, **RT Bedside:** \$154.00


**Paint & Body:** \$876.00 - **Hood:** \$636.00, Paint, Add for clear coat, Add for underside, **LT Fender:** \$120.00, Blend, **RT Fender:** \$120.00, Blend

**Parts:** \$984.00 - **Hood:** \$984.00

**Repaired By:** - Jake Wendt


#### Paintless Dent Repair: \$4,400.00

<b>Hood:</b> Conventional Repair	<b>Roof:</b> \$1,875.00
<b>LT Fender:</b> \$250.00	<b>LT Roof Rail:</b> \$312.50
<b>RT Fender:</b> \$175.00	<b>RT Roof Rail:</b> \$562.50
<b>LT Front Door:</b> \$175.00	<b>LT Bedside:</b> \$400.00
<b>RT Front Door:</b> \$175.00	<b>RT Bedside:</b> \$175.00
<b>LT Rear Door:</b> \$175.00	
<b>RT Rear Door:</b> \$125.00	



#### Paint & Body: \$730.00

**Hood:** \$636.00  
**LT Fender:** \$120.00  
**RT Fender:** \$120.00



Service Type	Description	Body Hours	Paint Hours	Total
<b>Front Bumper</b>				
R&I / R&R - \$126.00				
<b>Labor, R&amp;I</b>	<b>Bumper Assembly</b>	<b>1.8</b>	<b>--</b>	<b>\$126.00</b>

---

## Hood

R&I / R&R - \$63.00 | Paint & Body - \$371.00 | Paint Materials - \$265.00 | Parts - \$984.00

<b>Note</b>	Needs conventional repair	--	--	--
<b>Labor, R&amp;I</b>	<b>Insulator</b>	<b>0.3</b>	--	<b>\$21.00</b>
<b>Labor, R&amp;I</b>	<b>Hood</b>	<b>0.6</b>	--	<b>\$42.00</b>
<b>Labor, Paint</b>	<b>Paint</b>	--	<b>2.8</b>	<b>\$196.00</b>
<b>Labor, Paint</b>	<b>Add for clear coat</b>	--	<b>1.1</b>	<b>\$77.00</b>
<b>Labor, Paint</b>	<b>Add for underside</b>	--	<b>1.4</b>	<b>\$98.00</b>
<b>Part (OEM)</b>	<b>Hood</b> Part Number: 84858037	--	--	<b>\$984.00</b>

---

## LT Fender

PDR - \$250.00 | R&I / R&R - \$84.00 | Paint & Body - \$70.00 | Paint Materials - \$50.00

<b>PDR</b>	<b>16-30 dents, Quarter: \$250.00</b>	--	--	<b>\$250.00</b>
<b>Labor, R&amp;I</b>	<b>Fender Liner</b>	<b>0.4</b>	--	<b>\$28.00</b>
<b>Labor, R&amp;I</b>	<b>Headlamp</b>	<b>0.8</b>	--	<b>\$56.00</b>
<b>Labor, Paint</b>	<b>Blend</b>	--	<b>1.0</b>	<b>\$70.00</b>

---

## RT Fender

PDR - \$175.00 | R&I / R&R - \$84.00 | Paint & Body - \$70.00 | Paint Materials - \$50.00

<b>PDR</b>	<b>6-15 dents, Quarter: \$175.00</b>	--	--	<b>\$175.00</b>
<b>Labor, R&amp;I</b>	<b>Fender Liner</b>	<b>0.4</b>	--	<b>\$28.00</b>
<b>Labor, R&amp;I</b>	<b>Headlamp</b>	<b>0.8</b>	--	<b>\$56.00</b>
<b>Labor, Paint</b>	<b>Blend</b>	--	<b>1.0</b>	<b>\$70.00</b>

---

## LT Front Door

PDR - \$175.00 | R&I / R&R - \$98.00

<b>PDR</b>	<b>6-15 dents, Quarter: \$175.00</b>	--	--	<b>\$175.00</b>
<b>Labor, R&amp;I</b>	<b>Mirror</b>	<b>0.7</b>	--	<b>\$49.00</b>
<b>Labor, R&amp;I</b>	<b>Interior Trim Panel</b>	<b>0.4</b>	--	<b>\$28.00</b>
<b>Labor, R&amp;I</b>	<b>Belt Molding</b>	<b>0.3</b>	--	<b>\$21.00</b>

---

**RT Front Door**

PDR - \$175.00 | R&amp;I / R&amp;R - \$189.00

<b>PDR</b>	<b>6-15 dents, Quarter: \$175.00</b>	--	--	<b>\$175.00</b>
<b>Labor, R&amp;I</b>	<b>Mirror</b>	<b>0.7</b>	--	<b>\$49.00</b>
<b>Labor, R&amp;I</b>	<b>Interior Trim Panel</b>	<b>0.4</b>	--	<b>\$28.00</b>
<b>Labor, R&amp;I</b>	<b>Belt Molding</b>	<b>0.3</b>	--	<b>\$21.00</b>
<b>Labor, R&amp;I</b>	<b>Glass</b>	<b>1.3</b>	--	<b>\$91.00</b>

---

**LT Rear Door**

PDR - \$175.00 | R&amp;I / R&amp;R - \$49.00

<b>PDR</b>	<b>6-15 dents, Quarter: \$175.00</b>	--	--	<b>\$175.00</b>
<b>Labor, R&amp;I</b>	<b>Belt Molding</b>	<b>0.3</b>	--	<b>\$21.00</b>
<b>Labor, R&amp;I</b>	<b>Interior Trim Panel</b>	<b>0.4</b>	--	<b>\$28.00</b>

---

**RT Rear Door**

PDR - \$125.00 | R&amp;I / R&amp;R - \$49.00

<b>PDR</b>	<b>1-5 dents, Quarter: \$125.00</b>	--	--	<b>\$125.00</b>
<b>Labor, R&amp;I</b>	<b>Belt Molding</b>	<b>0.3</b>	--	<b>\$21.00</b>
<b>Labor, R&amp;I</b>	<b>Interior Trim Panel</b>	<b>0.4</b>	--	<b>\$28.00</b>

---

**Roof**

PDR - \$1,875.00 | R&amp;I / R&amp;R - \$301.00

<b>PDR</b>	<b>201-300 dents, Quarter: \$1,500.00 Tall Vehicle, 25.00%: \$375.00</b>	--	--	<b>\$1,875.00</b>
<b>Labor, R&amp;I</b>	<b>Antenna</b>	<b>0.8</b>	--	<b>\$56.00</b>
<b>Labor, R&amp;I</b>	<b>Headliner</b>	<b>3.3</b>	--	<b>\$231.00</b>
<b>Labor, R&amp;I</b>	<b>Third Brake Light</b>	<b>0.2</b>	--	<b>\$14.00</b>

---

**LT Roof Rail**

PDR - \$312.50

<b>PDR</b>	<b>6-15 dents, Quarter: \$250.00 Glue Pull, 25.00%: \$62.50</b>	--	--	<b>\$312.50</b>
------------	---	----	----	-----------------

---

**RT Roof Rail**

PDR - \$562.50

<b>PDR</b>	<b>16-30 dents, Quarter: \$450.00 Glue Pull, 25.00%: \$112.50</b>	--	--	<b>\$562.50</b>
------------	---	----	----	-----------------

---

**LT Bedside**

PDR - \$400.00 | R&amp;I / R&amp;R - \$49.00

<b>PDR</b>	<b>31-50 dents, Quarter: \$400.00</b>	--	--	<b>\$400.00</b>
<b>Labor, R&amp;I</b>	<b>Bed Cap</b>	<b>0.4</b>	--	<b>\$28.00</b>
<b>Labor, R&amp;I</b>	<b>Taillight</b>	<b>0.3</b>	--	<b>\$21.00</b>

---

**RT Bedside**

PDR - \$175.00 | R&amp;I / R&amp;R - \$154.00

<b>PDR</b>	<b>6-15 dents, Quarter: \$175.00</b>	--	--	<b>\$175.00</b>
<b>Labor, R&amp;I</b>	<b>Bed Cap</b>	<b>0.4</b>	--	<b>\$28.00</b>
<b>Labor, R&amp;I</b>	<b>Taillight</b>	<b>0.3</b>	--	<b>\$21.00</b>
<b>Labor, R&amp;I</b>	<b>Tonneau Cover</b>	<b>1.5</b>	--	<b>\$105.00</b>

---

**Invoice Totals**

Service Type	Rate	Hours	Total
<b>PDR</b>	--	--	<b>\$4,400.00</b>
<b>Labor, R&amp;I / R&amp;R</b>	<b>\$70.00</b>	<b>17.8</b>	<b>\$1,246.00</b>
<b>Parts</b>	--	--	<b>\$984.00</b>
<b>Labor, Paint</b>	<b>\$70.00</b>	<b>7.3</b>	<b>\$511.00</b>
<b>Labor, Body</b>	<b>\$70.00</b>	<b>0.00</b>	--
<b>Materials</b>	<b>\$50.00</b>	<b>7.3</b>	<b>\$365.00</b>

I have inspected my vehicle(s) and am satisfied that PINPOINT PDR has completed repairs to my satisfaction.

Grand Total: **\$7,506.00****BALANCE DUE: \$7,506.00**