

1022 N. TURBINE DR. RAPID CITY, SD 57703 P: (800) 233-3437

F: (605) 341-7516 605-348-4900





BILL TO CITY OF DEADWOOD - 41721 102 SHERMAN STREET DEADWOOD SD 57732

P:

F: (605) 578-2084

DELIVER TO
CITY OF DEADWOOD - 41721
67 DUNLAP ST
DEADWOOD SD 57732
P: (605) 641-7745

F: (605) 578-2084

SERVICE ESTIMATE: E201033532

DA	ATE ARRIVED	DATE INVOICE	SALES TYPE	ADVISO	R	TERMS	CUSTOMER RI	EFERENCE
10/1/2024	4:12:13PM		SRET	JENNIFE	RH	NET30		
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2014	FREIGHTLINER	SD	3ALDG5CY1EDFT8479		0	11/19/2013	73569561	14572

Estimate Operations

JOB#1 ea

EXPRESS ASSESSMENT

COMPLAINT

NO POWER TRUCK IS DERATED

CAUSE

CORRECTION

Unit would not communicate on the 1939 data link inspected and found one pin is pushed out of the 9-pin connector and the connector will need replaced. Was able to get the unit to make enough contact to hook up and pulled faults and the unit is derated due to the outlet NOX sensor. Sensor will need replaced along with the DLC connector. Did verify power and ground and data link to sensor and priced out needed parts for the unit.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
		EXPRESS ASSESSMENT		
1		ELECTRONIC HOOKUP FEE		
1		SENSOR,NITROGEN OXIDE		
1		(4326872D) SENSOR,NITROGEN OXI		
-1		(4326872D) SENSOR,NITROGEN OXI		9)
2		TERM-MALE,S16,G-PLD,0.8-1		
1		END CONNECTOR		
1		703003 FREIGHT-CUMMINS		
1		703003 FREIGHT-DTNA		

JOB #2 96 TOWING

COMPLAINT

TOWED IN

CAUSE

CORRECTION

QTY	ITEM	DESCRIPTION					UNIT PRICE	EXTD PRICE
		TOWING						0.00
			Prepay: \$0	Parts: \$0	Labor: \$0	Misc: \$0	Sublet: \$0	\$0.00

JOB #3 04 RECALLS / CAMPAIGNS

COMPLAINT

FL654-E - IMMI SEAT BELT BUCKLES

CAUSE

CORRECTION



SERVICE ESTIMATE: E201033532 ESTIMATE: R201046816:01

	Estimate Operations (Cont.)						
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE			
		RECALLS / CAMPAIGNS					
1		KIT, BUCKLE ASSEMBLY					
		DRIVER SIDE					
1		KIT,BUCKLE ASSMY L9 CMPGN					
		PASS. SIDE					

JOB #4 32 **SUSPENSION**

COMPLAINT

Drivers side drive axle spring pack has broken leaf. -

CAUSE

CORRECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
		SUSPENSION		
2		SPR ,RR SUSP,23K,4X4,M2		
2		PAD-RR SUSP,SLIPPER, U		
2		SCREW-CAP,HEX3/4-10X6,		
4		U-BOLT,SPR SUSP,M2,7/8		
8		WASHER-FLAT, STEEL, HARDENED, 7/8		
8		GR 8 HIGH NUT		

JOB #5 06 PTO/HYDRAULICS

COMPLAINT

HYD OIL LEAK AT PTO PUMP- this is for tear down only because need to find what is leaking

CAUSE

CORRECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
		PTO / HYDRAULICS		

JOB #6 01 **ENGINE**

COMPLAINT

NEED TO DO MORE DIAG ON TURBO SEE JOB 1

CAUSE CORRECTION

Ran the unit up to operating temp and the codes came back. Drained the coolant and removed the turbo actuator two of the bolts were so rusted they did not come loose they just striped out and had to be drilled and extracted. Got the actuator off and found the turbo is sticking when hot Recommend turbo and actuator due to both being original and possible damage caused to actuator from turbo not moving properly.



SERVICE ESTIMATE: E201033532

ESTIMATE: R201046816:01

Estimate Operations (Cont.)					
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE	
		ENGINE		1,750.00	
1		KIT, TURBOCHARGER ACTUATOR	1,915.97	1,915.97	
1		(4034090D) KIT, TURBOCHARGER AC	375.00	375.00	
-1		(4034090D) KIT, TURBOCHARGER AC	375.00	-375.00	
1		KIT,ICP TURBOCHARGER	5,898.88	5,898.88	
1		(3780074D) KIT,ICP TURBOCHARGE	937.50	937.50	
-1		(3780074D) KIT,ICP TURBOCHARGE	937.50	-937.50	
4		STUD	13.59	54.36	
4		NUT	4.92	19.68	
1		SEAL,O RING	8.66	8.66	
1		CLAMP,EXHAUST,EPA04,ISC-READ N	36.18	36.18	
1		CLAMP-V BAND, TURBOCHARGER, 4.1	35.85	35.85	
1		703003 FREIGHT	65.25	65.25	
		Prenay: \$0 Parts: \$7 969 58 Labor: \$1 750 00 Misc:	\$65.25 Sublet: \$0	\$9 784 83	

Prepay: \$0 Parts: \$7,969.58 Labor: \$1,750.00 Misc: \$65.25 Sublet: \$0 \$9,784.83

ADDITIONAL SERVICE REQUEST JOB #7 ASR

CLAIM NUMBER#

COMPLAINT

Clamp on Decomp tube broken.

CAUSE

CORRECTION

ΩΤΥ	ITEM	DESCRIPTION				UNIT PRICE	EXTD PRICE
-			Prepay: Parts:	Labor:	Misc:	Sublet:	

Factory Warranty. We do not guarantee that any repairs you request will be covered by your manufacturer warranty. We do not issue your warranty; we are merely a factory-authorized warranty repair facility. We will do our best to determine your warranty coverage prior to the repair, and we will submit to the manufacturer repairs that we believe qualify for manufacturer warranty coverage. But the manufacturer may deny your claim. In the event the manufacturer denies your claim, you are fully responsible for all charges incurred.

Workmanship Warranty; Disclaimer. We warranty labor and/or workmanship for 30 days following the completion of repair. No claim will be honored past the stated 30-day period. We expressly disclaim all other warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose. We do not assume nor authorize any other person to assume for it any liability in connection with the sale of the parts or repair. In no event are we liable to you or any third-party for any indirect, special, punitive, incidental, or consequential damage connected to, or arising out of, our work on your vehicle whether the damage arises from breach of contract or tort or whether we have been previously advised of the possibility of such damage. If we are found liable to you for any damage, our damages are limited to the replacement of parts and/or the labor cost of repeating the service.

Acts of God. We are not responsible for damage to your vehicle dur to acts of God that occur while your vehicle is in our possession. Acts of God include but are not

Payment. All charges for repairs, including labor and materials, are due at or before the time we tender the vehicle to you. We may tender the vehicle to you through a phone call, mail, email, or any other means of communication that shows, upon payment, we are returning the vehicle to your custody. If any charges remain unpaid for 30 days past due, we may hire attorneys to help with collection, and you are responsible for paying those attorney's fees. Further, we will charge you interest monthly on all past due amounts at a rate of 16% per annum.

Storage Charge. If you do not take custody of the vehicle within three days after we tender the vehicle to you, we will charge you a storage fee of \$25.00 per day.

Credit Card Surcharge: Our credit card processor will impose a surcharge on credit cards that will not be greater than our cost of acceptance. This surcharge will not reflect on this invoice but will reflect on credit card receipt.

TOTAL.	\$9,977.33
TAX	\$0_
MISC SUPPLIES	\$0.00
SHOP SUPPLIES	\$192.50
SUBTOTAL	\$9,784.83
PREPAY	\$0.00
SUBLET	\$0.00
MISC	\$65.25
PARTS	\$7,969.58
LABOR	\$1,750.00

Please Remit Payment to: FLOYD'S TRUCK CENTER-RAPID CITY PO BOX 536 RAPID CITY SD 57709 605-348-4900

Scan to leave a Google Review



AUTHORIZED BY	DATE	