

9892 40th Ave South Seattle, WA 98118 Phone: 206-518-1160

Email: sdavies@papemh.com

City Of Dillingham Attn:Dean Heyano 810 2Nd Ave W. Dillingham, AK 99576

Dear Dean,		
Thank you for the opportunity to pro	vide this estimate for servicing your equipment.	
Make Model S/N		Unit#
HY H1050HDS & H800E	A917E01599K & D117E01902D	
Travel Time, Round Trip Airfare & 8 Nights Lodging For 2 Techs.		\$11,400.00
H800E Carriage & Ss Repairs + Full 1000Hr. Filter 'C' Service		\$47,608.73
H1050Hds Carriage & Ss Repairs + Full 1000Hr. Filter 'C' Service		\$72,921.33
Additional Carry Over 1050 Repair For The New Control Valve		\$14,289.50
*Techs To Use Customer Oil, 0	Grease/Lube, And Man/Basket Lift*	
**Travel Day To Site, 7 Workin	g Days (2 Techs), Travel Day Home**	
***Sales Tax & Inbound Freigh	t Not Included In Quoted Total***	
Repair Totals		\$146,219.56
Related Costs		\$0.00
Pick Up & Delivery		N/A
Rental with Repair (per w	veek)	N/A
Grand Total		\$146,219.56
The prices listed on this proposal are based on to perform on	performing all work listed, and may change if all work is not comple ly certain items,we will re-quote them to reflect any price changes.	ted collectively. Should you elect
Freight on Inbount Parts: Unless otherwis days. Please indicate below if you would lik	se specified, out of stock items are shipped in ground and typ e expedited freight for an additional charge.	ically takes 4 to 5 business
	_ Next Day Air   2nd Day Air   3rd Day Select	
machine work. It is based on doing the complet	timate. This proposal does not include cartage, freight charges on inco te job, and is subject to 10% variance. Related costs include shop sup edule these repairs, or if you have any questions or require further infor	plies, miscellaneous hardware,
Respectfully Submitted,		epted
	PO#	
Sam Davies		
- Product Support Representative	Signed	