

Quality Refrigeration & Heating Inc.

37351 Co. Rd. 248  
 Deer River, MN 56636  
 218-246-2731

# Invoice

DATE	INVOICE #
7/9/2024	25368

BILL TO
Pokegama Golf Coarse 3910 Golf Course Road Grand Rapids, MN. 55744

P.O. NO.	TERMS	Service Date
	Due on receipt	

QTY	ITEM	DESCRIPTION	RATE	AMOUNT
		WI COOLER		
4	R-404A-24	R-404A-24(HP62) Refrigerant	31.95	127.80
1	1653401	914-0006-03 Start Capacitor	111.15	111.15
1	4934105	010-1483 Pressure Control	183.95	183.95
1	Truck Charge		12.00	12.00
2.25	Labor-RA	Found system low on charge. Added refrigerant for now. Will come back to leak check. Noticed WI Freezer compressor not starting. Found the start capacitor terminals corroded. Replaced and found system not pumping down. LP switch will not open. Replaced with new and compressor is inefficient. Will return.	106.00	238.50
Thank you for your business.			<b>Total</b>	\$673.40

1-1/2% Per Month Service Charge on Amount Past Due.

Quality Refrigeration & Heating Inc.

37351 Co. Rd. 248  
 Deer River, MN 56636  
 218-246-2731

**Invoice**

DATE	INVOICE #
11/12/2024	25754

BILL TO
Pokegama Golf Coarse 3910 Golf Course Road Grand Rapids, MN. 55744

P.O. NO.	TERMS	Service Date
	Due on receipt	

QTY	ITEM	DESCRIPTION	RATE	AMOUNT
1	Non-Stock	WI COOLER BEL0155AS6AMAB0000 / ST24K05859 Evaporator coil, SRSE-1-1/2-C TXV ZF09KAE-PFV / 24H8934AL Compressor	6,400.00	6,400.00
6	R-404A-24	R-404A-24(HP62) Refrigerant	31.95	191.70
1	Freight		107.00	107.00
		Pumped system down and replaced the evaporator coil, TXV and compressor with new. Checked operation. Charged system with refrigerant.		
Thank you for your business.			<b>Total</b>	\$6,698.70

1-1/2% Per Month Service Charge on Amount Past Due.

Quality Refrigeration & Heating Inc.

37351 Co. Rd. 248  
 Deer River, MN 56636  
 218-246-2731

# Invoice

DATE	INVOICE #
11/25/2024	25785

BILL TO
Pokegama Golf Coarse 3910 Golf Course Road Grand Rapids, MN. 55744

P.O. NO.	TERMS	Service Date
	Due on receipt	

QTY	ITEM	DESCRIPTION	RATE	AMOUNT
1	Quote	WI FREEZER	2,970.00	2,970.00
		ZS05XAE-PFV-818 / 24H4442DL Compressor		
1	Freight		49.00	49.00
2	R-404A-24	R-404A-24(HP62) Refrigerant	31.95	63.90
		Replace existing compressor with new high efficiency scroll compressor. Replaced starting components and evacuated system. Started up and checked operation.		
Thank you for your business.			<b>Total</b>	\$3,082.90

1-1/2% Per Month Service Charge on Amount Past Due.

Quality Refrigeration & Heating Inc.

37351 Co. Rd. 248  
 Deer River, MN 56636  
 218-246-2731

**Invoice**

DATE	INVOICE #
12/5/2024	25929

BILL TO
Pokegama Golf Course 3910 Golf Course Road Grand Rapids, MN. 55744

P.O. NO.	TERMS	Service Date
	Due on receipt	

QTY	ITEM	DESCRIPTION	RATE	AMOUNT
		WI COOLER/FREEZER		
2	Non-Stock	40446 Door snubbers	186.65	373.30
1	Freight		35.65	35.65
1	Truck Charge		12.00	12.00
1	Labor-RA	Replaced door snubbers on both WI Cooler and WI Freezer doors. Checked operation. Adjusted so the doors close properly.	108.00	108.00
Thank you for your business.			<b>Total</b>	\$528.95

1-1/2% Per Month Service Charge on Amount Past Due.