

ST JOHNS AVE.

12"

MATCH CURB/GUTTER

30.00'

HYDRANT

AREA TO BE REMOVED

89°51'43"(C)

FOUND 1/2" IRON ROD PIPELINE ILLEGIBLE

R84' N: 10037813 E: 5467293

75'

R15'

R60'

PIPE BUFFER

15'

DOWNRIGHT OF WAY

Grease St.

TOCOI  $\pi$  Engine

714 NORTH ORANGE AVENUE, GREEN COVE SF  
PH: 904-215-1388 E.B. NUMBER

ENGINEER OF RECORD  
CHARLES SOHM

FLORIDA  
REGISTRATION NUMBER:  
79289