

Security Lock Service, Inc.**Estimate**

401 Washington St.
Brighton, MI 48116

Date	Estimate #
5/2/2022	E1953

Prepared For:

Hamburg Township
P.O. Box 157
Hamburg, MI 48139
Attn: Accounts Payable
(810) 231-1000 ext 223

Ship To

Senior Center Doors
Double doors, unequal pair

Prices valid for 30 days from date shown on this Estimate

		P.O. No.	Terms
			Net 30
Description	Qty	Rate	Total
Pair of doors and frame to fit 74" x 80" rough opening - Unequal pair of medium stile doors, Main door is 42" x 79" tall, ADA compliant threshold and opening size, ADA 10" bottom rail. Extra width allows wheelchairs room to pass through the door without constraint. - Left door is 30 x 79, and can be opened whenever large deliveries are needed. Top and bottom flush bolts secure the door during normal use, and it functions as a sidelight panel. - Locking hardware: pair of push pad exit devices, see attached spec sheet - Exterior: 10" pull handle, offset smooth tubular design - 1" Clear tempered safety glass, insulated - Dark Bronze Anodized Aluminum doors and frame provide long life in a commercial environment, can be repaired and maintained over the life of the door. - Built in weather seals around perimeter of the door and frame provide double layer of protection against hot/cold air transfer - Door sweeps along bottom of door protect from air transfer	1	7,427.00	7,427.00
Labor: remove and replace door set. Anchor door frame to 2x6 wall stud. Caulk around exterior door jamb, threshold, and any trim needed to resolve gap along brick. Reuse interior trim where possible, some light drywall patching and/or trim may be needed (by others).	1	1,740.00	1,740.00
DOORS AND FRAMES SUBTOTAL:			9,167.00
7000 Series Low Energy Door Operator with Power Assist - Detects obstruction and automatically reduces power and stops operation - Fully programmable open, close, back check power and speeds. - Long arm option for wall header mount - Onboard relay control for lock control - Made in USA (TX) 1 year warranty - Compliant with ADA act of 1990	1	1,620.00	1,620.00
HCAP Button 4 1/2" Square with surface mount box	2	82.50	165.00
Please sign and return to indicate approval		Total	
Phone #	Fax #	E-mail	
810-227-5153	810-299-5121	joel@securitylock.biz	
		Signature	

Security Lock Service, Inc.**Estimate**

401 Washington St.
Brighton, MI 48116

Date	Estimate #
5/2/2022	E1953

Prepared For:

Hamburg Township
P.O. Box 157
Hamburg, MI 48139
Attn: Accounts Payable
(810) 231-1000 ext 223

Ship To

Senior Center Doors
Double doors, unequal pair

Prices valid for 30 days from date shown on this Estimate

		P.O. No.	Terms
			Net 30
Description	Qty	Rate	Total
42" Bollard post for approach from outside, allows swing clear of the door when activating the operator	1	312.00	312.00
Wireless receiver for HCAP OP	1	52.50	52.50
Wireless transmitter for HCAP Buttons - 9 volt standard battery	2	52.50	105.00
Labor: install handicap door operator in accordance with manufacturer specifications, configure opening, close, and power adjustments. Connect to building 110VAC outlet (provided by others, within 6. Max power draw is 3.15 amps')	1	870.00	870.00
DOOR OPERATOR SUBTOTAL:			3,124.50
Please sign and return to indicate approval		Total	\$12,291.50
Phone #	Fax #	E-mail	
810-227-5153	810-299-5121	joel@securitylock.biz	
			Signature