

Warning concerning the interior use of propane heaters. Please do not use these heaters indoors without proper ventilation. Death can occur. Please contact the Hildale Fire Department at 435-874-2400 or Hildale-Colorado City Utility Department 435-467-1160 for additional information about CO risks.

"Carbon monoxide is an odorless, colorless gas that often goes undetected, striking victims caught off guard or in their sleep. Hundreds of people in the U.S. die from unintentional carbon monoxide poisoning every year, according to the Centers for Disease Control and Prevention. More than 20,000 visit the emergency room, and more than 4,000 others are hospitalized. This "invisible killer" is produced by burning fuel in cars or trucks, small engines, stoves, lanterns, grills, fireplaces, gas ranges, portable generators or furnaces. When the gas builds up in enclosed spaces, people or animals who breathe it can be poisoned. Ventilation does not guarantee safety.

How Can I Prevent Carbon Monoxide Poisoning?

Anyone can be at risk. The CDC says infants, the elderly, and people with chronic heart disease, anemia or breathing problems are more prone to illness or death, but carbon monoxide doesn't discriminate. Winter can be a prime time for carbon monoxide poisoning as people turn on their heating systems and mistakenly warm their cars in garages. As the weather turns colder, it is important to take extra precautions.

The National Safety Council recommends you install a battery-operated or battery backup carbon monoxide detector in the hallway near each sleeping area in your home. Check or replace the battery when you change the time on your clocks each spring and fall, and replace the detector every five years.

The CDC offers these additional tips:

- Have your furnace, water heater and any other gas or coal-burning appliances serviced by a qualified technician every year
- Do not use portable flameless chemical heaters indoors
- Have your chimney checked and cleaned every year, and make sure your fireplace damper is open before lighting a fire and well after the fire is extinguished
- Never use a gas oven for heating your home
- Never use a generator inside your home, basement or garage, or less than 20 feet from any window, door or vent; fatal levels of carbon monoxide can be produced in just minutes, even if doors and windows are open
- Never run a car in a garage that is attached to a house, even with the garage door open; always open the door to a detached garage to let in fresh air when you run a car inside

Symptoms of Carbon Monoxide Poisoning

The U.S. Fire Administration has put together materials on the dangers of carbon monoxide, including a list of carbon monoxide poisoning symptoms. Symptom severity varies depending on the level of carbon monoxide and duration of exposure. Mild symptoms sometimes are mistaken for flu.

Page | 2

Low to moderate carbon monoxide poisoning is characterized by:

- Headache
- Fatigue
- Shortness of breath
- Nausea
- Dizziness

High-level carbon monoxide poisoning results in:

- Mental confusion
- Vomiting
- Loss of muscular coordination
- Loss of consciousness
- Death

If you think you are experiencing any of the symptoms of carbon monoxide poisoning, go outside and get fresh air immediately. You could lose consciousness and die if you stay in the home.

When the Carbon Monoxide Alarm Sounds

- The Consumer Product Safety Commission warns that you should never ignore a carbon monoxide alarm, and do not try to find the source of the gas. Instead, follow these steps:
- Immediately move outside to fresh air
- Call emergency services, fire department or 9-1-1
- Do a head count to check to account for everyone
- Do not reenter the premises until emergency responders have given you permission to do so"