
## **EQUIPMENT REPLACEMENT JUSTIFICATION**



UTILITY

94000

POLICE

PATROL

Model Hours/Mileage Department

Division

List current possible issues with the vehicle & price to repair:

TRANSMISSION
AC CONDENSER
WATER PUMP
CYLINDER HEADS
ENGINE CARBON REMOVAL

\$3,200.00
\$800.00
\$2,500.00
\$3,100.00
\$1,100.00
\$10,700.00

List of additional equipment necessary to purchase

EMERGENCY LIGHTING, CONSOLE	
PARTITIONS, EQUIPMENT TRAY	
DECALS	

	1
\$16,400.00	1
\$	
\$	1
\$16,400.00	1

Vehicle Replacement Cost


\$66,974.00

**Budget Amount** 

N/A

Additional Notes:

## EQUIPMENT REPLACEMENT JUSTIFICATION



POLICE

PATROL

Division

Hours/Mileage Department

*List current possible issues with the vehicle & price to repair:* 

THIS PATROL UTILITY WAS IS ACCIDENT
AND TOTALED
х. 

\$45,574.00	
	$\neg$
	_
\$45,574.00	_

List of additional equipment necessary to purchase

EMERGENCY LIGHTING, CONSOLE	
PARTITIONS, EQUIPMENT TRAY	
DECALS	

\$16,400.00	
2	
\$	
\$ 	l
\$16,400.00	

Vehicle Replacement Cost

\$66,974.00

N/A

Budget Amount

Additional Notes: