MEMBERS OF COUNCIL

HON. KIM REYNOLDS **GOVERNOR**

HON. PAUL D. PATE SECRETARY OF STATE

HON, ROB SAND AUDITOR OF STATE

HON, ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE



Executive Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

March 3, 2025

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for a supplemental emergency allocation in the amount of \$4,205.47. This brings the total allocation to \$19,961.30. On October 31, 2024, Vehicle #234 was damaged by a deer. Request was to cover repair costs.

This represents full and final payment and this allocation closed.

EXECUTIVE COUNCIL OF IOWA i Onstot

Kristi Onstot

Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services DAS Fleet Services, Risk

Matt Bender, Department of Management

Heather Hackbarth, Department of Management

OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

February 14, 2025

Kristi Onstot Executive Council L O C A L

Subject: Deer Damage to Vehicle #234 on October 31, 2024

Department of Administrative Services

Claim dated November 20, 2024

AOS Claim ID: 3948

The Department's request included a supplemental allocation request of \$4,205.47 because additional damages were identified. We recommend Executive Council approval of the supplemental allocation of \$4,205.47, which increases the allocation to \$19,961.30. In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to this loss. We have found the items to be in order as shown below:

Documented request		\$ 19,961.30
Executive Council allocation (Re	evised)	\$ 19,961.30
Less: Previous payments This payment Total	\$ 0.00 	\$ 19,961.30
Remaining Executive Council all	location	\$ 0.00

We recommend that reimbursement be made in the amount of \$19,961.30. This represents <u>full</u> and <u>final</u> payment on this allocation.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Bri R. Bris

cc: Adam Steen, Director, Department of Administrative Services
Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services



KIM REYNOLDS, GOVERNOR

ADAM STEEN, DIRECTOR

Date: January 28, 2025

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Ryan Betts, DAS Fleet Risk Manager

DAS Fleet Services

Department of Administrative Services

Re: REIMBURSEMENT REOUEST - 29C20 Claim

TELEVISION TO THE COURT OF THE				
3948				
#234/Deer				
October 31, 2024				
Vehicle 234 struck a deer. (293504)				
\$19,686.30 - Repair Invoice +\$275 - Tow Invoice 				

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: 0665-005-5790-0657.

If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

DAS Fleet Risk Manager ryan.betts1@iowa.gov

515-281-8008





Search here...











Ryan Betts Financial User



Warrants

Edit

Cancel

* Required fields















Fiscal Year 2025 **Vendor Customer**

00002112221

Amount \$19,686.30 Line Number

Warrant Number 73425014 **Last Updated** 01/21/2025 08:33 PM

Issue Information

Issued

01/21/2025 12:00 AM

Duplicate No

Line Amount \$4,132.50

Void No

Transaction Line Number

Comments

Transaction ID RISK00525016004

Stop No

Redeemed Information

Redeemed

Sequence Number

Batch Number

Redeemed Fund

Redeemed Bank

Redeemed Department

~ COA

Fund 0665

Sub Fund

Department 005

Object Class

Appropriation 0000

Sub BSA

Show More

Object

2715

Sub Object

Unit 5790

Revenue Source

Revenue Source Class

Dept Object

Dept Revenue

Sub Unit

Sub Revenue Source

BSA







WITHAM COLLISION CENTER

FORD-CHEVROLET-VW-KIA 2033 LAPORTE RD, WATERLOO, IA 50702 Phone: (319) 234-4200 Workfile ID: PartsShare:

85c3f77c 8dwks3

Federal ID: 42-1060951

Final Bill

RO Number: 18010068

Customer:

Insurance:

Adjuster:

Estimator:

Angela Williams

Isp 234 Deer

QUALITY CLAIMS SOLUTIONS

Phone: Claim:

Create Da

Create Date:

11/1/2024

APDSOIO293504-0

01

Loss Date:

(319) 939-2778

Deductible:

2023 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

VIN:

1C4SDJFT6PC676238

Interior Color:

Mileage In:

Vehicle Out:

License:

State: IA

Exterior Color:

Production Date:

Mileage Out: Condition:

Job #:

Line	Ver	Operation	Description	Qty	Extended	D t			200
		•		Qty	Price \$	Part Type	Labor	Туре	Paint
1	E01	Repair	pre scan			1,750	1.0	Mech	
2	E01	Repair	post scan					Mech	
3	E01		FRONT BUMPER				1.0	Mech	
4	E01	Remove/Replace	O/H front bumper				3.1	Body	
5	E01	Remove/Replace	Bumper cover w/prk aid	1	596.00	A/M		Body	2.0
6	E01		Add for Clear Coat		050.00	, , , ,	0.0	body	3.0
7.	E01	Remove/Replace	Add for distance sens				0.4	Body	
8	E01	Remove/Replace	Add for fog lamps				0.4	Body	
9	E01	Remove/Replace	Add for park sensor					Body	
10	E01	Remove/Install	License bracket						
11	E01	Remove/Replace	RT Bumper cover upper bracket	1	81.00	A/M		Body	
12	E01	Remove/Replace	RT Bumper cover lower bracket	1	10.40	OEM	0.0	Body	
13	E01	Remove/Install	push bar	-	10.40	OLIM		Body	
14	S01	Remove/Replace	Air deflector w/accent color	1	176.00	OEM		Body	
15	S01		Overlap Major Non-Adj. Panel	_	170.00	OLIM	0.0	Body	1.2
16	S01		Add for Clear Coat						(0.2)
17	E01		FRONT LAMPS						
18	E01	Remove/Replace	RT Headlamp assy w/o auto high beam black bezel	1	1,630.00	OEM	0.0	Body	
19	E01	Remove/Replace	Aim headlamps				0.5	Body	
20	E01	Remove/Install	LT Headlamp assy w/o auto high beam					,	
			black bezel				0.4	воау	
21	S01		RADIATOR SUPPORT						
22	S01	Remove/Replace	RT Support bracket	1	149.00	OEM	0.2	Body	
23	S01	Remove/Replace	Add for P/Strg cooler				0.2	,	
24	S01	Remove/Replace	Evacuate & recharge				1.4	150	
							1.7	Joury	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 18010068

2023 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

25	S01		Defined to 3.7L dasonile Sequential MPI						
26	S01	,	Refrigerant recovery				0.4	1 Body	
27	S01	-,	Add for skid plate				0.3	Body	
28	E01	, p	Add for trans cooler				0.3	Body	
29	E01		FENDER						
30	E01		RT Fender liner all	1	89.00) A/M	0.0	Body	
31	E01	Remove/Replace	RT Fender	1	344.16	A/M	2.0	Body	2.0
32	E01		Overlap Major Non-Adj. Panel						(0.2)
33	E01		Add for Clear Coat						0.1
34	E01		Add for Edging						0.5
35	E01	Remove/Replace	Add for Clear Coat						
36	E01	Remove/Replace	RT Wheel flare w/o body color	1	263.00	OEM	0.3	Body	
37	S02	Remove/Replace	RT Wheel flare retainer	5	64.50	OEM			
38	S02	Remove/Replace	WINDSHIELD						
39	S01	Remove/Replace	Windshield NAGS w/o rain sensor	1	680.75	Glass	2.0	Body	
40	S01	Remove/Install	CONSOLE						
41	E01	remove/mstall	R&I console assy center				0.6	Body	
42	E01	Remove/Replace	RESTRAINT SYSTEMS						
43	E01	Remove/Replace	RT Head air bag	1	483.00	OEM	0.8	Body	
44	S01	Remove/Replace	Air bag system diagnosis				0.7	Body	
45	S01	Remove/Replace	RT Ft seat air bag	1	444.00	OEM	0.5	Body	
46	E01	Remove/Replace	LT Retractor assy black	1	318.00	OEM	0.3	Body	
47	S01	Remove/Replace	RT Retractor assy black	1	328.00	OEM	0.3	Body	
48	E01	Remove/Replace	Occupant module all 3.6 L, 5.7 L	1	446.00	OEM	0.5	Body	
49	E01	Remove/Replace	RT Adjuster SEATS & TRACKS	1	70.85	OEM	0.2	Body	
50	E01	Remove/Replace	RT Seat back cover code: C5 black		200 Heller 100 10				
51	E01	Remove/Replace	RT Seat back cover code: C5 black	1	308.00	OEM		Body	
52	E01	Remove/Install	RT Cushion cover code: A7 black	1	554.00	OEM		Body	
53	E01	rtorrovej matan	ROOF				0.8	Body	
54	E01	Remove/Install	RT Roof molding						
55	E01	Remove/Replace	_				0.5		
		Remove/Replace	Headliner w/o sunroof, w/Illum vanity mirrors black	1	2,080.00	OEM	4.0	Body	
56	E01	Remove/Install	Police accessories				1.0	Pody	
57	E01		PILLARS, ROCKER & FLOOR				1.0 1	body	
58	S01	Repair	Door Opening panel				8.0 E	Rody	Γ.0
59	S01	Remove/Install	RT Lwr ctr plr trim black				0.3 E		5.0
60	E01	Blend	RT roof rail				0.5	body	1.4
61	E01	Remove/Replace	RT Rocker molding w/chrome	1	402.00	OEM	0.9 E	Rody	1.4
62	E01		Overlap Major Non-Adj. Panel				0.5	oody	(0.2)
63	E01		Add for Clear Coat						(0.2)
64	E01	Remove/Replace	RT Rocker molding rivet	1	12.25	OEM			
65	E01	Remove/Replace	RT Rocker molding screw	1	3.55	OEM			
66	E01	Remove/Replace	RT Rocker molding nut	1	1.75	OEM			
67	S01	Remove/Install	RT Upr ctr plr trim black				0.0 B	odv	
68	S01	Remove/Install	RT Sill cover front, w/o chrome insert				0.2 B		
							5.2 D		

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 18010068

2023 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

			black						
69	S01	Remove/Install	RT Cowl trim all				0.3	D = 4	
70	S01	Remove/Install	RT Sill cover rear black					Body	
71	E01		FRONT DOOR				0.2	2 Body	
72	E01	Remove/Replace	RT Door shell	1	1,485.00	OEM	5.6	Body	2.4
73	E01		Overlap Major Adj. Panel		27 100100	OLIT	5.0	body	3.4 (0.4)
74	E01		Add for Clear Coat						(0.4)
75	E01	Remove/Install	RT Applique				0.0	Body	
76	E01	Remove/Install	RT Power mirror w/o memory, w/blind spot detection gloss black					Body	
77	E01	Remove/Install	RT R&I trim panel				0.0	Body	
78	E01	Remove/Install	RT Handle, outside painted, all ceramic gray					Body	
79	S01	Remove/Install	RT Striker				0.2	Body	
80	S01	Remove/Install	RT Body w'strip					Body	
81	E01		REAR DOOR				0.0	Dody	
82	E01	Remove/Replace	RT Door shell	1	1,485.00	OEM	4.8	Body	3.4
83	E01		Overlap Major Adj. Panel						(0.4)
84	E01		Add for Clear Coat						(01.1)
85	E01	Remove/Install	RT Belt molding				0.0	Body	
86	E01	Remove/Install	RT Applique front					Body	
87	E01	Remove/Install	RT Applique rear					Body	
88	E01	Remove/Install	RT Handle, outside painted ceramic gray				0.0	Body	
89	E01	Remove/Install	RT R&I trim panel					Body	
90	S01	Remove/Install	RT Surround w'strip					Body	
91	E01		QUARTER PANEL					,	
92	E01	Repair	RT Quarter panel				1.0	Body	2.8
93	E01		Overlap Major Non-Adj. Panel					,	(0.2)
94	E01		Add for Clear Coat						2.5
95	E01	Remove/Install	RT Wheel flare w/o body color				0.3	Body	
96	E01	Remove/Install	RT Qtr glass Dodge w/o deep tint					Body	
97	E01		REAR LAMPS					,	
98	E01	Remove/Install	RT Tail lamp assy				0.3	Body	
99	E01		REAR BUMPER						
100	E01	Remove/Install	R&I bumper cover				1.2	Body	
101	E01		MISCELLANEOUS OPERATIONS						
102	E01		Hazardous waste removal	1	3.00	Other			
103	E01	Remove/Replace	Flex Additive	1	5.00	Other			
104	E01		Corrosion protection	1	5.00	Other	0.1	Body	
105	E01		4 Wheel Alignment	1	79.95	Other			
106	E01		Lift Reveal				0.5	Body	
107	E01		Cover Car	1	5.00	Other	0.2	Body	
108	E01		mask to prime	1	5.00	Other	0.2	Body	
109	E01		Denib and Polish				1.0	Body	
110	E01	Remove/Install	Light bar				1.0	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 18010068

2023 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

111	S01	Repair	cut holes in bumper for push bar	1.0 Bo	odv
112	S01	Sublet	check engine light dan deery 1 435.61 Other	1.0 0	ouy
113	S01		drive time to Dan Deery X2	1.0 Bo	odv
114	S02		Parts discount differance 1 1.03 Other	2.5 0	<i>-</i>

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts	(1,139.50)				11,465.66
Labor, Body			75.00	55.1	4,132.50
Labor, Refinish			135.00	25.1	3,388.50
Labor, Mechanical			130.00	2.0	260.00
Miscellaneous				2.0	439.64
Subtotal					
					19,686.30
Sales Tax					0.00
Grand Total					19,686.30
					19,080.30
Net Total					19,686.30

Estimate Version	Total \$
Original	15,104.78
Supplement S01	3,818.85
Supplement S02	762.67
Insurance Total \$:	19,686.30
Received from Insurance \$:	0.00
Balance due from Insurance \$:	19,686.30
Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural





Search here...















Warrants

Edit

Cancel

* Required fields















Fiscal Year 2025 **Vendor Customer** 00003190413

Amount \$275.00 Line Number 1

Warrant Number 73340564 Last Updated 11/25/2024 07:22 PM

Issue Information

Issued

11/21/2024 12:00 AM

Duplicate No

Line Amount \$275.00

Void No

Transaction Line Number

1

Comments

Transaction ID

RISK00525325501

Stop No

Redeemed Information

Redeemed

11/25/2024 12:00 AM Sequence Number

01905

Batch Number

0000

Redeemed Fund

0665

Redeemed Bank

0000

Redeemed Department

005

~ COA

Fund

0665

Sub Fund

Department

005

Object Class

Appropriation

0000 Sub BSA

Show More

Object

2715

Sub Object

Unit 5790

Revenue Source

Revenue Source Class

Dept Object

Dept Revenue

Sub Unit

Sub Revenue Source

BSA





Rasmusson Towing Inc

9716 University Ave Cedar Falls, IA 50613 Ph: 319-277-3802

rasmussontowing@gmail.com



Invoice #P-21258

Date: 11/11/2024

For:

Iowa State Patrol

Due Date	Terms	P.O. Number
	Due upon receipt	

From:

C 23 and jay ave, Wilmar,

To:

Witham Collision Center, 2033 Laporte Rd,

Waterloo, IA 50702

Owner:

Service Date: 10/31/2024 7:36:00 PM

Driver:

8

Ticket#:

Reason For Call: deer hit

Phone #: Member #:

Vehicle	VIN	Veh#	Tag	State	Odometer
dodge Durango		234			16088

Qty	Service	Rate	Adjustment	Tax	Amount
1.00	Flatbed	\$275.00	\$0.00	\$0.00	\$275.00
223.			Total Amount Du)	\$275.00

Received By:

Date:

RECEIVED

NOV 18 REC'D

POST 9



OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building Des Moines, Iowa 50319-0004 Telephone (515) 281-5834

January 21, 2025

Kristi Onstot Executive Council LOCAL

Subject: Deer Damage to Vehicle #234 on October 31, 2024

Department of Administrative Services Claim dated November 20, 2024

AOS Claim ID: 3948

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$15,755.83, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA

Pri R. Bres

Deputy Auditor of State

Adam Steen, Director, Department of Administrative Services cc: Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services Heather Hackbarth, Department of Management