MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE



Executibe Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

March 3, 2025

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$5,772.14, subject to an audit of actual invoices. On December 3, 2024, Vehicle #1035 was damaged by a deer. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

(risti Onstot

Kristi Onstot

Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services

DAS Fleet Services, Risk

Matt Bender, Department of Management

Heather Hackbarth, Department of Management

OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building Des Moines, Iowa 50319-0004 Telephone (515) 281-5834

February 6, 2025

Kristi Onstot **Executive Council** LOCAL

Subject: Deer Damage to Vehicle #1035 on December 3, 2024

Department of Administrative Services Claim dated December 10, 2024

AOS Claim ID: 3961

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$5,772.14, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA

Bri R. Bris

Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services Heather Hackbarth, Department of Management



KIM REYNOLDS, GOVERNOR

ADAM STEEN, DIRECTOR

Date: December 10, 2024

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#1035 / Animal
Event Date	December 3, 2024
Summary	Vehicle 1035- struck a deer. (295540)
Amount Requested	\$5,772.14 - Estimate for Repairs
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s)

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you

Ryan Betts

DAS Fleet Services

ryan.betts@iowa.gov

515-281-8008



Risk, DAS <das.risk@iowa.gov>

Fwd: Deer Versus Vehicle 1035

1 message

Risk, DAS <das.risk@iowa.gov>

Wed, Dec 4, 2024 at 9:11 AM

To: TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>, Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 1035 struck a deer on 12/3/2024. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

DAS Risk

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

109 SE 13th St, Des Moines, IA 50319

515-281-3162 office

das.risk@iowa.gov

https://das.iowa.gov



----- Forwarded message -----

From: Goldsberry, Alexandra <Alex.Goldsberry@iowaagriculture.gov>

Date: Tue, Dec 3, 2024 at 4:15 PM Subject: Deer Versus Vehicle 1035

To: DAS.Risk@iowa.gov <DAS.Risk@iowa.gov>, Potter, Lisa <Lisa.Potter@iowaagriculture.gov>

Cc: Rumsey, Katie < Katie. Rumsey@iowaagriculture.gov>

Good Afternoon.

Here is my paperwork for my deer accident today. Let me know if you need anything else.

Thank you,

Alex Goldsberry, *Animal Industry Inspector*Iowa Department of Agriculture & Land Stewardship
Central Iowa
515-313-8315

Alex.Goldsberry@iowaagriculture.gov




Vehicle Accident Report 2.pdf 20961K

Vehicle Accident Report

me and location of accide	nt		48.5		
cident Date (Mo/Day/Year)		Time	No. of Vehicles		
12/03/2024		10:30 A.M.	1		
ounty		State			
authrie					
/ehicle 1 (State vehicle)		IA			
Priver's Name		Work Street Address			
Hexandra Go	Usberry	50Z E 9th			
river's License No /State	•	City, State, Zip			
537AT9374	-l IA	pes moines, 1:	A 50319		
ate of Birth	Department	Work Phone	Home Phone		
11 121/1997	LA IDALS	515-313-8315	612-741-3960		
cense Plate No.	VIN	Year, Make, Model			
1035	3FA6P0677KR27821	2019 Ford Fu	sion		
stimate (\$) of Damage		Description of Damage			
		Front passanger bumper, fender	corner, hood,		
Vehicle 2 (other vehicle) if	f more than two vehicles-use a	dditional forms			
Driver's Name		Street Address			
Driver's License No./State		City, State, Zip			
Date of Birth	Work Phone	Home Phone	License Plate No.		
Description of Damage					

Property Damage other than vehicle (fence, utility pole, etc)					
Dwner's Name, Address and Phone	Description of Property Damaged				
Injured Persons (attach additional sheets if r	iecessary)				
Vehicle No. 1/ Name and Address	Describe Injuries				
Vehicle No. 2/ Name and Address	Describe Injuries				
Witness					
Name	Address/Phone				
boug Anderson	515-250-2757				
Name	Address/Phone				



	Accident Information Exchange Sheet
Other Vehicle information	
Driver's Name	
Street Address	
Driver Phone	
Driver's License No./State	
Vehicle Plate No.	
Vehicle year, make, model	
VIN	
Insurance Company Name	
Policy No.	
Agent name	
Agent phone	
Owner's Name/Address (if different)	
Submit this information	along with the accident report to DAS Fleet Service within 72 hours of the accident.

Complete the next section, tear at the dotted line and give to the other party involved.

Driver's Name	Alexandra Goldsberns
Driver's License No./State	537AT9374 1A
Vehicle Plate No.	1035
Vehicle year, makel, model	2019 Ford fusion
VIN	3FA6P0677KR278217
	The State of Iowa is self-insured. If you have any questions regarding an accident, please contact DAS Fleet Services at 515-281-3162 of DAS.Risk@iowa.gov

QUALITY CLAIMS SOLUTIONS

105 N Krohn Place SIOUX FALLS, SD 57103

Phone: (877) 237-3727, FAX:(605) 800-8591 qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: STATE OF IOWA

Job Number:

Workfile ID:

7daceed2

Written By: Mitch Christenson

Insured:

STATE OF IOWA

Policy #:

UNK

Claim #:

APDSOI0295540-001

Type of Loss: Point of Impact: 12 Front

Collision

Date of Loss:

12/6/2024 12:00 PM

Days to Repair:

Owner:

Inspection Location:

Repair Facility:

STATE OF IOWA

KARL CHEVROLET COLLISION CENTER

ANK

ANKENY, IA 50021

1101 SOUTHEAST ORLABOR ROAD

Ankeny, IA 50021

Other

(515) 299-4337 Evening

VEHICLE

2019 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI

VIN:

3FA6P0G77KR278217

Production Date:

0

Interior Color: Exterior Color:

License: State:

Odometer: Condition:

TRANSMISSION

Automatic Transmission

POWER

Power Steering

Power Brakes Power Windows

Power Locks

Power Mirrors

DECOR

Dual Mirrors

Tinted Glass

Console/Storage Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Backup Camera

RADIO AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

SAFETY

Drivers Side Air Bag

Passenger Air Bag Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device Blind Spot Detection

Lane Departure Warning

SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

WHEELS

Wheel Covers

PAINT

Clear Coat Paint

OTHER

Traction Control Stability Control

California Emissions

Owner: STATE OF IOWA

2019 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI

Job Number:

Line		Ope		Part Number	Qty	Extended Price \$	Labor	Pain
1	FRONT BU	JMPER &	GRILLE					
2			O/H bumper assy				2.7	
3		R&I	R&I bumper cover				Incl.	
4	* <>	Rpr	Bumper cover w/o auto park w/o tow hook				4.0	3.
5		Repl	RT Side trim w/o fog lamps, w/o SSV feature black w/o gloss	KS7Z17B814AA	1	34.27	Incl.	
6		Repl		HS7Z17C947AA	1	11.08	Total	
7	*	R&I	Emblem	1137217631774	1	11.08	Incl.	
8		R&I	Impact bar w/o tow hook				<u>Incl.</u>	
9	FRONT LAI	MPS					1.1	
10		Repl	RT Headlamp assy w/o signature lamps	HS7Z13008D	1	589.96	Incl.	
11			Aim headlamps				0.5	
12		R&I	LT Headlamp assy w/o signature				0.5 Incl.	
			lamps				ITICI.	
13	RADIATOR							
14	**	Repl	A/M Mount panel Flat Rock plant -20%	HS7Z16138A	1	192.00	2.1	
15	**	Repl	A/M Upper tie bar -20%	HP5Z8A284B	1	217.60	1.2	0.8
16		R&I	Sight shield				Incl.	0.0
17	HOOD							
18	**	Repl	A/M Hood (ALU) -20%	DS7Z16612B	1	689.60	1.7	2.8
19			Overlap Major Non-Adj. Panel					-0.2
20			Add for Underside(Complete)					1.4
21			Front w'strip				Incl.	
22		R&I	Insulator				Incl.	
23			RT Hinge	DS7Z16796A	1	45.08	0.9	0.4
24		Repl	LT Hinge	DS7Z16797A	1	44.95	0.9	0.4
25	FENDER							
26			RT Fender	HS7Z16005A	1	459.02	1.6	2.0
27			Overlap Major Adj. Panel					-0.4
28			Add for Edging					0.5
29			Deduct for Overlap				-0.3	
30			Deduct for Overlap				-0.5	
31			RT Fender liner w/o turbo w/2.5 liter DOHC				Incl.	
32		Repl	RT Upper molding bright/black	ES7Z16004DA	1	33.77	Incl.	
33	*		RT Support bracket			S	1.0	0.3
34	PILLARS, RO	OCKER & I	FLOOR					0.5
35	*	Rpr	RT Aperture panel			S	1.0	0.0
36			RT Rocker molding	DS7Z5410176A	1	247.55	0.7	1.8
37			Overlap Major Non-Adj. Panel				·.,	-0.2

42			Clear Coat				-0.4
41		Rpr	RT Door shell Overlap Major Adj. Panel			0.5	2.3
43	#		Decal removal	1			2.5
45		R&I R&I	RT Door w'strip RT Belt molding			0.3 0.3	
46		R&I	RT Applique all w/o keyless lock pad			0.2	
47		R&I	RT R&I mirror			-	
48		R&I	RT Handle, outside w/o passive entry			0.4 0.3	
49		R&I	RT R&I trim panel				
50	MISCELLA	ANEOUS OF	PERATIONS			0.5	
51	*	Repl	<u>Hazardous waste</u>	-			
52	#		Feather, prime & block	1	3.00	0.0	
53	#		Color Sand/ Buff	1		1.5	
54	#		Seam sealer	1		1.0	
55	VEHICLE	DIAGNOST		1	45.00	0.5	
56	*	Rpr					
57	*		Pre-repair scan		m	<u>0.5</u> M	
		Rpr	Post-repair scan		m	<u>0.5</u> M	
			SUBTOTALS		2,612.88	26.3	17.0

ESTIMATE TOTALS

Category	Basis		Data	
Parts	Dasis		Rate	Cost \$
Parts Discount				2,612.88
	\$ 1,468.68		-20.0 %	-293.74
Body Labor	25.3 hrs	@	\$ 60.00 /hr	1,518.00
Paint Labor	17.0 hrs	@	\$ 110.00 /hr	
Mechanical Labor	1.0 hrs	_		1,870.00
Subtotal	1.01 5	@	\$ 65.00 /hr	65.00
20 OCCUPATION COMMITTEE CO				5,772.14
Total Cost of Repairs				5,772.14
Deductible				0.00
Total Adjustments				
Net Cost of Repairs				0.00
				5,772.14

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

Owner: STATE OF IOWA

Job Number:

2019 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR2JP13, CCC Data Date 12/02/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

 $\label{eq:memoral} \begin{tabular}{ll} m=$MOTOR Mechanical component. & s=$MOTOR Structural component. & T=$Miscellaneous Taxed charge category. & T=$Misc$

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

Owner: STATE OF IOWA

Job Number:

2019 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Owner: STATE OF IOWA

Job Number:

2019 FORD Fusion S FWD 4D SED 4-2.5L Gasoline Sequential MPI

PARTS SUPPLIER LIST

Line	Supplier	Description	
14	Keystone-Complete-H-Webster 10 GOYA DRIVE WEBSTER MA 01570 (800) 544-0012 (508) 272-7763	#F01225239 A/M Mount panel Flat Rock plant -20%	Price \$ 192.00
15	Keystone-Complete-H-Webster 10 GOYA DRIVE WEBSTER MA 01570 (800) 544-0012 (508) 272-7763	#FO1225247 A/M Upper tie bar -20%	\$ 217.60