

MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE NAIG SECRETARY OF AGRICULTURE

Executive Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

May 5, 2025

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on this date, approved payment of the following cost item:

This represents full and final payment.

EXECUTIVE COUNCIL OF IOWA

Kristi Onstot

Kristi Onstot Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services
DAS Fleet Services, Risk
Matt Bender, Department of Management
Heather Hackbarth, Department of Management

OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004

Telephone (515) 281-5834

April 7, 2025

Kristi Onstot Executive Council L O C A L

Subject: Coyote Damage to Vehicle #127 on September 18, 2024

Department of Administrative Services Claim dated December 11, 2024

AOS Claim ID: 3917

In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to the loss and have found the items to be in order as shown below:

Documented request	\$ 5,348.00
Executive Council Allocation	\$ 5,348.00

Less:

Previous payments \$0.00This payment 5,348.00

Total \$ 5,348.00

Remaining Executive Council allocation \$ 0.00

We recommend reimbursement be made in the amount of \$5,348.00. This represents <u>full</u> and <u>final</u> payment of the loss.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Phi R Bis

CC: Adam Steen, Director, Department of Administrative Services

Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services



KIM REYNOLDS, GOVERNOR CHRIS COURNOYER, LT. GOVERNOR ADAM STEEN, DIRECTOR

Date: February 7, 2025

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Ryan Betts, DAS Fleet Risk Manager

DAS Fleet Services

Department of Administrative Services

Re: REIMBURSEMENT REQUEST - 29C20 Claim

AOS Claim #	3917
Vehicle / Event	#127/Coyote
Event Date	September 18, 2024
Summary	Vehicle 127 struck a coyote. (290499)
Amount Requested	\$5,348.00 Total

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: **0665-005-5790-0657**. If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts

DAS Fleet Risk Manager ryan.betts1@iowa.gov

515-281-8008



Search here...











Ryan Betts **Financial User**



Warrants

Edit

RB

Cancel

* Required fields











Fiscal Year 2025

Amount \$5,348.00 **Vendor Customer** Line Number 00003202049

Warrant Number 73301069 Last Updated 11/06/2024 08:26 PM

Issue Information

Issued 10/30/2024 12:00 AM **Duplicate** No

Line Amount \$5,348.00

Void No

Transaction Line Number

Comments

Transaction ID RISK00525303503

Stop No

Redeemed Information

Redeemed 11/06/2024 12:00 AM Sequence Number 02218

Batch Number 0000 Redeemed Fund 0665

Redeemed Bank 0000 Redeemed Department

~ COA

Fund 0665 Sub Fund

Department 005 **Object Class**

0000 Sub BSA

Appropriation

Show More

Object 2715

Sub Object

Unit 5790

Revenue Source

Revenue Source Class

Dept Object

Dept Revenue

Sub Unit

Sub Revenue Source

BSA



American Collision

2222 6th Street, Sioux City, IA 51101 Phone: (712) 255-1895

Workfile ID: PartsShare: b0e98187 88YcJG

Federal ID:

46-1606758

Final Bill

RO Number: 51323

Customer:

Iowa State Patrol

Insurance:

QUALITY CLAIMS SOLUTIONS

Adjuster:

Estimator: Create Date:

Drake Craft 9/19/2024

Phone: Claim:

APDSOI0290499-00

Loss Date: Deductible:

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

VIN:

2C3CDXKG9MH644686

Interior Color:

Mileage In:

Vehicle Out:

License:

Exterior Color:

Mileage Out:

State:

IΑ

Production Date:

Condition: Job #:

Line		Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		FRONT BUMPER & GRILLE		ф	1,700			
2	E01	Remove/Install	R&I bumper cover				1.0	Body	
3	E01	Remove/Install	Push bar					•	
4	E01		FRONT LAMPS				3.0	Body	
5	E01	Remove/Install	LT Headlamp assy halogen				0.4	Dado	
6	E01		FENDER				0.4	Body	
7	E01	Remove/Replace	Cavity wax	1	15.00	A/M	0.4	D. J	
8	S01	Repair	LT Fender w/o wide body	-	15.00	Ayırı		Body	
9	E01		Add for Clear Coat				7.0	Body	2.0
10	E01		remove and Replace decal						8.0
11	E01	Remove/Install	spot light					Body	
12	E01	Remove/Replace	Cover car for refinish	1	5.00	Λ /Λ4		Body	
13	E01		FRONT DOOR	1	3.00	A/M	0.2	Body	
14	S01	Repair	LT Door shell (HSS)				40.0		
15	E01		Overlap Major Adj. Panel				10.0	Body	2.1
16	E01		Add for Clear Coat						(0.4)
17	E01	Remove/Install	LT Applique				0.2	5	0.3
18	E01	Remove/Install	LT Power mirror w/o heat, w/o memory,					Body	
			w/o blind spot pnt to match				0.5	Body	
19	E01	Remove/Install	LT Handle, outside black				0.4	Rody	
20	E01	Remove/Install	LT R&I trim panel				0.5	,	
21	E01		Door decal						
22	E01		De Nib and Finesse (.5 per panel)					Body	
23	E01	Remove/Install	LT Belt w'strip				1.5		
24	S01	Remove/Install	LT R&I door assy				0.3		
25	E01		REAR DOOR				1.2	sody	
26	E01	Remove/Install	LT Belt w'strip				0.3	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech =

RO Number: 51323

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

		. 0.50					
S01	Remove/Replace	LT door assy	1	750.00	IKO	1.6. Dodu	2.0
S01		Overlap Major Adj. Panel	-	750.00	LIVQ	1.6 Body	3.0
S01		Add for Clear Coat					(0.4)
S01		Tear down used door				2.0 Rody	0.5
E01	Remove/Install	LT Applique				•	
E01	Remove/Install	LT Handle, outside black					
S01		attempt to repair				,	
E01	Remove/Install	LT R&I trim panel					
E01	Refinish	De Nib and Finesse (.5 per panel)				0.5 Body	
E01	Repair	Feather Prime and Block (.2 per repair hour)					3.0
E01	Remove/Replace	Cover car for primer	1	5.00	A/M	0.2 Rody	
E01	Remove/Replace	Corrosion protection primer	1				
E01	Repair	Color tint / color match	_	3.00	7911	U.I BOUY	0.5
E01		Vehicle#127					0.5
S01		QUARTER PANEL					
S01	Blend	LT Quarter panel w/o wide body					1.2
S01	Blend	Fuel door					1.3 0.2
S01	Remove/Install	top light				2.0 Rody	0.2
S01	Remove/Replace	American flag decal					
S01	Refinish	Blend roof rail				1.0 body	1.5
S01		REAR LAMPS					1.5
S01	Remove/Install	LT Tail lamp assy				0.3 Rody	
S01		REAR BUMPER				0.5 body	
S01	Remove/Install	R&I bumper cover				1.2 Body	
	S01 S01 S01 E01 E01 E01 E01 E01 E01 S01 S01 S01 S01 S01 S01 S01 S01 S01 S	S01 S01 S01 E01 Remove/Install E01 Remove/Install E01 Remove/Install E01 Refinish E01 Repair E01 Remove/Replace E01 Remove/Replace E01 Repair E01 S01 S01 Blend S01 Blend S01 Remove/Install S01 Remove/Replace S01 Remove/Install S01 Remove/Install S01 Remove/Replace S01 Refinish S01 S01 Remove/Install	Overlap Major Adj. Panel Add for Clear Coat Tear down used door E01 Remove/Install LT Applique E01 Remove/Install LT Handle, outside black S01 attempt to repair E01 Refinish De Nib and Finesse (.5 per panel) E01 Remove/Replace Cover car for primer E01 Remove/Replace Cover car for primer E01 Repair Color tint / color match E01 Repair Color tint / color match E01 Repair Color tint / color match E01 Vehicle#127 S01 QUARTER PANEL E01 Blend LT Quarter panel w/o wide body Fuel door E01 Remove/Replace American flag decal S01 Remove/Replace American flag decal S01 Refinish Blend roof rail S01 Remove/Install E1 down used door E1 Table I Table I Table I Tear down used door E1 Table I Table I Tear down used door E2 Tear down used door E3 Tear down used door E4 Tear down used door E5 Tear down used door E6 Tear down used door E6 Tear down used door E6 Tear door E6 Tear down used user E6 Tear down used user E6 Tear down user E6 Tear down user E6 Tear down user E6 Tear down user E6 Tear	Sol Overlap Major Adj. Panel Sol Add for Clear Coat Tear down used door Eol Remove/Install LT Applique Eol Remove/Install LT Handle, outside black Sol attempt to repair Eol Refinish De Nib and Finesse (.5 per panel) Eol Repair Feather Prime and Block (.2 per repair hour) Eol Remove/Replace Cover car for primer Eol Repair Color tint / color match Eol Repair Color tint / color match Eol Vehicle#127 Sol QUARTER PANEL Sol Blend LT Quarter panel w/o wide body Sol Remove/Install top light Sol Remove/Replace American flag decal Sol Remove/Install LT Tail lamp assy Sol Remove/Install LT Tail lamp assy REAR BUMPER	Sol Overlap Major Adj. Panel Sol Add for Clear Coat Sol Tear down used door Eol Remove/Install LT Applique Eol Remove/Install LT Handle, outside black Sol attempt to repair Eol Refinish De Nib and Finesse (.5 per panel) Eol Remove/Replace Cover car for primer 1 5.00 Eol Remove/Replace Corrosion protection primer 1 5.00 Eol Repair Color tint / color match Vehicle#127 Sol QUARTER PANEL Sol Blend LT Quarter panel w/o wide body Sol Blend LT Quarter panel w/o wide body Sol Remove/Replace American flag decal Sol Refinish Blend roof rail Sol Remove/Install LT Tail lamp assy Sol Remove/Install LT Tail lamp assy Sol REAR BUMPER	Sol Overlap Major Adj. Panel Sol Add for Clear Coat Tear down used door Eol Remove/Install LT Applique Eol Remove/Install LT R&I trim panel Eol Refinish De Nib and Finesse (.5 per panel) Eol Remove/Replace Cover car for primer Eol Remove/Replace Corrosion protection primer Eol Repair Color tint / color match Vehicle#127 Sol QUARTER PANEL Sol Blend LT Quarter panel W/o wide body Fuel door Sol Remove/Replace American flag decal Sol Remove/Replace American flag decal Sol Remove/Replace American flag decal Sol Remove/Install LT Tail lamp assy Sol Remove/Install LT Tail lamp assy	Soli

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Takal d
Parts			πατοφ	Total Hours	Total \$
Labor, Body					750.00
			65.00	44.8	2,912.00
Labor, Refinish			65.00	14.4	936.00
Material, Paint					
Miscellaneous					720.00
Subtotal					30.00
Subtotal					5,348.00
Sales Tax					
Grand Total					0.00
					5,348.00
Net Total					5,348.00

Estimate Version	Total \$
Original	2,952.00
Supplement S01	2,396.00
Insurance Total \$:	5,348.00
Received from Insurance \$:	0.00
Balance due from Insurance \$:	5,348.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 51323

2021 DODG Charger Police AWD (Fleet) 4D SED 6-3.6L Gasoline Sequential MPI

Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

TOR OF STATE OF TO

OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

February 6, 2025

Kristi Onstot Executive Council L O C A L

Subject: Coyote Damage to Vehicle #127 on September 18, 2024

Department of Administrative Services Claim dated December 11, 2024

AOS Claim ID: 3917

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$5,348.00, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Bri R. Bis

cc: Adam Steen, Director, Department of Administrative Services

Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services

Heather Hackbarth, Department of Management