MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE



Executibe Council of Jowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

May 5, 2025

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on this date, approved the Board of Regents – University of Iowa request for an emergency allocation in the amount of \$85,634.43, subject to an audit of actual invoices. On January 16, 2024, a failed heating unit caused Myriad Technology Plaza to lose power and pipes to freeze. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

)nstot

Kristi Onstot

Executive Secretary

cc: John Nash, Director of Facilities, Board of Regents, State of Iowa
Camille Walters Gott, Risk Management Administrator, University of Iowa
Andrea Anania, Board of Regents
Aimee Claeys, Board of Regents
Heather Hackbarth, Department of Management
Matt Bender, Department of Management

OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

April 28, 2025

Kristi Onstot Executive Council L O C A L

Subject: Heating Unit Failed Causing Myriad Technology Plaza to Lose Power and Pipes

to Freeze on January 16, 2024 University of Iowa – Board of Regents Claim dated February 27, 2025

AOS Claim ID: 3670

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the University of Iowa – Board of Regents is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$85,634.43 subject to an audit of <u>actual</u> invoices.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

mi RA

cc: Camille Walters Gott, Risk Management Claims Manager, University of Iowa John Nash, Director of Facilities, Board of Regents Heather Hackbarth, Department of Management



Business Services

Risk Management, Insurance and Loss Prevention

University of Iowa 202 Plaza Centre One Iowa City, Iowa 52242-2501 319-335-0010 Fax 319-353-1893

February 27, 2025

Executive Council of Iowa Office of Treasurer of State State Capitol Building Des Moines, IA 50319

Re: University of Iowa – Myriad Technology Plaza One Heat Failure Water Damage – Preliminary Loss Report (1/16/2024) – AOS Claim #3670

Dear Executive Council,

On January 16, 2024, a heating unit failed causing the building to lose power and water pipes to freeze at Myriad Technology Plaza One located at 2660 Crosspark Road, Coralville, Iowa. The damage affected the building sprinklers, sprinkler pipes, plumbing, electrical, reverse osmosis water system, boilers, and water heaters. The lights and ceiling tiles in room 137 were damaged and had to be replaced.

The purpose of this Preliminary Loss Report is to notify you of our current damage estimate and to request allocation of funds for repair/replacement of the damaged building components and equipment. Our estimated damage is approximately **\$85,634.43**. A Formal Loss Report will be provided with supporting invoice and payment documentation.

Please feel free to contact me with any questions or concerns.

Sincerely,

Camille Walters Gott

Risk Management Claims Manager

Camille Walters Hot

cc: Tammy Hollingsworth

John Nash Debby Zumbach Josey Bathke

Walters Gott, Camille S

From: Walters Gott, Camille S

Sent: Tuesday, January 16, 2024 3:32 PM

To: executivecouncil@tos.iowa.gov; Tammy Hollingsworth; John Nash (john.nash@iowaregents.edu)

Cc: Bathke, Josey; Zumbach, Debby J

Subject: University of Iowa Myriad Technology Plaza One - Property Loss Notice

Hello,

Risk Management was notified on 1/16/2024 of an incident at Myriad Technology Plaza One, located at 2660 Crosspark Road, Coralville, Iowa. On 1/16/2024, a heating unit failed causing the building to lose power and pipes to freeze. We are investigating the incident at this time. Damages are expected to exceed \$5,000. Incident photos have been requested and will be provided when received.

We will submit a preliminary loss report when detailed damage estimates are available.

Please feel free to contact me with any questions or concerns.

Thank you

Camille Walters Gott

Manager, Risk Management Insurance and Loss Prevention 202 Plaza Centre One, 125 S Dubuque St, Iowa City, Iowa 52242

Office: 319-335-5357

https://riskmanagement.fo.uiowa.edu/





Department of Risk Management Insurance & Loss Prevention

202 Plaza Centre One (PCO) lowa City, IA 52242-2500 Phone 319-335-0010

General Fund Property 29C:20 Cost Estimate - MTP1 Heat Failure Water Damage

Building:	Myriad Techno	ology Plaza One (MTP1)		Date of Loss:		1/16/2024
Department:	BioVentures			Completed by:	C	Camille Walters Gott
				UI Claim #:		PR-22231-SUI
			Α	OS 29C:20 Claim #:		#3670
				•		
Category	Reference #	Vendor	PO	Voucher		Cost Estimate
Building	1B Prelim	Blackhawk Sprinklers	1002965430	84806156	\$	16,750.00
Building	2B Prelim	Total Water Treatment Systems Inc	1002973626	84799447	\$	12,153.50
Building	3B Prelim	Total Water Treatment Systems Inc	1002973626	84881852	\$	12,663.50
Building	4B Prelim	AAA Mechanical	1003024961	85169191	\$	42,237.93
Building	5B Prelim	CEC - Communications Engineering Company	B000580368	84836023	\$	1,419.76
Building	6B Prelim	Nelson Electric	1003028109	84893766	\$	127.74
Building	7B Prelim	Hargers Acoustics Inc	1003036435	84914244	\$	282.00
				Building Estimate	\$	85,634.43
Equipment	N/A	None			\$	
Equipment	N/A	None			\$	-
	,		E	quipment Estimate	\$	-
				ESTIMATE TOTAL	ċ	85,634.43

1B Prelim - Page 1 of 1

BLACKHAWK AUTOMATIC **SPRINKLERS**, INC.

EMPLOYEE OWNED 525 EAST 148 STREET FAX: (319) 277-000 PROPOSAL SPREAD DATE January 20, 2024 TO: University of lowa Research Park 2660 Crosspark Road Coralville, IA stephanie-dengler@uiowa.edu RE: WORK TO BE COMPLETED: 1) Replace double check assembly & test 2) Replace all sprinklier heads per the Fire Department's request 3) Replace 2 broken lines on the dock including the ITV pipe We will air test the system before turning the water back on, any additional leaks will be repaired on a T&M basis. **Price based on underground shutoff holding tight** BLACKHAWK AUTOMATIC SPRINKLERS, INC. (SELLER) PROPOSES TO PROVIDE &/OR INSTALL: Make repairs listed above: Firm Price: Sixteen Thousand Seven Hundred Firity Dollars & 00/100 Price is good for fourteen days. Price Includes Freight & Transportation of Men to Site. EXCLUSIONS: Painting, Wiring, Supervisory Alarms, Special Markers, Centering of Sprinklers in Ceiling Tile, Special Environmental Requirements, Sprinklers in Combustible Blind Spaces, Installation From Other Than Concrete Slab Floors, Pollution Liability/Mold insurance coverage or any Overtime. Our firm follows the State of lowa, Illinois, Nebraska, and Missouri requirements as a licensed contractor and licensed sprinkler inspector. Our State of lowa contractor license is FES-2069. Our State of Illinois contractor license is FSC0103. Our State of Nebraska contractor license is 15097. All inspections performed per NFPA 25 Standard for the Inspection, Testing and Maintenance of Water-Based Fire Protection Systems. All Installations per NFPA 13 Standard for the Installation of Sprinkler Systems. By Realean Cole Blackhawk Automatic Sprinklers, Inc. Stephanie Dengler / U of I Research Park		FIRE PROTECTION CON	TRACTORS • DESIGN	, INSTALLATION & MAINTENANC	JE
TO: University of Iowa Research Park 2660 Crosspark Road Coralville, IA stephanie-dengler@uiowa.edu RE: WORK TO BE COMPLETED: 1) Replace double check assembly & test 2) Replace all syrinkler heads per the Fire Department's request 3) Replace 2 broken lines on the dock including the ITV pipe We will air test the system before turning the water back on, any additional leaks will be repaired on a T&M basis. **Price based on underground shutoff holding tight** BLACKHAWK AUTOMATIC SPRINKLERS, INC. (SELLER) PROPOSES TO PROVIDE &/OR INSTALL: Make repairs listed above: Firm Price: Sixteen Thousand Seven Hundred Fifty Dollars & 00/100					<u>`</u>
2660 Crosspark Road Coralville, IA stephanie-dengler@uiowa.edu 1) Replace double check assembly & test 2) Replace all sprinkler heads per the Fire Department's request 3) Replace 2 broken lines on the dock including the ITV pipe We will air test the system before turning the water back on, any additional leaks will be repaired on a T&M basis. **Price based on underground shutoff holding tight** BLACKHAWK AUTOMATIC SPRINKLERS, INC. (SELLER) PROPOSES TO PROVIDE &/OR INSTALL: Make repairs listed above: Firm Price: Sixteen Thousand Seven Hundred Fifty Dollars & 00/100 Price is good for fourteen days. Price Includes Freight & Transportation of Men to Site. EXCLUSIONS: Painting, Wiring, Supervisory Alarms, Special Markers, Centering of Sprinklers in Ceiling Tile, Special Environmental Requirements, Sprinklers in Combustible Blind Spaces, Installation From Other Than Concrete Slab Floors, Pollution Liability/Mold insurance coverage or any Overtime. Our firm follows the State of Iowa, Illinois, Nebraska, and Missouri requirements as a licensed contractor and licensed sprinkler inspector. Our State of Iowa contractor license is FES-2069. Our State of Illinois contractor license is FSC0103. Our State of Nebraska contractor license is 15097. All inspections performed per NFPA 25 Standard for the Inspection, Testing and Maintenance of Water-Based Fire Protection Systems. All installations per NFPA 13 Standard for the Installation of Sprinkler Systems. By RaeJean Code By RaeJean Code	EMP	LOYEE OWNED			, ,
BLACKHAWK AUTOMATIC SPRINKLERS, INC. (SELLER) PROPOSES TO PROVIDE &/OR INSTALL: Make repairs listed above: Firm Price: Sixteen Thousand Seven Hundred Fifty Dollars & 00/100	TO:	2660 Crosspark Road Coralville, IA	RE:	 Replace double check assembly Replace all sprinkler heads per Fire Department's request Replace 2 broken lines on the do including the ITV pipe We will air test the system before back on, any additional leaks will 	the ock turning the water
Make repairs listed above: Firm Price: Sixteen Thousand Seven Hundred Fifty Dollars & 00/100				**Price based on underground sho	atoff holding
EXCLUSIONS: Painting, Wiring, Supervisory Alarms, Special Markers, Centering of Sprinklers in Ceiling Tile, Special Environmental Requirements, Sprinklers in Combustible Blind Spaces, Installation From Other Than Concrete Slab Floors, Pollution Liability/Mold insurance coverage or any Overtime. Our firm follows the State of Iowa, Illinois, Nebraska, and Missouri requirements as a licensed contractor and licensed sprinkler inspector. Our State of Iowa contractor license is FES-2069. Our State of Illinois contractor license is FSC0103. Our State of Nebraska contractor license is 15097. All inspections performed per NFPA 25 Standard for the Inspection, Testing and Maintenance of Water-Based Fire Protection Systems. All installations per NFPA 13 Standard for the Installation of Sprinkler Systems. By RaeTean Cole By	Make	e repairs listed above:			
Special Environmental Requirements, Sprinklers in Combustible Blind Spaces, Installation From Other Than Concrete Slab Floors, Pollution Liability/Mold insurance coverage or any Overtime. Our firm follows the State of Iowa, Illinois, Nebraska, and Missouri requirements as a licensed contractor and licensed sprinkler inspector. Our State of Iowa contractor license is FES-2069. Our State of Illinois contractor license is FSC0103. Our State of Nebraska contractor license is 15097. All inspections performed per NFPA 25 Standard for the Inspection, Testing and Maintenance of Water-Based Fire Protection Systems. All installations per NFPA 13 Standard for the Installation of Sprinkler Systems. By RaeJean Cole By	Price	is good for fourteen days. Price Inclu	ıdes Freight & Transportat	ion of Men to Site.	
sprinkler inspector. Our State of Iowa contractor license is FES-2069. Our State of Illinois contractor license is FSC0103. Our State of Nebraska contractor license is 15097. All inspections performed per NFPA 25 Standard for the Inspection, Testing and Maintenance of Water-Based Fire Protection Systems. All installations per NFPA 13 Standard for the Installation of Sprinkler Systems. By	EXCL	Special Environmental Req	uirements, Sprinklers in Co	ombustible Blind Spaces, Installati	on From
RaeJean Cole Blackhawk Automatic Sprinklers, Inc. Stephanie Dengler / U of I Research Park	sprint Our S Testii Instal	kler inspector. Our State of Iowa cont State of Nebraska contractor license ng and Maintenance of Water-Base llation of Sprinkler Systems.	ractor license is FES-2069 is 15097. All inspections particle of the protection of the system are supported by By	9. Our State of Illinois contractor li performed per <i>NFPA 25 Standard</i> ns. <i>All installations per NFPA 13</i>	cense is FSC0103. I for the Inspection, I Standard for the
		RaeJean Cole Blackhawk Automatic S	Sprinklers, Inc. Sto	ephanie Dengler / U of I Research Par	·k



TOTAL WATER TREATMENT SYSTEMS INC A 100% EMPLOYEE OWNED COMPANY 5002 WORLD DAIRY DRIVE MADISON WI 53718 (608) 221-2236 (800) 929-2236

DELIVERY ADDRESS: UNIVERSITY OF IOWA HOSP & CLINICS DAVID MCLAIN UI-WATER PLANT 200 HAWKINS DR IOWA CITY IA 52242

2B Prelim - Page 1 of 1

INVOICE NUMBER 1099167

ACCOUNT NUMBER 287564 01

BILLING DATE 02/15/2024

DUE DATE 03/16/2024

PURCHASE ORDER #

1002973626

REFERENCE	DESC	RIPTION	QTY	PRICE	TOTAL
127	WATER EQUIPMENT REPLACEMENT	SHIPPED: 02/15/2024	1	12153.50	12153.50
	50% UPON ORDER				

TERMS

NET 30

PAY THIS AMOUNT

12153.50

RETURN THIS PORTION WITH PAYMENT



TOTAL WATER TREATMENT SYSTEMS INC A 100% EMPLOYEE OWNED COMPANY 5002 WORLD DAIRY DRIVE MADISON WI 53718

INVOICE NUMBER 1099167

ACCOUNT NUMBER 287564 01

DUE DATE 03/16/2024

AMOUNT DUE

AMOUNT PAID

12153.50

UNIVERSITY OF IOWA HOSP & CLINICS

ACCOUNTS PAYABLE & TRAVEL 202 PCO IOWA CITY IA 52242-2500

TOTAL WATER TREATMENT SYSTEMS INC A 100% EMPLOYEE OWNED COMPANY 5002 WORLD DAIRY DRIVE MADISON WI 53718



Total Water Treatment Systems Inc A 100% Employee Owned Company 5002 World Dairy Drive Madison, WI 53718

(608) 221-2236 (800) 929-2236

3B Prelim - Page 1 of 1

INVOICE

0035611

Invoice Date: 04/29/2024 Shipped: 04/29/2024 PO No: 1002973626 **Customer No:** 2875643 Web Portal Security Code: **TVRQ** Due Date: 05/29/2024

Balance: \$12663.50

Billing Address:

University Of Iowa Hosp & Clinics Accounts Payable & Travel 202 Pco Iowa City, IA 52242-2500

Location Address:

University Of Iowa Hosp & Clinics 200 Hawkins Dr David Mclain Ui-Water Plant Iowa City IA 52242-2500

Pay your bill online at WWW.CULLIGANTOTALWATER.COM You may register using your account number and security code above.

Service Date	Description	Comments	Reference	Qty.	Price Amount
04/29/2024	Replacement Water Equipment		T05544	1	12153.50
	50% Remaining Balance De				
04/29/2024	Freight		T05544	1	510.00

Total Water

Total Water Treatment Systems Inc A 100% Employee Owned Company 5002 World Dairy Drive Madison, WI 53718

(608) 221-2236 (800) 929-2236

INVOICE NUMBER

ACCOUNT NUMBER

DUE DATE

RETURN THIS PORTION WITH PAYMENT

0035611

2875643

05/29/2024

AMOUNT DUE

AMOUNT PAID

\$12663.50

Remit Payment to:

Total Water Treatment Systems Inc A 100% Employee Owned Company 5002 World Dairy Drive Madison, WI 53718

University Of Iowa Hosp & Clinics Accounts Payable & Travel 202 Pco Iowa City, IA 52242-2500

4B Prelim - Page 1 of 2

AAA Mechanical Contractors, Inc. 2755 Stoner Court North Liberty, IA 52317 319-351-1843



Bill To University of Iowa 202 Plaza Centre One Iowa City, IA 52242

https://www.aaamech.com

We service HVAC/R, building controls, and plumbing systems for commercial and industrial customers.

Invoice No.

12467598

Service Location

IDT

Customer PO No. Invoice For 1003024961

2660 Crosspark Road Coralville, IA 52241

Transaction Date

Repair Job #33270595 (02/22/2024)

4/9/2024

Due Date 5/9/2024 (Net 30)

Item	Svc	Qty	Unit Price	Amt
.Labor Journeyman Regular	HVAC	100	\$96.58	\$9,658.00
Labor Apprentice Regular	HVAC	60	\$76.25	\$4,575.00
Labor Journeyman OT	HVAC	3	\$124.70	\$374.10
Labor Apprentice OT	HVAC	1	\$101.25	\$101.25
Watts Backflow Preventor 1-1/2	HVAC	2	\$6,077.27	\$12,154.54
Insulation for Repair Piping	HVAC	1	\$4,685.00	\$4,685.00
Copper Fittings	HVAC	1	\$2,732.57	\$2,732.57
New Water Meter 2"	PLUMB	1	\$1,679.46	\$1,679.46
Propress Fittings	HVAC	1	\$1,032.44	\$1,032.44
1-1/2 Lead Free Reduced Pressure Zone Backflow Preventer Assembly	HVAC	1	\$1,023.25	\$1,023.25
1-1/2 Watts Bronze Strainer	HVAC	2	\$360.55	\$721.10
1" Water meter	OTHR	1	\$691.22	\$691.22
1" Watts Backflow	HVAC	1	\$688.92	\$688.92
Watts 2" Lead Free Ball Valve	HVAC	1	\$537.74	\$537.74
Drywall Patch Repair	HVAC	1	\$527.50	\$527.50
New Filter Housing	PLUMB	1	\$401.87	\$401.87
Brass Fittings	HVAC	1	\$382.47	\$382.47
Torch & Braze/Solder Supplies	HVAC	1	\$30.00	\$30.00
Trip Charge (IC Metro Area)	OTHR	14	\$17.25	\$241.50
		GRA	ND TOTAL	\$42,237.93

Notes

- During the low temperatures we had the Mechanical Room had some freezing that broke the water meter and filters. We will repair the mechanical room items, to include Boilers and Water Heater. We will also do a air test on the complete system to check for leaks out in the piping system.
- 2/22 Got into the mechanical room and walked straight to the water meter and filters to find the filters broken off and cracked meter. Took off water meter, removed all the insulation, and began a visual and leak check. Found broken valves, leaking sections of pipe, and cracked non copper pipe. Took off the unions connecting the filters and unscrewed the male adapter half unions. Brought in the new filters and meter, cleaned up insulation mess, and made a part list.
- 2/23 Installed new filter housings and filters. Installed new water meter. Put in isolation valves to isolate and air test the lab and bathroom plumbing hot and cold potable water piping. Found more freeze ruptures, a broken ball valve, and check valve. Air tested the hot potable water and there aren't any leaks in the lab and bathrooms. Air tested the cold potable water and it will not pressurize due to a leak that we haven't found yet.

4B Prelim - Page 2 of 2

- 2/26 Picked up copper and brass fittings. Found the leak in the building piping on the front water spigot piping inside the front office wall. Isolated the leak and pressurized the cold water piping and it held. Started cutting out all the freeze leaks in the mechanical room cold water piping. Got a parts list and remade some of the piping to repair the leaks.
- 2/27 Repaired more leaks in the mechanical room and installed pipe to replace ruptured pipe. Put air pressure on mechanical room piping and found more copper pipe freeze ruptures. Cut out and replaced pipe. Found that the two main 1-1/2" back flow preventers are bad and the small 1" backflow for the RO system is also bad and will need replaced.
- 2/28 Put in new backflow preventers. Fixed leaks and replaced 2" ball valves in water main header.
- 2/29 Filled mechanical room piping and building water piping. Flushed all sinks, toilets, and urinals. Turned on water heat and set temp, it is running correctly. Cleaned up machine room.
- 3/01 Got over to the RO pipe and put 3 new small lengths of soft copper into the compression fittings. We had to cut and bend new pipe. Turned water pressure on and found another leak on a 1 inch 45 so we unsoldered that out, cut, and cleaned a new piece of pipe with the right fittings. Then soldered that into place. Turned on water pressure again and everything held together.
- 3/06 Cut drywall out to expose the piping. Repaired the leak in the wall in the front office for the outside water hydrant. Checked for leaks. Turned on the water and cleaned up the drywall mess.
- 3/11 Got new water meter for irrigation. Installed new meter and backflow preventer. Checked for leaks and then left it off.
- 3/18 Got fittings list to hook up new softeners. Picked up the fittings.
- 3/19 Moved softener tanks into a good position to reconnect all the water interconnecting piping. Changed length of piping to accommodate the new softener heads and tanks. Tied in all the inlet water and outlet soft water piping to new softeners. Piped the drain lines. Installed the softener flow meter in the outgoing soft water line to the building.
- 3/20 Fixed leaks on softener piping in the old 2" and cleaned unions. Tried to put flow meter in several times, but the plastic fittings that come with it leaked and had no taper to the 2" pipe threads. Flow meter is still not installed in the outlet soft water piping.
- 3/27 Installed the flow meter and checked for leaks.
- 3/28 Got 10 new pro press couplings and a pro press 45. Pro pressed in 1/2" 45 and two couplings to repair a water leak in the existing soft water line that was isolated from the main water piping. Turned on the line and verified that there were no leaks.

Thank you for choosing AAA Mechanical as your contractor for HVAC, Plumbing, and Building Controls. We appreciate your business and look forward to serving you in the future. Your contracted labor and material rates have been applied to this invoice.



350512



Service Ticket #

CEC PO Box 488 405 Boyson Road Hiawatha, IA 52233 (319) 294-9000

Date	Invoice
03/20/2024	421085
Account #	
32203A	

Bill To:
The University of Iowa
Accounts Payable
202 PCO
Iowa City, IA 52242
United States

Ship To
The University of Iowa Accounts Payable 202 PCO Iowa City, IA 52242 United States

Payment Terms	Due Date	PO #	Reference #
NET 30	04/19/2024	B000578244	

Service ficket #	330312							
Summary	IDT/U of Iowa bldg 2660 crosspark-reconnect water monitoring modules to new waterflows.							
Resolution	Thu 3/7/2024/11:30 AM UTC-06/ Ryan Ham (time)- went on site found i needed different hardware to mount went to lowes got what was needed replaced the top tamper and it cleared went to replace the bottom and found bad resistor did not have the correct resistor so I made the value using what i had 4.7k. could not get it to clear the supervisory stays on even just adding the resistor. but the trouble clears. something is wrong with the notifier device. Thu 3/14/2024/11:00 AM UTC-05/ Josh Pennington (time)-							
	Thu 3/14/2024/11:00 AM UTC-05/ Josh Penni Work on researching EOL resistance needed Touch base with Ryan Ham about existing se Contact customer regarding access to buildi	l for Notifier s ervice ticket.	system.					
Thu 3/14/2024/1:00 PM UTC-05/ Josh Pennington (time)-install 47k resistor for Notifier I/o module fmm-101 for bottom tamper.								
Thu 3/14/2024/2:35 PM UTC-05/ Josh Pennington-replaced EOLs with 47k resistors @ tamper locations. Panel is now clear of all troubles.								
Contact Name	Stephanie Dengler							
			Hours	Rate	Amount			
Billable Labor			5.25	190.00	\$997.50			
			Tot	tal Labor:	\$997.50			
Material & Trip Charges	5	Quantity		Price	Amount			
Billable Material & Trip	Charges							
Parts from Lowes.		1.00		\$22.26	\$22.26			
Travel Charge Zone 2 -	IA	2.00	9	\$200.00	\$400.00			
		Tot	al Material Ch	l & Trip narges:	\$422.26			
	Please remit to:	Invoi	ce Subtotal	1:	\$1,419.76			
Comr	munications Engineering Company		Sales Tax	1	\$0.00			
	PO Box 488 Hiawatha, IA 52233	In	voice Total		\$1,419.76			
If you have guestions	,		Payments	::	\$0.00			
electronically, please	regarding your invoice or to receive your invoices contact statements@cecinfo.com or call toll-free 1-		Credits	::	\$0.00			
2.1	800-795-2630.	В	alance Due	::	\$1,419.76			
charged at a rate of a	ss due by the invoice due date may result in interest 1.5% per month on the outstanding principal, until y accrued interest is paid. CEC reserves the right to yments first towards outstanding interest.							

6B Prelim - Page 1 of 1

NELSON ELECTRIC CO. 618 14TH AVE S.W. P.O. BOX 967 CEDAR RAPIDS, IA 52406



CE	INVOI
182382	Number:
4/19/24	Date:
NET 30 DAYS	Terms

PHONE: 319-366-6257

EMAIL: info@nelsonelectric.com WEBSITE: www.nelsonelectric.com

1003028109 JV

U OF I RESEARCH PARK
BIOVENTURES CENTER
2500 CROSSPARK ROAD
CORALVILLE, IA 52241

Job: CR99838 IDT -2660 CROSSPARK, U OF 2660 CROSSPARK ROAD

CORALVILLE, IA 52241

CUSTOMER P	O#:	EMAIL	FROM	STEPHANIE
------------	-----	-------	------	-----------


FINAL

Work Description

2 X 4 TROFFER WAS DAMAGED DURING WINTER FREEZE

QUANTITY	U/M	UNIT PRICE	EXTENSION
			33.12
1.000	HR	87.62	87.62
1.000	HR	7.00	7.00
	1.000	1.000 HR	1.000 HR 87.62

SUBTOTAL:	127.74
TOTAL:	127.74



HARGER'S ACOUSTICS, INC.

2245 STATE STREET **ELY, IA 52227**

Phone:

(319) 848-4000

Fax:

(319) 848-4190

Invoice

Invoice Number 3186 Invoice Date 5/22/2024

1003036435 jv

Bill To: U | RESEARCH PARK & BIOVENTURE

2500 CROSS PARK ROAD

CORALVILLE, IA 52241

UI RESEARCH WATER DAMAGE

Dergler@UIava. Edu

Job No	Customer Job No	Purchase Order No	Terms	Due Date
13553-IC	STEPHANIE		Due Upon Receipt	5/22/2024
		Description		

Extended Price

282.00

ACOUSTICAL CEILING REPAIRS COMPLETED 05/21/24, AS DIRECTED

THANK YOU FOR YOU BUSINESS!

282.00 0.00 282.00 282.00 0.00
282.00 0.00

THIS IS YOUR ONLY INVOICE, 1.50% FINANCE CHARGES DUE IF NOT PAID IN 10 DAYS.

CUSTOMER COPY

A/R COPY

JOB FILE