MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE



Executive Council of Iowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

May 5, 2025

Accounting Department Office of the Treasurer Lucas Building 321 E 12th Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for a supplemental emergency allocation in the amount of \$1,193.46. This brings the total allocation to \$5,324.20. On January 10, 2025, Vehicle #105470 was damaged by a deer. Request was to cover repair costs.

This represents full and final payment and this allocation will be closed.

EXECUTIVE COUNCIL OF IOWA

Kristi Onstot

Kristi Onstot Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services
DAS Fleet Services, Risk
Matt Bender, Department of Management
Heather Hackbarth, Department of Management

OFFICE OF AUDITOR OF STATE





Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

April 7, 2025

Kristi Onstot Executive Council L O C A L

Subject: Deer Damage to Vehicle #105470 on January 10, 2025

Department of Administrative Services

Claim dated January 10, 2025

AOS Claim ID: 3970

The Department's request included a supplemental allocation request of \$1,193.46 because additional damages were identified. We recommend Executive Council approval of the supplemental allocation of \$1,193.46, which increases the allocation to \$5,324.20. In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to this loss. We have found the items to be in order as shown below:

Documented request	\$	5,324.20
Executive Council allocation (Revised)	\$	5,324.20
Less: Previous payments \$ 0.0 This payment 5,324.2 Total	-	5,324.20
Remaining Executive Council allocation	\$	0.00

We recommend that reimbursement be made in the amount of \$5,324.20. This represents <u>full</u> and <u>final</u> payment on this allocation.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Bu R Bus

CC: Adam Steen, Director, Department of Administrative Services

Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services



KIM REYNOLDS, GOVERNOR CHRIS COURNOYER, LT. GOVERNOR

ADAM STEEN, DIRECTOR

Date: February 19, 2025

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Ryan Betts, DAS Fleet Risk Manager

DAS Fleet Services

Department of Administrative Services

Re: REIMBURSEMENT REQUEST - 29C20 Claim

AOS Claim #	3970
Vehicle / Event	#105470/Deer
Event Date	January 10, 2025
Summary	Vehicle 105470 struck a deer. (297917)
Amount Requested	\$5,324.20 Total

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: **0665-005-5790-0657**. If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts

DAS Fleet Risk Manager ryan.betts1@iowa.gov

515-281-8008





Search here...











Ryan Betts Financial User



Warrants

Edit

Cancel

* Required fields



















Vendor Customer 00003028866

Warrant Information

Amount \$5,324.20 Line Number **Warrant Number** 73462329 **Last Updated** 02/14/2025 07:24 PM

Issue Information

Issued

02/06/2025 12:00 AM

Duplicate No

Line Amount \$1,800.00

Void No

Transaction Line Number

Comments

Transaction ID RISK00525037004

Stop No

Redeemed Information

Redeemed 02/14/2025 12:00 AM

Sequence Number

02183

Batch Number

0000

Redeemed Fund

0665

Redeemed Bank

0000

Redeemed Department

005

~ COA

Fund 0665

Sub Fund

Department

005

Object Class

Appropriation

0000 Sub BSA

Show More

Object

2715

Sub Object

Unit

5790

Revenue Source

Revenue Source Class

Dept Object


Dept Revenue

Sub Unit

Sub Revenue Source

BSA









NORTH IOWA COLLISION CENTER INC.

Serving your car, light & heavy duty truck, heavy equipment & RV repair needs. 11201 265TH ST, CLEAR LAKE, IA 50428

> Phone: (641) 421-8555 FAX: (641) 421-8558

Federal ID: Resale Number: Federal EPA:

Workfile ID:

PartsShare:

87-2591068 1-17-020011 IAR000007856

86bd7e66

8kRTN8

Final Bill

RO Number: 26737

Customer:

Insurance:

Adjuster:

Estimator:

Scott Larson

State of Iowa - Iowa Lottery

QCS

Phone:

Create Date:

1/10/2025

2900 - 4th Street SW

Claim:

APDSOI0297917-00

Mason City, IA 50401 (641) 424-6011

Loss Date: Deductible:

2021 CHRY Voyager LX FWD 4D VAN 6-3.6L Gasoline Sequential MPI Bright White Clearco

VIN:

2C4RC1CG2MR578089

Interior Color:

Black/Alloy/Black

Mileage In: Mileage Out: 56,384

Vehicle Out:

1/29/2025

License: CSR289 State: IΑ

Exterior Color: Production Date: Bright White Clearco 9/2021

Condition:

Job #:

Line Ver Operation Description Qty **Extended Part** Labor Type **Paint** Price \$ Type 1 E01 Rental Formula 28.8 / 4 = 7 2 E01 E01 **FRONT BUMPER & GRILLE** 3 4 E01 Remove/Replace O/H front bumper 3.9 Body 5 E01 Remove/Replace Bumper cover 1 667.00 A/M 0.0 Body 3.3 6 E01 Add for Clear Coat 1.3 E01 Refinish Tow eye cap 0.2 0.1 8 E01 Add for Clear Coat 9 E01 Remove/Replace LT Side bracket 1 10.55 **OEM** 0.0 Body E01 Remove/Install License bracket 0.2 Body 10 E01 Remove/Install License plate 0.1 Body 11 Upper grille 12 S01 Remove/Replace 1 81.00 A/M 0.0 Body Emblem chrome all 13 S01 Remove/Install 0.0 Body S01 **FRONT LAMPS** 14 15 S01 Remove/Replace LT Headlamp assy 1 333.33 Opt OEM 0.5 Body 16 S01 Remove/Replace Aim headlamps 0.5 Body OEM 17 S01 Remove/Replace LT Headlamp assy pin 1 3.30 18 S01 Remove/Replace LT Bracket 1 50.50 **OEM** 0.1 Body 19 E01 **RADIATOR SUPPORT** 20 E01 Remove/Install Sight shield 0.0 Body **FENDER** 21 E01 1 2.0 22 E01 Remove/Replace LT Fender w/o hybrid (HSS) 379.00 A/M 2.4 Body Overlap Major Non-Adj. Panel (0.2)23 E01 24 Add for Clear Coat 0.4 E01

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 26737

2021 CHRY Voyager LX FWD 4D VAN 6-3.6L Gasoline Sequential MPI Bright White Clearco

25	E01		Add for Edging					0.5
26	S01	Remove/Replace	LT Fender liner	1	81.00	A/M	0.0 Body	
27	S01	Remove/Replace	Fender Nutsert	1	10.30	OEM	,	
28	S01	A SAMONASSINA PRO MAN PROPRINCE	COWL					
29	S01	Remove/Replace	LT Side seal	1	25.40	OEM	0.1 Body	
30	E01	,	PILLARS, ROCKER & FLOOR				,	
31	S01	Remove/Replace	LT Glass assy Chrysler chrome	1	244.00	Glass	1.3 Body	
32	E01	Remove/Replace	Urethane / Glass Kit	1	15.00	A/M	,	
33	E01	Remove/Install	LT Rocker molding				0.0 Body	
34	S01		Rocker molding clips	4	16.40	OEM		
35	E01		FRONT DOOR					
36	S01	Remove/Install	LT R&I door assy				1.0 Body	
37	S01	Repair	LT Outer panel (HSS)				8.5 Body	2.1
38	E01		Overlap Major Adj. Panel					(0.4)
39	E01		Add for Clear Coat					0.3
40	E01	Remove/Replace	Mask for Primer Application	1	5.00	A/M	0.2 Body	
41	E01	Remove/Replace	Feather edge prime and block			A/M	1.0 Body	
42	S01	Remove/Install	LT R&I carrier assy				1.2 Body	
43	E01	Remove/Install	LT Belt molding outer chrome				0.3 Body	
44	E01	Remove/Install	LT R&I trim panel				0.6 Body	
45	E01	Remove/Install	LT Handle, outside painted, w/hands free ent, w/o chrome stone white				0.4 Body	
46	E01	Remove/Install	LT Power mirror man fold, w/painted base, w/blind spot bright white				0.5 Body	
47	S01	Remove/Install	LT Door glass Chrysler w/o acoustic glass				0.5 Body	
48	S01	Remove/Install	LT Window regulator				0.2 Body	
49	E01		VEHICLE DIAGNOSTICS					
50	S01	Sublet	Pre-repair scan	1	118.65	Sublet		
51	E01	Repair	Pre Repair Scan Labor				0.5 Mech	
52	S01	Sublet	Post-repair scan	1	98.90	Sublet		
53	E01	Repair	Post Repair Scan Labor				0.5 Mech	
54	E01		MISCELLANEOUS OPERATIONS					
55	E01	Remove/Replace	Cover car/bag	1	5.00	A/M	0.2 Body	
56	E01	Remove/Replace	Corrosion Protection	1	10.00	A/M	0.2 Body	
57	E01	Remove/Replace	Cavity wax	1	15.00	A/M	0.1 Body	
58	E01	Refinish	Tint color					0.5
59	S01	Remove/Replace	Rivet	3	12.30	A/M		
60	S01		Miniature Bulb	1	2.07	A/M		

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					1,966.15
Sublet/Miscellaneous					217.55
Labor, Body			75.00	24.0	1,800.00
Labor, Refinish			125.00	10.1	1,262.50

2/5/2025 8:28:38 AM Page 2

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 26737

2021 CHRY Voyager LX FWD 4D VAN 6-3.6L Gasoline Sequential MPI Bright White Clearco

Labor, Mechanical	75.00	1.0	75.00
E.P.C.			3.00
Subtotal			5,324.20
Sales Tax			0.00
Grand Total			5,324.20
Net Total			5,324.20

Estimate Version	Total \$
Original	3,964.50
Supplement S01	1,359.70
Insurance Total \$:	0.00
Received from Insurance \$:	0.00
Balance due from Insurance \$:	0.00
Customer Total \$:	5,324.20
Received from Customer \$:	0.00
Balance due from Customer \$:	5,324.20

2/5/2025 8:28:38 AM Page 3

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

TOR OF STATE AT THE OF TO

OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

February 6, 2025

Kristi Onstot Executive Council L O C A L

Subject: Deer Damage to Vehicle #105470 on January 10, 2025

Department of Administrative Services

Claim dated January 10, 2025

AOS Claim ID: 3970

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$4,130.74, subject to an audit of <u>actual</u> invoices.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Bu R Bus

cc: Adam Steen, Director, Department of Administrative Services

Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services

Heather Hackbarth, Department of Management