# OFFICE OF AUDITOR OF STATE



STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

September 11, 2025

Kristi Onstot Executive Council L O C A L

Subject: Hail Damage to Vehicle #351 on April 18, 2025

Department of Administrative Services

Claim dated April 29, 2025

AOS Claim ID: 4042

In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to the damages and have found the items to be in order as shown below:

Documented request			\$ 5,469.75
Executive Council Allocation			\$ 5,469.75
Less: Previous payments This payment Total	\$	0.00 5,469.75	\$ 5,469.75
Remaining Executive Council allo	ocation		\$ 0.00

We recommend reimbursement be made in the amount of \$5,469.75. This represents <u>full</u> and <u>final</u> payment of the loss.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Phi R Briss

CC: Kyle Wear, Fleet Services CFO, Department of Administrative Services Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services



KIM REYNOLDS, GOVERNOR CHRIS COURNOYER, LT. GOVERNOR ADAM STEEN, DIRECTOR

Date: August 6, 2025

Tammy Hollingsworth, Auditor of State To:

Victoria Newton, Treasurer of State

**Executive Council** 

From: Ryan Betts, DAS Fleet Risk Manager

**DAS Fleet Services** 

Department of Administrative Services

Re: REIMBURSEMENT REOUEST - 29C20 Claim

AOS Claim #	4042
Vehicle / Event	#351 / Hail
Event Date	April 18, 2025
Summary	Vehicle 351 sustained hail damage (Claim 305731)
Amount Requested	\$5,469.75 Total

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: 0665-005-5790-0657. If you have any questions or need additional information, please do not hesitate to contact me.

Thank you,

Ryan Betts

DAS Fleet Risk Manager ryan.betts1@iowa.gov

515-281-8008

Check Search &



Þ

← Back ::



#### CHEKOVEE COFFT2TOM CEMIEK

Federal ID:

42-1468487

Your Complete Auto Repair Center 111 INDIAN STREET, CHEROKEE, IA 51012

Phone: (712) 225-3877 FAX: (712) 225-3878

## **Final Bill**

RO Number: 7625

Customer:

Insurance:

Adjuster:

Estimator:

Rick Weaver

Iowa State Patrol

5116 IA-3 (712) 225-5119

Phone: Claim:

Create Date:

4/21/2025

Cherokee, IA 51012

Loss Date:

Deductible:

2023 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

VIN:

1C4SDJFT6PC676868

Interior Color:

Mileage In:

Vehicle Out:

License:

Exterior Color:

Mileage Out:

5/15/2025

State:

IΑ

Production Date:

Condition:

Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		Wash for PDR	1	30.00	Other	0.5	Body	
2	E01		Disconnect Battery & Disarm SRS				0.3	Mech	
3	E01		FRONT LAMPS						
4	E01	Remove/Install	RT Headlamp assy w/o auto high beam black bezel				0.4	Body	
5	E01		HOOD						
6	E01	Remove/Install	R&I hood assy				0.8	Body	
7	E01	Remove/Install	Insulator				0.3	Body	
8	E01	PDR	Hood (ALU) NOTE: PDR 50 quarter, 50 half	1	825.00	Other			
9	E01		FENDER						
10	E01	Remove/Install	RT Filler panel				0.2	Body	
11	E01	PDR	RT Fender NOTE: PDR 2 half	1	125.00	Other			
12	E01		ROOF						
13	E01	PDR	Roof panel w/o sunroof NOTE: PDR 65 quarter, 50 half	1	1,150.00	Other			
14	E01		Add for Oversized	8	400.00	Other			
15	E01	Remove/Install	R&I headliner				3.5	Body	
16	E01	Remove/Install	RT Sunvisor w/o illumination black				0.0	Body	
17	E01	Remove/Install	LT Sunvisor w/o illumination black	LT Sunvisor w/o illumination black		0.0	Body		
18	E01	Remove/Install	Police package trim/lights				2.5	Body	
19	E01		PILLARS, ROCKER & FLOOR						
20	E01	Remove/Install	RT W/S pillar trim black				0.0	Body	
21	E01	Remove/Install	LT W/S pillar trim black				0.0	Body	
22	E01	Remove/Install	RT Upr ctr plr trim black				0.0	Body	
23	E01	Remove/Install	LT Upr ctr plr trim black				0.0	Body	

2023 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

RO Number: 7625

2023	טטטט ט	diango Fursuit AVVD (116	eet) 4D 01V 6-3.7L Gasonile Sequential MP1				
24	E01	PDR	LT Aperture panel NOTE: PDR 5 half	1	125.00	Other	
25	E01	PDR	RT Aperture panel NOTE: PDR 5 half	1	125.00	Other	
26	E01		FRONT DOOR				
27	E01	PDR	RT Door shell NOTE: PDR 1 half	1	125.00	Other	
28	E01	PDR	LT Door shell NOTE: PDR 1 half	1	125.00	Other	
29	E01	Remove/Install	RT Belt molding				0.1 Body
30	E01	Remove/Install	LT Applique				0.2 Body
31	E01	Remove/Install	RT Power mirror w/o memory, w/blind spot detection gloss black				0.3 Body
32	E01	Remove/Install	LT Power mirror w/o memory, w/blind spot detection gloss black				0.3 Body
33	E01		REAR DOOR				
34	E01	PDR	LT Door shell NOTE: PDR 1 half	1	125.00	Other	
35	E01	Remove/Install	LT Belt molding				0.3 Body
36	E01	PDR	RT Door shell NOTE: PDR 1 half	1	125.00	Other	
37	E01	Remove/Install	RT Belt molding				0.3 Body
38	E01		QUARTER PANEL				
39	E01	Remove/Install	RT Pillar trim black				0.0 Body
40	E01	Remove/Install	LT Pillar trim black				0.0 Body
41	E01	Remove/Install	RT Rear trim panel w/o 3rd row all				0.0 Body
42	E01	Remove/Install	LT Rear trim panel w/o 3rd row all				0.0 Body
43	E01	PDR	LT Quarter panel NOTE: PDR 2 half	1	125.00	Other	
44	E01	PDR	RT Quarter panel NOTE: PDR 2 half	1	125.00	Other	
45	E01		REAR LAMPS				
46	E01	Remove/Install	LT Tail lamp assy				0.3 Body
47	E01	Remove/Install	RT Tail lamp assy				0.3 Body
48	E01		VEHICLE DIAGNOSTICS				
49	E01		Connect Battery & Arm SRS				0.2 Mech
50	E01		memory function reset				0.2 Body
51	E01	Repair	Battery support during PRE/POST scans				0.2 Mech
52	E01	Sublet	Pre-repair scan	1	120.00	Sublet	
53	E01	Sublet	Post-repair scan	1	120.00	Sublet	
54	E01	Remove/Replace	Hazardous Waste Charge	1	5.00	Other	
55	E01	Remove/Replace	Corrosion Protection	11	110.00	Other	0.3 Body
56	E01	Remove/Replace	Cover Car Charge	1	10.00	Other	0.2 Body
57	E01		pre delivery inspection and detail	1	30.00	Other	0.5 Body

<b>Estimate Totals</b>	Discount \$	Markup \$	Rate \$	<b>Total Hours</b>	Total \$
Parts					460.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

# RO Number: 7625

2023 DODG Durango Pursuit AWD (Fleet) 4D UTV 8-5.7L Gasoline Sequential MPI

Net Total			5,469.75
Grand Total			5,469.75
Sales Tax			0.00
Subtotal			5,469.75
Miscellaneous	556.25		3,781.25
Material, Shop	90.00	0.7	63.00
Labor, Mechanical	90.00	0.7	63.00
Labor, Body	75.00	11.5	862.50
Sublet/Miscellaneous			240.00

Estimate Version	Total \$
Original	5,469.75
Insurance Total \$:	0.00
Received from Insurance \$:	0.00
Balance due from Insurance \$:	0.00
Customer Total \$:	5,469.75
Received from Customer \$:	0.00
Balance due from Customer \$:	5,469,75

5/19/2025 5:54:26 PM

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

## OFFICE OF AUDITOR OF STATE

STATE OF IOWA

Rob Sand Auditor of State

State Capitol Building Des Moines, Iowa 50319-0004 Telephone (515) 281-5834

July 14, 2025

Kristi Onstot Executive Council LOCAL

Subject: Hail Damage to Vehicle #351 on April 18, 2025

Department of Administrative Services

Claim dated April 29, 2025

AOS Claim ID: 4042

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$5,469.75, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA Deputy Auditor of State

Phi RAS

cc: Adam Steen, Director, Department of Administrative Services Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services Heather Hackbarth, Department of Management