MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE



# Executive Council of Iowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

January 9, 2024

Accounting Department Office of the Treasurer Lucas Building 321 E 12<sup>th</sup> Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for a supplemental emergency allocation in the amount of \$1,818.91. This brings to total allocation to \$6,890.00. On June 26, 2023, Vehicle #2567 was damaged by a deer. Request was to cover repair costs.

This represents full and final payment and this allocation will be closed.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services DAS Fleet Services, Risk Matt Bender, Department of Management



## OFFICE OF AUDITOR OF STATE

STATE OF IOWA

State Capitol Building Des Moines, Iowa 50319-0004 Telephone (515) 281-5834 Facsimile (515) 281-6518

December 28, 2023

Victoria Newton Executive Council L O C A L

Subject: Deer Damage to Vehicle #2567 on June 26, 2023 Department of Administrative Services Claim dated June 28, 2023 AOS Claim ID: 3560

The Department's request included a supplemental allocation request of \$1,818.91 because additional damages were identified. We recommend Executive Council approval of the supplemental allocation of \$1,818.91, which increases the allocation to \$6,890.00. In accordance with Executive Council policy, we have examined the invoices and supporting documentation for final payment related to the damages and have found the items to be in order as shown below:

Documented request	\$ 6,890.00		
Executive Council Allocation (Revise	\$ 6,890.00		
Less: Previous payments This payment Total	\$	0.00 <u>6,890.00</u>	\$ 6,890.00
Remaining Executive Council alloca	\$ 0.00		

We recommend reimbursement be made in the amount of 6,890.00. This represents <u>full</u> and <u>final</u> payment of the loss.

Sincerely,

Ernest H. Ruben, Jr., CPA Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services Mariah Fucaloro, Fleet Services Manager, Department of Administrative Services

Rob Sand Auditor of State



Governor Kim Reynolds Lt. Governor Adam Gregg

Adam Steen, Director

Date: September 8, 2023

- To: Tammy Hollingsworth, Auditor of State Victoria Newton, Treasurer of State Executive Council
- From: Mariah Fucaloro, Fleet Manager DAS Fleet Services Department of Administrative Services

## Re: REIMBURSEMENT REQUEST - 29C20 Claim

Claim #	3560
Vehicle / Event	#2567/Deer
Event Date	June 26, 2023
Summary	Vehicle 2567 struck a deer. (261029)
Amount Requested	\$6,890.00 - TOTAL

The Department of Administrative Services, Central Procurement Fleet Services Enterprise, has paid all vendors to date. We are seeking an allocation for those funds under 29C20 Contingency Fund – Disaster Aid. Please deposit into the following account: **0665-005-5790-0657**.

If you have any questions or need additional information, please do not hesitate to contact me.

Thank you, 1100

Mariah Fucaloro, Fleet Manager DAS Fleet Services <u>Mariah.Fucaloro@iowa.gov</u> 515-414-6582

#### 8/30/23, 3:05 PM

## Warrants

Menu

Fiscal Year	Warrant Number	Line Number l	ine Amount	Issued	Redeemed	Vendor Customer
✓ 2024	72650383	1	\$1,267.20	08/18/2023	08/29/2023	00002107976
2024	72650383	2	\$126.00	08/18/2023	08/29/2023	00002107976
2024	72650383	3	\$918.00	08/18/2023	08/29/2023	00002107976
2024	2650383	4	\$4,578.80	08/18/2023	08/29/2023	00002107976
First Prev Next L	ast					
Search 🗸 🗸						
Warrant Informa	tion					
Fiscal Year			Amount : \$			
Warrant Number			Customer: 0			
Line Number	: 1	Last	Updated : 8	/29/23		
▼Issue Information						
	Issued : 08/18/20		Voi			
	ment ID: RISK00	524230604	Duplicat			
Document Line			Sto	p:		
	Amount : \$1,267.2	20				
Cor	nments :					
Redeemed Inform						
	eemed: 08/29/20		Batch Num			
	Bank: 0000	S	equence Num	ber: 04560		
	<b>Fund</b> : 0665					
Redeemed Depa	rtment: 005					
Fund Accounting						
Fund :	0665		Object :		Dept Object	ct:
Sub Fund :			Sub Object :		Dept Revenu	e :
Department : (			Object Class :			
Unit : :	5790		nue Source :			
Sub Unit :			nue Source :			
Appropriation : (	0000	Revenue S	ource Class :			
			BSA :			
			Sub BSA :			
Detail Accounting	)					
Location :		Report			Major Prog	gram :
Sub Location :		Sub Report	ing :		Prog	gram :
Activity :			ask :			hase :
Sub Activity :		Sub Ta			Program Pe	eriod :
Function :		Task Or	der:			
Sub Function :						

\_\_\_\_



----

. ..

.

## Abra - Dubuque

When You're Ready 3400 Center Grove Dr., Dubuque, IA 52003 Phone: (563) 556-0696 FAX: (563) 556-1899

#### **Final Bill**

RO Number: 34200			
Customer:	Insurance:	Adjuster:	Estimator: Chad Hahn
STATE OF IOWA/DNR	STATE OF IOWA	Phone:	Create Date: 6/26/2023
		Claim: UNIT-2567	
		Loss Date:	
(563) 590-6952		Deductible:	

#### 2018 RAM 1500 SSV Crew Cab 4WD w/5'7" Box (Fleet) 4D P/U 8-5.7L Gasoline Sequential MPI GREY

VIN:	1C6RR7XT3JS270620	Interior Color:		Mileage In:	96,618	Vehicle Out:	7/12/2023
License:	C-299	Exterior Color:	GREY	Mileage Out:	96,619		
State:	IA	Production Date:	4/2018	Condition:	Good	Job #:	

E01 E01 E01	Remove/Replace	FRONT BUMPER						
	Remove/Replace							
E01	Prevention and the second statement of the second	O/H front bumper				3.4T	Body	
	Remove/Replace	Upper cover black molded	1	199.00T	A/M	0.0T	Body	
E01	Remove/Replace	License bracket	1	31.00T	A/M	0.2T	Body	
501	Remove/Replace	Bumper painted, w/tow hooks w/o prk snsr w/o fog lamp	1	631.00T	A/M	0.0T	Body	2.6T
501		Add for Clear Coat						1.0T
E01		GRILLE						
E01	Remove/Replace	Grille black hexagon, primed surround bars	1	284.00T	A/M	0.0T	Body	1.5T
E01		Add for Clear Coat						0.6T
E01	Remove/Replace	RT Closure panel	1	27,60T	OEM			
E01	Remove/Replace	LT Closure panel	1	27.60T	OEM			
E01	Remove/Replace	Emblem chrome	1	153.00T	OEM	0.0T	Body	
E01		FRONT LAMPS						
E01	Remove/Install	RT R&I headlamp assy				0.0T	Body	
E01	Remove/Install	LT R&I headlamp assy				0.0T	Body	
E01		RADIATOR SUPPORT						
E01	Remove/Replace	Sight shield w/o diesel	1	210.00T	A/M	0.0T	Body	
E01	Remove/Replace	Radiator support w/o diesel	1	869.26T	A/M	3.6T	Body	
501	Remove/Install	Strobe lights and siren				2.0T	Body	
-01		COOLING						
E01						0.07	<b>D</b>	
	Remove/Replace	Radiator	1	259.99T	A/M	3.3T	Body	
501	Remove/Replace Remove/Replace	Radiator Deduct for Overlap	1	259.99T	A/M		Body Body	
	)1 )1 )1 )1 )1 )1 )1	01   Remove/Replace     01   Remove/Install     01   Remove/Install     01   Remove/Replace     01   Remove/Replace     01   Remove/Replace     01   Remove/Install	1 Remove/Replace Emblem chrome   11 Remove/Install FRONT LAMPS   11 Remove/Install RT R&I headlamp assy   11 Remove/Install LT R&I headlamp assy   11 Remove/Replace Sight shield w/o diesel   11 Remove/Replace Radiator support w/o diesel   11 Remove/Install Strobe lights and siren   11 COOLING	1 Remove/Replace Emblem chrome 1   1 FRONT LAMPS 1   11 Remove/Install RT R&I headlamp assy 1   11 Remove/Install LT R&I headlamp assy 1   11 Remove/Install LT R&I headlamp assy 1   11 Remove/Replace Sight shield w/o diesel 1   11 Remove/Replace Radiator support w/o diesel 1   11 Remove/Install Strobe lights and siren 1   11 COOLING COOLING	P1Remove/ReplaceEmblem chrome1153.00TP1FRONT LAMPSFRONT LAMPSFRONT LAMPSFRONT LAMPSP1Remove/InstallRT R&I headlamp assyFRONT LAMPSFRONT LAMPSP1Remove/InstallLT R&I headlamp assyFRONT SUPPORTFRONT SUPPORTP1Remove/ReplaceSight shield w/o diesel1210.00TP1Remove/ReplaceRadiator support w/o diesel1869.26TP1Remove/InstallStrobe lights and sirenCOOLINGFRONT	Mathematical 	1Remove/ReplaceEmblem chrome1153.00TOEM0.0T01FRONT LAMPSFRONT LAMPS0.0T01Remove/InstallRT R&I headlamp assy0.0T01Remove/InstallLT R&I headlamp assy0.0T01Remove/ReplaceSight shield w/o diesel1210.00T01Remove/ReplaceSight shield w/o diesel1869.26TA/M0.0T01Remove/ReplaceRadiator support w/o diesel1869.26TA/M3.6T01Remove/InstallStrobe lights and siren2.0T2.0T01COOLINGKenderKenderKenderKender	1Remove/ReplaceEmblem chrome1153.00TOEM0.0TBody1Remove/InstallRT R&I headlamp assy0.0TBody1Remove/InstallLT R&I headlamp assy0.0TBody1Remove/InstallLT R&I headlamp assy0.0TBody1Remove/ReplaceSight shield w/o diesel1210.00TA/M0.0TBody1Remove/ReplaceSight shield w/o diesel1210.00TA/M0.0TBody1Remove/ReplaceRadiator support w/o diesel1869.26TA/M3.6TBody1Remove/InstallStrobe lights and siren2.0TBody2.0TBody

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

WORKTHE ID: Federal ID: e4123830

42-0782245

Federal ID:

#### **RO Number: 34200**

2018 RAM 1500 SSV Crew Cab 4WD w/5'7" Box (Fleet) 4D P/U 8-5.7L Gasoline Sequential MPI GREY

		242 W.S. 12					
24	S01	Remove/Replace	Upper shroud	1	237.00T	OEM	0.0T Body
25	S01	Remove/Replace	Lower shroud 1 62.45T OEM			OEM	0.0T Body
26	E01		AIR CONDITIONER & HEATER				
27	S01	Remove/Replace	Condenser 6 speed trans	1	680.00T	A/M	0.8T Body
28	E01	Repair	AC Service evacuate & recharge				1.4T Mech
29	E01	Repair	AC Service refrigerant recovery				0.4T Mech
30	E01		HOOD				
31	E01	Remove/Install	Insulator w/o diesel				0.3T Body
32	E01	Repair	Hood w/o powr bulge				2.0T Body 2.5T
33	E01		Overlap Major Non-Adj. Panel				(0.2)T
34	E01		Add for Clear Coat				0.5T
35	E01		FENDER				
36	E01	Remove/Install	RT R&I fender assy				1.5T Body
37	E01	Remove/Install	LT R&I fender assy				1.5T Body
38	E01		ENGINE				
39	E01	Remove/Install	R&I air cleaner assy				0.5T Body
40	S01	Remove/Replace	Throttle body assy	1	351.90T	A/M	
41	S01	Remove/Replace	Gasket	2	51.60T	A/M	
42	E01		WINDSHIELD				
43	E01	Remove/Install	RT Washer nozzle				0.2T Body
44	E01	Remove/Install	LT Washer nozzle				0.2T Body
45	E01	Remove/Install	Washer reservoir w/o diesel				0.0T Body
46	S01	Remove/Replace	Coolant	1	70.00	OEM	
			NOTE: Subject to invoice				
47	E01		Hazardous waste removal	1	5.00T	Other	
48	E01	Remove/Replace	Cover Car	1	5.00T	Other	
49	E01		VEHICLE DIAGNOSTICS				
50	E01	Sublet	Pre-repair scan	1	60.00	Sublet	
51	E01	Repair	Pre-repair scan				0.5T Body
52	S01	Sublet	Diagnose and replace throttle body damage	1	300.00	Other	

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					4,218.80
Sublet/Miscellaneous					360.00
Labor, Body			66.00	19.2	1,267.20
Labor, Refinish			108.00	8.5	918.00
Labor, Mechanical			70.00	1.8	126.00
Subtotal					6,890.00
Sales Tax					0.00
Grand Total	-				6,890.00
Net Total					6,890.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

## RO Number: 34200

2018 RAM 1500 SSV Crew Cab 4WD w/5'7" Box (Fleet) 4D P/U 8-5.7L Gasoline Sequential MPI GREY

Estimate Version	Total \$		
Original	5,071.09		
Supplement S01	1,818.91		
Insurance Total \$:	0.00		
Received from Insurance \$:	0.00		
Balance due from Insurance \$:	0.00		
Customer Total \$:	6,890.00		
Received from Customer \$:	0.00		
Balance due from Customer \$:	6,890.00		

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



## OFFICE OF AUDITOR OF STATE

STATE OF IOWA

State Capitol Building Des Moines, Iowa 50319-0004 Telephone (515) 281-5834 Facsimile (515) 281-6518 Rob Sand Auditor of State

August 4, 2023

Victoria Newton Executive Council L O C A L

Subject: Deer Damage to Vehicle #2567 on June 26, 2023 Department of Administrative Services Claim dated June 28, 2023 AOS Claim ID: 3560

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$5,071.09, subject to an audit of <u>actual</u> invoices.

Sincerely,

Ernest H. Ruben, Jr., CPA Deputy Auditor of State

cc: Adam Steen, Director, Department of Administrative Services Mariah Flowers, Fleet Services Manager, Department of Administrative Services Joel Lunde, Department of Management MEMBERS OF COUNCIL

HON. KIM REYNOLDS GOVERNOR

HON. PAUL D. PATE SECRETARY OF STATE

HON. ROB SAND AUDITOR OF STATE

HON. ROBY SMITH TREASURER OF STATE

HON. MIKE. NAIG SECRETARY OF AGRICULTURE SEAL SEAL

Executive Council of Iowa

CAPITOL BUILDING DES MOINES, IOWA 50319 PHONE: 515 281-5368

September 5, 2023

Accounting Department Office of the Treasurer Lucas Building 321 E 12<sup>th</sup> Street Des Moines, IA, 50319

The Executive Council, in a meeting held on today's date, approved Department of Administrative Services request for an emergency allocation in the amount of \$5,071.09, subject to the audit of actual invoices. On June 26, 2023, Vehicle #2567 was damaged by a deer. Request was to cover repair costs.

EXECUTIVE COUNCIL OF IOWA

Victoria Newton

Victoria Newton Executive Secretary

cc: Adam Steen, Director, Department of Administrative Services DAS Fleet Services, Risk Joel Lunde, Department of Management

> AOS Claim # 3560 TOS Job # \_\_\_\_