

## **Agenda Item #2d**

### **Authorization to Seek Bids for Project 11-23, Rehabilitation of Horseshoe Park Storm Sewer**

#### **Background**

The flow line of the 72" Corrugated Metal Pipe (CMP) under Horseshoe Park has deteriorated and is allowing soil migration, leading to sink holes in the park. Photos of the pipe are attached. After assessing the pipe with staff and consultants we are recommending bidding out a contract to patch/rehabilitate the flow line of the pipe and make tuck-point repairs to structures in the system. In addition, we will be looking for alternate bids to install structural liner for the CMP sections.

#### **Recommended Action**

- Authorize Engineering Department to seek bids for Project 11-23, Rehabilitation of Horseshoe Park Storm Sewer.



