

ITEM

ITEM PICTURE

ITEM DESCRIPTION

2005 HD2500 Chevy Pickup



2005 HD2500 Chevy Pickup, extended cab, 2 WD, 8Ft Box, Major mechanical issues

Tires (x2)



Size 315/80R225 Bridgestone

Stream Lights (x2)



Telescopic Stream lights - bad batteries

Brooms X2



Air bags (x2)



Air bags with regulators (out of date)

Air Hammer



Air hammer with attachments

Air Hose



50 Ft air hose

Fire Extinguishers



20 fire extinguishers - multiple sizes

Extension Cord



50 FT extension cord

Wooden Box

Extension cords x2

EMS Bags (x2)

Draeger RIT Pack

Safety Harnesses

ARGUS Thermal Image Camera

Fiberglass SCBA Bottle

Steel SCBA Bottle

Headsets with Mic x3

Chock Blocks - Small

Chock Blocks - Large



Wooden box

2 - 25 Ft extension cords

Older EMS bags - stained/damaged zippers

Draeger RIT Pack with 1 mask and 1 bottle

4 Safety Harnesses (out of date)

ARGUS Thermal Image Camera - 2 batteries no charger

Fiberglass SCBA Bottle 2216 PSI

Steel SCBA Bottle 2216

TAIT Headsets with mic x3

Chock Blocks - Small

Chock Blocks - Large

Shovel



Bolt Cutter



Crowbars (x5 multiple sizes)



Long Board



John Deere UTV Box



Rope Bags with Rope x2



Rope Rescue Bag with Rope



Rope Rescue equipment



Gated Wye



Misc Spanner Wrenches x20



Misc. Fittings and caps



Shovel

Bolt Cutter

Crowbars (x5 multiple sizes)

Long Board

John Deere UTV Box

Rope Bags with Rope x2 - out of date /not tested

Rope Rescue Bag with Rope - out of date/not tested

Rope Rescue equipment - out of date/not tested

4in Storz to 2 1/2 Gated Wye

Misc Spanner Wrenches x20

Misc. Fittings and caps

Foam Nozzle (1 1/2")



Hydrant Wrenches x3/Rubber Mallet

Gated Wye

Gated Wye

Pepsi Machine

Foam Nozzle (1 1/2")

Hydrant Wrenches x3/Rubber Mallet

1" Gated Wye

2 1/2" Gated Wye

Pepsi Machine - non working - no freon