



EXISTING PICTURE P11



EXISTING PICTURE P12



EXISTING PICTURE P13



EXISTING PICTURE P14



EXISTING PICTURE P15



EXISTING PICTURE P16



EXISTING PICTURE P17



EXISTING PICTURE P18



EXISTING PICTURE P19

**GENERAL NOTES. TYP.**

AS SHOWN INTERIOR PICTURES; WOOD ROD AND TERMITE DAMAGED, INCLUDING BUT NOT LIMITED TO:

WINDOWS AND WINDOWS WOOD FRAMING, WOOD DOOR AND DOORS WOOD FRAMING, CASING, WOOD STUDS/ WOOD FRAMING, EXTERIOR WOOD SIDING AND SOME ROOF RAFTERS. STRUCTURAL ENGINEER VISITED THE SITE AND RECOMMENDED SHORING THE ROOF STRUCTURE.

architectural  
consultants  
inc.

ARCHITECTURE / DESIGN  
Lic. No. 26002046

2475 MERCER AVE.  
SUITE 201  
West Palm Beach, Florida 33401

Phone 561-655-0674

GUEST HOUSE  
RENOVATION TO  
414 GREENBRIAR DR  
LAKE PARK, FL 33405

CONTRACTOR AND ALL SUBCONTRACTORS PERFORMING ANY WORK ON THIS PROJECT ARE TO VISIT THE SITE AND VERIFY ALL MEASUREMENTS INCLUDING BUT NOT LIMITED TO BUILDING HEIGHTS, ROOF SLOPES, ROOM DIMENSIONS ETC. TO CONFIRM ALL EXISTING CONDITIONS BEFORE ORDERING OR FABRICATING ANY MATERIALS. CONTRACTOR SHALL REPORT ANY INCONSISTENCIES WITH THE CONSTRUCTION DOCUMENTS TO THE ARCHITECT BEFORE CONTINUING WORK.

REV # DATE DESCRIPTION

SEAL

ROGER HANSROTE, ARCHITECT  
FLAR # 14300

REVISION

JOB NUMBER: 2022-53  
DATE: 07-22-2022  
DRAWN BY: AL/MG  
APPROVED BY: RH

SHEET TITLE

EXISTING  
INTERIOR  
PHOTOGRAPHS

SHEET NUMBER