



1225 N.W. Avenue L
 Belle Glade, FL 33430
 www.trippmotors.com
 561.996.3333

Quote

Date	Quote #
5/5/26	25695



Name / Address
City of Lake Worth 7 North Dixie Highway Lake Worth, FL 33460

MFG	HP
Wilo	405

Item	Description	Qty	Cost	Total
Overhaul	Repair pump- WILO EMU, 405 HP, 891 RPM, 460 VAC, 520 AMPS, MODEL# FA30.78D + FKT56-8/78GEX, SERIAL# 312040	50	125.00	6,250.00
REW	Rewind AC Stator	1	18,827.57	18,827.57
MACHINE	MACHINE SUCTION COVER / ROTOR SHAFT / SS IMPELLER / ROTATING WEAR RINGS / STATIONARY WEAR RINGS.	1	25,525.00	25,525.00
NON-INV	MULLER 7703103 / 3/0 CABLE	92	92.55	8,514.60
NON-INV	12 MULLER 316 SS CONECTORS	4	569.77	2,279.08
NON-INV	E6002964 Wilo Temp Sensor	1	227.22	227.22
NON-INV	E6073838 Mechanical Seal	1	4,074.00	4,074.00
NON-INV	E6003905 Mechanical Seal	1	3,594.00	3,594.00
NON-INV	Casing O-rings / Gasket Kit	1	205.20	205.20
SANDBLAST	SANDBLAST & PRIMER PAINT	1	450.00	450.00
SRI-NLG12-1/14	Chevron Grease	2	29.92	59.84
T-68	Shell Turbo 68	120	10.56	1,267.20
Crane	Beyel Crane Install-not to exceed		800.00	800.00
BAL	Dynamic Balance		285.00	285.00
ENVIR	Hazardous material disposal fee		10.75	10.75
	SUBTOTAL			72,369.46
Thank You For Choosing Tripp Electric Motors For Your Equipment Repair Needs!!			Total	\$72,369.46