



Awarded Contract

Call Us first, for all of your Fleet Automotive, & Light Truck needs.

Quote

PHONE (800) ALANJAY (252-6529)		DIRECT 863-385-9610	WWW.ALANJAY.COM	34089-2
Corporate Office	2003 U.S. 27 South Sebring, FL 33870	MOBILE 904-838-4999	Mailing Address	P.O. BOX 9200 Sebring, FL 33871-9200
		FAX 863-402-4221		

ORIGINAL QUOTE DATE  
10/14/2021

# QUICK QUOTE SHEET

REVISED QUOTE DATE  
10/14/2021

REQUESTING AGENCY	LAKE WORTH, CITY OF		
CONTACT PERSON	FELIPE LOFASO	EMAIL	<a href="mailto:Flofaso@lakeworth.org">Flofaso@lakeworth.org</a>
PHONE	561-586-1720	MOBILE	FAX

**SOURCEWELL (FORMERLY NJPA) CONTRACT # 2021 120716-NAF & 060920-NAF** [www.NationalAutoFleetGroup.com](http://www.NationalAutoFleetGroup.com)

MODEL	TC10753 1SA	MSRP	\$35,560.00
2021 GMC SIERRA 1500 DOUBLE CAB 2WD 6.5' BED 147" WB WORK TRUCK			

**CUSTOMER ID** **BASE VEHICLE PRICE \$21,995.00**

**BED LENGTH 6.5' BED**

*\*\* All vehicles will be ordered white w/ darkest interior unless clearly stated otherwise on purchase order.*

FACTORY OPTIONS	DESCRIPTION	
GAZ H2G	EXTERIOR COLOR SUMMIT WHITE WITH JET BLACK VINYL INTERIOR.	\$0.00
LV3 MYC	4.3L ECOTEC V6 WITH 6-SPD AUTO TRANS	\$0.00
PEB	Sierra Value Package includes (PCI) Convenience Convenience Package includes (AQQ) Remote Keyless Entry, (QT5) EZ Lift power lock and release tailgate, (AKO) tinted glass, (UF2) LED cargo bed lighting, (C49) rear-window defogger, (K34) cruise control and (DLF) outside power mirrors(Not available with (ZLQ) Fleet Convenience Package. When (ZW9) pickup bed delete is ordered (QT5) EZ Lift power lock and release tailgate and (UF2) LED cargo bed lighting will not be available. Included with (PEB) Sierra Value Package.) and (Z82) Trailering Package(Not available with (ZW9) pickup bed delete or (ZLQ) Fleet Convenience Package.)	\$1,635.00
PCI	Convenience Package <b>**INCLUDED WITH PEB**</b> includes (AQQ) Remote Keyless Entry, (QT5) EZ Lift power lock and release tailgate, (AKO) tinted glass, (UF2) LED cargo bed lighting, (C49) rear-window defogger, (K34) cruise control and (DLF) outside power mirrors(Not available with (ZLQ) Fleet Convenience Package. When (ZW9) pickup bed delete is ordered (QT5) EZ Lift power lock and release tailgate and (UF2) LED cargo bed lighting will not be available. Included with (PEB) Sierra Value Package. Available to upgrade to (QK2) GMC MultiPro Tailgate without (ZW9) pickup bed delete.)	\$0.00
JL1	Trailer brake controller, integrated	\$270.00
VQO	LPO, BLACK ASSIST STEP.	\$445.00
5H1	2 ADDITIONAL KEYS FACTORY CUT DEALER PROGRAMMED	\$125.00
VK3	FRONT LICENSE PLATE BRACKET FACTORY ORDERED	\$0.00
MY22	2022 MODEL YEAR INCREASE. (2% OF MSRP (\$35,560 X 2% = \$711.20)	\$711.20

CONTRACT OPTIONS	DESCRIPTION	FACTORY OPTIONS	
NEW-TAG	New CITY tag Includes temp tag & two way overnight shipping for signature.		\$245.00
HD SOB SH	HD Scorpion spray on bed liner (short bed) under rail.		\$540.00
DTF 4 TRK	Deep tint film installed on four doors and back glass for extended/crew cab pickups.		\$255.00
MG575	MAJOR GUARD 5YR 75K MILE (NON-EMERGENCY) \$0 DED		\$2,551.00

**CONTRACT OPTIONS \$3,591.00**

--	--	--	--

VEHICLE TOTAL \$25,181.20

ACCESSORY TOTAL \$3,591.00

TRADE IN

CUSTOMER PRICE \$28,772.20

YES WE TAKE TRADE INS ~~~ ASK ABOUT MUNICIPAL FINANCING ~~~ \$0.00

TOTAL COST LESS TRADE IN(S) QTY 2 \$57,544.40

Estimated Annual payments for 60 months paid in advance: \$6,443.79 Extended: \$12,887.58  
Municipal finance for any essential use vehicle, requires lender approval, WAC.

Comments STOCK UNIT VIN: [VIN NA] READY FOR QUICK DELIVERY

VEHICLE QUOTED BY CHRISTY SELF GOVERNMENT ACCOUNT MANAGER [christy.self@alanjay.com](mailto:christy.self@alanjay.com)

"I Want to be Your Fleet Provider"

I appreciate the opportunity to submit this quotation. Please review it carefully. If there are any errors or changes, please feel free to contact me at any time.  
I am always happy to be of assistance.



# ALAN JAY FLEET

SCOTT WILSON | 863-402-4234 | SCOTT.WILSON@ALANJAY.COM

Vehicle: [Fleet] 2021 GMC Sierra 1500 (TC10753) 2WD Double Cab 147" (✔ Complete)



Note:Photo may not represent exact vehicle or selected equipment.

## Window Sticker

### SUMMARY

[Fleet] 2021 GMC Sierra 1500 (TC10753) 2WD Double Cab 147"

MSRP:\$34,000.00

Interior:Jet Black, Vinyl seat trim

Exterior 1:Summit White

Exterior 2:No color has been selected.

Engine, 4.3L EcoTec3 V6 with Active Fuel Management

Transmission, 6-speed automatic, electronically controlled

### OPTIONS

CODE	MODEL	MSRP
TC10753	[Fleet] 2021 GMC Sierra 1500 (TC10753) 2WD Double Cab 147"	\$34,000.00
<b>OPTIONS</b>		
1SA	Work Truck Preferred Equipment Group	\$0.00
5H1	Key equipment, two additional keys for single key system	\$45.00
AE7	Seats, front 40/20/40 split bench	\$0.00
AKO	Glass, deep-tinted	Inc.
AQQ	Remote Keyless Entry	Inc.
C49	Defogger, rear-window electric	Inc.

This document contains information considered Confidential between GM and its Clients uniquely. The information provided is not intended for public disclosure. Prices, specifications, and availability are subject to change without notice, and do not include certain fees, taxes and charges that may be required by law or vary by manufacturer or region. Performance figures are guidelines only, and actual performance may vary. Photos may not represent actual vehicles or exact configurations. Content based on report preparer's input is subject to the accuracy of the input provided.

Data Version: 14078. Data Updated: Jun 23, 2021 12:49:00 AM PDT.



# ALAN JAY FLEET

SCOTT WILSON | 863-402-4234 | SCOTT.WILSON@ALANJAY.COM

Vehicle: [Fleet] 2021 GMC Sierra 1500 (TC10753) 2WD Double Cab 147" (✔ Complete)

CTT	Hitch Guidance	Inc.	
DLF	Mirrors, outside heated power-adjustable	Inc.	
FE9	Emissions, Federal requirements		\$0.00
GAZ	Summit White		\$0.00
GU6	Rear axle, 3.42 ratio		\$0.00
H2G	Jet Black, Vinyl seat trim		\$0.00
IOR	Audio system, GMC Infotainment System with 7" diagonal color touch-screen, AM/FM stereo		\$0.00
JL1	Trailer brake controller, integrated		\$275.00
K34	Cruise control, steering wheel-mounted	Inc.	
LV3	Engine, 4.3L EcoTec3 V6 with Active Fuel Management		\$0.00
MYC	Transmission, 6-speed automatic, electronically controlled		\$0.00
PCI	Convenience Package	Inc.	
PEB	Sierra Value Package		\$1,640.00
QBN	Tires, 255/70R17 all-season, blackwall		\$0.00
QBR	Tire, spare 255/70R17 all-season, blackwall		\$0.00
QT5	Tailgate, gate function manual with EZ Lift	Inc.	
R9Y	Fleet Free Maintenance Credit.		(\$45.00)
RD6	Wheels, 17" x 8" (43.2 cm x 20.3 cm) painted steel, Silver		\$0.00
UF2	LED Cargo Area Lighting	Inc.	
VK3	License plate kit, front		\$0.00
VQ2	Fleet processing option		\$0.00
VQO	LPO, Black assist step		\$450.00
Z82	Trailer Package	Inc.	
—	Option/Package Discount		(\$2,500.00)

<b>SUBTOTAL</b>	<b>\$33,865.00</b>
Adjustments Total	\$0.00
Destination Charge	\$1,695.00
<b>TOTAL PRICE</b>	<b>\$35,560.00</b>

## FUEL ECONOMY

Est City:16 MPG

This document contains information considered Confidential between GM and its Clients uniquely. The information provided is not intended for public disclosure. Prices, specifications, and availability are subject to change without notice, and do not include certain fees, taxes and charges that may be required by law or vary by manufacturer or region. Performance figures are guidelines only, and actual performance may vary. Photos may not represent actual vehicles or exact configurations. Content based on report preparer's input is subject to the accuracy of the input provided.


Data Version: 14078. Data Updated: Jun 23, 2021 12:49:00 AM PDT.



# ALAN JAY FLEET

SCOTT WILSON | 863-402-4234 | SCOTT.WILSON@ALANJAY.COM

---

Vehicle: [Fleet] 2021 GMC Sierra 1500 (TC10753) 2WD Double Cab 147" (  Complete )

---

Est Highway:21 MPG

Est Highway Cruising Range:504.00 mi

---

This document contains information considered Confidential between GM and its Clients uniquely. The information provided is not intended for public disclosure. Prices, specifications, and availability are subject to change without notice, and do not include certain fees, taxes and charges that may be required by law or vary by manufacturer or region. Performance figures are guidelines only, and actual performance may vary. Photos may not represent actual vehicles or exact configurations. Content based on report preparer's input is subject to the accuracy of the input provided.

Data Version: 14078. Data Updated: Jun 23, 2021 12:49:00 AM PDT.



# ALAN JAY FLEET

SCOTT WILSON | 863-402-4234 | SCOTT.WILSON@ALANJAY.COM

Vehicle: [Fleet] 2021 GMC Sierra 1500 (TC10753) 2WD Double Cab 147" (✔ Complete)

## Standard Equipment

### Mechanical

Pickup bed (Deleted when (ZW9) pickup bed delete is ordered on Regular Cab models.)

Engine, 4.3L EcoTec3 V6 with Active Fuel Management (285 hp [212 kW] @ 5300 rpm, 305 lb-ft of torque [413 Nm] @ 3900 rpm) (Requires (MYC) 6-speed automatic transmission.) (STD)

Transmission, 6-speed automatic, electronically controlled with overdrive and tow/haul mode. Includes Cruise Grade Braking and Powertrain Grade Braking (Included and only available with (LV3) 4.3L EcoTec3 V6 engine or (L82) 5.3L EcoTec3 V8 engine.) (STD)

GVWR, 6800 lbs. (3084 kg) (Requires 2WD model with (LV3) 4.3L EcoTec3 V6 engine, 2WD Crew Cab or Double Cab models with (L3B) 2.7L Turbo engine or Double Cab or Regular Cab 2WD model and (L82) 5.3L EcoTec3 V8 engine.) (STD)

Rear axle, 3.42 ratio

Rear wheel drive

Cooling, external engine oil cooler (Not available with (L3B) 2.7L Turbo engine.)

Alternator, 170 amps

Battery, heavy-duty 730 cold-cranking amps/70 Amp-hr, maintenance-free with rundown protection and retained accessory power (Included and only available with (LV3) 4.3L EcoTec3 V6 engine.)

Frame, fully-boxed, hydroformed front section

Cargo tie downs (12), fixed, rated at 500 lbs per corner

Steering, Electric Power Steering (EPS) assist, rack-and-pinion

Brakes, 4-wheel antilock, 4-wheel disc with DURALIFE rotors

Capless Fuel Fill

Exhaust, single outlet

Exhaust, aluminized stainless-steel muffler and tailpipe

### Exterior

Wheels, 17" x 8" (43.2 cm x 20.3 cm) painted steel, Silver (STD)

Tires, 255/70R17 all-season, blackwall (STD)

Tire, spare 255/70R17 all-season, blackwall (Included with (QBN) 255/70R17 all-season, blackwall tires.) (STD)

Wheel, 17" x 8" (43.2 cm x 20.3 cm) full-size, steel spare

Tire carrier lock keyed cylinder lock that utilizes same key as ignition and door (Deleted with (ZW9) pickup bed delete.)

Bumper, front chrome lower (Requires (VJH) rear chrome bumper and (E63) pickup bed. Required with (UD7) Rear Park Assist.)

Bumper, rear chrome with bumper CornerSteps (Requires (V46) front chrome bumper and (E63) pickup bed.)

This document contains information considered Confidential between GM and its Clients uniquely. The information provided is not intended for public disclosure. Prices, specifications, and availability are subject to change without notice, and do not include certain fees, taxes and charges that may be required by law or vary by manufacturer or region. Performance figures are guidelines only, and actual performance may vary. Photos may not represent actual vehicles or exact configurations. Content based on report preparer's input is subject to the accuracy of the input provided.

Data Version: 14078. Data Updated: Jun 23, 2021 12:49:00 AM PDT.



# ALAN JAY FLEET

SCOTT WILSON | 863-402-4234 | SCOTT.WILSON@ALANJAY.COM

Vehicle: [Fleet] 2021 GMC Sierra 1500 (TC10753) 2WD Double Cab 147" (✔ Complete)

## Exterior

- CornerStep, rear bumper
- Grille (Chrome surround with Black mesh.)
- Headlamps, LED reflector with incandescent turn signals and LED signature Daytime Running Lamps
- Taillamps, LED tail and stop light with incandescent reverse light
- Mirrors, outside manual, Black
- Glass, solar absorbing, tinted
- Lamps, cargo area, cab mounted integrated with center high mount stop lamp, with switch in bank on left side of steering wheel
- Tailgate, standard (Deleted with (ZW9) pickup bed delete.)
- Tailgate, gate function manual, no lift assist (Deleted with (ZW9) pickup bed delete or (QK2) GMC MultiPro Tailgate.)
- Tailgate and bed rail protection caps, top
- Tailgate, locking utilizes same key as ignition and door (Deleted with (ZW9) pickup bed delete or (QK2) GMC MultiPro Tailgate.)
- Door handles, Black grained

## Entertainment

- Audio system, GMC Infotainment System with 7" diagonal color touch-screen, AM/FM stereo with seek-and-scan and digital clock, includes Bluetooth streaming audio for music and select phones; featuring wired Android Auto and Apple CarPlay capability for compatible phones (STD)
- Audio system feature, 6-speaker system (Requires Crew Cab or Double Cab model.)
- Bluetooth for phone connectivity to vehicle infotainment system

## Interior

- Seats, front 40/20/40 split bench with covered armrest storage (STD)
- Seat adjuster, driver 4-way manual
- Seat adjuster, passenger 4-way manual
- Seat, rear 60/40 folding bench (folds up), 3-passenger (includes child seat top tether anchor) (Not available with Regular Cab model.)
- Floor covering, rubberized-vinyl (Not available with LPO floor liners.)
- Steering column, Tilt-Wheel, manual with wheel locking security feature
- Steering wheel, urethane
- Instrument cluster, 6-gauge cluster featuring speedometer, fuel level, engine temperature, tachometer, voltage and oil pressure
- Driver Information Center, 3.5" diagonal monochromatic display

This document contains information considered Confidential between GM and its Clients uniquely. The information provided is not intended for public disclosure. Prices, specifications, and availability are subject to change without notice, and do not include certain fees, taxes and charges that may be required by law or vary by manufacturer or region. Performance figures are guidelines only, and actual performance may vary. Photos may not represent actual vehicles or exact configurations. Content based on report preparer's input is subject to the accuracy of the input provided.

Data Version: 14078. Data Updated: Jun 23, 2021 12:49:00 AM PDT.



# ALAN JAY FLEET

SCOTT WILSON | 863-402-4234 | SCOTT.WILSON@ALANJAY.COM

Vehicle: [Fleet] 2021 GMC Sierra 1500 (TC10753) 2WD Double Cab 147" (✔ Complete)

## Interior

Exterior Temperature Display, located in radio display

Brake lining wear indicator

Windows, power front, drivers express up/down (Standard on Crew Cab and Double Cab. On Regular Cab, included and only available with (PCI) Convenience Package or (ZLQ) Fleet Convenience Package.)

Window, power front, passenger express down (Standard on Crew Cab and Double Cab. On Regular Cab, included and only available with (PCI) Convenience Package or (ZLQ) Fleet Convenience Package.)

Windows, power rear, express down (Not available on Regular Cab models.)

Door locks, power (Standard on Crew Cab and Double Cab. On Regular Cab, included and only available with (PCI) Convenience Package or (ZLQ) Fleet Convenience Package.)

USB ports, 2 (first row) located on instrument panel

Power outlet, front auxiliary, 12-volt

Air conditioning, single-zone

Air vents, rear (Not available with Regular Cab model.)

Mirror, inside rearview, manual tilt

Assist handles front A-pillar mounted for driver and passenger, rear B-pillar mounted

## Safety-Mechanical

StabiliTrak, stability control system with Proactive Roll Avoidance and traction control, includes electronic trailer sway control and hill start assist

## Safety-Exterior

Daytime Running Lamps, LED signature lighting

## Safety-Interior

Airbags, Dual-stage frontal airbags for driver and front outboard passenger; Seat-mounted side-impact airbags for driver and front outboard passenger; Head-curtain airbags for front and rear outboard seating positions; Includes front outboard Passenger Sensing System for frontal outboard passenger airbag (Always use seat belts and child restraints. Children are safer when properly secured in a rear seat in the appropriate child restraint. See the Owner's Manual for more information.)

Rear Vision Camera (Deleted with (ZW9) pickup bed delete.)

Teen Driver a configurable feature that lets you activate customizable vehicle settings associated with a key fob, to help encourage safe driving behavior. It can limit certain available vehicle features, and it prevents certain safety systems from being turned off. An in-vehicle report card gives you information on driving habits and helps you to continue to coach your new driver

Tire Pressure Monitoring System with Tire Fill Alert (does not apply to spare tire)

Rear Seat Reminder (Requires Crew Cab or Double Cab model.)

This document contains information considered Confidential between GM and its Clients uniquely. The information provided is not intended for public disclosure. Prices, specifications, and availability are subject to change without notice, and do not include certain fees, taxes and charges that may be required by law or vary by manufacturer or region. Performance figures are guidelines only, and actual performance may vary. Photos may not represent actual vehicles or exact configurations. Content based on report preparer's input is subject to the accuracy of the input provided.

Data Version: 14078. Data Updated: Jun 23, 2021 12:49:00 AM PDT.





# ALAN JAY FLEET

SCOTT WILSON | 863-402-4234 | SCOTT.WILSON@ALANJAY.COM

Vehicle: [Fleet] 2021 GMC Sierra 1500 (TC10753) 2WD Double Cab 147" (✔ Complete)

## WARRANTY

Warranty Note: <<< Preliminary 2021 Warranty >>>

Basic Years: 3

Basic Miles/km: 36,000

Drivetrain Years: 5

Drivetrain Miles/km: 60,000

Drivetrain Note: HD Duramax Diesel: 5 Years/100,000 Miles; Qualified Fleet Purchases: 5 Years/100,000 Miles

Corrosion Years (Rust-Through): 6

Corrosion Years: 3

Corrosion Miles/km (Rust-Through): 100,000

Corrosion Miles/km: 36,000

Roadside Assistance Years: 5

Roadside Assistance Miles/km: 60,000

Roadside Assistance Note: HD Duramax Diesel: 5 Years/100,000 Miles; Qualified Fleet Purchases: 5 Years/100,000 Miles

Maintenance Note: 1 Year/1 Visit

This document contains information considered Confidential between GM and its Clients uniquely. The information provided is not intended for public disclosure. Prices, specifications, and availability are subject to change without notice, and do not include certain fees, taxes and charges that may be required by law or vary by manufacturer or region. Performance figures are guidelines only, and actual performance may vary. Photos may not represent actual vehicles or exact configurations. Content based on report preparer's input is subject to the accuracy of the input provided.

Data Version: 14078. Data Updated: Jun 23, 2021 12:49:00 AM PDT.