


	1995 Renovations	1999 Renovations
1.	Replace 6/8 existing windows w/	1. Existing 1"x10" rustic redwood siding
	dual glaze – windows will match all	2. New 1"x10" rustic to match existing
	other windows already installed.	3. Existing roof to be removed
2.	Replace one set of French doors	4. Class "A" Fire Rated – See Detail & Note
	with similar doors which are 6'-8"	5. 36" high redwood rail, posts & pickets
	high.	6. New redwood rail posts & pickets to match existing
3.	Add underpinning to foundation –	7. New 5'-6" x 6'-8" door & sidelight unit w/ 36" wide clear opening
	see structural engineer's drawings.	8. Approved zero-clearance fireplace w/ spark arrestor – built in cabinets
4.	Add retaining wall outside in yard –	9. New 16'-0" x 7'-0" steel roll-up garage door w/ garage door opener
	see structural engineer's drawings.	11. 6'-0" wide x 3'-1" tall 150° bay window w/ side casements (clad wood), (new)
5.	Replace old fireplace destroyed in	12. New wood-clad windows & doors to match existing
	earthquake w/ new.	13. Existing wood windows & doors
		14. New steel garage door.
		15. Existing galvanized gutters & downspouts
		16. New gable roof structure w/ 2x6" facia, siding, roof & gable vents
		17. Existing concrete block retaining walls
		18. Remove existing doors & windows
		19. Two 14½" x 12" combustion air openings. Locate one opening within the upper
		12 inches of the enclosure and one opening within the lower 12 inches of the
		enclosure












Existing Condition






Existing Condition



1995 Proposed Rear Elevation Drawing The propos



Existing Condition





This Page Intentionally Left Blank