General Construction Notes

ANY VARIATION FROM THE SPECIFIED DESIGN. FINISH PRODUCTS OR EXTERIOR ELEVATION STYLE IS TO BE BROUGHT TO THE ATTENTION OF THE DESIGNER PRIOR TO CONSTRUCTION,

BROUGHT TO THE ATTENTION OF DESIGNER PRIOR TO COMMENCEMENT OF THE WORK IN QUESTION, ALL WRITTEN DIMENSIONS SHALL TAKE PRECEDENCE OVER SCALED DIMENSIONS.

ANY DISCREPANCY DISCOVERED ON THESE PLANS SHALL BE

THE APPLICANT, DEVELOPER, AND CONTRACTORS ASSOCIATED WITH THE CONSTRUCTION OF THIS PROJECT SHALL BE RESPONSIBLE FOR IMPLEMENTING AND/OR COMPLYING WITH ALL ASPECTS OF THE CONDITION OF APPROVAL LISTED ON SHEET T2.

ALL WORK TO BE IN CONFORMANCE WITH 2022 CALIFORNIA BUILDING CODE

2022 CALIFORNIA RESIDENTIAL CODE 2022 CALIFORNIA MECHANICAL CODE

2022 CALIFORNIA PLUMBING CODE 2022 CALIFORNIA ENERGY CODI

2022 CALIFORNIA FIRE CODE 2022 CALIFORNIA EXISTING BUILDING CODE 2022 CALIFORNIA BUILDING STANDARDS CODE

2022 CALIFORNIA ELECTRICAL CODE 2022 CALIFORNIA CODE OF REGULATIONS TITLE-24, PARTS 1-12 2022 HEALTH AND SAFETY CODE

REACH CODES. AS WELL AS ANY STATE AND LOCAL CODES THAT MAY ALSO APPLY. CONTRACTOR ASSUMES FULL RESPONSIBILITY FOR METHOD AND MANNER OF CONSTRUCTION AND FOR ALL JOB SITE SAFETY DURING

AS ADOPTED BY THE TOWN OF LOS GATOS CODE, INCLUDING LOCALLY ADOPTED

VERIFY LOCATION OF UTILITIES AND EXISTING CONDITIONS AT SITE PRIOR TO CONSTRUCTION AND BIDDING.

SLOPE ALL FINISH GRADES A MIN. OF 5% FOR 10'-0" "AWAY" FROM STRUCTURE FOR POSITIVE DRAINAGE @ LANDSCAPED AREAS & SLOPE GRADE 2% MIN. @ PAVED AREAS.

THE BUILDER SHALL PROVIDE THE BUILDING OWNER, MANAGER, AND THE ORIGINAL OCCUPANTS A LIST OF THE ENERGY-SAVING CONSERVATION FEATURES DEVICES, MATERIALS, AND COMPONENTS INSTALLED IN THE BUILDING, AND INSTRUCTIONS ON HOW TO USE THEM EFFICIENTLY, SUCH FEATURES INCLUDE HEATING, COOLING WATER HEATING AND LIGHTING SYSTEMS. AS WELL AS INSULATION. WEATHERSTRIPPING WINDOW SHADES. AND THERMAL MASS MATERIALS, THE INSTRUCTIONS SHALL BE CONSISTANT WITH SPECIFICATIONS SET FORTH BY THE EXECUTIVE DIRECTOR

ALL WORK APPLIANCES AND EQUIPMENT SHALL COMPLY WITH C.E.C. TITLE 24 RESIDENTIAL ENERGY STANDARDS.

SEE SHEET T24 FOR ADDITIONAL ENERGY COMPLIANCE NOTES. DOCUMENTATION SHALL BE PROVIDED, PRIOR TO FIRST INSPECTION, CONFIRMING COMPLIANCE TO THE WASTE MANAGEMENT PLAN

PROVIDED TO THE TOWN OF LOS GATOS

ALL ADHESIVES, SEALANTS, CAULKS, PAINTS, COATINGS, AND AEROSOL PAINT CONTANERS MUST REMAIN ON SITE FOR FIELD VERIFICATION BY THE BUILDING INSPECTOR. PRIOR TO FINAL OWNER MUST BE PROVIDED TO THE TOWN OF LOS GATOS BUILDING OFFICAL CERTIFYING ALL ADHESIVES, SEALANTS, CAULKS, PAINTS, COATINGS, AEROSOL PAINTS, AEROSOL COATINGS, CARPET SYSTEMS RESILIENT FLOORING SYSTEMS. AND COMPOSITE WOOD PRODUCTS INSTALLED ON THIS PROJECT ARE WITHIN THE EMISSION LIMITS SPECIFIED IN CGBSC 4.504.

ALL ORNAMENTAL LANDSCAPING FOR THIS PROJECT SHALL BE DROUGHT TOLERANT AND NATIVE SPECIES

VEGETATION CLEARANCE SHALL BE IN COMPLIANCE WITH CBC SECTION 701A.3.2.4 PRIOR TO PROJECT FINAL APPROVAL PRIOR TO ISSUANCE OF A CERTIFICATE FOR OCCUPANCY

ALL FRONT YARD LANDSCAPING MUST BE INSTALLED.

A PAD CERTIFICATE PREPARED BY A LICENSED CIVIL ENGINEER OR LAND SURVEYOR SHALL BE SUBMITTED TO THE BUILDING INSPECTOR AT FOUNDATION INSPECTION, HORIZONTAL AND VERTICAL CONTROLS SHALL BE SET AND CERTIFIED BY A LICENSED CIVIL ENGINEER OR LAND SURVEYOR FOR THE FOLLOWING: a. BUILDING PAD ELEVATIONS

b. FINISH FLOOR ELEVATIONS c. FOUNDATION CORNER LOCATIONS

ALL PUBLIC IMPROVEMENTS SHALL BE MADE ACCORDING TO TOWN STANDARD PLANS, STANDARD SPECIFICATIONS, AND ENGINEERING DESIGN STANDARDS, ALL WORK SHALL CONFORM TO THE APPLICABLE VN ORDINANCES. THE ADJACENT PUBLIC RIGHT-OF-WAY SHALL BE KEPT CLEAR OF ALL JOB RELATED DIRT & DEBRIS AT THE END OF THE DAY, DIRT & DEBRIS SHALL NOT BE WASHED INTO STORM DRAINAGE FACILITIES, THE STORING OF GOODS & MATERIALS ON THE SIDEWALK AND/OR THE STREET WILL NOT BE ALLOWED UNLESS AN ENCROACHMENT PERMIT IS ISSUED. THE DEVELOPER'S REPRESENTATIVE IN CHARGE SHALL BE AT THE JOB SITE DURING ALL WORKING HOURS.

THE DEVELOPER OR HIS/HER REPRESENTATIVE SHALL NOTIFY THE ENGINEERING INSPECTOR AT LEAST TWENTY-FOUR (24) HOURS PRIOR TO STARTING ANY WORK PERTAINING TO ON-SITE DRAINAGE FACILITIES, GRADING OR PAVING, AND ALL WORK IN THE TOWN'S RIGHT=OF-WAY, FAILURE TO DO SO WILL RESULT IN REJECTION OF WORK THAT WENT WITHOUT INSPECTION.

NO VEHICLE HAVING A MANUFACTURE'S RATED GROSS VEHICLE WEIGHT EXCEEDING TEN THOUSAND (10,000) POUNDS SHALL BE ALLOWED TO PARK ON THE PORTION OF A STREET WHICH ABUTS PROPERTY IN A RESIDENTIAL ZONE WITHOUT PRIOR APPROVAL

> ASPHALTIC CONCRETE AIR CONDITIONING

CABINET
CEMENT
CERAMIC TILE
CAST IRON
CLOSET
CLEAR
CEILING
CONCRETE MASONRY UNIT

CONSTRUCTION CONTINUOUS CASEMENT COLD WATER

ELECTRICAL

FIBERGLASS

FACE OF STUD

APPROX**I**MATE

BOARD BUILDING

C.I.
CLO.
CLR
CLG
C.M.U.
C.O.
COL.
COMP.
CONC.
CONN.
CONST.
CONT.
CSMT.
C.W.

EXIST, or (E)

FROM THE TOWN ENGINEER. ALL PASSAGE DOORS SHALL BE AT LEAST 32" WIDE ON THE

THE PRIMARY ENTRANCE DOOR SHALL BE 36' WIDE DOOR INCLUDING A LEVEL 5' x 5' LANDING NOT LESS THAN 1" OUT OF PLANE WITH THE IMMEDIATE INTERIOR FLOOR LEVEL, AND WITH AN 18" CLEARANCE AT THE INTERIOR STRIKE EDGE.

HAULING OF SOIL ON-SITE OR OFF-SITE SHALL NOT OCCUR DURING THE MORNING OR EVENING PEAK PERIODS (BETWEEN 7:00 AM & 9:00 AM AND BETWEEN 4:00 PM & 6:00 PM), PRIOR TO THE ISSUANCE OF A BUILDING PERMIT. THE DEVELOPER SHALL WORK WITH THE TOWN BUILDING AND ENGINEERING DEPARTMENT ENGINEERING INSPECTORS TO DEVISE A TRAFFIC CONTROL PLAN TO ENSURE SAFE & EFFICIENT TRAFFIC FLOW UNDER PERIODS WHEN SOIL IS HAULED ON OR OFF THE PROJECT SITE. ALL TRUCKS TRANSPORTING MATERIALS SHALL BE COVERED TO AND FROM THE SITE.

BETWEEN THE HOURS OF 8:00 AM TO 8:00 PM WEEKDAYS AND 9:00 AM

TO 7,00 PM WEEKENDS AND HOLIDAYS, CONSTRUCTION, ALTERATION OR REPAIR ACTIVITIES SHALL BE ALLOWED. NO INDIVIDUAL PIECE OF EQUIPMENT SHALL PRODUCE A NOISE LEVEL EXCEEDING EIGHTY-FIVE (85) DBA AT TWENTY-FIVE (250 FEET FROM THE SOURCE. IF THE DEVISE IS LOCATED WITHIN A STRUCTURE ON THE PROPERTY, THE MEASUREMENT SHALL BE MADE AS CLOSE TO THE TWENTY-FIVE (25) FEET FROM THE DEVICE AS POSSIBLE, THE NOISE LEVEL AT ANY POINT OUTSIDE OF THE PROPERTY PLANE SAHLL NOT EXCEED EIGHTY-FIVE (85) DBA

SAN JOSE WATER COMPANY CONCURRENCE ON THE ADEQUACY OF WATER PRESSURE SHALL BE OBTAINED PRIOR ISSUANCE OF THE BUILDING PERMIT.

FIRE SPRINKLERS REQUIRED: AN AUTOMATIC RESIDENTIAL FIRE SPRINKLER SYSTEM SHALL BE INSTALLED IN ONE AND TWO FAMILY DWELLINGS AS FOLLOWS: IN ALL NEW ONE AND TWO FAMILY DWELLINGS. COVERED PORCHES, PATIOS, BALCONIES, AND ATTIC SPACES MAY REQUIRE FIRE SPRINKLER COVERAGE. FOR BUILDINGS IN EXCESS OF 6200 SQUARE FEET, THE (4) MOST HYDRAULICALLY

DEMANDING HEADS IN A ROOM OR COMPARTMENT SHALL BE CALCULATED FIRE DEPARTMENT CONNECTION. FOR BUILDINGS IN EXCESS OF 6200 SQUARE FEET, A FIRE DEPARTMENT (FDC) SHALL BE PROVIDED. THE FDC SHALL CONSIST OF AT LEAST ONE 2,5 INCH HOSE CONNECTION THAT IS CONNECTED TO THE SPRINKLER RISER WITH A PIPE NOT LESS THAN THE DIAMETER OF THE SPRINKLER RISE A STATE OF CALIFORNIA LICENSED (C-16) FIRE PROTECTION CONTRACTOR SHALL SUBMIT PLANS, CALCULATIONS, A COMPLETED PERMIT APPLICATION AND APPROPRIATE FEES TO SANTA CLARA COUNTY FIRE DEPARTMENT FOR REVIEW AND APPROVAL PRIOR TO BEGINNING THEIR WORK. THE OWNERS, OCCUPANTS, AND ANY CONTRACTORS OR SUB-CONTRATORS ARE RESPONSIBLE FOR CONSULTING WITH THE WATER PURVEYOR OF RECORD IN ORDER TO DETERMINE IF ANY MODIFICATION OR UPGRADE OF THE EXISTING WATER SERVICE IS REQUIRED.

WATER SUPPLY REQUIREMENTS: POTABLE WATER SUPPLIES SHALL BE PROTECTED FROM CONTAMINATION CAUSED BY FIRE PROTECTION WATER SUPPLIES. IT IS THE RESPONSIBILITY OF THE APPLICANT AND ANY CONTRACTORS AND SUBCONTRACTORS TO CONTACT THE WATER PURVEYOR SUPPLYING THE SITE OF SUCH PROJECT, AND TO COMPLY WITH THE REQUIREMENTS OF THAT PURVEYOR. SUCH REQUIREMENTS SHALL BE INCORPORATED INTO THE DESIGN OF ANY WATER-BASED FIRE PROTECTION SYSTEMS, AND / OR FIRE SUPPRESSION WATER SUPPLY SYSTEMS OR STORAGE CONTAINERS THAT MAY BE PHYSICALLY CONNECTED IN ANY MANNER TO AN APPLIANCE CAPABLE OF CAUSING CONTAMINATION OF THE POTABLE WATER SUPPLY OF THE PURVEYOR OF RECORD. FINAL APPROVAL OF THE SYSTEM(S) UNDER CONSIDERATION WILL NOT BE GRANTED BY THE FIRE DEPARTMENT UNTIL COMPLIANCE WITH THE REQUIREMENTS OF THE WATER PURVEYOR OF RECORD ARE DOCUMENTED BY THAT PURVEYOR AS HAVING BEEN MET BY THE APPLICANTS.

CONSTRUCTION FIRE SAFETY: ALL CONSTRUCTION SITES MUST COMPLY WITH APPLICABLE PROVISIONS OF THE CFC CHAPTER 33 AND STANDARD DETAIL AND SPECIFICATION SI-7

ADDRESS IDENTIFICATION: NEW AND EXISTING BUILDINGS SHALL HAVE APPROVED ADDRESS NUMBERS, BUILDING NUMBERS OR APPROVED BUILDING IDENTIFICATION PLACED IN A POSITION THAT IS PLAINLY LEGIBLE AND VISIBLE FROM THE STREET OR ROAD FRONTING THE PROPERTY. THESE NUMBERS SHALL CONTRAST WITH THEIR BACKGROUND, ADDRESS NUMBERS SHALL BE ARABIC NUMBERS OR ALPHABETICAL LETTERS. NUMBERS SHALL BE A MINIMUM OF 4 INCHES HIGH WITH A MINIMUM STROKE WIDTH OF 1/2 INCH WHERE ACCESS IS BY MEANS OF A PRIVATE ROAD AND THE BUILDING CANNOT BE VIEWED FROM THE PUBLIC WAY, A MONUMENTS, POLE, OR OTHER SIGN OF MEANS SHALL BE USED TO IDENTIFY THE STRUCTURE.

TOWN OF LOS GATOS CODE SECTION 6,40,020; PLUMBING CONTRACTOR SHALL PROVIDE AN APPROVED BACKWATER VALVE ON DRAINAGE PIPING SERVING FIXTURES THAT HAVE A FLOOD LEVEL RIMS LESS THAN 12 INCHES ABOVE THE ELEVATION OF THE NEXT UPSTREAM MANHOLE PER CPC SECTION 710.0

TOWN OF LOS GATOS CODE SECTION 6.40.020: VALVE ON DRAINAGE PIPING SERVING FIXTURES THAT HAVE A FLOOD LEVEL RIMS LESS THAN 12 INCHES ABOVE THE ELEVATION OF THE NEXT UPSTREAM MANHOLE PER CPC SECTION 710.0

A SEPARATE BUILDING PERMIT IS REQUIRED FOR THE PV SYSTEM THAT IS REQUIRED BY THE CALIFORNIA ENERGY CODE PERFORMANCE OR PRESCRIPTIVE STANDARDS. THE SEPARATE PV PERMIT MUST BE FINALED PRIOR TO THE ISSUANCE OF OF CERTIFICATE OF OCCUPANCY.

ELECTRIC APPLIANCE, ELECTRIC VEHICLE AND ENERGY STORAGE SYSTEM REQUIREMENTS IN ACCORDANCE WITH THE TOWN CODE. THE BUILDER SHALL PROVIDE THE HOMEOWNER WITH A LUMINAIRE SCHEDULE THAT INCLUDES A LIST OF LAMPS INSTALLED IN THE LUMINAIRES, AS REQUIRED BY TITLE-24 CALIFORNIA ENERGY CODE

THIS RESIDENCE SHALL COMPLY WITH THE TOWN OF LOS GATOS ALL

PRIOR TO FINAL INSPECTION, THE COMPLETED CF2R-LTG-01-E INSTALLATION CERTIFICATE MUST BE PROVIDED BY THE LIGHTING INSTALLATION CONTRACTOR TO THE TOWN BUILDING INSPECTOR.

RETURN AIR RADIUS ROUND RECESSED REFRIGERATOR REINFORCED/ING

RESILIENT ROOM ROUGH OPENING

SCHEDULE
SOLID CORE
SECTION
SQUARE FEET
SINGLE HUNG
SHEET
SHOWNER
SIMILAR
SLIDER
SLIDING GLASS DOOR
SPECIFICATIONS
SQUARE
SQUARE
SQUARE
SQUARE

SQUARE FEET

SYMMETRICAL 1

TOP OF SLAB TOP OF WALL TOILET PAPER

VERTICAL

WITH
WAINSCOT
WATER CLOSET
WOOD
WINDOW
WITH OUT
WATERPROOF

WELDED WIRE FABRIC

TELEPHONE
TEMPERED
THRESHOLD
TONGUE AND GROOVE
TOP OF FOOTING
TOP OF FOOTING

UNLESS NOTED OTHERWIS

SCHED S.C. SECT. S.F. SH

VERT.

Abreviations

GAUGE GALVANIZE(D) GALVANIZED IRON

GYPSUM BOARD

HOLD DOWN HEADER HARDWOOD

HORIZONTAL HOUR HOSE BIBB HEIGHT

AIR CONDITIONING

INSIDE DIAMETER

INTERIOR

KING STUD

MAXIMUM MACHINE BOL

NOT TO SCALE

PLATE
PROPERTY LINE
PLASTER
PLYWOOD
PANEL
POLE & SHELF

ON CENTER OUTSIDE FACE OF STUD

GROUND FAULT INTERRUPTER


Scope of Work

Architecture & Site: S-23-029

Approved Subdivision Application No. M-22-004 & Historic Review PHST-23-023 Deconstruct the existing residence, detached garage and shed on the property under a separate Demolition Permit. Provide a new two story single family residence with 2,800 sq. ft. living area with a 703 sq. ft. attached garage.

Deferred Submittals

THE ENTIRE STRUCTURE SHALL BE EQUIPPED WITH AN APPROVED, AUTOMATIC FIRE SPRINKLER SYSTEM. FIRE SPRINKLER PLANS SHALL BE SUBMITTED TO THE SANTA CLARA COUNTY FIRE DEPARTMENT BY A LICENSED C-16 FIRE SPRINKLER CONTRACTOR. LICENSED FIRE PROTECTION CONTRACTOR SHALL SUBMIT PLANS, CALCULATIONS, A COMPLETE PERMIT APPLICATION AND APPROPRIATE FEES TO THE SANTA CLARA COUNTY FIRE DEPARTMENT FOR REVIEW AND APPROVAL PRIOR TO ANY WORK RELATED TO THE FIRE SPRINKLER SYSTEM.



Title-24 Requirements

Consultants

CIVIL ENGINEER SF Civil Engineering 2532 Santa Clara Avenue Alameda, Calif. 94501 (510) 282-5281 sfcivil@yahoo.com

Vicinity Map RD. W. PARR AVE. KNOWLES DR WEDGEWOOD

DRAWING INDEX

Title Sheet T1 **Greenpoint Checklist**

Streetscape & Pictures

Tree Summary Report Tree Summary Report

Tree Summary Report

Civil Drawings

Topographic Survey

Tentative Map

Civil Cover Sheet

Erosion Control Plan & Demolition Plan

Pollution Prevention Plan

Grading & Drainage Plan and Utility Plan

Stormwater Plan

Design Drawings

OWNER:

LOT DATA:

Lot Size:

MGKG Properties LP

Saratoga, Calif. 95035

19341 Monte Vista Drive

409-14-026

R-1:8

14335 La Rinconada Dr. - Parcel 1

Maximum Allowable F.A.R.-House: 2,947 sq. ft.

Maximum Allowable F.A.R.-Garage: 810 sq. ft.

Proposed Floor Area: 2,805 sq. ft. 30%

Proposed Garage Area: 703 sq. ft.

Proposed Accessory: 0 sq. ft.

No attic area to be included in F.A.R.

744 sq. ft.

400 sq. ft.

93 sq. ft.

Gross Lot: 9,210 sq. ft.

Net Lot Size: 9,210 sq. ft.

Construction Type: VB

Number of Stories: 2

Occupancy Group: R3/U

Fire Sprinklers: Yes

Gross Lot Size: 9,210 sq. ft. Net Lot Size: 9,210 sq. ft.

Existing Floor Area:

Existing Accessory:

Existing Garage:

Parcel 1

Site plan

Main Level Floor Plan **Upper Level Floor PLan**

Exterior Elevations Exterior Elevations

Building Cross Sections

Roof Plan Floor Area Calculations

Shadow Drawings

Shadow Study - June 21st @ 9:00 am

Shadow Study - June 21st @ 12:00 pm Shadow Study - June 21st @ 3:00 pm

Shadow Study - Dec. 21st @ 9:00 am Shadow Study - Dec. 21st @ 12:00 pm

14335 La Rinconada Drive - Parcel

PROJECT DATA

Existing Lot Coverage:

Total Lot Coverage:

Proposed Lot Coverage:

Building Height:

Existing House: 14'-8"

Proposed House: 25'-6"

Existing Detached Garage: 400 sq. ft.

Existing Accessory Bldg.: 93 sq. ft.

1,237 sq. ft. / 9,210 sq. ft. = 13.4%

Proposed Residence: 1,614 sq. ft.

Proposed Garage: 703 sq. ft.

Proposed Front Porch: 212 sq. ft.

Proposed Rear Porch: 132 sq. ft.

Total Lot Coverage: 2,661 sq. ft.

2,661 sq. ft. / 9,210 sq. ft. = 28.9%

Existing Residence:

744 sq. ft.

1,237 sq. ft.

Shadow Study - Dec. 21st @ 3:00 pm

Home

0

0

THE THE DESI DESI USE CON ON T

NO./ DATE/ REVISIO

LOS GATOS ARCH. (SITE REVIEW 10-15-2

A LOS GATOS ARCH. 6 SITE REVIEW 1-16-25


LOS GATOS ARCH. (SITE REVIEW 9-6-24


Project Drive Rinconada La


SEPT. 1, 2024 PROJECT MANAGER GREG ZIERMAN 2023-MGKG L.G


EXHIBIT 14


GreenPoint Checklist 14335 La Rinconada Drive - Parcel 1











THESE PLANS ARE INTENDED ONLY FOR THE ORIGINAL SITE FOR WHICH THEY WERE DESIGNED AND ARE THE PROPERTY OF UNIQUE HOME ESIGNS. THESE PLANS ARE PROTECTED UNDER COPYRIGHT LAWS AND MAY NOT BE REVISED OR REPRODUCED IN WHOLE OR IN PART WITHOUT THE EXPRESSED WRITTEN CONSENT OF UNIQUE HOME DESIGNS. ANY USE OF THESE PLANS ON OTHER SITES IS PROHIBITED WITHOUT THE CONSENT OF UNIQUE HOME DESIGNS. ANY DISCREPANCY DISCOVERED ON THESE PLANS SHALL BE BROUGHT TO THE ATTENTION OF UNIQUE HOME DESIGNS PRIOR TO COMMENCEMENT OF THE WORK IN QUESTION. ALL WRITTEN DIMENSIONS SHALL TAKE PRECEDENCE OVER SCALED DIMENSIONS.

Planning and Residential

GreenPoint Checklist

The Rinconada Drive Project

Appress 14335 La Rinconada Drive - Parcel 1

DATE
SEPT. 1, 2024
SCALE
N/A
PROJECT MANAGER
GREG ZIERMAN
DRAWN
N/A
JOB NO.
2023-MGKG: L.G.

GP1

STREETSCAPE




14345 La Rinconada Drive

La Rinconada Drive

Parcel 2 View - West La Rinconada Drive


Parcel 1 View - West 14333 La Rinconada Drive



14355 La Rinconada Drive View - West



14345 La Rinconada Drive View - West



14335 La Rinconada Drive Existing Residence



14333 La Rinconada Drive View - West



14301 La Rinconada Drive View - Northwest



14294 La Rinconada Drive View - Northeast



14330 La Rinconada Drive View - East



14344 La Rinconada Drive View - East



14350 La Rinconada Drive View - East

LOS GATOS ARCH. & SITE REVIEW 7-1-24

IESE PLANS ARE INTENDED ONLY FOR THE ORIGINAL SITE FOR WHICH IEY WERE DESIGNED AND ARE THE PROPERTY OF UNIQUE HOME ISIGNS. THESE PLANS ARE PROTECTED UNDER COPYRIGHT LAWS AND IVY NOT BE REVISED OR REPRODUCED IN WHOLE OR IN PART WITHOUT IE EXPRESSED WRITTEN CONSENT OF UNIQUE HOME DESIGNS, ANY IE OF THESE PLANS ON OTHER SITES IS PROHIBITED WITHOUT THE NYSENT OF UNIQUE HOME DESIGNS. ANY DISCREPANCY DISCOVERED IN THESE PLANS SHALL BE BROUGHT TO THE ATTENTION OF UNIQUE OME DESIGNS ANY DISCREPANCY DISCOVERED IN THESE PLANS SHALL TAKE PRECEDENCE OVER SCALED WENSIONS.

Residential Designate, California 95123

nd Planning an Chinook Lane, San

ada Drive Project

La Rincor

Mes ADDRESS 14335 La Ri

DATE
SEPT. 1, 2024
SCALE
1/8" = 1'-0"
PROJECT MANAGER
GREG ZIERMAN
DRAWN

JOB NO. 2023-MGKG: L.G. SHEET

ST1

Tree Summary Report 14335 La Rinconada Drive

LOS GATOS ARCH. 4 SITE REVIEW 7-1-24

LOS GATOS ARCH. SITE REVIEW 10-1-2

106 GATOS ARCH. 4 SITE REVIEW 12-11-24

SE PLANS ARE INTENDED ONLY FOR THE ORIGINAL SITE FOR WHICH SY WERE DESIGNED AND ARE THE PROPERTY OF UNIQUE HOME SIGNS. THESE PLANS ARE PROTECTED UNDER COPYRIGHT LAWS AND Y NOT BE REVISED OR REPRODUCED IN WHOLE OR IN PART WITHOUT EXPRESSED WRITTEN CONSENT OF UNIQUE HOME DESIGNS. ANY E OF THESE PLANS ON OTHER SITES IS PROHIBITED WITHOUT THE USENT OF UNIQUE HOME DESIGNS. ANY DISCREPANCY DISCOVERED THESE PLANS SHALL BE BROUGHT TO THE ATTENTION OF UNIQUE ME DESIGNS PRIOR TO COMMENCEMENT OF THE WORK IN QUESTION. WRITTEN DIMENSIONS SHALL TAKE PRECEDENCE OVER SCALED ENSIONS.

ME DESIGNS

Id Residential Design

nmary Report

nada Drive Project
inconada Drive - Parcel 2

Tree Substitute La Rir

DATE
AUGUST 26, 2024
SCALE
N/A
PROJECT MANAGER
GREG ZIERMAN
DRAWN

DRAWN
N/A

JOB NO.
2023-MGKG: L.G.
SHEET

TS1

Tree Inventory, Assessment and Protection Report 14335 La Rinconada Drive, Los Gatos Tree inventory, Assessment and Protection Report Tree Inventory, Assessment and Protection Report 14335 La Rinconada Drive, Los Gatos 14335 La Pinconada Drive, Los Gatos November 6, 2020 Tree Inventory, Assessment, Appendix B: Tree Inventory and Assessment Tables17 Qualifications, Assumptions, and Limiting Conditions..... **Table of Content** Cartification of Parformance..... Protection Report B2: Parcel 2 14335 La Rinconada Drive C1:#731 through #736......21 Los Gatos, CA 95032 Asalgnment......1 C2: #737 through #747......22 Limits of the assignment Prepared for: C4: #751 through #755..... Town of Los Gatos Observations...... C5: Pepper #760 **November 6, 2023** Appendix D: Tree Protection Guidelines..... Revised December 5, 2024 D1: Plan Sheet Detail S-X (Type I) D2: Plan Sheet Detail S-Y (Type III) Prepared By: D3: Section 29.10.1005. - Protection of Trees During Construction Tree Protection Zones and Fence Specifications..... All persons, shall comply with the following precautions.......................29 Prohibited Activities..... Boring or Tunneling.......30 Monarch Consulting Arborists Tree Pruning and Removal Operations......30 Glossary of Terms......13 Appendix E: Tree Protection Signa.....31 Appendix A: Tree Inventory Map and Proposed Grading and Drainage Plan15 www.monarcharborists.com E1: English..... A1: Parcel 1 A2: Parcel 2 Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 Monarch Consulting Arborists LLC - P.O Box 1010, Falton, CA 95018 Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 831.331.8682 - rick@monarcharborist.com 831.331.8982 - rick@monarcharborist.com 831.331.8982 - rick@monarcharborist.com 14335 La Rinconada Drive, Los Gatos 14335 La Rinconada Drive, Los Gatos 14335 La Rinconada Drive, Loe Gatos 14335 La Rinconada Drive, Los Gatos The plans reviewed for this assignment were as follows The inventory contains thirty-three (33) trees comprised of eleven (11) different species.. One Peruvian pepper #760 is considered Purpose and use of the report Introduction Summary Large Protected1 ("Large Protected" by aggregate of stems) and five trees are Exempt2 with four being fruit trees #731, #733, #735, and #751, and one privet #763. There are seventeen trees on Parcel one and sixteen on Parcel 2 (Charts 1 and 2). The report is intended to identify all the trees within the plan fable 1: Plans Reviewed Checklist Tree appraisal was performed according to the Council of Tree & Landscape Appraisars Guide for Plant Appraisal 10th Edition, 2019 The applicant is requesting approval for demolition of an Background area that could be affected by a project. The report is to be used existing single-family residence and construction of a new (CLTA) along with Western Chapter International Society of Arboriculture Species Classification and Group Assignment, 2004. The Sheet Review Source by the Town of Los Gatos and the property owners as a trees were appraised using the "Cost Approach" and more specifically the "Trunk Formula Technique" (Appendix B). single-family residence for Parcel 1 and Parcel 2 site The Town of Los Gatos asked me to assess the site, trees, and reference for existing tree conditions to help satisfy planning Chart 2: Species improvements requiring a grading permit on property zoned proposed footprint plan, and to provide a report with my Chart 1: Species Distribution Parcel 2 Existing Site R-1:8. APN 409-14-026 and APN 409-14-026. Categorically "Trunk Formula Technique" is calculated as follows: Basic Tree Cost = (Unit tree cost x Appraised trunk area), Appraised Value = findings and recommendations to help satisfy planning Distribution Parcel 1 Topographic exempt pursuant to CEQA guidelines section 15303: new (Basic tree cost X functional Limitations (percentage) X Condition (percentage) X External Limitations (percentage)). Quantity Observations construction. 0 2 4 6 8 10 The trunk formula valuations are based on four tree factors; size (trunk cross sectional area), condition, functional limitations, and 01234567 Assignment The plans are to build two new residences on the subdivided external limitations. There are two steps to determine the overall value. The first step is to determine the "Basic Tree Cost" based on Tree Inventory ash (Fraxinus angustifolia 'Raywood') lots. The inventory contains thirty-three (33) trees comprised of size and unit tree cost. Unit tree cost is calculated by dividing the nursery wholesale cost of a 24 inch box specimen and its Provide an arborist's report including an assessment of the eleven (11) different species.. One Peruvian pepper #760 is replacement size (cost per square inch trunk caliper) which is determined by the Species Classification and Group Assignment, 2004 The inventory consists of trees protected by the Town of Los trees within the project area and on the adjacent sites. The coast live oak (Quercus agrifolia) considered Large Protected ("Large Protected" by aggregate of glossy privet (Ligustrum (ucidum) Western Chapter Regional Supplement, The cost of the 24 inch box wholesale specimen was determined through personal Gatos located on site and those in close preximity on assessment is to include the species, size (trunk diameter), parcela communications with BrightView and Normans nurseries in Farmington and Central Wholesale in San Jose for an average of \$214.00. stems) and five trees are Exempt with four being fruit trees neighboring properties. Sec. 29.10.0960. - Scope of protected incense cedar (Calocedrus decurrens) condition (health, structure, and form), and suitability for ocast redwood (Sequois sempervirens) #731, #733, #735, and #751, and one privet #763. There are Utility Plan trees. All trees which have a four-inch or greater diameter preservation ratings. Affix number tags on the trees for and Hock-up The second part is to depreciate the tree's Basic Cost through an assessment of condition, functional limitations, and external seventeen trees on Parcel one and sixteen on Parcel 2. lemon (Citrus (imon) (twelve and one half-inch circumference) of any trunk, when reference on site and on plans. crape myrtle (Lagerstoemia indica) locations limitations. The condition assessment guidelines and percentages are defined in the "Condition Rating" section of this report. removal relates to any review for which zoning approval or Provide tree protection specifications, guidelines, and impact mulberry (Morus alba) Exterior Elevations Parcel 1: Six tree will be highly impacted on parcel one and the Functional limitations are based on factors associated with the tree's interaction to its planting site that would affect condition, limit deodar cedar (Cedrus deodara) subdivision approval is required. (Appendix A and B). Los ratings for those affected by the project. Peruvian pepper (Schinus molis) remaining eleven moderately affected. The plum "moderatedevelopment, or reduce the utility in the future and include genetics, placement, and site conditions for the individual tree. External Gatos Town Ordinance 29.10.0970 Exceptions (1) states the Provide appraised values using the Trunk Formula Technique. plum (Prunus domestica) plum (Prunus domestica) highly" impacted should be removed and is not protected Landecape Plan limitations are outside the property, out of control of the owner and also affect condition, limit development, or reduce the utility in the following: "A fruit or nut tree that is less than eighteen (18) (exempt). The trees retained are primarily along the driveway to future (i.e power lines, municipal restrictions, drought adaptations, or species susceptibility to pests). inches in diameter (fifty-seven-inch circumference). Limits of the assignment Parcel two and one large pepper tree. The applicant will be irrigation Plan required to replace three protected trees on Parcel 1. There were thirty-three trees appraised for a rounded depreciated value of \$81,210.00. Plans • The information in this report is limited to the condition of T-1 Tree the trees during my inspection on June 27, 2022. No tree risk Protection Parcel 2: Two trees will be highly impacted and removed. The Parcel 1 = seventeen trees \$53,470.00 The plans are to build two new residences on the subdivided assessments were performed. trees to be retained will require protection at their calculated Parcel 2 = sixteen trees \$27,740.00 · Troo heights and canopy diameters are estimates. radii and no grading within the TPZ. 1 Large protected tree means any oak (Querous app.), California buokeys (Aesculus osiffornios), or Psolific madrone (Arbuitus menziesif) which has a 24-inch or Appraisal worksheets are available upon request greater diameter (75-inch circumference); or any other epocles of tree with a 48-inch or greater diameter (150-inch circumference). ² A fruit or nut tree that is less than eightsen (18) inches in diameter (fifty-seven-inch piroumference). Monarch Consulting Arborists LLC - P.O Box 1010, Falton, CA 95018 Monarch Consulting Arborista LLC - P.O Box 1010, Felton, CA 95018 Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 Page 1 of 34 Page 3 of 34 Page 2 of 34 Page 4 of 34 831.331.8982 - rick@monarcharborist.com 831.331.8982 - rick@monercharborist.com 831.331.8982 - rick@monarcharborist.com November 6, 2023 Revised December 5, 2024 November 6, 2023 Revised December 5, 2024 14335 La Rinconada Drive, Los Gatos 14335 La Rinconada Drive, Los Gatos 14336 La Rinconada Drive, Los Gatos 14335 La Rinconada Drive, Los Gatos November 8, 2023 Revised December 5, 2024 Tree Inventory, Assessment Chart 4: Expected Impact Parcel 1 Tree Protection **Expected Impact Level** Mitigation for Removals To measure an asymmetrical canopy of a tree, the widest Discussion measurement shall be used to determine canopy size. Twelve trees are in good condition, ten fair, nine poor, one very Typically there are three different tree protection schemes which are called Type I (Appendix D1), Type II and Type III (Appendix D2) Impact level defines how a tree may be affected by construction The table below indicates the recommended replacement values Condition Rating 0 2 4 6 8 10 poor, and one is dead (Chart 3). Trees in poor shape include the trunk protection only. The tree protection zone (TPZ) is the defined area in which certain activities are prohibited to minimize activity and proximity to the tree, and is described as low, (Table 2). The applicant will be required to replace three ²Often, it is not possible to replace a single large, older tree neighbor's incense cedar #732 and the two on the site #734 and protected trees on Parcel 1 and two on Parcel 2 according to the moderate, or high. The following scale defines the impact potential injury to the tree and should encompass the critical root zone. There are two tree protection zones determined which include with an equivalent tree(s). In this case, the tree may be replaced A tree's condition is a determination of its overall health, #736. Pepper #743 has a large internal cavity that encompasses the "calculated" and "specified" tree protection zones. The "calculated" tree protection zone is determined by a multiplication factor ordinance. Alternatively it may be possible to create an with a combination of both the Tree Canopy Replacement structure, and form. The assessment considered all three criteria the entire lower trunk. based on species tolerance, tree age/vigor/health, and trunk diameter (Table 3). The "specified" tree protection zone is adjusted in size approved landscape plan or provide an in-lieu payment. Standard and in-lieu payment in an amount set forth by Town for a combined condition rating. Low = The construction activity will have little influence on and shape to accommodate the existing infrastructure, planned construction, and specific site constraints. This "specified" zone Council resolution paid to the Town Tree Replacement Fund. Table 2: Town of Los Gatos Tree Canopy - Replacement Chart 3: Condition Ratings includes tree canopy conformation, visible root orientation, size, condition, maturity, and species tolerances (Gilpin, R, Hauer, R, - 100% - Exceptional - Good health and structure with Standard Quantity - Moderate = The construction may cause future health or Matheny, N, and Smiley, E.T. 2023). ³Single Family Residential Replacement Option is available for significant size, location or quality. structural problems, and steps must be taken to protect the Replacement Single Family Requirement (2)(4) Residential Canopy Size of developed single family residential lots under 10,000 square 61-80% - Good = Normal vigor, well-developed structure, Removed Tree (1) Parcel 1: Parcel 1 has one Large Protected Peruvian pepper #760 which would require a tree protection radius of 23 feet. The other tree to reduce future problems. feet that are not subject to the Town's Hillside Development function and aesthetics not compromised with good longevity . High = Tree structure and health will be compromised and trees on this parcel requiring protection will be the row along the south driveway flag to Parcel 2 #737 to #744 and require a radius of Standards and Guidelines. All 15-gallon trees must be planted removal is recommended, or other actions must be taken seven feet. There will be some driveway excavation adjacent to these trees and monitoring construction will be required. The last tree on-site. Any in-lieu fees for single family residential shall be • 41-60 % - Fair = Reduced vigor, damage, dieback, or pest Two 24 Inch box Two 15 gallon regarding this parcel is #732 which is located on the adjacent property to the north and calculated tree protection is 19 feet due to the for the tree to remain. The tree is located in the building based on 24" box tree rates as adopted by Town Council. problems, at least one significant structural problem or Chart 5: Expected Impact Parcel 2 trunk size of this tree. The tree is in poor condition but not under the control of the applicant/owners. multiple moderate defects requiring treatment. Major More than 10 feet to 25 Three 24 Inch box Three 15 gallon Replacement Trees shall be approved by the Town Arborist asymmetry or deviation from the species normal habit, Parcel 1: Six tree will be highly impacted on parcel one Parcel 2: Parcel 2 has several trees around the perimeter and only one (#759) has protection fence around it indicated on the plans. and shall be of a species suited to the available planting function and aesthetics compromised. and the remaining eleven moderately affected. The plum More than 25 feet to 40 | Four 24 inch box The remaining trees to be retained will also require fence and no grading within their calculated TPZs. Four 15 gallon location, proximity to structures, overhead clearances, soil type, 21-40% - Poor = Unhealthy and declining appearance with "moderate-highly" impacted should be removed and is not trees or two 36 Inch | trees compatibility with surrounding canopy and other relevant poor vigor, abnormal foliar color, size or density with protected (exempt). The trees retained are primarily along factors. Replacement with native species shall be strongly potential irreversible decline. One serious structural defect or the driveway to Parcel two and one large papper tree. More than 40 feet to 55 Six 24 inch box encouraged. Replacement requirements in the Hillsides shall multiple significant defects that cannot be corrected and traes; or three 36 comply with the Hillside Development Standards and failure may occur at any time. Significant asymmetry and Parcel 2: Two trees will be highly impacted and removed. Guidelines Appendix A and Section 29.10.0987 Special compromised acethetics and intended use. The remaining trees could be impacted primarily due to the Greater than 55 feet Ten 24 Inch box Not available Provisions—Hillsides. 6-20% - Very Poor = Poor vigor and dying with little foliage trees; or five 36 inch drainage around the site. There appears to be activity in irreversible decline. Severe defects with the likelihood of box trees around the trees based on the grading plan and more tree failure being probable or imminent. Aesthetically poor with protection will need to be added. little or no function in the landscape. 0-5% - Dead/Unstable = Dead or imminently ready to fail. Monarch Consulting Arborists LLC - P.O Box 1010, Feiton, CA 95018 Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 Monarch Conculting Arborists LLC - P.O Box 1010, Felton, CA 95018 Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 Page 6 of 34 31.331.8982 - rick@monarcharborist.com Page 6 of 34 Page 7 of 34 31.331.8982 - rick@monarcharborist.com Page 8 of 34 31,331,8982 - rick@monarcharborist.com 31.331.8982 - rick@monarcharborist.com

Tree Summary Report 14335 La Rinconada Drive

14335 La Rinconada Drive, Los Gatos

14335 La Rinconada Drive, Los Gatos

LOS GATOS ARCH. SITE REVIEW 1-1-24 LOS GATOS ARCH. 4 SITE REVIEW 10-1-2 A LOS GATOS ARCH. 4 SITE REVIEW 12-11-2

NO./ DATE/ REVISION

GNS g 2 α

g

roject - Parcel Report rive

November 6, 2023 Revised December 5, 2024

Depreciated TPZ (8X DBH Value ft.)

Page 20 of 34

AUGUST 26, 2024 SCALE GREG ZIERMAN

PROJECT MANAGER JOB NO. 2*0*23-MGKG L.G.

Tree inventory, Assessment and Protection Report Tree Inventory, Assessment and Protection Report November 6, 2023 Revised December 5, 2024 Tree Invantory, Assessment and Protection Report November 6, 2023 Ravised December 5, 2024 Tree inventory, Assessment and Protection Report November 6, 2023 Revised December 5, 2024 Conclusion Recommendations Bibliography 3. All tree maintenance and care shall be performed by a qualified arborist with a C-61/D-49 California Contractors License. Tree maintenance and care shall be specified in writing according to American National Standard for Tree Care Operations: Tree, Shrub American National Standard for Tree Care Operations: Tree, Shrub and Other Woody Plant Management : Standard Practices The plans are to build two new residences on the subdivided lots. The inventory coxtains thirty-three (33) trees comprised of eleven and Other Woody Plant Management: Standard Practices parts 1 through 10 and adhere to ANSI Z133.1 safety standards and (11) different species.. One Peruvian pepper #760 is considered Large Protected ("Large Protected" by aggregate of stems) and five (Management of Trees and Shrubs During Site Planning, Site Development, and Construction)(Part 5). Londonderry, NH: local regulations. All maintenance is to be performed according to ISA Best Management Practices. trees are Exempt with four being fruit trees #731, #733, #735, and #751, and one privet #763. There are seventeen trees on Parcel one Large Protected Peruvian pepper #760 which would require a tree protection radius of 23 feet which would extend into Parcel 2. Secretariat, Tree Care Industry Association, 2019. Print. and sixteen on Parcel 2. . The south driveway flag to Parcel 2 trees #737 to #744 require a radius of seven feet, which may not be feasible. There will be some 4. Refer to Appendix D for general tree protection guidelines including recommendations for arborist assistance while working under driveway excavation adjacent to these trees and monitoring construction will be required. Fite, Kelby, and Edgar Thomas. Smiley. Managing trees during construction, second edition. Champaign, IL: International Society of trees, trenching, or excavation within a trees drip line or designated TPZ. Twelve trees are in good condition, ten fair, nine poor, one very poor, and one is dead. Trees in poor shape include the neighbor's Tree #732 which is located on the adjacent property to the north and calculated tree protection is 19 feet due to the trunk size of this incense cedar #732 and the two on the site #734 and #736. Pepper #743 has a large internal cavity that encompasses the entire lower tree. The tree is in poor condition but not under the control of the applicant/owners. 5. Place all the tree protection fence locations and guidelines on the plans including the grading, drainage, and utility plans. ISA. Guide For Plant Appraisal 9th Edition. Sevoy, IL: International Society of Arboriculture, 2000. Print. Alternatively create a separate plan sheet that includes all three protection measures labeled "T-1 Tree Protection Plan." Parcel 2: ISA. Guide For Plant Appraisal 10th Edition. Savoy, IL: International Society of Arboriculture, 2018. Print. Parcel 1: Six tree will be highly impacted on parcel one and the remaining eleven moderately affected. The plum "moderate-highly" 6. Provide a copy of this report to all contractors and project managers, including the architect, civil engineer, and landscape designer impacted should be removed and is not protected (exempt). The trees retained are primarily along the driveway to Parcel two and one • Crape myrtle #758 tree protection fence should be placed at least five feet and more if possible. or architect. It is the responsibility of the owner to ensure all parties are familiar with this document. . It may be possible to save some other trees but the way the C1 sheet is drawn at this time it appears there is drainage and grading ISA. Species Classification and Group Assignment, 2004 Western Chapter Regional Supplement. Western Chapter ISA large pepper tree. The applicant will be required to replace three protected trees on Parcel 1. requirements around the exterior which would compromise most of the trees. Altering this plan if possible could save some trees. 7. Arrange a pre-construction meeting with the project arborist or landscape architect to verify tree protection is in place, with the Parcel 1: Parcel 1 has one Large Protected Peruvian pepper #760 which would require a tree protection radius of 23 feet. The other Matheny, Nelda P., Clark, James R. Trees and development: A technical guide to preservation of trees during land development. correct materials, and at the proper distances. trees on this parcel requiring protection will be the row along the south driveway flag to Parcel 2 #737 to #744 and require a radius of **Both Parcels** Bedminster, PA: International Society of Arboriculture 1998. seven feet. There will be some driveway excavation adjacent to these trees and monitoring construction will be required. The last tree regarding this parcel is #732 which is located on the adjacent property to the north and calculated tree protection is 19 feet due to the 1. Place tree numbers on all the plans. Make sure the trees are clearly indicated for removal on all the plans. The trees should also be Smiley, E, Matheny, N, Lilly, S, ISA. Best Management Practices: Tree Risk Assessment: International Society of Arboriculture, 2017. trunk size of this tree. The tree is in poor condition but not under the control of the applicant/owners. very clearly marked on site prior to removal. Parcel 2: Two trees will be highly impacted and removed and fourteen retained. 2. Install temporary irrigation or sosker hoses in all tree protection zones and provide supplemental watering during construction within all TPZ areas. Monitor watering times or amounts to ensure adequate soil saturation. (A 5/8" scaker hose requires about Parcel 2: Parcel 2 will require tree protection fence at the calculated radii and no grading within those zones 200 minutes to deliver one inch of water to a garden. This number is affected by the length of the hose and the overall rate of flow from the faucet. A good rule of thumb is to expect about 1/2 GPM as a standard faucet flow rate.). Infrequent deeper watering is There were thirty-three trees appraised for a rounded depreciated value of \$81,210.00. Parcel 1 = seventeen trees \$53,470.00; Parcel preferred. 2 =sixteen trees \$27,740.00. The applicant will be required to replace three protected trees on Parcel 1 and two on Parcel 2 according to the ordinance. Monarch Consulting Arborista LLC - P.O Box 1010, Felton, CA 95018 Monarch Consulting Arborists LLC - P.O Box 1010, Falton, CA 95018 Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 Page 9 of 34 Page 10 of 34 Page 11 of 34 Page 12 of 34 831.331.8982 - rick@monarcharborist.com 831.331.8982 - rick@monarcharborist.com 831.831.8982 - rick@monarcharborist.com 831.331.8982 - rick@monarcharborist.com 14335 La Rinconada Drive, Los Gatos November 6, 2023 14335 La Rinconada Drive, Los Gatos November 6, 2023 Revised December 6, 2024 14335 La Rinconada Drive, Los Gatos November 6, 2023 Revised December 5, 2024 14335 La Rinconada Drive, Los Gatos November 6, 2023 Revised December 5, 2024 A2: Parcel 2 Glossary of Terms Appendix A: Tree Inventory Map and Proposed Grading and Drainage Plan scaffold branches: Permanent or structural branches that for the scaffold architecture or structure of a tree. A1: Parcel 1 calculated tree protection zone: A TPZ calculated using the trunk diameter and a multiplication factor based on species tolerance to specified tree protection zone (specified TPZ): a TPZ that is adjusted in size or shape to accommodate the existing infrastructure, construction and tree age. It is often plotted on a plan as a circle or other arbitrary shape and can be used as a guide for establishing the planned construction, and aspects of the site, as well as the tree canopy conformation, visible root orientation, size, condition, specified TPZ. maturity, and species response to construction. critical root zone: a conceptual soil area containing the minimal amount of all the essential parts of the root zone needed to sustain straw wattle: also known as straw worms, bio-logs, straw noodles, or straw tubes are man made cylinders of compressed, weed free tree health and structural integrity. There are no universally accepted methods to calculate the CRZ. straw (wheat or rice), 8 to 12 inches in diameter and 20 to 25 feet long. They are encased in jute, nylon, or other photo degradable materials, and have an average weight of 35 pounds. basic Tree Cost: The cost of replacement for a perfect specimen of a particular species and cross sectional area prior to location and condition depreciation. structure: Evaluation focused on the crown, trunk, trunk flare, above ground roots and the site conditions contributing to conditions cost Approach: An indication of value by adding the land value to the depreciated value of improvements. Tree Protection Zone (TPZ): Defined area within which certain activities are prohibited or restricted to prevent or minimize potential defect: An imperfection, weakness, or lack of something necessary. In trees defects are injuries, growth patterns, decay, or other injury to designated trees, especially during construction or development. conditions that reduce the tree's structural strength. Tree Risk Assessment: Process of evaluating what unexpected things could happen, how likely it is, and what the likely outcomes diameter at breast height (DBH): Measures at 1.4 meters (4.5 feet) above ground in the United States, Australia (arboriculture), New are. In tree management, the systematic process to determine the level of risk posed by a tree, tree part, or group of trees. Zealand, and when using the Guide for Plant Appraisal, 9th edition; at 1.3 meters (4.3 feet) above ground in Australia (forestry), Canada, the European Union, and in UK forestry; and at 1.5 meters (5 feet) above ground in UK arboriculture. trunk: Stem of a tree. drip Line: Imaginary line defined by the branch spread or a single plant or group of plants. The outer extent of the tree crown. Trunk Formula Technique: Method to appraise the monetary value of frees considered too large to be replaced with nursery or field grown stock. Based on developing a representative unit cost for replacement with the same or comparable species of the same size and form: Describes a plant's habit, shape or silhouette defined by its genetics, environment, or management. in the same place, subject to depreciation for various factors. Contrast with replacement cost method. health: Assessment is based on the overall appearance of the tree, its leaf and twig growth, and the presence and severity of insects or volunteer; A tree, not planted by human hands, that begins to grow on residential or commercial property. Unlike trees that are b drought in and installed on property, volunteer trees usually spring up on their own from seeds placed onto the ground by natural causes or accidental transport by people. Normally, volunteer trees are considered weeds and removed, but many desirable and mechanical damage: Physical damage caused by outside forces such as cutting, chopping or any mechanized device that may strike attractive specimens have gone on to become permanent residents on many public and private ground. the tree trunk, roots or branches. Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 831.331.8982 - rick@monarcharborist.com Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 Monarch Consulting Arborists LLC - P.O Box 1010, Feiton, CA 95018 Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 Page 13 of 34 831.331.8982 - rick@monercharborist.com Page 14 of 34 Page 15 of 34 831.331.8982 - rick@monarcharborist.com Page 16 of 34 831.331.8982 - rick@monarcharborist.com

Appendix B: Tree Inventory and Assessment Tables

14335 La Rinconada Drive, Los Gatos

14335 La Rinconada Drive, Los Gatos

Tree Species	I.D. #	Trunk Diameter (in.)	~ Canopy Diameter (ft.)	Condition	Expected Impact	Protection Status	Rounded Depreciated Value	Calculated TPZ (8X DBH ft.)
plum (<i>Prunus domestica</i>)	731	Multi 4	15	Very poor	Moderate- High	Exempt	\$360.00	6
Incense cedar (Calocedrus decurrens)	732	28	25	Poor	Moderate	Protected	\$7,300.00	19
plum (<i>Prunus domastica</i>)	733	Multi 4	10	Dead/ Unstable	High	Exempt	80.00	6
incense cedar (<i>Calocedrus</i> decurrens)	734	28	25	Poor	High	Protected	\$7,300.00	19
lemon (<i>Citrus limon</i>)	735	8	10	Poor	High	Exempt	\$870.00	4
incense cedar (Calocedrus decurrens)	738	11	20	Poor	High	Protected	\$1,120.00	7
ocast redwood (<i>Sequola</i> sempervirens)	737	18	15	Good	Moderate	Protected	\$3,800.00	10
ocast redwood (Sequola samparvirana)	738	10	15	Good	Moderate	Proteoted	\$1,730.00	7
opast redwood (Sequois sampervirens)	739	11	15	Good	Moderate	Protected	\$2,100.00	7
coast redwood (Sequola sempervirens)	740	10	15	Good	Moderate	Protested	\$1,730.00	7
coast redwood (Sequola sempervirens)	741	11	15	Good	Moderate	Protected	\$2,100.00	7

Tree inventory, Assessment and Proteotion Report

4335 La Rinconada Drive, Los Gatos		Tree Inventory, Assessment and Protection Report				November 6, 2023 Revised December 6, 2024		
Tree Species	I.D. #	Trunk Diameter (in.)	~ Canopy Diameter (ft.)	Condition	Expected Impact	Protection Status	Rounded Depreciated Value	Calculated TPZ (8X DBH ft.)
coast redwood (Sequois sempervirens)	742	8	15	Good	Moderate	Protected	\$1,400.00	8
Peruvian pepper (Schinus molis)	743	38	25	Poor	Moderate	Protected	88,600.00	24
coast redwood (Sequola sempervirans)	744	9	15	Fair	Moderate	Protected	\$1,000.00	8
Paruvian pepper (Schinus molis)	780	29, 20	25	Fair	Moderate	Large Protected	\$13,500.00	23
mulberry (<i>Morus albą</i>)	762	8	40	Good	High	Protected	\$580.00	4
glossy privet (<i>Ligustrum</i>	783	Multi 4	10	Good	High	Exempt	\$200.00	5

14935 La Rinconeda Drive, Los Gatos

November 8, 2023

November 8, 2023

		(m.)	(π.)				value	π.,
coast redwood (Sequola sempervirans)	742	9	15	Good	Moderate	Protected	\$1,400.00	8
Peruvian pepper (Schinus molis)	743	38	25	Poor	Moderate	Protected	88,600.00	24
coast redwood (Sequola sempervirans)	744	9	15	Fair	Moderate	Protected	\$1,000.00	8
Peruvian pepper (Schinus molia)	760	29, 20	25	Fair	Moderate	Large Protected	\$13,500.00	23
mulberry (<i>Morus albą</i>)	782	6	40	Good	High	Protected	\$580.00	4
glossy privet (<i>Ligustrum</i> iuoldum)	783	Multi 4	10	Good	High	Exempt	\$200.00	5
		-						
	Maria				1010, Felton, C			

Tree Species	I.D. #	Trunk Diameter	~ Canopy Diameter	Condition	Expected Impact	Protection Status	Rounded Depreciated	Calculated TPZ (8X DBH
		(in.)	(ft.)		Impact	Status	Value	ft.)
coast redwood (Sequola sempervirens)	745	11	15	Fair	Low- moderate	Protected	\$1,500.00	7
coast redwood (<i>Sequola</i> sempervirans)	748	13	15	Fair	Low- moderate	Protected	\$2,090.00	9
coast redwood (<i>Sequola</i> sempervirens)	747	12	15	Fair	Low- moderate	Protected	\$1,780.00	8
ocast redwood (Sequols sempervirens)	748	11	15	Fair	Low- moderate	Protected	\$1,500.00	7
coast redwood (<i>Sequola</i> sempervirens)	749	9, 13	15	Fair	High	Proteoted	\$3,170.00	11
deoder cedar (<i>Cedrus deodare</i>)	750	13	15	Good	High	Proteoted	\$3,880.00	9
plum (<i>Prunus domestics</i>)	751	4	10	Good	Low- moderate	Exampt	\$420.00	3
ocast radwood (Saquola samparvirans)	752	9	15	Poor	Low- moderate	Protected	\$800.00	8
coast redwood (<i>Sequole</i> sem <i>pervirens</i>)	753	11	15	Poor	Low- moderate	Protected	\$900.00	7
coast redwood (Sequola sempervirens)	754	8	15	Poor	Low- moderate	Protected	8480.00	5
coast live oak (<i>Quercue</i>	755	13	25	Fair	Low-	Protected	\$3,360.00	9

Tree Species	I.D. #	Trunk Diameter (in.)	~ Canopy Diameter (ft.)	Condition	Impact	Protection Status	Rounded Depreciated Value	TPZ (8X DBH ft.)
coast redwood (Sequola sempervirens)	745	11	15	Fair	Low- moderate	Protected	\$1,500.00	7
coast redwood (<i>Sequola</i> sempervirens)	748	13	15	Fair	Low- moderate	Protected	\$2,090.00	9
coast redwood (<i>Sequola</i> sempervirens)	747	12	15	Fair	Low- moderate	Protected	\$1,780.00	8
ocast redwood (<i>Sequol</i> s sempervirens)	748	11	15	Fair	Low- moderate	Protected	\$1,800.00	7
ocast redwood (<i>Sequola</i> sempervirens)	749	9, 13	15	Fair	High	Proteoted	\$3,170.00	11
deoder cedar (<i>Cedrus deodare</i>)	750	13	15	Good	High	Protected	\$3,880.00	9
plum (<i>Prunus domestics</i>)	751	4	10	Good	Low- moderate	Exampt	\$420.00	3
ocast redwood (<i>Sequole</i> sem <i>pervirens</i>)	752	9	15	Poor	Low- moderate	Protected	\$800.00	8
coast redwood (<i>Sequole</i> sem <i>pervirens</i>)	753	11	15	Poor	Low- moderate	Protected	\$900.00	7
coast redwood (Sequola sempervirens)	754	8	15	Poor	Low- moderate	Protected	8480.00	5
coast live oak (Quercus agrifolia)	755	13	25	Fair	Low- moderate	Protected	\$3,380.00	9

		Ula de Lace de				I -		
	T,D. #	ble 4: Invent Trunk	~ Canopy		-	The same of the sa	Rounded	Calculated
		Diameter (in.)	Diameter (ft.)		Impact	Status	Depreciated Value	TPZ (8X DBH ft.)
luota	745	11	15	Fair	Low- moderate	Protected	\$1,500.00	7
lnoja	748	13	15	Fair	Low- moderate	Protected	\$2,090.00	9
tuola	747	12	15	Fair	Low- moderate	Protected	\$1,780.00	8
iuola	748	11	15	Fair	Low- moderate	Protected	\$1,500.00	7
lnote	749	9, 13	15	Fair	High	Proteoted	\$3,170.00	וד
us deodare)	750	13	15	Good	High	Protected	\$3,880.00	9
stica)	751	4	10	Good	Low- moderate	Exempt	\$420.00	3
				B	1	Tour to a tour	****	_

14335 La Rinconada Drive, Los Gatos

Tree inventory, Assessment

Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 931.391.8982 - rick®monarcharborist.com

14335 La Rinconada Drive, Los Gatos

Tree Inventory Report 14335 La Rinconada Drive

LOS GATOS ARCH. SITE REVIEW 1-1-2-LOS GATOS ARCH.

SITE REVIEW 10-1-2

A LOS GATOS ARCH.

SITE REVIEW 12-11-2

November 6, 2028 Revised December 5, 2024

Page 25 of 34

roject - Parcel Report rive Summary

ISA Board Certified Master Arborist® WE-4341B

November 6, 2023

Revised December 5, 2024

asaa

© Copyright 2023, Monarch Consulting Arborists LLC. Other than specific exception granted for copies made by the client for the express uses stated in this report, no parts of this publication may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, recording, or otherwise without the express, written permission

I further certify that I am a Registered Consulting Arberist®

with the American Society of Consulting Arborists, and that I

acknowledge, accept and adhere to the ASCA Standards of

Arborioulture Board Certified Master Arborist®. I have been

involved with the practice of Arboriculture and the care and

Professional Practice. I am an International Society of

ASCA Registered Consulting Arborist® #496

study of trees since 1998.

Certification of Performance

That I have personally inspected the tree(s) and/or the property

That I have no current or prospective interest in the vegetation

or the property that is the subject of this report, and I have no

personal interest or bias with respect to the parties involved;

That the analysis, opinions and conclusions stated herein are

accurately. The extent of the evaluation and/or appraisal is

stated in the attached report and Terms of Assignment;

referred to in this report, and have stated my findings

That my analysis, opinions, and conclusions were developed

and this report has been prepared according to commonly accepted Arboricultural practices;

That no one provided significant professional assistance to the consultant, except as indicated within the report.

That my compensation is not contingent upon the reporting of a predetermined conclusion that favors the cause of the client or any other party, nor upon the results of the assessment, the attainment of stipulated results, or the occurrence of any other subsequent events;


Page 33 of 34

Monarch Consulting Arborists LLC - P.O Box 1010, Falton, CA 95018 631.331.8982 - rick@monarcharborist.com

Paga 34 of 34

AUGUST 26, 2024 SCALE PROJECT MANAGER GREG ZIERMAN

> JOB NO. 2*0*23-MGKG L.G.





C3: Cavity in #743

Size and materials: Six (6) foot high chain link fencing, mounted on two-inch diameter galvanized iron posts, shall be driven into

the ground to a depth of at least two (2) feet at no more than ten-foot spacing. For paving area that will not be demolished and

Area type to be fenced: Type I: Enclosure with chain link fencing of either the entire dripline area or at the tree protection zone

fence around the entire planter strip to the outer branches. Type III: Protection for a tree located in a small planter cutout only

(such as downtown); orange plastic fencing shall be wrapped around the trunk from the ground to the first branch with two-inch

Duration of Type I, II, III fencing: Fencing shall be erected before demolition, grading or construction permits are issued and

Warning Sign: Each tree fence shall have prominently displayed an eight and one-half-inch by eleven-inch sign stating: "Warning -Tree Protection Zone-This fence shall not be removed and is subject to penalty according to Town Code 29.10.1025," Text on

remain in place until the work is completed. Contractor shall first obtain the approval of the project arborist on record prior to

Monarch Consulting Arboriets LLC - P.O Box 1010, Felton, CA 95016 831.331.5982 - rick@menarcharborist.com

wooden boards bound securely on the outside. Caution shall be used to avoid damaging any bark or branches.

(TPZ), when specified by a certified or consulting arborist. Type II: Enclosure for street trees located in a planter strip: chain link

Moneron Consulting Arborists LLC - P.O Box 1010, Felton, CA 98018

Prior to the commencement of construction, install the fence at the dripline, or tree protection zone (TPZ) when specified in an

approved arborist report, around any tree and/or vegetation to be retained which could be affected by the construction and prohibit

any storage of construction materials or other materials, equipment cleaning, or parking of vehicles within the TPZ. The dripline

Prohibit all construction activities within the TPZ, including but not limited to: excavation, grading, drainage and leveling within

Prohibit disposal or depositing of oil, gasoline, chemicals or other harmful materials within the dripline of or in drainage channels,

Retain the services of a certified or consulting arborist who shall serve as the project arborist for periodic monitoring of the project

site and the health of those trees to be preserved. The project arborist shall be present whenever activities occur which may pose a

The Director and project arborist shall be notified of any damage that occurs to a protected tree during construction so that proper

Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 851.831.8982 - rick@monarcharborist.com

November 6, 2023

Revised December 5, 2024

shall not be alfered in any way to as to increase the encroachment of the construction.

Design utility services and irrigation lines to be located outside of the dripline when feasible.

potential threat to the health of the trees to be preserved and shall document all site visits.

Pedestrian and equipment traffic that could compact the soil or physically damage roots;

Storing soil, construction materials, petroleum products, water, or building refuse; and,

Disposing of wash water, fuel or other potentially damaging liquids.

All persons, shall comply with the following precautions

the dripline of the tree unless approved by the Director.

The following are prohibited activities within the TFZ:

swales or areas that may lead to the dripline of a protected tree. Prohibit the attachment of wires, signs or ropes to any protected tree.

Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 831.331.8982 - Hok@monarcharborist.com

C5: Pepper #760

Any trenching, construction or demolition that is expected to damage or encounter tree roots should be monitored by the project

arborist or a qualified ISA Certified Arborist and should be documented The site should be evaluated by the project arborist or a qualified ISA Certified Arborist after construction is complete, and any necessary remedial work that needs to be parformed should be noted.

Roots greater than two inches in diameter shall not be cut. When roots over two inches in diameter are encountered and are authorized to be out or removed, they should be pruned by hand with loppers, handsaw, reciprocating saw, or chain saw rather than left crushed or torn. Roots should be out beyond sinker roots or outside root branch junctions and be supervised by the project arborist. When completed, exposed roots should be kept moist with burlap or backfilled within one hour.

Boring machines should be set up outside the drip line or established Tree Protection Zone. Boring may also be performed by digging a trench on both sides of the tree until roots one inch in diameter are encountered and then hand dug or excavated with an Air Spade® or similar air or water excavation tool. Bore holes should be adjacent to the trunk and never go directly under the main stem to avoid oblique (heart) roots. Bore holes should be a minimum of three feet deep.

Tree Pruning and Removal Operations All tree pruning or removals should be performed by a qualified arborist with a C-61/D-49 California Contractors License. Treatment, including pruning, shall be specified in writing according to the most recent ANSI A-300A Standards and Limitations and performed

according to ISA Best Management Practices while adhering to ANSI Z133.1 safety standards. Trees that need to be removed or pruned should be identified in the pre-construction walk through.

Page 29 of 34

14335 La Rinconada Drive, Los Gatos

I Richard Gessner, Certify:

Monarch Consulting Arborists LLC - P.O Box 1010, Feiton, CA 95018 831.331.8982 - rick® monarcharborist.com

Page 30 of 34

14335 La Rinconada Drive, Los Gatos

E1: English

Appendix E: Tree Protection Signs

Moneroh Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 931.931.8982 - rick@monercharborist.com

Warning

Tree Protection Zone

This Fence Shall Not Be Removed

And Is Subject To Penalty According To

Town Code 29.10.1025

Monarch Consulting Arborista LLC - P.O Box 1010, Felton, CA 95018

831.331.8982 - rick@monarcharborist.com

Novembar 6, 2023 Revised December 5, 2024

8-Y TRUNK PROTECTION WITH WATTLE

14335 La Rinconada Drive, Los Gatos

E2: Spanish

Monarch Consulting Arborista LLC - P.O Box 1010, Felton, CA 95018 831.331.8982 - rick@monarcharborist.com

Page 27 of 34

Trunk Protection Vertical Timber

November 8, 2023 Revised December 5, 2024

D3: Section 29.10.1005. - Protection of Trees During Construction

when stipulated in a tree preservation plan, posts may be supported by a concrete base.

Tree Protection Zones and Fence Specifications

the signs should be in both English and Spanish (Appendix E).

removing a tree protection fence.

Tree Inventory, Assessmen and Protection Report 14335 La Rinconada Drive, Los Gatos

Page 28 of 34

November 6, 2026 Revised December 5, 2024

Page 23 of 34

14885 La Rinconada Drive, Los Ge

G4: #751 through #755

Qualifications, Assumptions, and Limiting Conditions Any legal description provided to the consultant is assumed to be correct. Any titles or ownership of properties are assumed to be good and marketable. All property is appraised or evaluated as though free and clear, under responsible ownership and competent

Prohibited Activities

Root cuts;

Grade changes (e.g. soil outs, fills);

Burning of brush and woody debris;

All property is presumed to be in conformance with applicable codes, ordinances, statutes, or other regulations.

Care has been taken to obtain information from reliable sources. However, the consultant cannot be responsible for the accuracy of information provided by others.

The consultant shall not be required to give testimony or attend meetings, hearings, conferences, mediations, arbitration, or trials by reason of this report unless subsequent contractual arrangements are made, including payment of an additional fee for such services.

This report and any appraisal value expressed herein represent the opinion of the consultant, and the consultant's fee is not contingent upon the reporting of a specified appraisal value, a stipulated result, or the occurrence of a subsequent event.

Sketches, drawings, and photographs in this report are intended for use as visual aids, are not necessarily to scale, and should not be construed as engineering or architectural reports or surveys. The reproduction of information generated by architects, engineers, or other consultants on any sketches, drawings, or photographs is only for coordination and ease of reference. Inclusion of said information with any drawings or other documents does not constitute a representation as to the sufficiency or accuracy of said

Unless otherwise expressed: a) this report covers only examined items and their condition at the time of inspection; and b) the inspection is limited to visual examination of accessible items without dissection, excavation, probing, or coring. There is no warranty or guarantee, expressed or implied, that structural problems or deficiencies of plants or property may not arise in the future.

Monarch Consulting Arboriste LLC - P.O Box 1010, Faiton, CA 95018

831.331.8982 - rick@monarcharborist.com

Page 32 of 34


Código Ciudad del 29.101025

Cuidado Zona De Arbol Pretejido

Esta valla no podrán ser sacados Y está sujeta a sanción en función de

Page 31 of 34


Monarch Consulting Arborists LLC - P.O Box 1010, Felton, CA 95018 831.331.8982 - rick@monarcharborist.com



CONDITION nada Drive

EXISTING (14335 La Los G

21-276



7-14-22 1"=10'

GENERAL NOTES:

- WORK SHOWN HEREON SHALL BE DONE IN ACCORDANCE WITH THE CALIFORNIA BUILDING CODE LATEST VERSION AND EDITION, CALIFORNIA PLUMBING CODE LATEST VERSION AND EDITION, AND TOWN OF LOS GATOS STANDARD DETAILS AND SPECIFICATIONS.
- 2. ALL GRADING WORK SHALL BE PERFORMED IN ACCORDANCE WITH THE REQUIREMENTS AND RECOMMENDATIONS CONTAINED IN THE PROJECT GEOTECH
- 3. EXISTING TOPOGRAPHY SHOWN HEREON WAS TAKEN FROM A SURVEY PROVIDED BY OTHERS.
- 4. THE CONTRACTOR SHALL ASSUME SOLE AND COMPLETE RESPONSIBILITY FOR THE JOB SITE CONDITIONS, INCLUDING SAFETY OF ALL PERSONS AND PROPERTY, DURING THE COURSE OF CONSTRUCTION OF THIS PROJECT. THIS REQUIREMENT SHALL APPLY CONTINUOUSLY, AND SHALL NOT BE LIMITED TO NORMAL WORKING HOURS.
- 5. PRIOR TO COMMENCING CONSTRUCTION, THE CONTRACTOR SHALL VERIFY ALL SITE CONDITIONS FOR GRADING, DRAINAGE AND UNDERGROUND FACILITIES INCLUDING LOCATION AND ELEVATION OF EXISTING UNDERGROUND FACILITIES AT CROSSINGS WITH PROPOSED UNDERGROUND FACILITIES. IF CONDITIONS DIFFER FROM THOSE SHOWN ON THE PLANS, THE CONTRACTOR SHALL NOTIFY THE ENGINEER AND SHALL NOT BEGIN CONSTRUCTION UNTIL THE CHANGED CONDITIONS HAVE BEEN EVALUATED.
- 6. ALL DRAWINGS ARE CONSIDERED TO BE A PART OF THE CONTRACT DOCUMENTS. THE CONTRACTOR SHALL BE RESPONSIBLE FOR THE REVIEW AND COORDINATION OF ALL DRAWINGS AND SPECIFICATIONS PRIOR TO THE START OF CONSTRUCTION. ANY DISCREPANCIES THAT OCCUR SHALL BE BROUGHT TO THE ATTENTION OF THE ARCHITECT PRIOR TO THE START OF CONSTRUCTION SO THAT A CLARIFICATION CAN BE ISSUED. ANY WORK PERFORMED IN CONFLICT WITH THE CONTRACT DOCUMENTS OR ANY CODE REQUIREMENTS SHALL BE CORRECTED BY THE CONTRACTOR AT THEIR OWN EXPENSE AND AT NO EXPENSE TO THE OWNER OR ARCHITECT.
- 7. THE ENGINEER PREPARING THESE PLANS WILL NOT BE RESPONSIBLE FOR, OR LIABLE FOR, UNAUTHORIZED CHANGES TO OR USES OF THESE PLANS. ALL CHANGES TO THE PLANS MUST BE IN WRITING AND MUST BE APPROVED BY THE PREPARER OF THESE PLANS.
- 8. NOTES AND DETAILS ON DRAWINGS SHALL TAKE PRECEDENCE OVER GENERAL NOTES AND TYPICAL DETAILS. WHERE NO DETAILS ARE GIVEN, CONSTRUCTION SHALL BE AS SHOWN FOR SIMILAR WORK.
- 9. THE EXISTENCE, LOCATION AND CHARACTERISTICS OF UNDERGROUND UTILITY INFORMATION SHOWN ON THESE PLANS HAVE BEEN OBTAINED FROM A REVIEW OF AVAILABLE RECORD DATA. NO REPRESENTATION IS MADE AS TO THE ACCURACY OR COMPLETENESS OF SAID UTILITY INFORMATION. THE CONTRACTOR SHALL TAKE PRECAUTIONARY MEASURES TO PROTECT THE UTILITY LINES SHOWN AND ANY OTHER LINES NOT OF RECORD OR NOT SHOWN ON THESE PLANS.
- 10. IF AT ANY TIME DURING GRADING OPERATIONS, ANY UNFAVORABLE GEOLOGICAL CONDITIONS ARE ENCOUNTERED, GRADING IN THAT AREA WILL STOP UNTIL APPROVED CORRECTIVE MEASURES ARE OBTAINED.
- 11. THE PROPOSED GRADE IS THE FINAL GRADE AND NOT THE ROUGH GRADE. THE CONTRACTOR SHALL SUBTRACT THE THICKNESS OF THE PAVED SECTION AND/OR LANDSCAPE TOPSOIL SECTION TO ARRIVE AT THE ROUGH GRADE ELEVATION.
- 12. STRAIGHT GRADE SHALL BE MAINTAINED BETWEEN CONTOUR LINES AND SPOT ELEVATIONS UNLESS OTHERWISE SHOWN ON THE PLANS.
- 13. ALL DEBRIS AND FOREIGN MATERIAL SHALL BE REMOVED FROM THE SITE AND DISPOSED OF AT APPROVED DISPOSAL SITES. THE CONTRACTOR SHALL OBTAIN NECESSARY PERMITS FOR THE TRANSPORTATION OF MATERIAL TO AND FROM THE SITE.
- 14. ALL FILL SOILS OR SOILS DISTURBED OR OVEREXCAVATED DURING CONSTRUCTION SHALL BE COMPACTED PER THE REQUIREMENTS OF THE SOILS REPORT BUT NOT LESS THAN 90% MAXIMUM DENSITY AS DETERMINED BY A.S.T.M. SOIL COMPACTION TEST D-1557.
- 15. THE CONTRACTOR SHALL OBTAIN AN O.S.H.A. PERMIT FROM THE CALIFORNIA DIVISION OF INDUSTRIAL SAFETY PRIOR TO THE CONSTRUCTION OF TRENCHES OR EXCAVATIONS WHICH ARE FIVE FEET OR DEEPER.
- 16. DIMENSIONS TO PIPELINES ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
- 17. ALL WATER LINES SHALL BE INSTALLED WITH 36" MINIMUM COVER FROM TOP OF PIPE TO FINISHED GRADE, UNLESS OTHERWISE NOTED.
- 18. CONSTRUCTION STAKING FOR IMPROVEMENTS SHOWN ON THESE PLANS SHALL BE PERFORMED BY A LICENSED LAND SURVEYOR.
- 19. THE CONTRACTOR SHALL REPLACE ALL EXISTING IMPROVEMENTS DAMAGED DURING CONSTRUCTION TO MATCH EXISTING, INCLUDING PERMANENT TRENCH RESURFACING.
- 20. CONTRACTOR TO CONTACT UNDERGROUND SERVICE ALERT (800-227-2600) AT LEAST TWO WORKING DAYS PRIOR TO EXCAVATION.
- 21. ALL DIMENSIONS ARE IN FEET OR DECIMALS THEREOF.
- 22. ALL CURB DIMENSIONS AND RADII ARE TO PAVEMENT FACE OF CURB.
- 23. CONTRACTOR TO BE AWARE OF ALL OVERHEAD LINES AT ALL TIMES, SO AS NOT TO DISTURB THEM.
- 24. STORM DRAINAGE SYSTEMS SHOWN ON THESE PLANS HAVE BEEN DESIGNED FOR THE FINAL SITE CONDITION AT COMPLETION OF THE PROJECT. THE CONTRACTOR IS RESPONSIBLE FOR MAINTAINING ADEQUATE DRAINAGE OF THE SITE, DURING INTERIM CONDITIONS OF CONSTRUCTION.
- 25. CONTRACTOR SHALL OBTAIN ALL REQUIRED PERMITS, INCLUDING NPDES, FROM THE APPROPRIATE JURISDICTIONAL AGENCIES FOR DISCHARGE OF GROUNDWATER THAT MAY BE NECESSARY TO ACCOMPLISH EXCAVATIONS SHOWN ON THESE PLANS.

LEGEND:

PROPOSED

4" SEWER PIPE. PVC ASTM D3034, DR 26 OR APPROVED EQUAL.

4444 44 44

CONCRETE

CLEANOUT

SAWCUT LINE

_ _ _ _ _ _

1" WATER PIPE. COPPER TYPE K OR APPROVED EQUAL.

-START

SLOPED TRENCH AT TOP OF PIPE.

MATERIAL (ND ROCKS,

UNDISTURBED SOIL

STORM DRAIN LINE ELECTRICAL LINE

PROPERTY LINE

LIMIT LINE OF WORK

> \sim EXISTING SURFACE FLOW DIRECTION \leadsto PROPOSED SURFACE FLOW DIRECTION

27% SLOPE AND DIRECTION SANITARY SEWER CLEANOUT

METER BOX. TYPICALLY INSTALLED BY UTILITY COMPANY.

ABBREVIATIONS:

BACK OF WALK EXISTING FINISHED FLOOR FLOW LINE FORCE MAIN FINISHED SURFACE HIGH DENSITY POLY ETHYLENE INVERT PROPERTY LINE STANDARD DIMENSION RATIO STORM DRAIN SANITARY SEWER SANITARY SEWER CLEAN OUT

TOP OF CURB

WATER SHEET INDEX:

CIVIL	DRAWINGS

CO.1 CIVIL COVER PLAN EROSION CONTROL AND DEMOLITION PLAN C0.2 POLLUTION PREVENTION PLAN

C0.3 GRADING AND DRAINAGE PLAN AND UTILITY PLAN

C2.0 STORMWATER PLAN

SEWER CLEANOUT BOX 8-1/2" I.D. x 11-3/4" WITH REINFORCED CONCRETE FOR LID ON GREEN AREAS LID MUST BE MARKED 'SEVER' INSTALL MAXIMUM 1 FT. DE STRAIGHT PIPE CHRISTY G-5 TRAFFIC VALVE BOX OR WHEN NECCESSARY TO EQUAL 10-3/8" I.D x 12" CAST IRON G5C LID IN TRAVELED AREAS. LID MUST BE MARKED 'SEVER' PROPERLY PLACE CLEANOUT BOX VARIES (TO TOP OF 1/8" BENTO -1/8 DR 1/16 PVC BEND DR 6" SEWER LATERAL-FROM BUILDING SEWER ASEE NOTE 1 3/4' CRUSHED ROCK PER -SECTION 200-1,2 (SEE GREENBOOK) (FOR NEW LATERAL DNLY) DNE PIECE WYE PVC DNLY-PARTS MRS6 44 ARC FOR 4" DR MRS6 66 ARC FOR 6" BY MISSION RUBBER PRODUCTS OR EQUAL NOTES 1. AT PROPERTY LINE, CONNECT PVC CLEANOUT WYE TO LATERAL WHEN SAME MATERIAL; OTHERWISE, INSTALL ADJUSTABLE REPAIR COUPLING AND 1 FT. MAXIMUM SECTION OF STRAIGHT PVC PIPE TO CONNECT TO PVC CLEANOUT WYE Revision By Date 2. ACCEPTABLE PLASTIC PIPE PVC SDR 26 A.K. 12/04/2015 PVC PIPE A.K. 8/27/2020 WEST VALLEY SANITATION DISTRICT OF SANTA CLARA COUNTY STANDARD SEWER LATERAL CLEANOUT


CURB AND GUTTER


STREET SURFACE

T CONE EXPANDABLE PIPE PLUG

PRODUCTS INC. OR EQUAL

- FOR PVC SDR-26 BY ETCO SPECIALITY





4 0 3 3


CONSULTANT: COMPANY NAME: SF CIVIL CIVIL ENGINEER: PATRICK MACDONALD 2532 SANTA CLARA AVE #151 ALAMEDA, CALIFORNIA 94501 (P) 510-282-5281 (E) sfcivil@yahoo.com




REVISIONS	
	DATE
\triangle	
\triangle	

SHEET TITLE CIVIL COVER PLAN

SHEET NUMBER



ALONG A LEVEL CONTOUR



EROSION CONTROL NOTES:

- 1. IT IS THE CONTRACTOR'S RESPONSIBILITY TO MAINTAIN CONTROL OF THE ENTIRE CONSTRUCTION OPERATION AND TO KEEP THE ENTIRE SITE IN COMPLIANCE WITH LOCAL, STATE, & FEDERAL REGULATIONS. IN GENERAL, THE CONTRACTOR IS RESPONSIBLE FOR KEEPING SEDIMENT STORM RUNOFF FROM LEAVING THE SITE. SEDIMENT ROLLS AND SILT FENCES SHALL BE USED BY THE CONTRACTOR ON AN AS NEEDED BASIS TO PREVENT SILT FROM LEAVING THE SITE AND ENTERING THE STORM DRAIN SYSTEM. THIS PLAN MAY NOT COVER ALL THE SITUATIONS THAT ARISE DURING CONSTRUCTION DUE TO UNANTICIPATED FIELD CONDITIONS, BUT IT IS THE CONTRACTORS RESPONSIBILITY TO MAINTAIN THE SITE AND PREVENT SEDIMENT FROM LEAVING THE SITE.
- 2. THE RAINY SEASON IS DECLARED BY THE STATE WATER RESOURCES CONTROL BOARD (SWRCB). ADDITIONAL EROSION AND SEDIMENT CONTROL DEVICES AND ACTIONS MAY BE NECESSARY DURING THE RAINY SEASON. THE CONTRACTOR IS RESPONSIBLE FOR INCLUDING SUCH MEASURES REQUIRED PER THE CALIFORNIA STORMWATER QUALITY ASSOCIATION (CASQA).

 3. THIS PLAN IS TO BE USED FOR INTERIM EROSION AND
- . THIS PLAN IS TO BE USED FOR INTERIM EROSION AND SEDIMENT CONTROL ONLY. TEMPORARY EROSION CONTROL DEVICES SHOWN ON THE GRADING PLAN WHICH INTERFERE WITH THE WORK SHALL BE RELOCATED OR MODIFIED, AS AND WHEN, DIRECTED AS THE WORK PROGRESSES TO MEET "AS GRADED" CONDITIONS.
- E. CONTRACTOR IS RESPONSIBLE FOR MONITORING EROSION AND SEDIMENT CONTROL MEASURES PRIOR, DURING, AND AFTER STORM EVENTS.

 EXCEPT WHEN DIRECTED OTHERWISE ALL DEVICES.
- 5. EXCEPT WHEN DIRECTED OTHERWISE, ALL DEVICES SHOWN TO BE IN PLACE AT THE END OF EACH WORKING DAY, WHEN RAIN IS FORECASTED, AND MAINTAINED.
- S. TAKE REASONABLE CARE WHEN HAULING ANY EARTH, SAND, GRAVEL, STONE, DEBRIS, PAPER OR ANY OTHER SUBSTANCE OVER ANY PUBLIC STREET, ALLEY OR OTHER PUBLIC PLACE. IF DIRT, MATERIALS, OR SEDIMENT BLOW, SPILL, OR TRACK OVER AND UPON SAID PUBLIC OR ADJACENT PRIVATE PROPERTY, THEN THE DIRT, MATERIALS, OR SEDIMENT SHOULD IMMEDIATELY BE CLEANED UP.
- DURING THE RAINY SEASON, KEEP ALL PAVED AREAS CLEAR OF EARTH MATERIAL AND DEBRIS. THE SITE SHALL BE MAINTAINED SO AS TO MINIMIZE SEDIMENT LADEN RUNOFF TO ANY STORM DRAINAGE SYSTEM, INCLUDING EXISTING DRAINAGE SWALES AND WATER COURSES. ALL LOOSE SOIL AND DEBRIS SHALL BE REMOVED FROM THE STREET AREAS UPON STARTING OPERATIONS AND PERIODICALLY THEREAFTER AS DIRECTED BY THE CITY INSPECTOR.
- BY THE APPROPRIATE FEDERAL, STATE AND LOCAL AGENCY REQUIREMENTS.

 FILLED FILTER BAGS SHALL BE STOCKPILED ON SITE,
- READY TO BE PLACED IN POSITION WHEN RAIN IS FORECASTED, OR WHEN THE CITY OR INSPECTOR SO DIRECTS.
- DIRECTS.

 10. CONTRACTOR PROVIDES WATER ONSITE AND USE IT FOID DUST CONTROL DURING CONSTRUCTION.
- 11. CONTRACTOR MAINTAINS STABILIZED ENTRANCE AT EACH VEHICLE ACCESS POINT TO EXISTING PAVED STREETS.
 ANY MUD OR DEBRIS TRACKED ONTO PUBLIC STREETS SHALL BE REMOVED DAILY AND AS REQUIRED BY THE
- CITY INSPECTOR.

 12. INSTALL INLET PROTECTION AT OPEN INLETS TO PREVENT SEDIMENT FROM ENTERING THE STORM DRAIN SYSTEM. INLETS NOT USED IN CONJUNCTION WITH EROSION CONTROL ARE TO BE BLOCKED TO PREVENT ENTRY OF SEDIMENT.
- 13. BEST MANAGEMENT PRACTICES (BMPS) SHOWN ARE OUTLINED IN, BUT NOT LIMITED TO, THE CONSTRUCTION BEST MANAGEMENT PRACTICE HANDBOOK, CALIFORNIA STORMWATER QUALITY ASSOCIATION (CASQA), 2009, OR THE LATEST REVISED EDITION, AND APPLY DURING THE CONSTRUCTION OF THIS PROJECT (ADDITIONAL MEASURES MAY BE REQUIRED IF DEEMED APPROPRIATE BY CITY INSPECTORS).
- 14. MAINTENANCE IS TO BE PERFORMED PER THE CASQA BMP HANDBOOK AND AS FOLLOWS:
 - A. REPAIR DAMAGES CAUSED BY SOIL EROSION OR CONSTRUCTION BY THE END OF EACH WORKING
 - B. INSPECT SEDIMENT TRAPS, BERMS, AND SWALES PERIODICALLY AND AFTER EACH STORM AND REPAIRS MADE AS NEEDED.
 C. REMOVE SEDIMENT AND RESTORE SEDIMENT BARRIER TO ITS ORIGINAL DIMENSIONS WHEN
 - SEDIMENT HAS ACCUMULATED TO A DEPTH OF HALF THE SEDIMENT BARRIER HEIGHT.

 D. DEPOSIT SEDIMENT THAT HAS BEEN REMOVED FROM BARRIER SHALL BE DEPOSITED IN A SUITABLE AREA AND IN SUCH A MANNER THAT
- IT WILL NOT ERODE.


 17. CLEAN OUT INLET PROTECTION WHENEVER SEDIMENT DEPTH IS ONE HALF THE HEIGHT OF ONE FILLED FILTER BAG.
- 18. THOROUGHLY SWEEP ALL PAVED AREAS EXPOSED TO SEDIMENT, DUST, AND JOB SITE MATERIALS TO PREVENT THESE MATERIALS FROM LEAVING THE SITE.

 19. IF VEHICLES ARE USED DURING CONSTRUCTION
- TO ACCESS THE PROJECT SITE, THEN THE CONTRACTOR SHALL USE DRAIN ROCK AS A GRAVEL ROADWAY/DRIVEWAY FOR THE VEHICLES TO ACCESS THE SITE. THE GRAVEL DRIVEWAY/ROADWAY SHALL HAVE 8" MINIMUM THICKNESS AND BE WIDE ENOUGH FOR VEHICLES TO ACCESS AND LEAVE THE SITE. CONSTRUCTION ROADWAY/DRIVEWAY SHALL BE APPROVED BY THE CITY'S CONSTRUCTION INSPECTOR OR ENGINEER. THE VEHICULAR ROADWAY/DRIVEWAY SHALL BE ACCOMPANIED WITH A VEHICULAR WASHING STATION. ALL VEHICLES SHALL WASH TIRES AND UNDERSIDE OF VEHICLES AS APPROPRIATE WHEN LEAVING THE SITE. ANY MUD THAT IS TRACKED ONTO PUBLIC STREETS SHALL BE REMOVED THE SAME DAY.

PARCEL 1 1335 LA RINCONADA DRIVE LOS GATOS, CA APN: 409-14-026

CONSULTANT:

COMPANY NAME: SF CIVIL
CIVIL ENGINEER: PATRICK MACDONALD
2532 SANTA CLARA AVE #151
ALAMEDA, CALIFORNIA 94501
(P) 510-282-5281
(E) sfcivil@yahoo.com



R	REVISIONS	
		DATE
Δ		
\setminus		
$\overline{\setminus}$		
\triangle		
$\overline{\ }$		
\setminus		
\triangle		
\triangle		
\triangle		
\setminus		

SHEET TITLE EROSION CONTROL PLAN

SHEET NUMBER C0.2

2)—

ROSION CONTROL DETAILS
N.T.S.

Gravel Bags

(Do not use sand bags near inlets)

LEGEND:

C0.2—/

PROPERTY LINE

-DETAIL NUMBER

→PAGE NUMBER OF DETAIL SHEET

STORM DRAIN INLET PROTECTION.

APPROVED EQUAL STORM DRAIN

INLET GUARD AS SHOWN ON

FIBER ROLL SEDIMENT BARRIER.

SEE DETAIL 1 ON THIS SHEET.

CONCRETE WASHOUT. USE AS

NECESSARY. SEE DETAIL 2 ON

USE GRAVEL BAGS OR

DETAIL ON THIS SHEET.

THIS SHEET, TYP.

SPACING MEASURED ALONG

SHOWN ON PLANS

BURY FIBER ROLL

IN NATIVE SOIL

2" MINIMUM

4" MAXIMUM

THE FACE OF THE SLOPE AS

TYPICAL FIBER ROLL INSTALLATION

FIBER ROLL

3/4" X 3/4" WOOD STAKES

MAX 4' SPACING ENTRENCHMENT DETAIL

8" MIN


Pollution Prevention - It's Part of the Plan

Make sure your crews and subs do the job right!

Runoff from streets and other paved areas is a major source of pollution and damage to creeks and the San

and crews plan ahead to keep dirt, debris, and other construction waste away from storm drains and local creeks. Following these guidelines and the project specifications will ensure your compliance with

Francisco Bay. Construction activities can directly affect the health of creeks and the Bay unless contractors



Materials storage & spill cleanup

Non-hazardous materials management

- ✓ Sand, dirt, and similar materials must be stored at least 10 feet (3 meters) from catch basins. All construction material must be covered with a tarp and contained with a perimeter control during wet weather or when rain is forecasted or when not actively being used within 14 days.
- Use (but don't overuse) reclaimed water for dust control as needed.
- Sweep or vacuum streets and other paved areas daily. Do not wash down streets or work areas with water!
- Check dumpsters regularly for leaks and to make sure they are not overfilled.
 Repair or replace leaking dumpsters promptly.
- Cover all dumpsters with a tarp at the end of every work day or during wet weather.

Hazardous materials management

- Label all hazardous materials and hazardous wastes (such as pesticides, paints, thinners, solvents, fuel, oil, and antifreeze) in accordance with city, county, state, and federal regulations.
- ✓ Store hazardous materials and wastes in water tight containers, store in appropriate secondary containment, and cover them at the end of every work day or during wet weather or when rain is forecasted.
- Follow manufacturer's application instructions for hazardous materials and be careful not to use more than necessary. Do not apply chemicals outdoors when rain is forecasted within 24 hours.
- Be sure to arrange for appropriate disposal of all hazardous wastes.

Spill prevention and control

- ✓ Keep a stockpile of spill cleanup materials (rags, absorbents, etc.) available at the construction site at all times.
- When spills or leaks occur, contain them immediately and be particularly careful to prevent leaks and spills from reaching the gutter, street, or storm drain.

 Never wash spilled material into a gutter, street, storm drain, or creek!
- Dispose of all containment and cleanup materials properly.
- Report any hazardous materials spills immediately! Dial 911 or the Public Works Department by dialing 311

Construction Entrances and Perimeter

- ✓ Establish and maintain effective perimeter controls and stabilize all construction entrances and exits to sufficiently control erosion and sediment discharges from site and tracking off site.
- Sweep or vacuum any street tracking immediately and secure sediment source to prevent further tracking.

Vehicle and equipment maintenance & cleaning

requirements.

- Inspect vehicles and equipment for leaks
- frequently. Use drip pans to catch leaks until repairs are made; repair leaks
- ► Fuel and maintain vehicles on site only
- in a bermed area or over a drip pan that
- is big enough to prevent runoff.If you must clean vehicles or equipment
- on site, clean with water only in a bermed area that will not allow
- rinse water to run into gutters, streets, storm drains, or creeks.

 Do not clean vehicles or equipment
- ✓ Do not clean vehicles or equipment on-site using soaps, solvents, degreasers, steam cleaning equipment, etc.

Earthwork & contaminated soils

- ✓ Keep excavated soil on the site where it will not collect in the street.
- ✓ Transfer to dump trucks should take place on the site, not in the street.
- Use fiber rolls, silt fences, or other control measures to minimize the flow of silt off the site.



- ➤ Earth moving activities are only allowed during dry weather by permit and as approved by the City Inspector in the Field.
- ✓ Mature vegetation is the best form of erosion control. Minimize disturbance to existing vegetation whenever possible.
- ✓ If you disturb a slope during construction, prevent erosion by securing the soil with erosion control fabric, or seed with fastgrowing grasses as soon as possible. Place

fiber rolls down-slepe until soil is secure.

✓ If you suspect contamination (from site history, discoloration, odor, texture, abandoned underground tanks or pipes, or buried debris), call the Engineer for help in determining what should be done, and manage disposal of entaminated soil according to their instructions.

Dewatering operations

- Effectively manage all run-on, all runoff within the site, and all runoff that discharges from the site. Run-on from off site shall be directed away from all disturbed areas or shall collectively be in compliance.
- ✓ Reuse water for dust control, irrigation, or another on-site purpose to the greatest extent possible.
- ✓ Be sure to notify and obtain approval from the Engineer before discharging water to a street, gutter, or storm drain. Filtration or diversion through a basin, tank, or sediment trap may be required.
- In areas of known contamination, testing is required prior to reuse or discharge of groundwater.

 Consult with the Engineer to determine what testing is required and how to interpret results.

 Contaminated groundwater must be treated or hauled eff-site for proper disposal.

Saw cutting

- ✓ Always completely cover or barricade storm drain inlets when saw cutting. Use
- filter fabric, catch basin inlet filters, or sand/gravel bags to keep slurry out of the storm drain system.
- ✓ Shovel, absorb, or vacuum saw-cut slurry and pick up all waste as soon as you are finished in one location or at the end of each work day (whichever is sooner!).
- ✓ If saw cut slurry enters a catch basin, clean it up immediately.

Paving/asphalt work



Always cover storm drain inlets and manholes when paving or applying seal coat, tack coat, slurry seal, or fog seal.
Protect gutters, ditches, and drainage courses with sand/gravel bags, or earthen berms.
Do not sweep or wash down excess sand from sand sealing into gutters, storm drains, or creeks. Collect sand and return it to the stockpile, or dispose of it as trash.
Do not use water to wash down fresh asphalt concrete pavement.

Concrete, grout, and mortar storage & waste disposal

- Store concrete, grout, and mortar under cover, on pallets, and away from drainage areas. These materials must never reach a storm drain.
- ✓ Wash out concrete equipment/trucks off-site or into contained washout areas that will not allow discharge of wash water onto the underlying soil or onto the surrounding areas.



✓ Collect the wash water from washing exposed aggregate concrete and remove it for appropriate disposal off site.

Painting

- Never rinse paint brushes or materials in a gutter or street
- Paint out excess water-based paint before rinsing brushes, rollers, or containers in a sink.
- Paint out excess oil-based paint before cleaning brushes in thinner.
 Filter paint thinners and solvents for reuse whenever possible.
 Dispose of oil-based paint sludge and unusable thinner as hazardous waste.


Landscape Materials

- Contain, cover, and store on pallets all stockpiled landscape materials (mulch, compost, fertilizers, etc.) during wet weather or when rain is forecasted or when not actively being used within 14 days.
- ✓ Discontinue the application of any erodible landscape material within 2 days of forecasted rain and during wet weather.

14335 LA RINCONADA DRIVE LOS GATOS, CA

COMPANY NAME: SF CIVIL
CIVIL ENGINEER: PATRICK MACDONALD
2532 SANTA CLARA AVE #151
ALAMEDA, CALIFORNIA 94501
(P) 510-282-5281
(E) sfcivil@yahoo.com


CONSULTANT:



REVISI	ONS
	DATE

SHEET TITLE
POLLUTION
PREVENTION
PLAN

SHEET NUMBER C0.3



HARCEL 1

14335 LA RINCONADA DRIVE
LOS GATOS, CA
APN: 409-14-026

CONSULTANT:


COMPANY NAME: SF CIVIL
CIVIL ENGINEER: PATRICK MACDONALD
2532 SANTA CLARA AVE #151
ALAMEDA, CALIFORNIA 94501
(P) 510-282-5281
(E) sfcivil@yahoo.com





SHEET TITLE
GRADING AND DRAINAGE PLAN
UTILITY PLAN

SHEET NUMBER C1.0



Unit Basin Storage volume (UBS x) = 0.3 (inches) (corrected for slope of site)

Step 9. <u>Determine the Adjusted Unit Basin Storage Volume</u> for the site, using the following equation:

Adjusted UBS = (Step 5) \times (Step 8)

Adjusted UBS = 0.47 inches

Step 10. <u>Determine the BMP Design Volume</u>, using the following equation: 0.475 acres=20,703 sf Design Volume = Adjusted Unit Basin Storage Volume × Drainage Area Design Volume = $(Step 9) \times (Step 1) \times 1$ foot/12 inch

corresponding to the nearest rain gage. Figure B-2, B-3, or B-4 for San Jose, Palo Alto, or Morgan Hill, respectively. Find the percent imperviousness of the drainage area (from **Step 2**) on the x-axis. From there, find the line corresponding to the soil type (from **Step 6**), and obtain the unit basin storage

Unit Basin Storage for 1% slope (UBS $_{1\%}$) = 0.3 (inches) b) Slope ≥ 15% Use the figure at the end of this Appendix entitled "Unit Basin Volume for 80% Capture, 15% Slope" corresponding to the nearest rain gage: Figure B-5, B-6, or B-7 for San Jose, Palo Alto, or Morgan Hill, respectively. Find the percent imperviousness of the drainage area (from **Step 2**) on the x-axis. From there, find the line corresponding to the soil type (from Step 6), and obtain the unit basin storage

Unit Basin Storage for 15% slope (UBS 15%) = (inches)

portion of the project shown here in order of increasing infiltration capability:

____ Silt Loam/Loam (B) ____ Not Applicable (100% Impervious)

that the soils outside the building footprint are not graded/compacted? N (Y/N)

b) Does the site planning allow for protection of natural areas and associated vegetation and soils so

If your answer is no, and the soil will be compacted during site preparation and grading, the soil's infiltration ability will be decreased. Modify your answer to a soil with a lower infiltration rate (e.g.,

Modified soil type: CLAY LOAM

Use the figure at the end of this Appendix entitled "Unit Basin Volume for 80% Capture, 1% Slope"

____ Clay (D) ____ Sandy Clay (D) ____ Clay Loam (D)

DRAIN BOX WITH 18"X19 ½" GRATE SLOPE GROUND TOWARDS
DRAIN BOX

Silt Loam to Clay Loam or Clay).

a) Slope ≤ 1%

volume on the y-axis.

Step 8. Determine the unit basin storage volume from sizing curves.

SEE WIDTH ON PLANS GEO-TEXTILE FABRIC, TO ENCLOSE ALL DRAIN ROCK GRAVEL BASIN 3/4" DRAIN ROCK DETAIL 1 4" PERFORATED PIPE

a. Estimate the amount of impervious surface (rooftops, hardscape, streets, and sidewalks, etc.) in the area draining to the BMP: 0.207 acres

Step 3. Find the mean annual precipitation at the site (MAP_{site}). To do so, estimate where the site is on Figure

Step 4. Identify the reference rain gage closest to the project site from Table B-2b and record the MAP_{gage}:

B-1 and estimate the mean annual precipitation in inches from the rain line (isopleth) nearest to the

MAP_{site} = 22 inches

MAP_{gage} = 13.9 inches

Table B-2b: Precipitation Data for Three Reference Gages

Mean Annual Precipitation (MAP_{gage})

13.9

13.7

19.5

b. % impervious area = (amount of impervious area/drainage area for the BMP) × 100

% impervious area = (Step 2.a/Step 1) \times 100

project site.⁶ Interpolate between isopleths if necessary.

Reference Rain

San Jose Airport

Palo Alto

Morgan Hill

% impervious area = 43.5

AREA SUMMARY:

BUILDINGS TOWARDS GRAVEL BASINS (DRY WELLS).

GRAVEL BASINS ARE SIZED PER THE C3 MANUAL.

PER THE C3, CASQA SIZING, BMP VOLUME 810 CUBIC FEET.

TOTAL PROJECT AREA = 20,703 SF

TOTAL IMPERVIOUS AREA = 9,000 SF

FEET OF GRAVEL BASIN PROVIDED.


a. Total Site Area: 20,703	_(ft²)	b. Total Land Area Disturbed During Construction: 20,703 (including clearing, grading, stockpiling, or excavating)						
Project Totals	Total Existing (Pre- project) Area (ft²)	Existing Area Retained ¹ (ft ²)	Existing Area Replaced ² (ft ²)	New Area Created ² (ft ²)	Total Post- Project Area (ft			
Impervious Area (IA)								
c. Total on-site IA	5,833	0	0	9,000	9,000			
d. Total off-site IA ³	0		0	0	0			
e. Total project IA	5,833	0	0	9,000	9,000			
f. Total new and replaced IA			9,0	000				
Pervious Area (PA) ⁴								
g. Total on-site PA	14,870				11,703			
h. Total off-site PA ³								
i. Total project PA	14,870				11,703			
j. Total Project Area (2.e.+2.i.)	20,703				20,703			

k. Percent Replacement of IA in Redevelopment Projects: (Existing on-site IA Replaced ÷ Existing Total on-site IA) x 100%

REQUIRED GRAVEL BASIN VOLUME = 810 CUBIC FEET / 0.4 POROSITY = 2,025 GRAVEL BASIN AREA


THE PROPOSED SITE HAS BEEN DESIGNED WITH 8 GRAVEL BASINS (DRY WELL). TOTAL SQUARE FOOT

AREA OF GRAVEL BASINS = 500 SQUARE FEET. DEPTH OF BASINS = 5 FEET MINIMUM. 2,500 CUBIC



Adjusted UBS = Rain Gage Correction Factor × Unit Basin Storage Volume

Design Volume = 0.18 acre-feet × 43,560 square feet/acre = 810 cubic feet



SHEET TITLE

10-28-2024

REVISIONS

3

CONSULTANT:

COMPANY NAME: SF CIVIL

(P) 510-282-5281


(E) sfcivil@yahoo.com

2532 SANTA CLARA AVE #151 ALAMEDA, CALIFORNIA 94501

CIVIL ENGINEER: PATRICK MACDONALD

STORMWATER

SHEET NUMBER



NO./ DATE/ REVISION

LOS GATOS ARCH. \$
SITE REVIEW 8-28-24

LOS GATOS ARCH. \$
SITE REVIEW IØ-15-24

ALOS GATOS ARCH. \$
SITE REVIEW I-16-25

ESE PLANS ARE INTENDED ONLY FOR THE ORIGINAL SITE FOR WHICH EY WERE DESIGNED AND ARE THE PROPERTY OF UNIQUE HOME SIGNS. THESE PLANS ARE PROTECTED UNDER COPYRIGHT LAWS AND Y NOT BE REVISED OR REPRODUCED IN WHOLE OR IN PART WITHOUT EXPRESSED WRITTEN CONSENT OF UNIQUE HOME DESIGNS. ANY E OF THESE PLANS ON OTHER SITES IS PROHIBITED WITHOUT THE NSENT OF UNIQUE HOME DESIGNS. ANY DISCREPANCY DISCOVERED THESE PLANS SHALL BE BROUGHT TO THE ATTENTION OF UNIQUE ME DESIGNS PRIOR TO COMMENCEMENT OF THE WORK IN QUESTION. WRITTEN DIMENSIONS SHALL TAKE PRECEDENCE OVER SCALED MENSIONS.

HOME DESIGNS
and Residential Design
San Jose, California 95123

Land Planning and 499 Chinook Lane, San J (408) 972 - 8594

Site Plan - Parcel 1


La Rinconada Drive Project

195 California

DATE
SEPT. 1, 2024

SCALE
|"=10'
PROJECT MANAGER
GREG ZIERMAN
DRAWN
GZ

JOB NO. 2023-MGKG: L.G. SHEET




NO, DATE/ REVISION LOS GATOS ARCH & SITE REVIEW 9-6-24 LOS GATOS ARCH & A LOS GATOS ARCH &

HOME DESIGNS

Land Planning 499 Chlnok Lane, (408) 972-8594

La Rinconada Drive Project 14335 La Rinconada Drive - Parcel 1 Los Gatos, California Main Level Floor Plan

SCALE 1/4"=1"-0" PROJECT MANAGER GREG: ZIERMAN GΖ 2023-MGKG L.G.



NO./ DATE/ REVISION

LOS GATOS ARCH. & SITE REVIEW 9-6-24

LOS GATOS ARCH. & SITE REVIEW IO-15-24

LOS GATOS ARCH. & SITE REVIEW I-16-25

PLANS ARE INTENDED ONLY FOR THE ORIGINAL SITE FOR WHICH VERE DESIGNED AND ARE THE PROPERTY OF UNIQUE HOME AS THESE PLANS AND THESE PLANS ARE PROTECTED UNDER COPYRIGHT LAWS AND TO BE REVISED OR REPRODUCED IN WHOLE OR IN PART WITHOUT OPESSED WRITTEN CONSENT OF UNIQUE HOME DESIGNS, ANY FITHESE PLANS ON OTHER SITES IS PROHIBITED WITHOUT THE INT OF UNIQUE HOME DESIGNS, ANY DISCREPANCY DISCOVERED ESE PLANS SHALL BE BROUGHT TO THE ATTENTION OF UNIQUE DESIGNS PRIOR TO COMMENCEMENT OF THE WORK IN QUESTION. ANTERN DIMENSIONS SHALL TAKE PRECEDENCE OVER SCALED SIONS.

OME DESIGNS and Residential Design San Jose, California 95123

Land Planning and

Upper Level Floor Plan

La Rinconada Drive Project

14335 La Rinconada Drive - Parcel 1

DATE
SEPT. 1, 2024

SCALE
1/4"=1"-0"

PROJECT MANAGER
GREG ZIERMAN

DRAWN

GZ

JOB NO.
2023-MGKG L.G.

SHEET

A2 2





NOJ DATE/ REVISION

LOG GATOS ARCH. 6
SITE REVISION 19-6-24

LOG GATOS ARCH. 1
SITE REVISION 19-6-24

A LOG GATOS ARCH. 1
SITE REVISION 11-6-29

ISSE PARS MEINTENDED ONLY TOR THE CORSERVA, SITE FOR WIGHNEW VINED COSSEROR, AND ARE PROPERTY OF URDADE, SHORE
SOURCE, TREES TAMES MER PROTECTED UNDER COPPRISH. LAWS AND
WAY NOT SEE RESURE OR REPORTICED BY WAILCO.
FOR THE SEEP AND SOUR THE TIES REPORTICED MITHOUT THE
SEPRESSED WHITE CORSERVE OF URDADE, AND
FOR THE SEEP AND SOUR OR THE SITE REPORTIVED MITHOUT THE
SERVEY OF WAILCH HOUSE TO SHORE THE SEEP AND
MITHOUGH TO THE MITHOUGH TO THE MITHOUGH OF URBADOW
HERE WAS PAULE BY RECOVERED
THE SEEP AND SOUR THE SEEP AND SOUR THE SEEP
WEST OF URBADOW TO COMMENSE AND THE THE SEEP AND
MITHOUGH TO THE MITHOUGH TO THE MITHOUGH ASSETTING
HERE SEEP AND SOUR THE SEEP AND THE SEEP AND
HERE SEEP AND THE SEEP AND THE SEEP AND
HERE SEEP AND THE SEEP AND THE SEEP AND
HERE SEEP AND THE SEEP AND THE SEEP AND
HERE SEEP AND THE SEEP AND THE SEEP AND
HERE SEEP AND THE SEEP AND
HERE SEEP
HERE SEEP AND
HERE SEEP AND
HERE SEEP
HERE SEEP AND
HERE SEEP

HOME DESIGNS and Residential Design San Jose, Callionia 95123

Land Planning ar 499 Chinook Lane, Sar (408) 972-8594

Exterior Elevations - Parcel 1 La Rinconada Drive Project

DATE SEPT. 1, 2024

SCALE 1/"=1'-0"

PROJECT MANAGER
GREG ZIERMAN

DRAWN

GZ

JOS NO.
2023-MGKG LG

REST





NO./ DATE/ REVISION LOS GATOS ARCH. 4 SITE REVIEW 9-6-2 LOS GATOS ARCH. A LOS GATOS ARCH. 4 SITIE REMIEW II-16-28


DESIGNS HOME

Land Planning 499 Chinook Lane, (408) 972 - 8594

La Rinconada Drive Project 14335 La Rinconada Drive - Parcel 1 Exterior Elevations - Parcel 1

DATE SEPT. 1, 2024 SCALE |/* n|' -0* PROJECT MANAGER
GREG ZIERMAN ĢΖ JOB NO. 2023-MGKG: L.G

A3.2



NO./ DATE/ REVISION LOS GATOS ARCH. 4 SITE REVIEW 9-6-2 LOS GATOS ARCH. 4 SITE REVIEW 10-15-24 LOS GATOS ARCH. 4 SITE REVIEW 11-16-25


THE DESI NA VIOLE CON THE CONT T

DESIGNSResidential Design

Land Pl. 499 Ching (408) 972

Drive Project ada Drive - Parcel onada Rinco La

SEPT. 1, 2024 1/"=1'-0" PROJECT MANAGER GREG ZIERMAN 2023-MGKG L.G.



ROOF SLOPE IS TO BE 6:12.

ARROWS INDICATE DIRECTION OF ROOF SLOPE.

MAIN LEVEL PLATE HEIGHT SHALL BE 10'-034" U.N.O. UPPER LEVEL PLATE HEIGHT SHALL BE 9'-034" UN.O. OVERHANGS ARE TO BE 16" AT EAVES \$ 12"

AT GABLES U.N.O. PROVIDE EAVE VENTS FOR ATTIC VENTILATION PER CBC TYPICAL

INSTALL G.I. MATERIAL ROOF JACKS FOR PLUMBING VENTS, ETC. AS REQUIRED.

PROVIDE 5" 26 GA. G.I. OGEE GUTTER W/ DOWNSPOUTS. ALL DOWNSPOUTS SHALL DIRECT RAIN WATER AWAY FROM STRUCTURES AND ONTO VEGETATED AREAS.

NO./ DATE/ REVISION LOS GATOS ARCH. 4 SITE REVIEW 9-6-24

LOS GATOS ARCH. 4 SITE REVIEW 10-15-2 LOS GATOS ARCH. 4 SITE REVIEW 1-16-25


DESIGNSsidential Design and San J

QUE

Project Parcel Roof Plan La 143

SEPT. 1, 2024 SCALE 1/4"=1'-0" PROJECT MANAGER GREG ZIERMAN

JOB NO. 2023-MGKG L.G.



UPPER LEVEL FLOOR AREA DIAGRAM SCALE: 3/16" = 1'-0"

LOS GATOS ARCH. 4 SITE REVIEW 9-6-24 A LOS GATOS ARCH. 4 SITE REVIEW 11-16-25


DESIGNSesidential Design
California 95123

HOME Land Planning 499 Chinook Lane, (408) 972 - 8594

Area Diagram - Parcel La Rinconada Drive Project 14335 La Rinconada Drive - Parcel

DATE SEPT. 1, 2024 3/16"=1'-0" PROJECT MANAGER GREG ZIERMAN


JOB NO. 2023-MGKG: L.G.



NO./ DATE/ REVISION LOS GATOS ARCH. \$ SITE REVIEW 10-15-24

La Rinconada Drive Project 14335 La Rinconada Drive - Parcel Los Gatos, California


DATE SEPT. 1, 2024 1"=10" PROJECT MANAGER
GREG ZIERMAN ĢΖ **JOB NO.** 2023-MGKG; L.G.



NO./ DATE/ REVISION LOS GATOS ARCH. 4 SITE REVIEW 10-15-24

- June 21st @ Drive Project Shadow Study

SEPT. 1, 2024 1"=10" PROJECT MANAGER GREG ZIERMAN ĢΖ **JOB NO.** 2023-MGKG: L.G.




NO./ DATE/ REVISION LOS GATOS ARCH. \$
4 SITE REVIEW 9-6-24 LOS GATOS ARCH. 4 SITE REVIEW 10-15-24

sidential California

- June 21st @ 3:00 pm La Rinconada Drive Project 14335 La Rinconada Drive - Parcel

SEPT. 1, 2024

1"=10" PROJECT MANAGER GREG ZIERMAN GΖ **JOB NO.** 2023-MGKG; L.G.




NO./ DATE/ REVISION LOS GATOS ARCH. 4 SITE REVIEW 9-6-24 LOS GATOS ARCH. 4 SITE REVIEW 10-15-24

sidential California HOME \simeq and San J

1"=10' PROJECT MANAGER GREG ZIERMAN

JOB NO. 2023-MGKG: L.G.



NO./ DATE/ REVISION


LOS GATOS ARCH. 4 SITE REVIEW 10-15-24

SEPT. 1, 2024 1"=1Ø' PROJECT MANAGER GREG ZIERMAN GΖ

Project

Drive

JOB NO. 2023-MGKG: L.G.



NO./ DATE/ REVISION

LOS GATOS ARCH. 4
SITE REVIEW 9-6-24

LOS GATOS ARCH. 4
SITE REVIEW 10-15-24

Shadow Study - Dec. 21st @ 3

JOS TODA STUDY - Dec. 21st @ 3

La Rinconada Drive Project

JOS Gatos California

DATE
SEPT. 1, 2024

SCALE
1"=10"

PROJECT MANAGER
GREG ZIERMAN

DRAWN

GZ

JOB NO. 2023-MGKG L.G. SHEET This Page Intentionally Left Blank