

Manhole Quote

Sold To Robert (Bob) Vanmoer Date 11/3/2020

Marshall, MN Bob.vanmoer@ci.marshall.mn.us <u>1 (507) 530-3044</u> PO No.

			Mobilization:	\$1,000.00
Manhole	Location	Depth (ft)	Description of Repair	Cost
1	MH 4NW15	14.10	Old Precast, Medium leaks, Bypass, Traffic Control	8,204.00
2	MH4NW15A	12.10	Old Precast, Medium leaks, Traffic Control	6,324.00
3 "Grout Only"	MH4NW37A	0.00	Old Precast, Low leaks	0.00
4	MH9NE33	20.80	Old Precast, High leaks, Hose Pull: 60ft	10,076.00
5	MH10NW22	21.10	Old Precast, Low leaks, Bypass, Traffic Control	10,151.00
6	MH10NW21	21.20	Old Precast, Low leaks, Traffic Control	9,692.00
7	MH10NW20	20.50	Old Precast, Low leaks, Traffic Control	9,405.00
8	MH10SW7	18.80	Old Precast, Low leaks, Traffic Control	8,708.00
9	MH10NW19	18.90	Old Precast, Low leaks, Traffic Control	8,749.00
			Total	\$72,309.00

Notes:

- A site visit is agreed upon prior to mobilization if deemed necessary by HIPERLINE.
- Owner shall be responsible for providing a disposal site for all debris during the installation of the SpectraShield Liner System. This debris shall include, but not be limited to sand, chipped concrete, old linings, effluents, etc.
- Invoice(s) will be based upon field measurements and may increase or decrease the actual invoice/contract/purchase order amount accordingly.
- Our invoices are NET 30 DAYS, no retainage. A 1.5% interest charge per month for invoices over 30 days will apply.
- Sanitary sewer manholes include our industry leading 10 year warranty; storm sewer structures come with a standard 1 year warranty
- Removing manhole steps is part of the standard process unless noted otherwise
- If excessive grouting/leak-stopping is required (more than 1 workday), we will notify customer before proceeding. Additional grouting rates are \$300 per hour for the truck and crew, \$100 per gallon of grout, and \$25 per tube of grout

Customer Name	
Customer Signature	
Send Invoice To	

Additional Notes:

Cut 90 degree elbow drop off at MH10NW20, leave straight stub about 10 inches. Complimentary grout stop leaks around inbound pipe on MH37A.

Thanks for the Opportunity to Serve You!