



© 2020 Google
© 2020 Google

report a problem

LEGEND

- 1) Remove metal overhang
- 2) Cover section with wood sheet product
- 3) Replace shingles with new shingles
- 4) Replace siding with new lap siding
- 5) Paint of recover metal section
- 6) Add new illuminated sign
(Separate permit application from vendor)

