EXHIBIT A





Lots 27-28 Rockbury North Subdivision Parcel 27 Partial Vacation of Easement Legal Description

A strip of land 6-feet wide within a portion of Lots 27-28 as shown on the Rockbury North Subdivision, recorded in Book 117 of Plats at Pages 17775-17779, now known as Parcel P-27 as shown on the Property Boundary Adjustment – Record of Survey No. 12710, recorded as Instrument No. 2021-013552, situate in the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian, Ada County, Idaho, more particularly described as follows:

COMMENCING at the northwest corner of Parcel P-27 monumented by a found 1/2-inch rebar with cap stamped "PLS 8575", thence along the westerly boundary line of P-27, South 01°27'21" East, 14.81 feet; thence South 79°24'17" East, 10.23 feet to the easterly boundary of the 10-foot-wide platted front utility easement and the **POINT OF BEGINNING**;

Thence South 79°24′17" East, 78.22 feet to the westerly boundary of the 10-foot-wide platted rear utility easement;

Thence along said easement boundary, South 01°27′21" East, 6.14 feet;

Thence North 79°24'17" West, 78.22 feet to the easterly boundary of the 10-foot-wide platted front utility easement;


Thence along said easement boundary, North 01°27′21″ West, 6.14 feet to the POINT OF BEGINNING.

Containing 469 square feet more or less

Refer to the attached Easement Vacation Map.

Prepared by: Ronald M. Hodge, PLS Survey Department Manager 8575

OF OF JOHN HOUSE



	LINE TABLE	
LINE	DIRECTION	LENGTH_
L5	N60, 33, 10,E	18 71'

ļ	CURVE TABLE						
CURVE	RADIUS	DELTA	LENGTH	CH. BEARING	CH. LENGTH-		
C6	227.50'	023°55'40"	95.01'	S13°25'11"E	94,32'		
C19	56.50°	019°15'30'	18.59	S68°42'44"W	18.90*		
C20	56.50°	032"30'23"	32.05'	S42°49'47"W	31.63'		
C21	56.50	018*13'34*	17.97	S17*27'49*W	17.90'		
C22	56.50'	009*48'22*	9 67'	N03°26'50'E	9 66,		

(PRIVATE)

LANE

ASISSI

ż

34 (P-3¢)

N89° 25' 45"W 45,39

1

(35)

8

CURVE TABLE					
CURVE	RADIUS	DELTA	LENGTH	CH. BEARING	CH. LENGTH
C23	14.50	062°07'01"	15.72	N29"36'10"E	14.96
C31	227.50	003°39'28'	14.52	\$03°17'05"E	14.52
C32	227.50'	008°23'50'	33.34"	S09°18'44"E	33.31
C33	227.50	011°52'22"	47.14'	S19°26'50"E	47.00'

TREE HAVEN WAY (55' WIDE PUBLIC)

(25)

\$77-14'57"E 74.53

26

S88"32'39'W 96.50"

S88°32'39'W 96.50'

588°32'39"W 96.50"

30 \$88°32 39'W 95.96

(P-31) (31) SB8*32'39"W 102 34"

(28)

Instrument No. 2021. 613552 State of Idaho, County of ADA ss Filed for record at the request of Rockbury 88, LLC 7_ Min. past 1 ___ o'clock ____ M. this ____ day of January, 2021 Phil McGrane

12710



RECORD OF SURVEY NO.

LEGEND

SUBDIVISION BOUNDARY

NEW PARCEL LINE

PLATTED LOT LINE

PLATTED EASEMENT

Ó FOUND 5/8" REDAR, FLSI "PLS0575"

FOUND 5/8" REBAR, REMOVED FOUND 1/2" REDAR, FLSI "PLS8575"

FOUND 1/2" REBAR, REMOVED FOUND COPPER CAP MONUMENT, "FLSI PLS8575"

Z SET 5/8" REBAR, PLASTIC CAP "FLSI PLS8575" SET 1/2" REBAR, PLASTIC CAP

SET COPPER CAP MONUMENT, "FLSI PLS575"
SEWER MANHOLE

RECORD DATA

(xx)

"Rockbury North Subdivision" Book 117, Page 17775; 11-07-2019

NEW ROCKBURY NORTH SUBDIVISION PARCEL NUMBER

EXISTING ROCKBURY NORTH SUBDIVISION LOT NUMBER

CERTIFICATE OF SURVEYOR I, Ronald M. Hodge, do hereby certify that I am a Professional Land Surveyor, Ilcensed by the State of Idaho, and this map has been prepared from an actual survey made on the ground under my direct supervision, and is an accurate representation of said survey. It is in conformity with the Corner Persetuation and Filing Act, State of Idaho Code 55-1601 through 55-1612 and to the Idaho Code relating to Surveys.

INDEX#414-22-3-2-0-117-17775

PROPERTY BOUNDARY ADJUSTMENT - RECORD OF SURVEY FOR Rockbury 88, LLC

Lots 26 through 34, Block 1, Rockbury North Subdivision,

Situated in the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian, Ada County, Idaho



FOX LAND SURVEYS

680 #2B S. Progress Avenue, Meridian, ID 83642 208-342-7957 - vww.hmh-llc.com

ACAD DWG. FILE S20010PBA26-34 TOR. TRO CR RWH PLO DATE: January 2021

NOTES

- 1. The recording of this Record of Survey does not enable the owners of the parcels to convey ownership based solely on this map. A written conveyance must accompany such change in ownership. This Record of Survey does not serve as a legal description for the property shown on this map.
- 2. Fox Land Surveys, assumes no Hability for current or future compliance with applicable planning and zoning ordinances and/or restrictions.
- This survey was tentatively approved by City of Meridian PBA-2020-0008 on January 25, 2021. In accord with UDC 11-68-8C.2 deeds must be recorded and new tax parcel numbers assigned within
- Lut 30 on the original plat no longer exists.

 Side lot easements to be vacated through a vacation process.
- Dimensions are between current monuments only. Removed
- monuments are shown for reference only.

NARRATIVE

The purpose of this survey is to adjust the lot lines to accommodate for a different Townhome configuration than what was platted. The lines between Lots 26 thru 34 were changed. The total number of lots were

New monuments were set, and the old monuments were removed.





Lots 29-30 Rockbury North Subdivision Parcel 29 Partial Vacation of Easement Legal Description

A strip of land 6-feet wide within a portion of Lots 29-30 as shown on the Rockbury North Subdivision, recorded in Book 117 of Plats at Pages 17775-17779, now known as Parcel P-29 as shown on the Property Boundary Adjustment — Record of Survey No. 12710, recorded as Instrument No. 2021-013552, situate in the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian, Ada County, Idaho, more particularly described as follows:

COMMENCING at the northwest corner of Parcel P-29 monumented by a found 1/2-inch rebar with cap stamped "PLS 8575", thence along the westerly boundary line of P-29, South 01°27'21" East, 4.82 feet; thence South 79°24'17" East, 10.23 feet to the easterly boundary of the 10-foot-wide platted front utility easement and the **POINT OF BEGINNING**;

Thence South 79°24′17" East, 78.22 feet to the westerly boundary of the 10-foot-wide platted rear utility easement;

Thence along said easement boundary, South 01°27′21" East, 6.14 feet;

Thence North 79°24′17" West, 78.22 feet to the easterly boundary of the 10-foot-wide platted front utility easement;


Thence along said easement boundary, North 01°27′21″ West, 6.14 feet to the **POINT OF BEGINNING**.

Containing 469 square feet more or less Refer to the attached Easement Vacation Map.

Prepared by: Ronald M. Hodge, PLS Survey Department Manager 8575

SONALD M. HOOSE

RONALD M. HOOSE



LINE TABLE				
LINE DIRECTION		LENGTH		
L5	N60, 38, 40,,E	18.71		

	CURVE TABLE					
CURVE	RADIUS	DELTA	LENGTH	CH. BEARING	CH. LENGTH	
C6	227.50'	023°55'40"	95.01*	S13°25'11"E	94.32'	
C19	56.50	019°15'30'	18.59'	S68°42'44"W	18.90*	
C20	55.50*	032°30'23"	32.05'	S42°49'47"W	31.63'	
C21	56.50	0181334	17.97'	S17"27'49"W	17.90	
C22	56.50	009"48'22"	9.67'	N03°26'50'E	9 66'	

(PRIVATE)

LANE

SSI

ASI

(34) (P-34)

N89" 25' 45"W 45.39

1

(35)

CURVE TABLE					
CURVE	RADIUS	DELTA	LENGTH	CH. BEARING	CH. LENGTH
C23	14.50	062"07'01"	15.72	N29°36'10"E	14.96
C31	227.50	003"39'28"	14.52	503°17'05"E	14.52'
C32	227.50	00B°23'50"	33.341	S09°18'44"E	33.31'
C33	227.50	011"52'22"	47.14'	S19*26'50"E	47.00

TREE HAVEN WA (55' WIDE PUBLIC)

(25)

\$77-14'57"E 74.53

26

S88°32'39"W 96.50

\$88°32'39"W 96.50"

588°32'39"W 96.50"


(30) S88°32'39"W 96.96"

(P-31) (31) 588*32'39*W 102.34"

(32)

(28)





RECORD OF SURVEY NO. 1.2710

7 Min. past 1 o'clock A M. Ihis 260 day of January, 2021

Instrument No. 2021__013552 State of Idaho, County of ADA ss Filed for record at the request of Rockbury 88, LLC

By Deputy Recorder

Ö $\hat{\Omega}_{H}$

(xx)

LEGEND

SUBDIVISION BOUNDARY NEW PARCEL LINE
PLATTED LOT LINE
PLATTED EASEMENT

Phil McGrane Ex-Officio Recorder

FOUND 5/8" REBAR, FLSI "PLS8575" FOUND 5/8" REBAR, REMOVED

FOUND 1/2" REDAR, REMOVED FOUND 1/2" REBAR, REMOVED FOUND COPPER CAP MONUMENT, "FLSI PLS8575" 0

SET 5/8" REBAR, PLASTIC CAP "FLSI PLS8575" SET 1/2" REBAR, PLASTIC CAP

SET COPPER CAP MONUMENT, "FLSI PLS575" SEWER MANHOLE WATER METER

RECORD DATA

"Rockbury North Subdivision" Book 117, Page 17775; 11-07-2019

NEW ROCKBURY NORTH SUBDIVISION PARCEL NUMBER

EXISTING ROCKBURY NORTH SUBDIVISION LOT NUMBER

CERTIFICATE OF SURVEYOR

1, Ronald M. Hodge, do hereby certify that I am a
Professional Land Surveyor, licensed by the State of rioressocial cano active you, recrised by the State of idatio, and this map has been prepared from an actual survey made on the ground under my direct supervision, and is an accurate representation of said survey. It is in conformity with the Corner Perpetuation and filing Act, State of Idaho Code 55-1601 through 55-1612 and to the Idaho Code relating to Surveys.

INDEX#414-22-3-2-0-117-17775

PROPERTY BOUNDARY ADJUSTMENT - RECORD OF SURVEY

Rockbury 88, LLC

Lots 26 through 34, Block 1, Rockbury North Subdivision, Situated in the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian. Ada County, Idaho



FOX LAND SURVEYS

680 #2B S. Progress Avenue, Meridian, ID 83642 208-342-7957 - www.hmh-llc.com

ACAD DWG, FILE \$20010PBA26-34 DR. TRC CK, RMH PLOT SCALE: 1:1 SCALE: 1"= 30" DATE: January 2021 SHEET 1 ●F 1

- NOTES

 1. The recording of this Record of Survey does not enable the owners of the parcels to convey ownership based solely on this map. A written conveyance must accompany such change in ownership. This Record of Survey closs not serve as a legal description for the property shown on this map.
- 2. Fox Land Surveys, assumes no liability for current or future compliance with applicable planning and toning ordinances and/or restrictions.
- This survey was tentatively approved by City of Meridian PBA-2020-0008 on January 25, 2021. In accord with UDC 11-68-8C.2 deeds must be recorded and new tax parcel numbers assigned within
- one year.

 Lot 30 on the original plat no longer exists.

 Side lot easements to be vacated through a vacation process.

 Dimensions are between current monuments only. Removed

monuments are shown for reference only.

NARRATIVE

The purpose of this survey is to adjust the lot lines to accommodate for a different Townhome configuration than what was platted. The lines between Lots 26 thru 34 were changed. The total number of lots were

New monuments were set, and the old monuments were removed.





Lots 32-33 Rockbury North Subdivision Parcel 33 Partial Vacation of Easement Legal Description

A strip of land 6-feet wide within a portion of Lots 32-33 as shown on the Rockbury North Subdivision, recorded in Book 117 of Plats at Pages 17775-17779, now known as Parcel P-33 as shown on the Property Boundary Adjustment – Record of Survey No. 12710, recorded as Instrument No. 2021-013552, situate in the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian, Ada County, Idaho, more particularly described as follows:

COMMENCING at the northeasterly corner of Parcel P-33 monumented by a found 5/8-inch rebar with cap stamped "PLS 8575", thence along the southeasterly boundary line of P-33, South 44°23'21" West, 26.19 feet; thence North 56°58'43" West, 10.20 feet to the westerly boundary of the 10-foot-wide platted rear utility easement and the **POINT OF BEGINNING**;

Thence North 56°58'43" West, 85.17 feet to the easterly boundary of the 10-foot-wide platted front utility easement;

Thence along said easement boundary on the arc of a non-tangent curve to the left 6.00 feet, having a radius of 66.50 feet, a central angle of 05°10'17" and a chord bearing North 33°01'17" East, 6.00 feet;


Thence South 56°58'43" East, 86.37 feet to the westerly boundary of the 10-foot-wide platted rear utility easement;

Thence along said easement boundary, South 44°23'21" West, 6.12 feet to the **POINT OF BEGINNING**.

Containing 514 square feet more or less Refer to the attached Easement Vacation Map.

Prepared by: Ronald M. Hodge, PLS Survey Department Manager





LINE TABLE					
LINE	DIRECTION	LENGTH_			
L5	Neo, 38, 40E	18 71'			

The recording of this Record of Survey does not enable the owners of the parcels to convey ownership based solely on this map. A written

Fox land Surveys, assumes no liability for current or future compliance with applicable planning and zoning ordinances and/or

Lot 30 on the original plat no longer exists.

Side lot easements to be vacated through a vacation process.

Dimensions are between current monuments only. Removed monuments are shown for reference only.

conveyance must accompany such change in ownership. This Record of Survey does not serve as a legal description for the property

This survey was tentatively approved by City of Meridian PBA-2020-0008 on January 25, 2021. In accord with UDC 11-6B-8C,2

deeds must be recorded and new tax parcel numbers assigned within

		CUI	RVE TABLE	E	
CURVE	RADIUS	DELTA	LENGTH	CH. BEARING	CH. LENGTH
	227.50	023"55'40"	95.01'	S13°25'11"E	94.32'
C19	56,50	019"15'30"	18.99'	S68°42'44''W	18 90'
C20	56.50	032°39'23"	32.05'	S42°49'47"W	31.63'
C21	56.50	018*13'34*	17.97	S17"27'49"VV	17.90
C22	56.50	009°48'22°	9.67'	N03"26'50"E	9 66'

CURVE TABLE					
CURVE	RADIUS	DELTA	LENGTH	CH. BEARING	CH. LENGTH
C23	14.50	062°07'01"	15.72	N29°36'10"E	14.96'
C31	227.50'	003°39'28"	14.52	503°17′05"E	14.52
C32	227.50	008°23'50°	33.34	S09°18'44"E	33.31'
C33	227.50	011"52'22"	47.14'	S19"26'50"E	47.06

(25)

\$77-14'57"E 74.53

SCALE: 1"= 30"

RECORD OF SURVEY NO. 12710

Phil McGrane Ex-Officio Recorder

Instrument No. 2021 - 613552 State of Idaho, County of ADA ss Filed for record at the request of Rockbury 88, LLC

LEGEND SUBDIVISION BOUNDARY

NEW PARCEL LINE
PLATTED LOT LINE
PLATTED EASEMENT FOUND 5/6" REDAR, FLSI "PLS8575" FOUND 5/8" REBAR, REMOVED FOUND 1/2" REDAR, FLSI "PLS8575" FOUND 1/2" REBAR, REMOVED FOUND COPPER CAP MONUMENT, "FLSI PLS8575"

Σ SET 5/8" REBAR, PLASTIC CAP "FLSI PLSE575" SET 1/2" REBAR, PLASTIC CAP

SET COPPER CAP MONUMENT, "FLSI PLS575" SEWER MANHOLE WATER METER

RECORD DATA

"Rockbury North Subdivision" Book 117, Page 17775; 11-07-2019

NEW ROCKBURY NORTH SUBDIVISION PARCEL NUMBER

EXISTING ROCKBURY NORTH SUBDIVISION LOT NUMBER

(xx)

CERTIFICATE OF SURVEYOR I, Ronald M. Hodge, do hereby certify that I am a Professional Land Surveyor, licensed by the State of ldaho, and this map has been prepared from an actual survey made on the ground under my direct supervision, and is an accurate representation of said survey. It is in conformity with the Corner Percetuation and Filing Act, State of Idaho Code 55-1601 through 55-1612 and to the Idaho Code relating to Surveys.

INDEX#414-22-3-2-0-117-17775

PROPERTY BOUNDARY ADJUSTMENT - RECORD OF SURVEY Rockbury 88, LLC

Lots 26 through 34, Block 1, Rockbury North Subdivision, Situated in the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian, Ada County, Idaho



FOX LAND SURVEYS

680 #2B S. Progress Avenue, Meridian, ID 83642 208-342-7957 - www.hmh-llc.com

ACAD DWG. FILE \$20010PBA26-34 OR. TRC CK RMH PLOT SCALE

DATE: January 2021 SHEET

26 (P-26) S88"32'39'W 96.50' (PRIVATE) (P-27) (27) TREE HAVEN (55' WIDE PUBL S88°32'39'W 96.50 ASISSI LANE (28) 588°32'39"W 96.50" ż (30) SB8°32'39'W 96.96' -(P-31) 588°32'39"W 102.34" (32) C19 31 (P-3¢) (35)

N89° 25' 45"W 45.39

NARRATIVE

NOTES

shown on this map.

The purpose of this survey is to adjust the lot lines to accommodate for a different Townhome configuration than what was platted. The lines between Lots 26 thru 34 were changed. The total number of lots were

New monuments were set, and the old monuments were removed





Lots 4-5

Partial Vacation of Easement Legal Description Rockbury North Subdivision

A strip of land 6-feet wide within a portion of Lots 4-5 as shown on the Rockbury North Subdivision, recorded in Book 117 of Plats at Pages 17775-17779, situate within the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian, Ada County, Idaho, more particularly described as follows:

COMMENCING at the northeast corner of Parcel P-6 monumented by a found 1/2-inch rebar with capstamped "PLS 8575", thence along the easterly boundary line of P-6, North 01°27'21" West, 29.00 feet; thence South 88°32'39" West, 10.00 feet to the westerly boundary of the 10-foot-wide platted front utility easement and the **POINT OF BEGINNING**;

Thence continuing South 88°32'39" West, 82.50 feet to the original rear boundary line of Lot 5;

Thence along the original rear boundary line of Lots 5-4, North 01°27′21" West, 6.00 feet;


Thence North 88°32'39" East, 82.50 feet to the westerly boundary of the 10-foot-wide platted front utility easement;


Thence along said easement boundary, South 01°27′21″ East, 6.00 feet to the **POINT OF BEGINNING**.

Containing 495 square feet more or less Refer to the attached Easement Vacation Map.


Prepared by: Ronald M. Hodge, PLS Survey Department Manager








	CURVE TABLE					
CURVE	RADIUS	DELTA	LENGTH	CH. BEARING	CH. LENGTH	
C1	19.50	117°52'59°	40.12	\$60°23'50°E	33.41'	
C2	29.50'	092°01'36"	47.38*	S44°33'27"W	42.45'	
СЗ	37.20	038°17'57"	24.87"	N70°05'34"W	24.41*	
C4	14.41'	110°20′51"	27.75'	N05°40'16°E	23.66	



NARRATIVE
The purpose of this survey is to adjust the lot lines to accommodate for a different townhome configuration than what was platted. The lines between Lots 3 & 4 and 5 & 6 and between Lot 2 and 3 thru 6 were changed. The line between Lots 4 & 5 remains unchanged.

New monuments were set, and the old monuments were removed.

- NOTES
 This survey was tentatively approved by City of Meridian
 PBA-2021-0019 on . . th accord with UDC 11-68-8C.2
 deeds must be recorded and new tax parcel numbers assigned within one year.
- Dimensions are between current monuments only.
 Removed monuments are shown for reference only.





LEGEND

NEW PARCEL LINE
PLATTED LOT LINE
PLATTED CASEMENT LINE
NEW GRANTED EASEMENT LINE

FOUND 1/Z' REBAR, FLSI "PLS8575"
FOUND 1/Z' REBAR, REMOVED
FOUND COPPER CAP MONUMENT, "FLSI PLS8575" 0

 \boxtimes ⊠R FOUND COPPER CAP MONUMENT, REMOVED SET 1/2" REBAR, PLASTIC CAP "PLS8575" ⊠s SET COPPER CAP MONUMENT, "PLS575"

RECORD DATA

"Rockbury North Subdivision" Book 117, Page 17775; 11-07-2019

NEW ROCKBURY NORTH SUBDIVISION PARCEL NUMBER





Existing Platted Easement

New Granted Utility Easement For Idalio Power Co, Intermountain Gas Co. and Lumens (Centurylink)



CERTIFICATE OF SURVEYOR

I. Ronald M. Hodge, do hereby certify that I am a Professional Land
Surveyor, licensed by the State of Idalio, and this map has been
prepared from an actual survey made on the ground under my direct
supervision, and it an accurate representation of said survey. It is in
conformity with the Corner Perpetuation and Filing Act, State of
Idaho Code S-1601 through S-5 1612 and to the Idalio Code relating

INDEX# 414-22-3-2-0-117-17775

PROPERTY BOUNDARY ADJUSTMENT - RECORD OF SURVEY Rockbury 88, LLC

Lots 2 through 6, Block 1, Rockbury North Subdivision, Situated in the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian, Ada County, Idaho



FOX LAND SURVEYS

680 #28 S. Progress Avenue, Meridian, ID 83642 208-342-7957 - www.hmh-llc.com

ACAD DWG. FILE S20010 PB	A 2-6	DR. TRC	cx. RMH	PLOT SCA	LE: 1:1	
SCALE: 1"= 30'	DATE: Se	otember 2	022	SHEET	1 or	1





Lots 45-46 Rockbury North Subdivision Parcel 45 Partial Vacation of Easement Legal Description

A strip of land 6-feet wide within a portion of Lots 45-46 as shown on the Rockbury North Subdivision, recorded in Book 117 of Plats at Pages 17775-17779, now known as Parcel P-45 as shown on the Property Boundary Adjustment – Record of Survey No. 12975, recorded as Instrument No. 2021-103799, situate in the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian, Ada County, Idaho, more particularly described as follows:

COMMENCING at the southwesterly corner of Parcel P-45 monumented by a found 5/8-inch rebar with cap stamped "PLS 8575", thence along the southerly boundary line of P-45, South 89°25'45" East, 17.00 feet; thence North 00°34'15" East, 10.00 feet to the southerly boundary of the 10-foot-wide platted rear utility easement and the **POINT OF BEGINNING**;

Thence North 00°34'15" East, 97.10 feet to the northerly boundary of the 10-foot-wide platted front utility easement;

Thence along said easement boundary on the arc of a non-tangent curve to the left 8.48 feet, having a radius of 73.59 feet, a central angle of 06°36'21" and subtended by a chord bearing South 44°28'06" East, 8.48 feet;


Thence South 00°34'15" West, 91.11 feet to the southerly boundary of the 10-foot-wide platted rear utility easement;


Thence along said easement boundary, North 89°25'45" West, 6.00 feet to the **POINT OF BEGINNING**.

Containing 564 square feet more or less

Refer to the attached Easement Vacation Map.

Prepared by: Ronald M. Hodge, PLS Survey Department Manager






LINE TABLE					
LINE	DIRECTION	LENGTH			
L1	N60" 39' 40'E	32.35'			
L2	N60° 39' 40"E	1.76			
1.3	N00' 34' 15'E	4.78			

CURVE TABLE					
CURVE	RADIUS	DELTA	LENGTH	CH. DEARING	CH. LENGTH
C1	100 00'	014"05'25"	24.59	S77°33'00"E	24,53'
C2	100.00	025°09'44"	43.92	N82°49'25"E	43.56'
СЗ	100.00	C09°34'53"	16.72	N65°27'06"E	16.70
C4	14.54'	003"43'40"	21.24	S77*25'16"E	19.40'
C5	63 59	027*04'39*	30.05	S49*00'51"E	29.77
CB	63.59	026"51'28"	29 81'	S75*58'55"E	29.53

RECORD OF SURVEY NO
Instrument No. 2021- <u>23.799</u> State of Idaho, County of ADA as Filed for record at the request of Rockbury 88, LLC
Min. past 10 o'clock 4 M. this 4 day of July, 2021
By Deputy Regirger Ex-Officio Recorder
- ·



BASIS OF BEARING

The Basis of Bearings for this survey was established by GPS observations, projected to the Maho state plane coordinate system, IAD 83 datum, West Zone, A1 bearings shown are on grid azimuth and all distances shown are at ground. Refer to the drawing far the specific line and monumental used.

The purpose of this survey is to adjust the lot lines to accommodate for a different Townhome configuration than what was platted. The lines between Lots 42 thru 53 were changed. The rotal number of lots were reduced by 2.

New monuments were set, and the old monuments were removed.

NOTES

- The recording of this Record of Survey does not enable the owners of the parcels to convey ownership based solely on this map. A written conveyance must accompany such change in ownership. This Record of Survey does not serve as a legal description for the property shown on
- 2. Fox Land Surveys, assumes no liability for current or future compliance with applicable planning and runing ordinances and/or restrictions.
- Lots 52 and 53 on the original plat no longer exists.

 Side lot easements to be vacated through a vacation process.
- Dimensions are between current monuments only. Removed monuments are shown for reference
- This survey was tentatively approved by City of Meridian PDA-2021-0505 on July 1, 2021. In accord with UDC 11-68-8C.2 deeds must be recorded and new tax parcel numbers-assigned within one



LEGEND SUBDIVISION DOUNDARY

SUBDIVISION DOUNDARY

REWPARCEL LINE

PLATTED LOT LINE

PLATTED EASEMENT

FOUND 5/8" REBAR, FLSI "PLS8575" ₽n FOUND 5/8" REBAR, REMOVED FOUND 1/2" REBAR, FLSI "PLS8575" О

FOUND 1/2" REBAR, REMOVED FOUND COPPER CAP, FLSI "PLS8575" **13**

FOUND COPPER CAP, REMOVED SET 5/0" REBAR, PLASTIC CAP "PLS8575" SET 1/2" REBAR, PLASTIC CAP "PLS8575 Ø, SET COPPER CAP, FLSI PLS8575"

RECORD DATA

"Rockbury North Subdivision" Book 117, Page 17775; 11-07-2019

(#II) NEW ROCKBURY NORTH SUBDIVISION PARCEL NUMBER (XX) EXISTING ROCKBURY NORTH SUBDIVISION LOT NUMBER



CERTIFICATE OF SURVEYOR

I, Ronald M. Houlge, do hereby certify that I am a Professional Land Surveyor, licensed by the State of Idaho, and this map has been prepared from an actual survey made on the ground under my direct supervision, and is an accurate representation of sald survey. It is in conformity with the Corner Perpetuation and Filing Act, State of Idaho Code 55-1601 through 55-1612 and to the Idaho Code relating to Surveys.

INDEX#414-22-3-2-0-117-17775

RECORD OF SURVEY

Rockbury 88, LLC

Lots 42 through 53, Block 1, Rockbury North Subdivision,

Situated Within the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian, Ada County, Idaho



FOX LAND SURVEYS

680 II2B S. Progress Avenue, Meridian, ID 83642 208-342-7957 - www.hmh-llc.com

ACAD DWG. FILE S20010 PBA 42-53 DR. TRC CK. RMH PLOT SCALE: 1:1

SCALE: 1"= 20 DATE: July 2021 SHEET 1 OF





Lots 49-50 Rockbury North Subdivision Parcel 48 Partial Vacation of Easement Legal Description

A strip of land 6-feet wide within a portion of Lots 49-50 as shown on the Rockbury North Subdivision, recorded in Book 117 of Plats at Pages 17775-17779, now known as Parcel P-48 as shown on the Property Boundary Adjustment – Record of Survey No. 12975, recorded as Instrument No. 2021-103799, situate in the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian, Ada County, Idaho, more particularly described as follows:

COMMENCING at the southwesterly corner of Parcel P-48 monumented by a found 5/8-inch rebar with cap stamped "PLS 8575", thence along the southerly boundary line of P-48, South 89°25'45" East, 16.16 feet; thence North 00°34'15" East, 10.00 feet to the southerly boundary of the 10-foot-wide platted rear utility easement and the **POINT OF BEGINNING**;

Thence North 00°34'15" East, 78.24 feet to the northerly boundary of the 10-foot-wide platted front utility easement;


Thence along said easement boundary on the arc of a non-tangent curve to the left 6.28 feet, having a radius of 110.00 feet, a central angle of 03°16'16" and subtended by a chord bearing South 72°16'28" East, 6.28 feet;


Thence South 00°34'15" West, 76.39 feet to the southerly boundary of the 10-foot-wide platted rear utility easement;

Thence along said easement boundary, North 89°25'45" West, 6.00 feet to the **POINT OF BEGINNING**.

Containing 464 square feet more or less Refer to the attached Easement Vacation Map.

Prepared by: Ronald M. Hodge, PLS Survey Department Manager






LINE TABLE				
LINE DIRECTION		LENGTH		
L1	N60° 39' 40"E	32.35		
L2	N60° 39' 40°E	1.76		
L3	N00° 34' 15"E	4.78		

CURVE TABLE					
CURVE	RADIUS	DELTA	LENGTH	CH. BEARING	CH. LENGTH
C1	100 00	014"05'25"	24,59	S77*33'CO"E	24.53'
C2	100.00	025°C9'44"	43.92	N82"49'25"E	43.56'
C3	100.00	C09°34'53'	16.72	N65°27'06"E	16.70'
C4	14.54	003"43'48"	21.25	S77°25'16"E	19.40'
C5	63 59	027"04'39"	30.05'	S49*00'51'E	29.77
C6	63.59	026"51'26"	29 B1'	S75°58'55"E	29.53

RECORD OF SURVEY NO	775
Instrument No. 2021- 10.3 749 State of Idaho, County of ADA ss Filed for record at the request of Rockbury 88, LLC	
Min. past 10 o clock AM this 4	day of July, 2021
By Donus Rechards	Phil McGrane Ex-Officio Recorder



BASIS OF BEARING

The Basis of Beanngs for this survey was established by GPS observations, projected to the Idoho state plane coordinate system, NAD 83 datum. West Zone, All bearings shown are on grid ozimuth and all distances shown are at ground. Ruler to the drawing for the specific Lite and monuments used.

NARRATIVE

The purpose of this survey is to adjust the lot lines to accommodate for a different Townhome configuration than what was platted. The lines between Lots 42 thru 53 were changed. The total number of lots were reduced by 2.

New monuments were set, and the old monuments were removed.

NOTES

- 1. The recording of this Record of Survey does not enable the owners of the parcels to convey ownership based solely on this map. A written conveyance must accompany such change in ownership. This Record of Survey does not serve as a legal description for the property shown on this map.

 2. Fox Land Surveys, assumes no liability for current or future compliance with applicable planning
- and coning ordinances and/or restrictions.
 Lots 52 and 53 on the original plat no longer exists.
- Side for easements to be vacated through a vacation process.

 Dimensions are between current monuments only. Removed monuments are shown for reference
- 6 This survey was tentatively approved by City of Meridian PBA-2021-0505 on July 1, 2021. In accord with UDC 11-68-BC, 2 deeds must be recorded and new tax parcel numbers assigned within one



LEGEND

SUBDIVISION DOUNDARY

NEW PARCEL LINE

PLATTED LOT LINE

PLATTED EASEMENT

FOUND 5/8* REBAR, FLSI "PLS8575" FOUND 5/8* REBAR, REMOVED

FOUND 1/2" REBAR, FLSI "PLS8575" FOUND 1/2" REBAR, REMOVED On **13** FOUND COPPER CAP, FLSI*PLS8575* FOUND COPPER CAP, REMOVED

SET 5/8" REBAR, PLASTIC CAP "PLS8575" SET 1/2" REBAR, PLASTIC CAP "PLS8575 Ø_s SET COPPER CAP, FLS1*PLSE575*

RECORD DATA

"Rockbury North Subdivision" Book 117, Page 17775; 11-07-2019

NEW ROCKBURY NORTH SUBDIVISION PARCEL NUMBER XX EXISTING ROCKBURY NORTH SUBDIVISION LOT NUMBER



Fee: 5--

CERTIFICATE OF SURVEYOR

I, Ronald M. Hodge, do hereby certify that I am a Professional Land Surveyor, licensed by the State of Idaho, and this map has been prepared from an actual survey made on the ground under my direct supervision, and is an accurate representation of said survey. It is in conformity with the Corner Perpetuation and Filing Act, State of Idaho Code 55-1601 through 55-1612 and to the Idaho Code relating to Surveys.

INDEX#414-22-3-2-0-117-17775

RECORD OF SURVEY

Rockbury 88, LLC

Lots 42 through 53, Block 1,

Rockbury North Subdivision, Situated Within the Southeast 1/4 of the Southwest 1/4 of Section 22, Township 4 North, Range 1 West, Boise Meridian, Ada County, Idaho



FOX LAND SURVEYS

680 #28 S. Progress Avenue, Meridian, ID 83642 208-342-7957 - www.hmh-llc.com

[ACAD DWG. FILE \$20010 P	BA 42-53 DR. TRC CK. RI	MH PLOT SCALE: 1:1
I	SCALE: 1"= 20'	DATE: July 2021	SHEET 1 OF 1