## Exhibit A - Key Item List

|                        | Item List  | oct coct      | Staff Priority | Council  |
|------------------------|--|---------------|----------------|----------|
|                        | item ast   | est cost      | Reco           | Priority |
|                        | Park Safety and ADA Loss Control measures  |               | High           |          |
|                        | Main parking lot - 115 spaces- handicap space need sign and post for current     |               |                |          |
|                        | spots and need 3 additional spots with sign, post, and striping                  | \$<br>415     |                |          |
|                        | Secondary parking lot 1 handucap space   | \$<br>95      |                |          |
|                        | Playground sign - replace with pictogram sign                                    | \$<br>26      |                |          |
|                        | 2 Additional ADA picnic tables   | \$<br>1,298   |                |          |
|                        | Ground-level play components - need a min of 1 additional                        | \$<br>1,000   |                |          |
|                        | ADA child swing safety strap   | \$<br>50      |                |          |
| ar<br>X                | Playground fill replacement - pour-in-place (recommended)                        | \$<br>64,650  |                |          |
| L P                    | Playground fill replacement - loose rubber mulch (alternative option)            | \$<br>23,900  |                |          |
| oriż                   | Railing on the band shell ADA ramp   | \$<br>2,000   |                |          |
| em                     | Bandshell outlet covers - 2 total  | \$<br>12      |                |          |
| Σ<br>«                 | Bathroom door replacement  | \$<br>1,316   |                |          |
| Veterans Memorial Park | Sidewalk around the bandshell - currently not ADA compliant (est 570 sq ft)      | \$<br>5,700   | High           |          |
| <b>√</b> eti           | Walkway adjusted to prevent driving on grass and the sidewalk (2 fixed Bollards) | \$<br>1,400   | High           |          |
|                        | Consession stand, Announcer booth and Dugout- Shingles, sofit, Facia             | \$<br>40,000  | High           |          |
|                        | <b>E</b> lag lights  | \$<br>800     | High           |          |
|                        | Paint the concession stand and announcer booth (1,800 sq ft.)                    | \$<br>5,880   | Medium         |          |
|                        | Shade trees (est 5 trees)  | \$<br>1,500   | Medium         |          |
|                        | Picnic Shelter with bathrooms & kitchenette                                      | \$<br>300,000 | Medium         |          |
|                        | Pollinator garden  | \$<br>1,200   | Low            |          |
|                        | Seal Coating for walkways  | \$<br>1,472   | Low            |          |
|                        | More benches around the playgrounds (2X)   | \$<br>6,000   | Low            |          |

|               |   |               | Staff Priority | Council  |
|---------------|---|---------------|----------------|----------|
|               | Item List   | est cost      | Reco           | Priority |
|               | Park Safety and ADA Loss Control measures                                     |               | High           |          |
|               | Replacement of the infant swings (higher priority)                            | \$<br>3,200   |                |          |
|               | Replace the playstructure   | \$<br>81,700  |                |          |
|               | Ground-level play components - need a min of 1 additional                     | \$<br>1,000   |                |          |
|               | Circle parking lot - needs 1 handicap parking spot - sign, post, and striping | \$<br>95      |                |          |
|               | Playground sign - replace with pictogram sign                                 | \$<br>26      |                |          |
|               | 1 Additional ADA picnic tables  | \$<br>649     |                |          |
|               | Playground fill replacement - pour-in-place (recommended)                     | \$<br>99,300  |                |          |
| 논             | Playground fill replacement - loose rubber mulch (alternative option)         | \$<br>36,431  |                |          |
| . Pa          | Paint teeter totter (scrape and paint)  | \$<br>400     |                |          |
| Rain bow Park | Park shelter GFCI outlets - need to upgrade two                               | \$<br>360     |                |          |
| aint          | Bathrooms ramp to get into the doors  | \$<br>150     |                |          |
| č             | Bathrooms handrails   | \$<br>230     |                |          |
|               | Alternate solution - rent an ADA portable bathroom (annual cost)              | \$<br>1,500   |                |          |
|               | De rink maintence - replacement of fiber boards                               | \$<br>40,000  | High           |          |
|               | Ece rink maintence - Level the ground   | \$<br>10,125  | High           |          |
|               | <b>B</b> lag lights   | \$<br>800     | High           |          |
|               | Pickleball courts - convert one of the tennis courts to a pickle ball court   | \$<br>6,500   | Medium         |          |
|               | Resurface of tennis/pickle ball court   | \$<br>5,000   | Medium         |          |
|               | Restore the gravel walkways to grass  | \$<br>11,667  | Medium         |          |
|               | Seal Coating for walkways   | \$<br>9,476   | Low            |          |
|               | Total   | \$<br>270,678 |                |          |

|                    |   |               | Staff Priority | Council  |
|--------------------|---|---------------|----------------|----------|
|                    | Item List   | est cost      | Reco           | Priority |
|                    | Park Safety and ADA Loss Control measures   |               | High           |          |
|                    | Playground fill replacement - pour-in-place (recommended)   | \$<br>78,630  |                |          |
|                    | Playground fill replacement - loose rubber mulch (alternative option)   | \$<br>28,946  |                |          |
|                    | Street handicap parking - 1 at each enterence   | \$<br>190     |                |          |
|                    | Playground sign - with pictogram sign 1 for each structure (3)  | \$<br>78      |                |          |
|                    | 1 Additional ADA picnic tables  | \$<br>649     |                |          |
| Drugntusod         | Replace the stainless steel playstructure   | \$<br>61,700  |                |          |
| Bryantwood<br>Park | Replacement of the infant swings (higher priority) and address the exit zones   | \$<br>3,200   |                |          |
| Paik               | ADA child swing safety strap  | \$<br>50      |                |          |
|                    | Concrete pad and 1 Additional ADA picnic tables (outside of play area)  | \$<br>2,189   |                |          |
|                    | Replace railroad ties with cement around the playgrounds with accessibility access point and expand the exit zone for the slide | \$<br>24,900  | High           |          |
|                    | More shade trees around the playground (est 10 trees)   | \$<br>3,000   | Medium         |          |
|                    | More benches around the playgrounds (2X)  | \$<br>6,000   | Low            |          |
|                    | Seal Coating for walkways   | \$<br>2,352   | Low            |          |
|                    | Total   | \$<br>182,938 |                |          |

|            |              |   |              | Staff Priority | Council  |
|------------|--------------|---|--------------|----------------|----------|
|            |              | Item List   | est cost     | Reco           | Priority |
| Pioneer Pa | Diopoor Dark | Convert to a dog park (est 9k sq. ft) or a drive through business | \$<br>21,500 | Low            |          |
|            |              | Seal Coating for walkways   | \$<br>2,548  | Low            |          |
|            |              | Total   | \$<br>24 048 |                |          |

|         |   |              | Staff Priority | Council  |
|---------|---|--------------|----------------|----------|
|         | Item List   | est cost     | Reco           | Priority |
|         | Park Safety and ADA Loss Control measures                             |              | High           |          |
|         | Ground-level play components - need a min of 1 additional             | \$<br>1,000  |                |          |
|         | Street handicap parking - 1 spot                                      | \$<br>95     |                |          |
| Tot Lot | Playground sign - replace with pictogram sign                         | \$<br>26     |                |          |
|         | Playground fill replacement - pour-in-place (recommended)             | \$<br>27,600 |                |          |
|         | Playground fill replacement - loose rubber mulch (alternative option) | \$<br>10,981 |                |          |
|         | Move the trash bin to a cement slab                                   | \$<br>200    | Medium         |          |
|         | Total   | \$<br>28,921 |                |          |

note: all alternative options are not included in the totals for each park