

Staff Report to the North Ogden City Council

SYNOPSIS

Description: The intersection at 2100 North Fruitland Drive has been a hazardous

intersection for a while. Eastbound traffic must navigate this intersection cautiously. The sight distance for these vehicles is very short which does not leave a lot of time to cross the intersection. Southbound and northbound vehicles are restricted to a small turning radius to make the turn. Fortunately, this intersection has not seen many accidents in the last 5 years. A big challenge for this intersection is the location of a culinary water booster station which is situated in the northwest corner. This is also a hazard as our crews

must maintain this station while being out in the roadway.

Date: September 5, 2024

STAFF INFORMATION

Eric Casperson
ecasperson@nogden.org
801-737-3308

QUESTION FOR COUNCIL

What option does the council want to pursue on the intersection design?

STAFF RECOMMENDATION

Staff recommends we explore different options for this intersection such as a roundabout or aligning Fruitland Drive to allow vehicles to safely navigate this intersection from all directions.


DISCUSSION

There are a few options for this intersection to make it better and easier to navigate. A roundabout was suggested for this intersection to help with traffic flow and safety. To make this work the home on southwest corner and/or the land on the northeast corner would need to be purchased. Re-aligning Fruitland Drive would also require purchasing the home or the land, depending on which option is chosen. As growth happens this intersection will continue to see increased traffic.

I will be in attendance as well as the Public Works Director available to answer questions and help the council strategize on what would be the best way to accomplish our goals with the intersection design.











PREPARED B



NORTH OGDEN CITY CORPORATION

PUBLIC WORKS

ENGINEERING DIVISION
185 EAST LOWOND WIEW DRIVE
NORTH OCDEN CITY, UTAH 84414
TELEPHONE: 801-782-8111
FAX: 801-782-6815
E-MAIL: WWW.NORTHOGDENCTIY.COM

PROFESSIONAL SEAL:

PROJECT IDENTIFICATION:

FRUITLAND DRIVE 2100 North Intersection

PROJECT OWNER:

NORTH OGDEN CITY CORPORATION

CORPORATION

505 EAST 2600 NORTH
NORTH GODEN CITY, UTAH 84414
WWW.NORTHOGDENCITY.COM



ENG .JOB #: P.U. JOB #: **N**

IFAS NO.:
PREPARER #: NOC

DRAWING FILE NAME:

DRAWN BY: E. CASPERSON CHECKED BY:

HEET TITLE:

FRUITLAND DRIVE 2100 North Option 1

HEET IDENTIFIER:

EXHBT1

BINDING ORDER





NORTH OGDEN CITY CORPORATION

PUBLIC WORKS

ENGINEERING DIVISION
165 EAST LOMOND VIEW DRIVE
NORTH OCDEN CITY, UTAH 84414
TELEPHONE: 801-782-8451
FAX: 801-782-6453
E-MAIL: WWW.NORTHOGDENCITY.COM

PROFESSIONAL SEAL:

FRUITLAND DRIVE 2100 North Intersection

PROJECT OWNER:

NORTH OGDEN CITY

CORPORATION

505 EAST 2600 NORTH
NORTH GODEN CITY, UTAH 84414
WWW.NORTHOGDENCITY.COM



FRUITLAND DRIVE 2100 North Option 2

EXHBT2

BINDING ORDER