

Owner Change Order

Change Order Number: 005

City of Norman - North Base Complex Phase 1

Flintco LLC (40-000)

1310-1380 DA Vinci Street

Project # 20136

Norman, Oklahoma 73069

Date: 3/18/2022

To Owner:City of Norman
201-C West Gray
Norman, Oklahoma 73069

Contract Number: K-2021-35
Contract Date: 10/13/2020

The Contract is hereby revised by the following items:

Details

Includes Cost for the Following:

- RFIs Nos. 119, 122, 123, 125 & 126
- · Revised Signage for Restroom M117
- Replacement Hinges
- M200AA & M138A Door Hardware Changes
- · Saw Cut & Install Plates for Saw Cut Trench at Vehicle Lifts
- Paint (3) Light Pole Bases
- · Regrade Area North of DaVinci & Add Grate to Junction Box
- Automatic Drain for Waste Oil
- · Dams for Wash Bay
- Additional Door Hardware for Exterior Doors
- · Addition of Expansion Joint at North Wall of Fleet Work Bays
- · Additional Fire Extinguisher Cabinet
- · Flooring Replacement at Parks Admin Area
- Unbalanced Airflow Issues (Hot & Cold) from MAUs Test Air Blender
- Delays Days***

Items with *** have no cost impact.

PCO #005 - CE #065 - Change Order No. 05

CE#	Detail Description		Amount
065	Main Job		\$51,189.75
065	Alternate		\$29,994.66
		PCO Total:	\$81,184.41

The original Contract Value	\$8,648,000.00
Sum of changes by prior Prime Contract Change Orders	\$335,752.96
The Contract Value prior to this Prime Contract Change Order	\$8,983,752.96
The Contract Value will be changed by this Prime Contract Change Order in the amount of	\$81,184.41
The new Contract Value including this Prime Contract Change Order will be	\$9,064,937.37
The Contract duration will be changed by	14 days
The revised Substantial Completion date as of this Prime Contract Change Order	1/21/2022

Flintco, LLC	City of Norman
CONTRACTOR	OWNER
2302 S. Prospect Oklahoma City, Oklahoma 73129	201-C West Gray Norman, Oklahoma 73069
Address	Address
Ву	Ву
SIGNATURE	SIGNATURE
DATE	DATE
CCD Inc. Auchitecto 9 Planners	
GSB, Inc. Architects & Planners ARCHITECT	-
3555 NW 58TH Street, Suite 700W Oklahoma City, OK 73112	
Address	-
Ву	-
SIGNATURE	-
DATE	_

PROPOSED CHANGE ORDER SUMMARY--- CONSTRUCTION MANAGER

Construction Manager:

Flintco, LLC

THE CITY OF NORMAN

Proj Name/#: Norman North Base - Phase 1 / 20136

PCO No.: #005 PCO Title: Owner Owner Change Order No. 5

PCO Date: 4/5/2022

1.	Subcontractors' Work (enter amounts from Subcontractor Summary Sheets)		
DIV 09	Apex: RFI #119 - Additional Rubber Base		\$ 742.50
DIV 32/5/9	Turning Point/K&E/Naff: RFI #122 - Additional Bollards at Exterior MEP Equipment		\$ 11,590.50
DIV 10	Felix: Revised Signage for Restroom M117 & RFI #123 - Address Signage		\$ 399.50
DIV 5	K&E: RFI #125 - IR Heater Corrections per City Inspector Comments		\$ 2,196.00
DIV 08	Convergint: Replacement Hinges (No Markup Included)		\$ 506.91
DIV 08	Felix: M200AA & M138A Door Hardware Changes		\$ 778.00
DIV 5	K&E: Plates for Saw Cut Trench at Vehicle Lifts		\$ 786.10
DIV 9	Naff: Paint (3) Light Pole Bases		\$ 280.00
DIV 26/32	DSE/Greenshade: RFI 126: Backflow & Irrigation Controller Location		\$ 9,193.60
DIV 32	H&H/Greenshade: Regrade Area North of DaVinci & Add Grate to Junction Box		\$ 3,739.38
	Ram Products: Automatic Drain for Waste Oil		\$ 611.84
	Garady: Dams for Wash Bay (Material Only)		\$ 739.75
DIV 10	Felix: Additional Door Hardware for Exterior Doors		\$ 1,530.74
DIV 9	Wiljo/Naff: Addition of Expansion Joint at North Wall of Fleet Work Bays		\$ 1,000.00
	Subtotal for Subcontractors' Work		\$ 34,094.82
2.	Itemized Direct Project Management Cost Increases (if any)		
	Field Engineer (Layout): 0 Days @ \$70/HR		\$ -
	Labor Foreman: 0 Days @ \$65/HR		\$ -
	Burden Rate (58% DPM Costs)		\$ -
	Subtotal for Direct Project Management Cost Increases (if any)		\$ -
	Subtotal 1. + 2.		\$ 34,094.82
3.	Construction Manager's Self Performed Work		
	RFI #125 - IR Heater Corrections per City Inspector Comments		\$ 5,649.72
	Saw Cut & Install Plates for Saw Cut Trench at Vehicle Lift		\$ 2,961.48
	Labor Cost: 23 Hours @ \$45/HR (Incl. Burden Rate @ 58%)		\$ 1,635.30
	Note: Labor Cost To Install Signage, Additional Door Hardware & Dams at Wash Bay	-	
	Subtotal for Construction Manager's Self Perfrom Work		\$ 10,246.50
	Subtotal, Cost of Work and Direct Proj Mgmt Cost		\$ 44,341.32
4.	Construction Manager Fee (Percent of Subtotal 1. and 2. above)	10.00%	3,358.79
5.	Construction Manager Overhead (Percent of Subtotal 1. and 2. above)	5.00%	1,679.40
6.	CM's Liability Insurance	0.65%	\$ 320.97
7.	Subcontractor Default Insurance, if authorized (% of Subcontractor Subtotal)	1.60%	\$ 795.21
8.	CM's Builders Risk Insurance	0.55%	\$ 277.73
9.	Project Bonds	0.82%	\$ 416.34
	Total Cost of Change		\$ 51,189.75

Approved for Construction Any cost component may be adjusted in accordance with the Agreement for At-Risk Construction Manage Services.	men
Services.	

Construction Manager	Architect/Engineer	Owner

PROPOSED CHANGE ORDER SUMMARY--- CONSTRUCTION MANAGER

Construction Manager:

_		
	lintco.	-11C

THE CITY OF NORMAN

Proj Name/ #: Norman North Base - Phase 1 / 20146

PCO No.: #005

PCO Title: Owner Change Order No. 5

PCO Date: 4/5/2022

1.	Subcontractors' Work (enter amounts from Subcontractor Summary Sheets)			
DIV 9/21/23/24/26	Alpine/DSE/Orcutt/Wiljo/Naff: RFI #118 - Added Ceiling in Riser Room	-	\$	3,740.00
DIV 09	Apex: RFI #119 - Additional Rubber Base	-	\$	247.50
DIV 10	Felix: RFI #123 - Address Signage	-	\$	226.50
DIV 22	Orcutt: RFI #125 - IR Heater Corrections per City Inspector Comments	-	\$	9,566.00
DIV 10	Automic Fire Control: Additional Fire Extinguisher Cabinet (No Markup Included)		\$	282.90
DIV 09	Apex: Flooring Replacement Parks Admin		\$	2,428.00
DIV 10	Felix: Additional Door Hardware for Exterior Doors	_	\$	1,113.26
DIV 23	Orcutt: RFI #128 - Unbalanced Airflow Issues (Hot & Cold) from MAUs		\$	6,541.65
	Note: Cost for RFI #128 is the Mechanical Costs for the Test Air Blender Only. Electrical, Additional Mechanical and Additional Overhead Cost for Additional Air Blenders to be included in a seperate CO #006.			
	Subtotal for Subcontractors' Work		\$	24,145.81
2.	Itemized Direct Project Management Cost Increases (if any)			
	Field Engineer (Layout): 0 Days @ \$70/HR		\$	-
	Labor Foreman: 0 Days @ \$65/HR		\$	-
	Burden Rate (58% DPM Costs)	-	\$	-
	Subtotal for Direct Project Management Cost Increases (if any)	=	\$	-
	Subtotal 1. + 2.		\$	24,145.81
3.	Construction Manager's Self Performed Work			
	Labor Cost: 17 Hours @ \$45/HR (Incl. Burden Rate @ 58%) Note: Labor Cost To Install Signage, Additional Door Hardware & Additional FE Cabinet		\$	1,208.70
	Subtotal for Construction Manager's Self Perfrom Work	_	\$	1,208.70
	Subtotal, Cost of Work and Direct Proj Mgmt Cost		\$	25.354.51
			Ψ	20,004.01
4.	Construction Manager Fee (Percent of Subtotal 1. and 2. above)	10.00%	\$	2,386.29
5.	Construction Manager Overhead (Percent of Subtotal 1. and 2. above)	5.00%	\$	1,193.15
6.	CM's Liability Insurance	0.65%	\$	188.07
7.	Subcontractor Default Insurance, if authorized (% of Subcontractor Subtotal)	1.60%	\$	465.95
8.	CM's Builders Risk Insurance	0.55%	\$	162.73
9.	Project Bonds	0.82%	\$	243.96
	Total Cost of Change		\$	29,994.66

Approved for	Construction Ar	ny cost component n	nay be adjusted ir	n accordance with th	ne Agreement for At-R	isk Construction Managemer
Services.						

Construction Manager	Architect/Engineer	Owner

Current Delay Days Requested:

Additional Days Associated with CO# 005: 10 Working 12/22/2021 (14 Calendar Days)***

Total Working Days Requested: 10 Working Days (14 Calendar Days)
Requested Revised Substantial Completion Date: 01/21/2022

*** Note: The cause for the 10 Working Days (14 Calendar Days) delay has been a direct result of:

Our suppliers being unable to receive materials due to the current market shortages. Flintco provided notified the Owner of these delays and has worked diligently with suppliers to expedite manufacturing and delivery, if possible, and help minimize this impact.

Additions to scope & contract requested by Owner and/or Building Inspector.