

DATE:

December 18, 2020

TO:

Jeanne Snider, Assistant City Attorney II

FROM:

Brian McNabb, Traffic Signal Supervisor

SUBJECT:

Damage Cost Report - Eastbound State Highway 9 On-Ramp from

Classen Boulevard

On October 09, 2020, a roadway light pole assembly located along the eastbound State Highway 9 On-Ramp from Classen Boulevard was damaged in a vehicle accident. A responsible party has been identified on the attached collision report #2020-00065580. Listed below are the costs associated with the necessary repairs that were performed.

Material Cost

1 - ea 35-foot light pole

1 - ea 10-foot luminaire arm

1 - ea cast aluminum breakaway base 125 feet of 1/c No. 12 electrical cable

]	123 rect of 1/c No. 12 electrical caste		Total Replacement Cost			\$ 1,257.65
)	<u>Labor Cost Breakdown</u>			Total Replacement cost		
]	D. Birkhimer	0.50 hr/s reg.	@	\$ 28.07	\$ 14.04	
)			(A) St	ıbtotal	\$ 14.04	
	Supervision/Miscellaneous Time Cost					
	K. Coffin B. McNabb	1.00 hr/s reg. 1.50 hr/s reg.	@	\$ 18.72 \$ 39.43	\$ 18.72 \$ 59.15	
)	D. Riesland	1.00 hr/s reg.	@	\$ 62.41	\$ 62.41	
]			(B) Subtotal Total Labor Costs		\$ 140.28) + (B)	\$ 154.32
J	Equipment Time Cost Breakdown					
)	Unit 624	0.50 hr/s	@	\$ 15.00	\$ 7.50	
)			Total Equipment Time Costs TOTAL CHARGES			\$ 7.50 \$ 1419.47

If reimbursement funds are received, please have them deposited in Account No. 10550223-43212. Should additional information be desired, please advise.

BM/kc

Cc:

Shawn O'Leary, Director of Public Works David Riesland, Acting Transportation Engineer Barbara Andros, Revenue Collection Supervisor