


SHORT FORM PLAT NO. SFP-2526-1
BLOCK "B"
HILLTOP ADDITION
NORMAN, OKLAHOMA





UTILITY NOTE
The underground utilities shown have been located from field survey information and existing drawings. The surveyor makes no guarantee that the underground utilities shown comprise all such utilities in the area, either in service or abandoned. The surveyor further does not warrant that the underground utilities shown are in the exact location indicated although he does certify that utilities are located as accurately as possible from information available. The surveyor has not physically located the underground utilities.

[illegible][illegible][illegible][illegible]

CERTIFICATION
The field work was completed on 01/02/2024.
I further certify that this survey meets the Oklahoma Minimum Standards for the practice of land surveying and that there are no visible encroachments across the boundary lines other than those shown.

Prepared By

GOLDEN

LAND SURVEYING

4131 NW 127th St., Suite 100, Golden, CO, California 71210
CA # 265 / Exp. Date = 6/30/2026
Telephone: (410) 849-5010 Email: traygold@comcast.net
Surveyor License # 14001 Registered since 10/01/2016

Sheet 1 Of 1



10/01/2016 to 10/01/2026
Professional Engineer
State of Colorado
License No. 14001