

Young PLUMBING & HEATING CO.

Mechanical Contractors

2/18/2020

Oelwein Public Library

Brent was out recently and found a compressor shorted out and needs replaced.

Below is a cost of repair:

Labor and material to replace the compressor in the west zone:

Price..... \$9,742.00

This does not include any additional work on refrigeration lines. Additional work may be needed and is not included in this bid.

Thanks!
Lindsey Nissen
Service Department Director
Young Plumbing and Heating Co.